

Veron Chen (LKKAUTO)

From: mtreg <mtreg@income.com.sg>
Sent: Friday, 14 December 2018 7:21 PM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi

Claim created.

With Regards

Azlin Rani
Senior Administrator, Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

*'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504.
Please forward all motor claims related correspondences to mtcl@income.com.sg so that we can attend to it accordingly.'*

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 14 December, 2018 10:08 AM
To: mtreg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Please provide us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/1021545 - 002	SMRT TAXIS PTE LTD	SHC 4684P	YN 974U

D.O.A	Time of Accident	Estimate	Tentative repair cost
23/11/2018	15:00	\$5,556.50	\$2,450.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

23/11/2018 18:01

Vehicle No.(For Motor)

YN974U

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="checkbox"/>	5072502790-02		TVH SINGAPORE PTE. LTD.	200203510Z	GCV	Comprehensive	YN974U	YN974U	06/07/2017	10/12/2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4684P
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6129034
Chassis No.:	JTDKN36U405748758
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	10 Sep 2014
First Registration Date:	10 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	09 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$23,960.00
Total Rebate Amount:	\$30,026.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2018 10:10
Date Of Accident	23/11/2018 15:00
Exact Location Of Accident	57 SENOKO ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4684P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIR AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAN AI BEE
NRIC No	S1212800B
Date Of Birth	01/09/1955
Occupation	OUTDOOR
Date Of Driving Pass	29/05/1974
Driving Experience	44 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : WOO HON KIAT
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS ALIGHTING A PASSENGER ALONG 57 SENOKO ROAD. THERE WAS LORRY STATIONARY AND THERE WAS NO DRIVER IN THE LORRY. WHILST MY PASSENGER (MALE CHINESE) WAS GOING TO OPEN THE DOOR TO ALIGHT, SUDDENLY THE LORRY ROLLED BACKWARD AND THE PASSENGER QUICKLY CLOSED THE DOOR AND I WAS TRYING TO MOVE FORWARD. BUT IT WAS TOO LATE, THEN THE LORRY HIT ONTO THE LEFT PORTION OF MY TAXI. I SAW THE SECURITY GUARD AND I SHOUTED AT HIM. THE DRIVER OF THE LORRY WAS ALSO STANDING BESIDE THE SECURITY GUARD AT THE POINT OF TIME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN974U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOHD YAZID BINABDUL GANI
NRIC/Passport Number	S7098137H
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Case Details

Case Reference Number : TAX/11/18/2107
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4684P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4683-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 23/11/2018 07:00 AM
 Vehicle Age(In Months) : 50

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			DOOR RR/LH <i>gt</i>	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace ▾
One Time Key In	Main			FENDER RR/LH <i>gt</i>	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace ▾
One Time Key In	Main			QUARTER GLASS RR/LH <i>ne</i>	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace ▾
One Time Key In	Main			SEALANT W/SCREEN <i>ne</i>	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace ▾
One Time Key In	Main			CAP ASSY, FUEL TANK <i>R</i>	1	68.10	68.10	25.00	51.07	Replace	1	0	Repair ▾
One Time Key In	Main			PIXEL STICKER <i>ne</i>	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾
One Time Key In	Main			STICKER SMRT LOGO <i>ne</i>	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾
One Time Key In	Main			STICKER DECAL 6555 8888 <i>ne</i>	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾
Total Spare Part Cost									1,998.47		Surveyor Total	1,603.45	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									1,598.78		Final Sur Total	1,282.76	

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	0	0	Not Give

Total Spare Part Cost 1,998.47

Surveyor Total 1,603.45

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 1,598.78

Final Sur Total 1,282.76

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR LH PORTION	845.00	600	
Total:		845.00	600.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FUEL LID COVER	180.00	50	
2	TO RESPRAY REAR DOOR LH	378.00	200	
3	TO RESPRAY REAR FENDER LH	378.00	200	
4	TO REPSRAY REAR BUMPER	378.00	0	XAN
Total:		1,314.00	450.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60	
3	TO TRANSFER DOOR MECHANISM	120.00	60	
4	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00	
Total:		825.00	405.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	TO REMOVE / REFIT SEAT	120.00	60	
6	TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	60	
7	TO WASH AND VACUUM	60.00	0	^ 1
8	TO REPLACE SUNDRY PARTS	100.00	0	^ ^
Total:		825.00	405.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,598.78	1,282.76
Total Labour Cost	845.00	600.00
Total Spray Painting	1,314.00	450.00
Other	825.00	405.00
Overall Total	4,582.78	2,737.76
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,600.00	2,750.00
Surveyor Approved Amount		2,750.00
No of Repair Days*	5	5
Remarks	-	Surveyor Remarks

Surveyor Name

Rasul

Signature

Rasul



29/11/18

Save

Clear

Survey Date

26/11/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Acknowledged by Repairer

Signature:

Date:



Section A - Accident Details

Registration Number	SHC4684P
Case Reference Number	TAX/11/18/2107
Registration Date	10/09/14
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN AI BEE
Type of Accident	Others
Accident Date and Time	23/11/18 3:00 PM
Accident Reported Date and Time	23/11/18 4:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098901
Special Instruction to ARC, if any	TP
Prepared Date and Time	26/11/18 11:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



10c

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$1,314.00	\$450.00
Total Spare Part Cost	\$1,988.47	\$1,603.45
Total Other Cost	\$825.00	(\$203.45)
TOTAL COST	\$4,982.47 <i>5556.50</i>	\$2,450.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	5.0
Prepared / Adjusted By	Zhi Yang Phua	RASUL (LKK) / NTUC
ARC / Surveyor Sign Off Date	28/11/2018 9:22 AM	26/11/2018 5:01 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0170	Invoice Number	
Quotation Date	10.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FUEL LID COVER	\$180.00	\$50.00
TO RESPRAY REAR DOOR LH	\$378.00	\$200.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,314.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$608.45)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$125.00
TO REMOVE / REFIT SEAT	\$120.00	\$60.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	\$120.00	\$60.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$825.00	(\$203.45)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67004-47080	DOOR RR/LH	1.00	\$954.50	25.00	\$715.88	Replace	Replace
		61602-47091	FENDER RR/LH	1.00	\$766.80	25.00	\$575.10	Replace	Replace
		82720-47031	QUARTER GLASS RR/LH	1.00	\$168.10	25.00	\$126.07	Replace	Replace
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace
		77300-52030	CAP ASSY, FUEL TANK	1.00	\$68.10	100.00	\$0.00	Replace	Repair
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
			STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace
		52159-47905	BUMPER REAR	0.00	\$458.60	0.00	\$0.00	Replace	Not Given
Total					\$2,542.50		\$1,603.45		

1603.45
+ 600.00
+ 855.00

3058.45
- 20%

2446.77

5586.50

45 \$2450/-

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 13 December 2018 12:39 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Rasul (LKKAUTO)
Cc: SUR; CS A Team; 'Leong Chee kwong'
Subject: RE: SHC4684P-DOA: 23/11/2018

Dear Poh Suan,

WITHOUT PREJUDICE

Confirmed Lump Sum \$2,450 @ 5 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>
Sent: Thursday, 13 December 2018 10:52 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; 'Leong Chee kwong' <cheekwongwega@gmail.com>
Subject: SHC4684P

Hi Rasul,

Attached herewith the repair estimate of SHC 4684P having Case No: TAX/11/18/2107.

There is no change to the approved amount of \$2,450 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Sent: Thursday, 13 December 2018 10:53 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18021519/R1vd3e2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 27-12-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 974U	Veh. Inspected	SHC 4684P
Policy No.	5072502790-02	Coverage (\$)	0.00
Claim No.	MT/1021545-002	Excess (\$)	0.00
Assign From		Assign Date	26/11/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U405748758	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/11/2018	Inspection Date	26/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4684P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR RR/LH (DISC 25%)	BENT	954.50	715.88
1	FENDER RR/LH (DISC 25%)	BENT	766.80	575.10
1	QUARTER GLASS RR/LH (DISC 25%)	NECESSARY	168.10	126.07
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER REAR	SERVICEABLE	458.60	-
1	CAP ASSY, FUEL TANK	TO REPAIR SEE LABOUR	68.10	-
			2,602.50	1,603.45
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF CAP ASSY, FUEL TANK.		845.00	600.00
	SPRAY PAINT.		1,314.00	450.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	60.00
	TO TRANSFER DOOR MECHANISM.		120.00	60.00
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.		125.00	125.00
	TO REMOVE / REFIT SEAT.		120.00	60.00
	TO REMOVE & REFIT REAR QUARTER GLASS LH.		120.00	60.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
			-	-
			-	-
			-	-
			-	-
			-	-
			2,984.00	1,455.00
	GRAND TOTAL		5,586.50	3,058.45

Report Ref No. NS/INC18021519/R1vd3e2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,450.00
---	--	--	----------

Report Ref No. NS/INC18021519/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.