

ASS. REC. BY:

REF:

CS/CTI/802/524/RI+d3ⁿ²

Special Instruction:

Surveyor:

Razul

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 27/11/18 @ 10.53am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 3871B

Insured:

SLW 809X

at Workshop m/s

World Auto

Tel:

63621776

of

No 1 Krungi Loop

Policy No:

DMPCSN3019901800

Claim No:

SNM18D05514C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/11/18

CA / REV / REP. / REV 24 HRS

1up

28/11/18

H.O.D. Endorsement:

Date/Time:

12.23pm @ 27/11/18

Person Contacted:

Ainee

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 3871B - X
	SLW 809X - X
26/12 -	COR \$3326.40, 5 days confirm with Sophia (Red: 6640! 63%)

Surveyor *P. S. S. S.*

REF: CTI

4597K

ASSIGNMENT

From: _____ Date: **28/11/18**

Estimated Cost: _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SLQ 3871B**

at Workshop m/s **World Auto**

of **No. 1 Krunji loop**

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: **Morning**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **lup**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLQ 3871B** Yr Regn: **2017 / July**

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Vezel Hybrid 1.5A c.c 1496**

Colour: **Grey** A/C: Insured / Std / NI / NA

Sp. Reading: **125510** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **RU31222469**

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modl: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: **215/60R16**

R: **7**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **ROVELLO**

Front

Rear

R/Bal. **5** mm R/Bal. **5** mm

L/Bal. **5** mm L/Bal. **5** mm

D.O.A. **23/11/18** D.O.I. **28/11/18**

Survey held at **World Auto**

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 26 DEC 2018

Date/Time, File Pass to?

1) **26/12 Typist**

Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.V: (\$) **3326.40**

TP

Days Of Repair: **5**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos:

) Others:

TOTAL

220

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 November 2018 10:53 AM
To: ainee31@worldauto.com.sg; ganping@worldauto.com.sg
Cc: assignments; Admin A; Lucas Lee
Subject: CTP REF NO. SLW809X YOUR REF NO. SLQ3871B - ACCIDENT INVOLVING SLW809X AND SLQ3871B ON 23 NOVEMBER 2018

Dear Sir,

We refer to the above matter and our telephone conversation a moment ago.

As spoken, you have requested for LKK to survey your vehicle.

Aside to LKK: Please liaise with Ms Ganping from World Auto for the PRS.

Thank you.

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 26 December 2018 10:25 AM
To: 'tggtan@worldauto.com.sg'; Rasul (LKKAuto)
Cc: Admin A; SUR
Subject: RE: SLQ 3871B Our ref: TP/2342/18

Dear Sophia,

Confirm COR \$3826.40, 5 repair days

Please submit all relevant documents to China tai ping directly.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Thursday, 6 December 2018 1:21 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: SLQ 3871B Our ref: TP/2342/18

Hi Rasul

Attach is our estimate markings for your attention.

Can we finalise COR \$3826.40/5 REPAIR DAYS.

Kindly revert.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

-----Original Message-----

From: DocuCentre-VI C3370 <worldautopl@yahoo.com.sg>
Sent: Thursday, 6 December 2018 12:18 PM
To: tggtan@worldauto.com.sg
Subject: Scan Data from FX-11BF95

Number of Images: 2
Attachment File Type: PDF

Device Name: DocuCentre-VI C3370

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED

105 CECIL STREET #18-00 & #19-00 THE OCTAGON
069534

Attention : Motor Claim Department

Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000410

Date : 24/11/2018

Vehicle Num. : SLQ 3871B (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 23/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | | | |
|-----|---|-------------------------------------|--------|--------------|
| 1. | 1 | REAR BOOT LID DD | | 1,300.00 ✓ |
| 2. | 1 | REAR BOOT HYBRID EMBLEM (VEZEL) NEC | | 89.00 ✓ |
| 3. | 1 | REAR BOOT VEZEL EMBLEM (VEZEL) NEC | | 89.00 ✓ |
| 4. | 1 | REAR WINDSCREEN GLASS MOULDING NEC | | 250.00 ✓ |
| 5. | 2 | REAR BOOT REFLECTOR LAMP NN | 580.00 | 1,160.00 X ✓ |
| 6. | 1 | REAR BOOT LOCK ASSY NN | | 300.00 X ✓ |
| 7. | 1 | REAR BOOT WEATHER STRIP NEC | | 180.00 ✓ |
| 8. | 1 | REAR BUMPER DD | | 900.00 ✓ |
| 9. | 1 | REAR ANTENNA SENSOR NN | | 180.00 X ✓ |
| 10. | 1 | SMART BUZZER SENSOR NN | | 180.00 X ✓ |
| 11. | 1 | REAR END PANEL NN | | 680.00 X ✓ |
| 12. | 1 | REAR END PANEL TOP GARNISH NN | | 260.00 X ✓ |
| 13. | 2 | REAR TAIL LAMP NN | 580.00 | 1,160.00 X ✓ |
| 14. | 1 | REAR COMPARTMENT BOX NN | | 280.00 X ✓ |

List TotalS\$:

20.00% Discount S\$:

7,008.00

1,401.60

5,606.40

SPECIAL NETT ITEMS :

- | | | | | |
|----|---|-------------------------------------|-------|----------------|
| 1. | 1 | REAR WINDSCREEN SEALANT NEC | | 60 100.00 ✓ |
| 2. | 1 | REAR BUMPER CLIP NEC | | 40.00 ✓ |
| 3. | 1 | REVERSE SENSOR | | 200 280.00 ? ✓ |
| 4. | 1 | REAR END PANEL TOP GARNISH CLIPS NN | | 40.00 X ✓ |
| 5. | 2 | REAR TAILLAMP CLIPS NN | 40.00 | 80.00 X ✓ |

Special Nett Total S\$:

540.00

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

60 180.00 ✓

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED

105 CECIL STREET #18-00 & #19-00 THE OCTAGON
069534

Attention : Motor Claim Department

Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000410

Date : 24/11/2018

Vehicle Num. : SLQ 3871B (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 23/11/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REFIT REAR WINDSCREEN GLASS	120	180.00 ✓
		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.	40	180.00 ✓
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	500	4,500.00 ✓
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	500	4,200.00 ✓
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	60	180.00 ✓
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X 17
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)	450.00	X 17
		Labour Total S\$:		4,320.00

E. & O.E.

Total S\$: 10,466.40

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Resul
Ap 90010068
5 days
P/P
28/11/18 @ 1050
Resurvey 60 parts

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000410

Date : 24/11/2018
 Vehicle Num. : SLQ 3871B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 23/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR BOOT LID DD		1,300.00 ✓
2.	1	REAR BOOT HYBRID EMBLEM (VEZEL) NEC		89.00 ✓
3.	1	REAR BOOT VEZEL EMBLEM (VEZEL) NEC		89.00 ✓
4.	1	REAR WINDSCREEN GLASS MOULDING NEC		250.00 ✓
5.	2	REAR BOOT REFLECTOR LAMP NN	580.00	1,160.00 X
6.	1	REAR BOOT LOCK ASSY NN		300.00 X
7.	1	REAR BOOT WEATHER STRIP NEC		180.00 ✓
8.	1	REAR BUMPER DD		900.00 ✓
9.	1	REAR ANTENNA SENSOR NK		180.00 X
10.	1	SMART BUZZER SENSOR NN		680.00 X
11.	1	REAR END PANEL NN		260.00 X
12.	1	REAR END PANEL TOP GARNISH NN	580.00	1,160.00 X
13.	2	REAR TAIL LAMP NN		280.00 X
14.	1	REAR COMPARTMENT BOX NN		
List Total S\$:			2808	7,008.00
20.00% Discount S\$:			202	1,401.60
			2246.40	5,606.40

SPECIAL NETT ITEMS :				
1.	1	REAR WINDSCREEN SEALANT NEC	60	100.00 ✓
2.	1	REAR BUMPER CLIP NEC		40.00 ✓
3.	1	REVERSE SENSOR	200	200.00 X
4.	1	REAR END PANEL TOP GARNISH CLIPS NN		40.00 X
5.	2	REAR TAILLAMP CLIPS NN	40.00	80.00 X
Special Nett Total S\$:				540.00
LABOUR :			60	180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				

CONTINUE / ...

2808.00
 202
 2246.40
 SN 300.00
 Labour 1280.00
 3826.40

5 days

5

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA INSURANCE COMPANY LIMITED
 105 CECIL STREET #18-00 & #19-00 THE OCTAGON
 069534

Attention : Motor Claim Department
 Contact : 6222 2366 Fax No. : 62247478

Estimate : ES000410

Date : 24/11/2018
 Vehicle Num. : SLQ 3871B (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 23/11/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & REFIT REAR WINDSCREEN GLASS	120	180.00 ✓
		TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.	40	180.00 ✓
		REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	500	4,500.00 ✓
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	500	1,200.00 ✓
		TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	60	180.00 ✓
		DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 X
		PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00 X
		Labour Total S\$:		4,320.00 1280

E. & O.E.

Total S\$: 10,466.40

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resul
 Ap 90010068
 5 days
 P/P
 28/11/18 @ 1450
 Resur 60 paid

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021524/R1TD3N2
Date: 28/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3019901800
Claimant Vehicle No :	SLQ3871B	Insured Vehicle No :	SLW809X
Date of Loss:	23/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05514C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ3871B	Engine No:	LEB5922482
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31222469
Reg. Date:	07/07/2017 (Man. Year: 2016)	Odometer:	125510 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Rovelo 5 mm	Rear Left Side:	Rovelo 5 mm
Front Right Side:	Rovelo 5 mm	Rear Right Side:	Rovelo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,146.40	2,546.40	3,600.00	58.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,280.00	3,040.00	70.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,466.40	3,826.40	6,640.00	63.44
+ GST 7.00/7.00% (\$\$)	732.65	267.85	464.80	63.44
Nett Amount (\$\$)	11,199.05	4,094.25	7,104.80	63.44

INSPECTION

Date of Assignment:	06/12/2018	
Date Inspected:	28/11/2018	Inspected At: World Auto Pte Ltd (HQ) 47 Jln Pemimpin, #01-02/03 Halcyon 2 Singapore 577200
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2018)
Parts: M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ3871B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,300.00 FL	*1,300.00 FL
2	1		*REAR BOOT HYBRID EMBLEM (VEZEL)	Necessary	89.00 FL	*89.00 FL
3	1		*REAR BOOT VEZEL EMBLEM (VEZEL)	Necessary	89.00 FL	*89.00 FL
4	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	250.00 FL	*250.00 FL
5	2		*REAR BOOT REFLECTOR LAMP	Not Necessary	1,160.00 FL	*- FL
6	1		*REAR BOOT LOCK ASSY	Not Necessary	300.00 FL	*- FL
7	1		*REAR BOOT WEATHER STRIP	Necessary	180.00 FL	*180.00 FL
8	1		*REAR BUMPER	Dented	900.00 FL	*900.00 FL
9	1		*REAR ANTENNA SENSOR	Not Necessary	180.00 FL	*- FL
10	1		*SMART BUZZER SENSOR	Not Necessary	180.00 FL	*- FL
11	1		*REAR END PANEL	Not Necessary	680.00 FL	*- FL
12	1		*REAR END PANEL TOP GARNISH	Not Necessary	260.00 FL	*- FL
13	2		*REAR TAIL LAMP	Not Necessary	1,160.00 FL	*- FL
14	1		*REAR COMPARTMENT BOX	Not Necessary	280.00 FL	*- FL
15	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
16	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
17	1		*REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
18	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
19	2		*REAR TAILLAMP CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,548.00	3,108.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,401.60	561.60
Total Parts (\$\$)	6,146.40	2,546.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
2	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS	New	180.00	40.00
3	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	1,500.00	500.00
4	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	New	1,200.00	500.00
5	TO CHECK REAR WIRES,CONNECTORS,REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITATIONS	New	180.00	60.00
6	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	-
7	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	-
8	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
Gross Labour Cost (S\$)			4,320.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >