



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



PORSCHE

LONPAC INSURANCE BHD		NAME : Ms Tong How Teng		WIP : 40203	
101 THOMSON ROAD		ADDRESS : Blk 7 Alexandra View		EXCESS :	
#19-00 SHAW TOWER		#29-06		DATE: 29.11.2018	
SINGAPORE 189702		Singapore 158741			
ATTN. : MOTOR CLAIMS		TEL :			
FAX :					
VEH NO :	SMF3369G	DATE IN :		CONTACT PERSON :	EVA 63310683
CHASSIS NO :	WP0ZZZ98ZKS200071	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	Boxster PDK	DATE REG.:	05.11.2018	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	P982-898-352-A -G2X	de ✓	\$ 1,584.60
2	BUMPER SPOILER SUPPORT	1	P982-807-125- -OK1	?	\$ 220.80
3	BUMPER COVER	1	P982-898-307- -	de ✓	\$ 424.00
4	SENSOR PARKASSIST	2	P5Q0-919-275-C -G2X	X	\$ 455.20
5	SENSOR GASKET	2	P5Q0-919-133- -9B9	nei ✓	\$ 5.00
6	TAIL PIPE COVER	1	P982-815-099- -OK1	? i	\$ 174.00
7	TOP REAR SPOILER	1	P982-827-934- -G2X	R x	\$ 657.70
8	LOGO"BOXSTER"	1	P981-559-237-01-	nei ✓	\$ 124.00
9	LOGO "718"	1	P982-853-675-A -	nei ✓	\$ 130.70
10	TAIL PIPE <i>- photo old & new</i>	1	P982-251-187-K -	cut ✓	\$ 1,135.50
11	CLAMP	2	P981-111-240-00-	X	\$ 143.20
12	EXHAUST GASKET	2	P982-251-263- -	nei ✓	\$ 18.00
13	HEXAGON NUT (WF57)	4	P900-910-003-03-	nei ✓	\$ 20.40
TOTAL PARTS					\$ 5,093.10
LESS 10%					\$ 509.31
TOTAL PARTS COST					\$ 4,583.79

Labour Description

1	TO REMOVE / REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560	2340	\$ 4,680.00
2	TO RESPRAY REAR BUMPER & TOP SPOILER .		1850	\$ 2,600.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.		NETT ✓	\$ 1,560.00
4	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.		NETT X	\$ 70.00
5	TO APPLY SPECIAL COATING. <i>check for invoice</i>		NETT ?	TBA
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		100	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		480	\$ 600.00

8	SUNDRIES.	NETT 30	\$ 50.00
		TOTAL LABOUR	\$ - \$ 9,810.00
		TOTAL PARTS	\$ - \$ 4,583.79
		TOTAL	\$ - \$ 14,393.79
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Taughm 97495749
WP
30/11/18.
Resurvey before paint.
04 days.
sur@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: