



**STUTTGART AUTO PTE LTD**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**ESTIMATE COST OF REPAIRS**



**PORSCHE**

<b>LONPAC INSURANCE BHD</b>		<b>NAME :</b>	<b>Ms Tong How Teng</b>	<b>WIP :</b>	40203
101 THOMSON ROAD		<b>ADDRESS :</b>	Blk 7 Alexandra View	<b>EXCESS :</b>	
#19-00 SHAW TOWER			#29-06	<b>DATE:</b>	29.11.2018
SINGAPORE 189702			Singapore 158741		
<b>ATTN. :</b>	MOTOR CLAIMS	<b>TEL :</b>			
<b>FAX :</b>					

<b>VEH NO :</b>	<b>SMF3369G</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	EVA	63310683
<b>CHASSIS NO :</b>	WP0ZZZ98ZKS200071	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	TP	
<b>MODEL :</b>	Boxster PDK	<b>DATE REG.:</b>	05.11.2018	<b>POLICY NO. :</b>		

**NATURE OF WORKS**

<b>S/NO</b>	<b><u>Parts Description</u></b>			<b>REVISED</b>	<b>PRICES</b>
	<b>QTY</b>				
1	REAR BUMPER	1	P982-898-352-A -G2X		\$ 1,584.60
2	BUMPER SPOILER SUPPORT	1	P982-807-125- -OK1		\$ 220.80
3	BUMPER COVER	1	P982-898-307- -		\$ 424.00
4	SENSOR PARKASSIST	2	P5Q0-919-275-C -G2X		\$ 455.20
5	SENSOR GASKET	2	P5Q0-919-133- -9B9		\$ 5.00
6	TAIL PIPE COVER	1	P982-815-099- -OK1		\$ 174.00
7	TOP REAR SPOILER	1	P982-827-934- -G2X		\$ 657.70
8	LOGO"BOXSTER"	1	P981-559-237-01-		\$ 124.00
9	LOGO "718"	1	P982-853-675-A -		\$ 130.70
10	TAIL PIPE	1	P982-251-187-K -		\$ 1,135.50
11	CLAMP	2	P981-111-240-00-		\$ 143.20
12	EXHAUST GASKET	2	P982-251-263- -		\$ 18.00
13	HEXAGON NUT (WF57)	4	P900-910-003-03-		\$ 20.40
	<b>TOTAL PARTS</b>				\$ 5,093.10
	<b>LESS 10%</b>				\$ 509.31
	<b>TOTAL PARTS COST</b>				<b>\$ 4,583.79</b>

	<b><u>Labour Description</u></b>		
1	TO REMOVE / REPLACE REAR BUMPER, OTHER DAMAGED PARTS & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 4,680.00
2	TO RESPRAY REAR BUMPER & TOP SPOILER .		\$ 2,600.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ 1,560.00
4	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT	\$ 70.00
5	TO APPLY SPECIAL COATING.	NETT	TBA
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 600.00

8	SUNDRIES.	NETT	\$ 50.00
		TOTAL LABOUR	\$ - \$ 9,810.00
		TOTAL PARTS	\$ - \$ 4,583.79
		TOTAL	\$ - \$ 14,393.79
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		<b>GRAND TOTAL</b>	<b>\$ - \$ -</b>

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.