

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#27-01/02 AXA Tower

Singapore 068811

Attn: Motor Claims Department

Date : 27/11/2018

Vehicle No : SGT3939J

Veh Make/Model : Mazda M6 SP20 SDN

YOM : 2007

Chassis No : JM6GG10F270540463

Date of Accident : 26/11/2018

Not authorized
1/1 Sep @ 7
Resurvey After P.A.M
3 days

No	Qty	Description	Amount \$
List Items:-			
1	1	Rear bootlid	\$ 1,003.60 X
2	1	Rear bumper	\$ 913.30 ✓
3	1	Rear bumper reflector (LH)	\$ 34.40 X
4	1	Rear bumper reflector (RH)	\$ 34.40 X
5	2	Rear bumper side retainer	\$ 74.00 X
6	1	Rear bumper reinforcement	\$ 529.60 7
7	1	End panel	\$ 401.70 X
8	1	Rear LH mudflap cover	\$ 73.00 X
9	1	Rear RH mudflap cover	\$ 73.00 X
Total - List Item			\$ 3,137.00
Less 20%			\$ 627.40
Total			\$ 2,509.60
Special Nett Items:-			
1	1	Rear number plate with holder	\$ 55.00 X
2	1 Set	Rear reverse sensor	\$ 380.00 2000
3	10	Rear bumper clip	\$ 45.00 ✓
Total - SN Item			\$ 480.00
Labour Charges:-			
1		Spray painting on all affected area.	\$ 600.00 4000
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 700.00 3000
3		To apply anti rust treatment.	\$ 80.00 X
4		To check wiring system & light.	\$ 60.00 150
6		To remove and replace reverse sensor.	\$ 120.00 500
Total - L/C			\$ 1,560.00
Sub-Total			\$ 4,549.60
7% GST			\$ 318.47
Total			\$ 4,868.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: