

Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.

GST Registration No: 53076555A Email: paul@soonbee-vbm.com.sg

Quotation No. : SB-GA-TCC18027

Date: 30-Nov-18

AXA INSURANCE PTE LTD

8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sir/Mdm,

Estimated Cost of Repair Job for:

SBS6465D

Accident on 22/11/2018, along UPPER SERANGOON ROAD BEFORE HOUGANG AVE 8 and AVE 7 involving SBS6465D and SKD5699A

We are pleased to submit the below estimated quotation for your consideration.

1)	Vehicle No : Model :	SBS6465D MERCEDES-BENZ CITARO O530-6.4 L AT TURBO ABS (A)		
2)	List Item: Light amber LED Off Side no. 4 body panel <i>X Rep</i> Paint Material (Green/ White/ thinner/ Lacquer)	Qty 2 1 1	Nett Unit Price: (S\$) \$120.00 \$3,202.29 \$800.00	Sub Total: (S\$) \$240.00 \$3,202.29 \$800.00 <i>700</i>
Parts Total Sum:				\$4,242.29
Labour: Labour charges to remove and refit off side no. 4 body panel and light amber LED Labour charges to repair and realign damaged near side battery cover panel and battery cover bracket holder, near side radiator access door Labour charges to repair and realign damaged near side rear corner bumper and light amber LED and near side frame skirting Labour charges to check and rectify wiring Labour charges to re-spray and polishing affected area				
				\$3,200.00 <i>1800</i> \$180.00 <i>50</i> <i>1200</i> \$1,600.00
Labour Total Sum:				\$4,980.00
Parts and Labour Total Cost:				\$9,222.29
GST (7%) :				\$645.56
Total :				\$9,867.85
Repair Duration: 6 Working Day				
Term of Payment: 30 Days Upon Invoice				

Regards,

Acknowledged by Repairer
Signature:

Date:

Surveyor Name:

Surveyor NRIC:

1st Signature /Date:

2nd Signature / Date:

3rd Signature / Date:

Appointed Surveyor confirmation & agreed:



Paul

3 Rep.

4/5
After Repair p lta