

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

TPAXA.
Asher.

Estimate Quotation

Quotation No	Nov 003/2018
Date	24/11/2018
Vehicle No	SJQ6708U
Make / Model	Toyota Altis

MR0532EE106144914

To:

Address:

Qty	DESCRIPTION Items	UNIT	Amount
1 pc	front bumper <i>del</i>		\$ 563.00 ✓
1 set	front bumper clip <i>re</i>		\$ 40.00 ✓
2 pcs	front bumper side retainer <i>re</i>	\$ 78.00	\$ 156.00 ✓
1 pc	front bumper reinforcement <i>Best</i>		\$ 392.00 ✓
1 pc	front number plate <i>del</i>		\$ 60.00 ✓
1 pc	front grille <i>del</i>		\$ 352.00 ✓
1 pc	front grille emblem <i>re</i>		\$ 73.00 ✓
1 pc	front lock <i>re</i>		\$ 110.00 ✓
1 pc	front brace panel <i>Best</i>		\$ 113.00 ✓
2 pcs	headlamp <i>RT del, LH re</i>	\$ 485.00	\$ 970.00 ✓ 485
1 set	front grille clip <i>re</i>		\$ 40.00 ✓ 20
1 pc	aircon condenser <i>re</i>		\$ 1,289.00 ✓
1 pc	radiator <i>re</i>		\$ 1,550.00 ✓
1 pc	aircon suction pipe <i>re</i>		\$ 185.00 ✓
1 pc	aircon drochange pipe <i>re</i>		\$ 175.00 ✓
1 pc	o/s front fender <i>re</i>		\$ 687.00 ✓
1 pc	n/s front fender <i>re</i>		\$ 675.00 ✓
2 pcs	front fender inner shield <i>re</i>	\$ 195.00	\$ 390.00 ✓
2 set	front fender inner shield clip <i>re</i>	\$ 40.00	\$ 80.00 ✓
1 pc	rear bumper <i>del</i>		\$ 594.00 ✓
1 set	rear bumper clip <i>re</i>		\$ 40.00 ✓
2 pcs	rear bumper side retainer <i>re</i>	\$ 78.00	\$ 156.00 ✓
2 pcs	rear bumper reflector <i>re</i>	\$ 93.00	\$ 186.00 ✓ 153
1 pc	boot lid <i>del</i>		\$ 997.00 ✓
1 pc	boot lid "CENTRE" emblem <i>re</i>		\$ 75.00 ✓
1 pc	boot lid "1.6" emblem <i>re</i>		\$ 71.00 ✓
1 pc	boot lid "COROLLA" emblem <i>re</i>		\$ 73.00 ✓
1 pc	boot lid "ALTIS" emblem <i>re</i>		\$ 71.00 ✓
1 pc	boot lid outer chrome moulding <i>del</i>		\$ 263.00 ✓
1 pc	rear number plate <i>re</i>		\$ 60.00 ✓
2 pcs	boot lid hinge <i>Best</i>		\$ 77.00 ✓
1 pc	boot lid inner lock <i>del</i>		\$ 136.00 ✓
1 pc	boot lid windstrip <i>re</i>		\$ 195.00 ✓
2 pcs	boot lid reflector <i>RT del, LH re</i>	\$ 195.00	\$ 390.00 ✓ 195
2 pcs	tail lamp <i>RT del, LH re</i>	\$ 475.00	\$ 950.00 ✓ 770
1 pc	rear end panel <i>del</i>		\$ 680.00 ✓
1 pc	rear end panel top garnish <i>del</i>		\$ 252.00 ✓
1 set	rear end panel top garnish clip <i>re</i>		\$ 40.00 ✓ 20
1 set	reverse sensor <i>del</i>		\$ 200.00 ✓
1 pc	spare tyre hard board <i>re</i>		\$ 385.00 ✓
1 pc	boot lid inner trim <i>re</i>		\$ 285.00 ✓

6875

515625

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

1	Labour Charge			
2	to dismantle damaged parts, panel beat, repair		\$	1,500.00
3	to putty and spray painting on affected area		\$	1,600.00
4	anti rust		\$	200.00
5	wiring check		\$	80.00
6	air con		\$	150.00
7	reverse sensor		\$	80.00
Subtotal:			\$	17,686.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian Lij
H/S 29/11/18

10 Days

total: 7836.25

H/S: 5.51C.
(Nett Value)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: