

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD3454M

MAKE :

MODEL : HYUNDAI i40

DATE 26/11/2018 16:48

PD

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 553.00	
	Rear Bumper Clip 10 pcs ✓			\$ 22.00	
	Rear Bumper Bracket ✗		\$ 35.60	\$ 71.20	
	Rear Bumper Under Cover ✗			\$ 228.00	
	SUB TOTAL			\$ 874.20	
	LESS 20%			\$ 174.84	
	DISCOUNTED TOTAL			\$ 699.36	
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 400.00 ²⁰⁰	
	Spray Painting Charge			\$ 300.00 ²⁰⁰	
	Wiring Charge			\$ 30.00 ✗	
	Remove/Refix Reverse Sensor			\$ 80.00 ³⁰	
	TOTAL LABOUR			\$ 810.00	
	ESTIMATE TOTAL			\$ 1,809.36	
<i>Ka Lin 10/11/18</i> <i>29/11/18 1330h</i> <i>2 Days</i> <i>PIP</i> <i>Before Paint photo</i> LKK Auto Consultants hereby notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged parts during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					