

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05894

Vehicle Insured : SLL7768S

Accident Date : 24-Nov-2018

Date : 28-Nov-2018

Our Ref : 218200 (AIG) / CHAN

PAGE : 1

TENG KOK WAI
224 WESTWOOD AVENUE
#05-14
Singapore 648356

Not Authorised
Resurvey B & paint

5 days

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER PREMIUM SKR5214S

=====

1 pc	Tail gate	<i>RM</i>	1,369.50	✓
1 pc	Tail gate inner lock		863.10	✓
1 pc	Tail gate inner trim cover	<i>RM</i>	673.60	✓
1 pc	Tail gate rubber	<i>RM</i>	410.40	✓
1 pc	Tail gate glass moulding	<i>RM</i>	81.80	✓
1 pc	Tail gate "HARRIER" emblem	<i>RM</i>	72.10	✓
1 pc	N/s tail gate lamp	<i>RM</i>	412.20	✓
1 pc	Rear bumper fascia	<i>RM</i>	1,712.60	✓
1 pc	Rear bumper lower spoiler	<i>RM</i>	482.70	✓
2 pcs	Rear lower spoiler reflector @ S\$ 54.10		108.20	✓
2 pcs	Rear bumper side retainer <i>MSD</i> @ S\$ 90.80		181.60	✓
1 pc	Rear bumper sponge		137.80	✓
2 pcs	Rear bumper parking sensor @ S\$381.60	<i>RM</i>	763.20	✓
2 pcs	Rear bumper lower spoiler clip @ S\$ 3.90	<i>RM</i>	7.80	✓
1 pc	Rear end panel	<i>RM</i>	715.70	✓
1 pc	End panel top garnish	<i>RM</i>	385.70	✓
1 pc	Spare tyre panel	<i>RM</i>	842.20	✓

9,220.20

Less 25% : 2,305.05

- 1 pc Rear w/s glass sealant
1 pc Rear no.plate with box

6,915.15 *40%*
RM 60.00 sn
RM 50.00 sn *45%*

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 *120%*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLL7768S

Page : 2

To remove roof lining, front and
rear seats, trim board and carpet

601
120.00

To apply undersealing

100.00 *601*

To putty and spray replaced parts

1,200.00 *800*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,400.00 *?*

To remove and refix exhaust
silencer box

na 80.00 *X*

Total : S\$10,075.15
=====

Singapore Dollars Ten Thousand and Seventy Five
and Cents Fifteen Only