T K MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56 SINGAPORE 417883 TEL:96273323 FAX: 68442641 CO. REG NO:53049097L

DATE: 30/11/2018

WENDY WONG SWEE LIAN 24 GLASGOW RD #03-08 SINGAPORE 549340

TO ALG.

DEAR SIR

20%

ACCIDENT DATE:26/11/2018

ESTIMATE COST OF REPAIRS BILL TO TOYOTA C-HR HYBRID 1.8G CVT CAR NO:SJG6702M

1 PC REAR BUMPER (TOP) Could 1 PC REAR BUMPER (LOWER) Defined 1 PC REAR BUMPER REINFORCEMENT BEAM 844 8 PC REAR BUMPER CLIP @ 12.30 X 8PC 1 SET REAR REVERSE PARKING SENSOR 2 PC REAR BUMPER BRACKET COULD 1 PC REAR KEYLESS SENSOR	782.20 543.10 517.40 98.40 280.00 64.80 278.90	782.20 543.10 517.40 98.49 280.00 64.80 278.90 × 4
TO CHECK WIRING. TO SPRAY PAINTING. TO REMOVE & REFIX REAR INTERIOR UPHOSLY & CUSHION.	50.00 650.00 80.00	59.99 3 0 950.90 500 80.00 *
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION. TO MEASURE, DRILL THE REPLACED BUMPER, POSITION & RESTALL REAR REVERAE SENSOR, CONTROL UNIT, CHECK & TEST FOR FUNCTIONING. TO CARRY OUT DIAGNASTIC CHECKS & RESET FAULT CODE.	80.00 80.00 150.00	80.00 × 50 150.00 ×
TO LABOUR CHARGE FOR PANEL BEATING, WELDING REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.	550.00	550.00 250

TOTAL S\$

4,204.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer.

Signature:

Deter

Hot. 1937.30 Lends/ 1452.97 S.N: 200 Labour 880 total 2482.97 L/S 1950 030ays.

