



Case Details

Case Reference Number : TAX/11/18/2120
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5487R

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-4711-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 24/11/2018 04:45 AM
Vehicle Age(In Months) : 12

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair ▾
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace ▾
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0	Check ▾
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	175.80	175.80	25.00	131.85	Replace	0	0	Not Give ▾
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace ▾
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0	Check ▾
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check ▾
									Total Spare Part Cost	4,510.90	Surveyor Total	411.30	
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0	
									Final Spare Part Cost	4,510.90	Final Sur Total	411.30	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT LH PORTION	845.00	300	
Total:		845.00	300.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT FENDER LH	378.00	200	
2	TO REPSRAY FRONT BUMPER	378.00	200	
Total:		756.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	TO WASH AND VACUUM	60.00	0	
5	TO REPLACE SUNDRY PARTS	100.00	20	
Total:		460.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,510.90	411.30
Total Labour Cost	845.00	300.00
Total Spray Painting	756.00	400.00
Other	460.00	60.00
Overall Total	6,571.90	1,171.30
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,171.30

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Surveyor Approved Amount		1,171.30
No of Repair Days*	5	3
Remarks	.	Resurvey before paint
Surveyor Name		Taufikh
Signature		
Survey Date	27/11/2018	Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: