

INSURANCE

INS. CASE OWNER:

CC h/AIG1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st): 04/12/18

Non-Reporting ltr (2nd): 21/03/19 - 1st AR

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MEB

Repair Cost:

SS 4,494.75

(4 days) Reduction: 60 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 29.11.19

Confirm with LEE GEX

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

SS 4,494.75

O.D (CHANGED LANE HIT TP

Loss of Rental (LOR):

SS 120.38

(6 days) x 120.38

Loss of Use (LOU):

SS -

(\$ x days)

Loss of Income (LOI):

SS 300.00

(\$ 50 x 6 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

SS 1.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 5,504.03

Global Sum SS: 5,500.00

FINAL PAYMENT

Date/Time: 29.11.19

Confirm with: LEE GEX

Email ☒ Call ☐

Payee 1:

SS 5,500.00

Name 1:

SMRT TAXI PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Pasme

REF:

5369K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHF 330X

Yr Regn:

2017 DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIMS HYBRID 1.8 1798

Colour:

MAROON

A/C:

Insured / Std / NI / NA

Sp Reading:

51762

T/Radio:

Insured / Std / NI / NA

Eng No:

C/N:

3TDKB3FU303576548

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front:

Rear:

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A:

27/11/18

D.O.I:

28/11/18

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

~~FR~~ N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

PLP \$4,494.75

CRAB: \$9,865.93 (68%)

11/18/2124

ATG

SGJ342C

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S-RS: \$

2) Prices

3) Notes

4) TOTAL

\$2.5 x 2

TOTAL

Report Format:

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp: (\$

☐

Interview: (\$

☐

Tech Invs: (\$

☐

Weekend: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933



TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18021556/R1hb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 29-11-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGJ 342C	Veh. Inspected	SHF 330X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/11/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	27/11/2018	Inspection Date	28/11/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Section A - Accident Details

Registration Number	SHF330X
Case Reference Number	TAX/11/18/2124
Registration Date	14/12/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YAP ENG MENG
Type of Accident	Side Swipe
Accident Date and Time	27/11/18 1:15 PM
Accident Reported Date and Time	27/11/18 4:14 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	27/11/18 1:31 PM
Replacement Vehicle issued?	No
Job Card Number	24098982
Special Instruction to ARC, if any	TOWED \$40 / AIG - LKK
Prepared Date and Time	28/11/18 1:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Diagram

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,674.00	\$450.00
Total Spare Part Cost	\$10,415.68	\$3,544.75
Total Other Cost	\$1,426.00	\$200.00
TOTAL COST	\$14,360.68	\$4,494.75 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	RASUL (LKK) / AIG
ARC / Surveyor Sign Off Date	28/11/2018 2:14 PM	28/11/2018 4:50 PM
Signature		
Remarks		P/P resurvey before paint

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1812-0138	Invoice Number	
Quotation Date	07.12.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$300.00 ✓
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO REPSRAY FRONT HOOD	\$378.00	\$0.00 xan
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00 xan
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 ✓
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00 xan
TO RESPRAY RIM	\$180.00	\$50.00 ✓
Total Spray Painting & Panel Beating	\$1,674.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$50.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00 ✓
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00 xan
TO TOP UP A/C GAS	\$120.00	\$0.00 xan
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	\$120.00	\$0.00 xan
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 xan
TO WASH AND VACUUM	\$60.00	\$0.00 xan
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00 xan
Total Other Costs	\$1,426.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63 ✓	Replace	Replace
		52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25 ✓	Replace	Replace
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given

52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check	X
52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check	X
81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	✓
51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Check	X
53301471 10	HOOD SUB-ASSY	0.00	\$938.40	0.00	\$0.00	Replace	Not Given	X
53420471 30	HINGE ASSY, HOOD, LH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X
53410471 30	HINGE ASSY, HOOD, RH	0.00	\$57.00	0.00	\$0.00	Replace	Not Given	X
53205479 00	SUPPORT S/A UPPER	0.00	\$364.90	0.00	\$0.00	Replace	Not Given	X
53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given	X
53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given	X
81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	✓
81056476 90	COMPUTER SUBASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X
28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Not Given	X
74404470 30	CLAMP SUB-ASSY, BATTERY	0.00	\$41.40	0.00	\$0.00	Replace	Not Given	X
74482470 10	CLAMP, BATTERY, NO.2	0.00	\$43.30	0.00	\$0.00	Replace	Not Given	X
53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	100.00	\$0.00	Replace	Repair	R
75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	✓
53876471 10	LINER, FR FENDER, LH	0.00	\$194.30	0.00	\$0.00	Replace	Check	X
53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	0.00	\$0.00	Replace	Not Given	X
42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	R
	COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Not Given	X
Total			\$12,761.90		\$3,544.75			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3544.75
 + 300.00
 + 650.00

 4494.75

4 days

16770.40

Case Details

Case Reference Number : TAX/11/18/2124
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF330X

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4733-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 27/11/2018 05:15 AM
 Vehicle Age(In Months) : 11

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace ▾
One Time Key In	Main			COVER, FR BUMPER LH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give ▾
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Not Give ▾
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give ▾
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check ▾
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check ▾
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace ▾
Total Spare Part Cost									10,415.68		Surveyor Total	3,544.74	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									9,237.06		Final Sur Total	3,544.74	

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Check	▼
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0	Not Give	▼
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0	Not Give	▼
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0	Not Give	▼
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Give	▼
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	▼
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Not Give	▼
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	▼
One Time Key In	Main			COMPUTER SUBASSY, HEADLAMP, LH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	▼
One Time Key In	Main			BATTERY	1	1,584.90	1,584.90	10.00	1,426.41	Replace	0	0	Not Give	▼
One Time Key In	Main			CLAMP SUB-ASSY, BATTERY	1	41.40	41.40	25.00	31.05	Replace	0	0	Not Give	▼
One Time Key In	Main			CLAMP, BATTERY, NO.2	1	43.30	43.30	25.00	32.47	Replace	0	0	Not Give	▼
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	▼
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	▼
									Total Spare Part Cost	10,415.68	Surveyor Total	3,544.74		
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0		
									Final Spare Part Cost	9,237.06	Final Sur Total	3,544.74		

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace				
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER, LH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Give	
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair	
One Time Key In	Main			COOLANT	1	12.30	12.30	0.00	12.30	Replace	0	0	Not Give	
Total Spare Part Cost									10,415.68		Surveyor Total	3,544.74		
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0		
Final Spare Part Cost									9,237.06		Final Sur Total	3,544.74		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT LH PORTION	845.00	300	
Total:		845.00	300.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO REPSRAY FRONT HOOD	378.00	0	
3	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	TO RESPRAY FRONT FENDER LH	378.00	200	
5	TO RESPRAY APRON PANEL LH	180.00	0	
6	TO RESPRAY RIM	180.00	50	
Total:		1,674.00	450.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TOWING CHARGE	56.00	50	
2	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40	
3	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
4	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
5	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
6	TO REMOVE AND REFIT WIRE HARDESS	200.00	0	
7	TO TOP UP A/C GAS	120.00	0	
8	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	0	
9	TO REPLACE SUNDRY PARTS	100.00	0	
10	TO WASH AND VACUUM	60.00	0	
11	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
Total:		1,426.00	200.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	9,237.06	3,544.74
Total Labour Cost	845.00	300.00
Total Spray Painting	1,674.00	450.00
Other	1,426.00	200.00
Overall Total	13,182.06	4,494.74
Lump Sum Repair Option		
Lump Sum Total	0.00	4,494.74
Surveyor Approved Amount		4,494.74
No of Repair Days*	6	4

Remarks

Estimator Assesment(\$)

Surveyor Assesment(\$)

P/P resurvey before paint

Surveyor Name

Rasul

Signature



Survey Date

28/11/2018

Save

Clear

View Received Message

This mail is associated with :

***SHF330X (08472237815G)
[SGJ342C]**

TP

SMRT TAXIS PTE LTD

Nov 27 2018 1:00PM

[Lim Huey Chuen (Lin Hui Jun)]
SMRT Automotive Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 30/11/2018 08:27 AM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Please be advise that no OI GIA report received.
Please find OI details below for your further actions.

OI Name: Lim Huey Chuen (Lin Hui Jun)

Address: 21 Tampines Central 7 #15-23 SINGAPORE 528608

Mobile No.: 92388896

Thanks & Regards,
Yin Rul, Hor (Viviane)

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18021556/R1hb3

04 December, 2018

Lim Huey Chuen (Lin Hui Jun)
21 Tampines Central 7 #15-23
SINGAPORE 528608

Dear Sirs,

ACCIDENT INVOLVING SHF 330X AND SGJ 342C ON 27.11.2018 ALONG/ AT PASIR RIS GROVE

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Vic Alpeh Sanghilan
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

View Sent Message

This mail is associated with :

***SHF330X (0847223781SG)**
[SGJ342C]

TP

SMRT TAXIS PTE LTD

Nov 27 2018 1:00PM

[Lim Huey Chuen (Lin Hui Jun)]
SMRT Automotive Services Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **13/03/2019 13:35 PM**.
To NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosi
ngh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
CC AIG_SG; admin-a@lkkauto.com; vicalpeh@lkkauto.com
Subject **Re: No OI GIA Report**

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Suwanna Te-uttaruang
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 30/11/2018 08:27 AM
Subject: No OI GIA Report

Hi,

Please be advise that no OI GIA report received.
Please find OI details below for your further actions.

OI Name: Lim Huey Chuen (Lin Hui Jun)

Address: 21 Tampines Central 7 #15-23 SINGAPORE 528608

Mobile No.: 92388896

Thanks & Regards,
Yin Rul, Hor (Viviane)

DOCUMENTS SUMMARY

There are no documents.



Hsiao Tong (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 13 March 2019 4:20 PM
To: NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
Cc: Admin A; Vic (LKKAuto)
Subject: Re: No OI GIA Report

This mail is associated with :
***SHF330X (0847223781SG)**
[SGJ342C]
TP
SMRT TAXIS PTE LTD
Nov 27 2018 1:00PM
[Lim Huey Chuen (Lin Hui Jun)]
SMRT Automotive Services Pte Ltd

Dear Suwana,

OI has not reported till date.

Thanks and regards,

Syaza Irdina

<-- Original Message -->

From: LKK_HQ
To: NoorMariesa.AbuKassim@aig.com; ShengYang.Lim@aig.com; Imran.Ishak@aig.com; yokeshi.chan@aig.com; Aashweenjeetkaur.Mithoosingh@aig.com; Syazairdina.Azlan@aig.com; Yinrul.Hor@aig.com
CC: AIG_SG; admin-a@lkkauto.com; vicalpeh@lkkauto.com
Sent On: 13/03/2019 01:35 PM
Subject: Re: No OI GIA Report

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,
Suwanna Te-uttaruang
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 30/11/2018 08:27 AM
Subject: No OI GIA Report

Hi,

Please be advise that no OI GIA report received.
Please find OI details below for your further actions.

OI Name: Lim Huey Chuen (Lin Hui Jun)

Address: 21 Tampines Central 7 #15-23 SINGAPORE 528608

Mobile No.: 92388896

Thanks & Regards,
Yin Rul, Hor (Viviane)

This is an auto-generated email. Do not reply to this email.

Sent by : Azlan, Syazairdina (AIG Asia Pacific Insurance Pte. Ltd.)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18021556/R1hb3

21 March 2019

By Registered Mail

Lim Huey Chuen (Lin Hui Jun)

21 Tampines Central 7 #15-23
SINGAPORE 528608

Dear Sir,

**ACCIDENT INVOLVING SHF 330X AND SGJ 342C ON 27.11.2018 ALONG/ AT
PASIR RIS GROVE**

RG We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, China Taiping Insurance (Singapore) Pte Ltd to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of China Taiping Insurance (Singapore) Pte Ltd reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note that you had been notified by our via mail by post from our office on 04/12/2018

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by 04/04/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s China Taiping Insurance (Singapore) Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan
Claims

Tel : 6841 2096

Fax: 6741 4108

Email : vicalpeh@lkkauto.com

c.c *Claims Manager*
 China Taiping Insurance (Singapore) Pte Ltd
 (Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18021556/R1hb3

21 March 2019

By Registered Mail

Lim Huey Chuen (Lin Hui Jun)
21 Tampines Central 7 #15-23
SINGAPORE 528608

Dear Sir,

**ACCIDENT INVOLVING SHF 330X AND SGJ 342C ON 27.11.2018 ALONG/ AT
PASIR RIS GROVE**

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 04/12/2018

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by 04/04/2019).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghila
Claims
Tel : 6841 2096
Fax: 6741 4108
Email : vicalpeh@lkkauto.com

c.c *Claims Manager*
 AIG Asia Pacific Insurance Pte. Ltd
 (Motor Claims Dept)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18021556/R1hb3

15 APRIL 2019

By Registered Mail
(FINAL REMINDER)

Lim Huey Chuen (Lin Hui Jun)

21 Tampines Central 7

#15-23

Singapore 528608

Dear Sir,

ACCIDENT INVOLVING SHF 330X AND SGJ 342C ON 27.11.2018 ALONG/ AT PASIR RIS GROVE

We refer to the above subject matter. Your insurer AIG Asia Pacific Insurance Pte Ltd (AIG) has received a third party claim(s) against your motor insurance policy, and has appointed LKK Auto Consultants Pte Ltd to act on their behalf to handle this matter.

We highlight that this accident has not been reported to AIG.

Please note that you had been notified by our via mail by post from our office on 04/12/2018 & 21/03/2019.

Kindly proceed to lodge your accident report immediately, giving the version of the accident amongst other things related to the accident. The accident report can be lodged at any of AIG reporting centres. For the listing of AIG reporting centres, you may refer to your Certificate of Insurance or visit AIG Singapore's website.

To enable us to look into the matter immediately, please let us hear from you within fourteen (14) days from date of this letter (by **1st MAY 2019**).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s AIG Asia Pacific Insurance Pte Ltd reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Vic Alpeh Sanghilan

Claims

Tel : 6841 2096

Fax: 6741 4108

Email : vicalpeh@lkkauto.com

c.c *Claims Manager*
 AIG Asia Pacific Insurance Pte. Ltd
 (Motor Claims Dept)

To : Traffic Police – Deputy Head, Investigations Department
Fax : 65474885

ONLY FOR ACCIDENTS IN SINGAPORE

NON-INJURY MOTOR ACCIDENT REPORT SCHEME
FORM ON NON-REPORTING BY INSURED

Please be informed that we have yet to receive a motor accident report from our insured with regard to a non-injury motor accident as follows:-

Date of accident : 27/11/2018
Time of accident : 13:15
Place of accident : PASIR RIS GROVE
Third Party's name : SMRT TAXIS PTE LTD
Third Party's vehicle number : SHF 330X
Our insured's name : LIM HUEY CHUEN (LIN HUI JUN)
Our insured's vehicle number : SGJ 342C
Our insured's NRIC number : NIL
Our insured's address : 21 TAMPINESE CENTRAL 7 #15-23
SINGAPORE 528608
Our Insured's telephone number : 92388896

A letter dated **(21/03/2019)** was sent to remind our insured to report the non-injury motor accident to us. No report has yet been made.

Please do not hesitate to contact the following for any clarification on the matter.
(Please cite our reference number: **(CC3/AIG18021556/R1hb3)**)

Name and address of insurance company : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#08-16
Singapore 079120

Name of contact person : Vic Alpeh Sanghlan
Contact Number : 6841 2096 Fax: 6741 4108
Date : 12/04/2019

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 31 July 2019 3:49 PM
To: Ler, Bernard-JQ
Subject: [NON REQPORTING] Your Ref 0847223781SG, ACCIDENT INVOLVING SGJ 342C (OI) AND SHF 330X (TP) ON 27/11/2018
Attachments: NON-REPORTING LETTER.pdf; 1ST AR NON REPORTING LETTER.pdf; Traffic Police (Non-Reporting).pdf; 2ND AR NON REPORTING LETTER.pdf

Your Ref: 0847223781SG

Hi Bernard,

We refer to the above matter.

ACCIDENT INVOLVING SGJ 342C (OI) AND SHF 330X (TP) ON 27/11/2018

We have post out all letter including traffic police letter, however insured yet report till date.

Kindly let us have your instruction.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2018 Edit Reg		28 Nov 2018 00:00 Edit Adj Rpt	S\$4,494.75 Edit Estimates	S\$4,494.75 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lim Huey Chuen (Lin Hui Jun), ID: S7311828Z		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHF330X	Date of Loss:	27/11/2018 13:00 - :59 [11 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0847223781SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SGJ342C	Policy No. (Claimant):	D-18090213MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 10/12/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (09/05/2019): Re: No OI GIA Report
- AIG_SG (10/04/2019): Re: No OI GIA Report
- AIG_SG (13/03/2019): Re: No OI GIA Report
- AIG_SG (30/11/2018): No OI GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHF330X (0847223781SG)**
[SGJ342C]

TP

SMRT TAXIS PTE LTD

Nov 27 2018 1:15PM

[Lim Huey Chuen (Lin Hui Jun)]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	☒
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Thumbnail	Print
			Edit	
Assessment Reports				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	1 per page	☒
1	06/11/19 10:06	Accident Statement From: SC - Reg. No: SGJ342C, Claimant: LIM HUEY CHUEN	Thumbnail	Print
			Load HTM	
Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	☒
1	31/07/19 15:45	Odometer Reading	Thumbnail	Print
2	31/07/19 15:45	Chassis Number	Load JPG	☒
3	31/07/19 15:45	General View	Load JPG	☒
4	31/07/19 15:45	General View	Load JPG	☒
5	31/07/19 15:45	General View	Load JPG	☒
6	31/07/19 15:45	General View	Load JPG	☒
7	31/07/19 15:45	General View	Load JPG	☒
8	31/07/19 15:45	General View	Load JPG	☒
9	31/07/19 15:45	General View	Load JPG	☒
10	31/07/19 15:45	General View	Load JPG	☒
11	31/07/19 15:45	General View	Load JPG	☒
12	31/07/19 15:45	General View	Load JPG	☒
13	31/07/19 15:45	General View	Load JPG	☒
14	31/07/19 15:45	General View	Load JPG	☒
15	31/07/19 15:45	General View	Load JPG	☒
16	31/07/19 15:45	General View	Load JPG	☒
17	31/07/19 15:45	General View	Load JPG	☒
18	31/07/19 15:45	General View	Load JPG	☒
19	31/07/19 15:45	General View	Load JPG	☒
20	31/07/19 15:45	General View	Load JPG	☒
21	31/07/19 15:45	General View	Load JPG	☒
22	31/07/19 15:45	General View	Load JPG	☒
23	31/07/19 15:45	General View	Load JPG	☒
24	31/07/19 15:45	General View	Load JPG	☒
25	31/07/19 15:45	Reinspection Photo	Load JPG	☒
26	31/07/19 15:45	Reinspection Photo	Load JPG	☒
27	31/07/19 15:45	Reinspection Photo	Load JPG	☒
28	31/07/19 15:45	Reinspection Photo	Load JPG	☒
Documentation				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 per page	☒
1	29/11/18 17:27	TP ESTIMATE- MARKED	Thumbnail	Print
2	29/11/18 17:27	TP GIA REPORT	Load PDF	
3	04/12/18 09:18	Non reporting letter	Load PDF	

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	31/07/19 15:43	NON-REPORTING LETTER	 Load PDF	
5	31/07/19 15:43	1ST AR NON REPORTING LETTER	 Load PDF	
6	31/07/19 15:43	2ND AR NON REPORTING LETTER	 Load PDF	
7	31/07/19 15:43	Traffic Police (Non-Reporting)	 Load PDF	
8	28/11/19 15:17	LETTER TO OI	 Load PDF	
9	10/12/19 16:36	AUTHORISATION TO ACT	 Load PDF	
10	10/12/19 16:36	LOD	 Load PDF	
11	10/12/19 16:36	LTA SEARCH	 Load PDF	
12	10/12/19 16:36	REGISTERED MAIL FEE	 Load PDF	
13	10/12/19 16:36	RELEASE VOUCHER	 Load PDF	
14	10/12/19 16:36	RENTAL MILEAGE	 Load PDF	
15	10/12/19 16:36	RENTAL RECEIPT	 Load PDF	
16	10/12/19 16:36	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGJ342C (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHF330X (TP veh)		
Date of Accident:	27/11/2018		

Global Sum Settlement	:	☒ [X] Yes	☐ [] No	
Repair Estimate	:	\$		16,720.40
Final Repair Cost	:	\$		5,500.00
Loss of Use	:	\$		6.00 days at \$50.00 per day
Rental (if any)	:	\$		6 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (GLOBAL SUM)	:	\$		5,500.00
Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 5,500.00
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

10 Dec
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)

LKK Auto Consultants Pte Ltd

 (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 Our File No: CC3/AIG18021556/R1EB3S2
 Date: 10/12/2019

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SHF330X	Insured Vehicle No :	SGJ342C
Date of Loss:	27/11/2018	Nature of Claim:	TP
		Claim No:	0847223781SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF330X	Engine No:	2ZR8259485
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU303576548
Reg. Date:	14/12/2017 (Man. Year: 2017)	Odometer:	51762 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,775.40	3,544.75	9,230.65	72.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,945.00	950.00	2,995.00	75.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	16,720.40	4,494.75	12,225.65	73.12
+ Loss of Use (6.0 x S\$50.00/day) (\$\$)		300.00		
+ Car Rental (6.0 x S\$120.38/day) (\$\$)		722.28		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		5,524.03		
Global Sum Settlement (\$\$)		5,500.00		

INSPECTION

Date of Assignment:	28/11/2018	
Date Inspected:	28/11/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FR BUMPER (DISC 25%)	Deformed	495.50 F	*371.63 F
2	1		*CLIP PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	1		*EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
4	1		*LAMP ASSY, FOG LH (DISC 10%)	Cracked	910.20 F	*819.18 F
5	1		*UNIT, HEADLAMP, LH (DISC 10%)	Cracked	2,558.90 F	*2,303.01 F
6	1		*COVER, FR BUMPER LH	Not Necessary	28.10 F	*- F
7	1		*GRILLE, RADIATOR	Not Necessary	165.00 F	*- F
8	1		*SUPPORT, FR BUMPER LH	Not Necessary	82.30 F	*- F
9	1		*ABSOBER, FR BUMPER	Not Necessary	70.30 F	*- F
10	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
11	1		*COVER ASSY, ENGINE	Not Necessary	180.10 F	*- F
12	1		*HOOD SUB-ASSY	Not Necessary	938.40 F	*- F
13	1		*HINGE ASSY, HOOD, LH	Not Necessary	57.00 F	*- F
14	1		*HINGE ASSY, HOOD, RH	Not Necessary	57.00 F	*- F
15	1		*SUPPORT S/A UPPER	Not Necessary	364.90 F	*- F
16	1		*SUPPORT S/A LH	Not Necessary	237.00 F	*- F
17	1		*SUPPORT, RADIATOR UPPER LH	Not Necessary	76.70 F	*- F
18	1		*COMPUTER SUBASSY, HEADLAMP, LH NO.1	Not Necessary	486.40 F	*- F
19	1		*BATTERY	Not Necessary	1,584.90 F	*- F
20	1		*CLAMP SUB-ASSY, BATTERY	Not Necessary	41.40 F	*- F
21	1		*CLAMP, BATTERY, NO.2	Not Necessary	43.30 F	*- F
22	1		*LINER, FR FENDER, LH	Not Necessary	194.30 F	*- F
23	1		*APRON SUB-ASSY, FRONT FENDER, LH	Not Necessary	944.20 F	*- F
24	1		*COOLANT	Not Necessary	12.30 F	*- F
25	1		*FENDER SUB-ASSY, FR LH	Repair	933.10 F	*- F
26	1		*WHEEL, DISC FRONT	Repair	1,555.10 F	*- F

F=Franchise part.

Total Parts (\$\$) 12,775.40 3,544.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	845.00	300.00
2	SPRAY PAINT.	New	1,674.00	450.00
3	TOWING CHARGE.	New	56.00	50.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	40.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	20.00
6	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	New	120.00	60.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
8	TO REMOVE AND REFIT WIRE HARNESS.	New	200.00	0.00
9	TO TOP UP A/C GAS.	New	120.00	0.00
10	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.	New	120.00	0.00
11	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
12	TO WASH AND VACUUM.	New	60.00	0.00
13	TO CHECK & RESET SYSTEM FUNCTION.	New	350.00	0.00
Gross Labour Cost (S\$)			3,945.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >