

VGS Singapore, 247, 159934 Singapore

SIONG KIEM LIANG LORETTA
6A ROBIN WALK
Singapore, 258151
Singapore

Tanpin 9744544
WP
30/11/18 1145
Resing before paint
sure (Heand.com)
4-5 days

VGS Singapore

247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV035267
Quote No. SER/QUO/1802015
QuoteDate 28/11/18
Salesperson Eric Tan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	17,615	Wong Mei
License No.	VIN	Initial Registration	Sales Advisor
SGF133K	WVWZZZ16ZGM022003	30/09/16	Eric Tan
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F84054	1634G7

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	5	Labor		1680 4,200.00
P B&P ALEX PAINT	SPRAY PAINT	4	Labor		1600 3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		✓ 480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		✓ 280.00
	Sum Labor				8,160.00
P 5C6807251E	FOAM INSERT	1	Pieces		? 1,243.83
P 5C6807305	BUMPER REINFORCEMENT	1	Pieces		? 498.22
P 5C6807375	BUMPER BRACKET LHR	1	Pieces		? 91.14
P 5C6807376	BUMPER BRACKET RHR	1	Pieces		? 91.14
P 5C6807393D	GUIDE LHR	1	Pieces		? 91.14
P 5C6807394D	GUIDE RHR	1	Pieces		? 91.14
P 5C6807417J GRU	REAR BUMPER	1	Pieces		all 1,154.94
P 5C6807433J	SPOILER	1	Pieces		de 535.27
P 5C6807863B	STRIP	1	Pieces		de 96.99
P 5C6827025E	LID	1	Pieces		Ry 1,539.60
	Predecessor 5C6827025D				
P 5C6827505G	LOCK	1	Pieces		Y 167.96
	Use Predecessor 5C6827505F				
P 5C6853630F ULM	VW SIGN	1	Pieces		de 108.42
P 5C6853675APGQF	NAME PLATE (TSI)	1	Pieces		de 50.97
P 5C6853687 739	NAME PLATE (JETTA)	1	Pieces		de 67.50
P 5C6919491D	SENSOR BRACKET LEFT REAR	1	Pieces		de 23.79
P 5C6919491E	SENSOR BRACKET RIGHT REAR	1	Pieces		de 23.79
Sum carried forward					14,035.84

Payments to:

- BBN: - Acc.-No.:

VGS Singapore, 247, 159934 Singapore

SIONG KIEM LIANG LORETTA
6A ROBIN WALK
Singapore, 258151
Singapore

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV035267
Quote No. SER/QUO/1802015
QuoteDate 28/11/18
Salesperson Eric Tan
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	17,615	Wong Meiy
License No.	VIN	Initial Registration	Sales Advisor
SGF133K	WVWZZZ16ZGM022003	30/09/16	Eric Tan
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F84054	1634G7

		Continued	14,035.84
P 5C6919491E	SENSOR BRACKET LEFT REAR	1 Pieces	23.79
P 5C6919492D	SENSOR BRACKET RIGHT REAR	1 Pieces	23.79
P 5Q0919133 9B9	O-RING	4 Pieces	6.88
	Sum Item		5,930.30

Sum Labor	8,160.00
Sum Item	5,930.30

Total SGD	14,090.30
7% GST	14,090.30 986.32
Total SGD Incl. GST	15,076.62

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.: