| CWS<br>From (Person) Jurene Ler   | ASSIGNMENT (Office                | VT         | Time: 3.13 pm@    |
|-----------------------------------|-----------------------------------|------------|-------------------|
| Estimated Cost:                   | Bill to:                          |            |                   |
| OD / TP WS / TP RES / OD RES / EV | VA/INV/MV7CS                      | •          |                   |
| To Inspect Vehicle No:            | 3179664B                          | Insured:   | SHC 8939D         |
| at Workshop m/s                   | In-Auto                           | Tel:       | 6289812           |
| ofBIK 14                          | #01-410/412 De                    | efutine 10 |                   |
| Policy No:                        | Claim No                          | D1800      | 8452MF8H          |
| Sum Insured:                      | Excess                            |            |                   |
| Make of Veh: (Client's Record)    |                                   | D.O.       | A. 05/11/201      |
| CA / REV / REP. / REV 24 HRS      | up)                               | H.         | O.D. Endorsement: |
| Date/Time: 3:47pm6 29/11/18 P     | erson Contacted:                  | Vehic      | e INAOUT          |
| Date/Time Action/Instruction (    | ) Estimate                        |            |                   |
| 31796648-                         |                                   | -          |                   |
| SHC 8939B-X                       |                                   |            |                   |
| 30/11/1e- UNI YET                 |                                   |            |                   |
|                                   | to Sevene lev by MA: 5 7468 ; NV: | email      |                   |
|                                   |                                   |            |                   |

| (08/11/13) wef REF:                               | 2.1/  |
|---|---|
| ASS. REC. BY: Moreus                              | · Fel/  |
| . <u>AS</u>                                       | SIGNMENT  |
| From: Date:                                       | Veh No: 5779 66 4 Byr Regn: 11109                                   |
| Estimated Cost:                                   | Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /    |
| OD TEN WS TP RES OD RES EVALINVINV                | Truck/Trailer or (A)  |
| To Inspect Vehicle No: 3J 7 9 66 43               | Make: Hunda Zif c.c 1339  |
| at Workshop m/s J. 1 Pr.                          | Colour Black A/C: Insured / Std / NI / NA                           |
| of  | Sp.Reading // 2587 T/Radio: Insured / Std / NI / NA                 |
| Insured: 5 M C 8939 D                             | Eng/No:   |
| Policy No.  | C/NO: 0E6 (073678   |
| Claims No.  | Gen. Cond. Good / Fair / Poor / Burnt                               |
| Sum Insured: Excess:                              | Steering: Inorder / Jammed / Leaked / Burnt or                      |
| (Client's Record)                                 | Brake: Inorder / Jammed / Leaked / Burnt or                         |
| Make of Veh:                                      | Modi: Nil V.S/Rim T STD A/Rim or -                                  |
|   | Tyre Size: F: 205/60281,  |
| (Policy Condition)                                | R: /3020/6  |
| Remark: The veh had commenced its N/S O/S         | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /     |
| repair at the time of inspection.                 | TOYOTYOKO or  |
| Bal, or Market Value:                             | Front Rear  |
| IDAC Accident Rport: Consistent? : Yes or No      | R/Bal. 6 mm R/Bal. mm   |
| GIA / PR Seen: L Consistent?: Yes or No           | L/Bal. 6 mm L/Bal. 6 mm   |
| Est. Repairs: Gays Res.: Yes or No                | D.O.A. 25-14/18 D.O.I. 4/11/16                                      |
| Lum Sum: 70 % 3 Val.: Yes or No                   | Survey held at  |
| 71/64   | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or         |
| CA   REV   REP.   24 HRS                          |   |
| Date: Person Contacted:                           | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time   Action / Instruction                |   |
| 1 1 ( Confined 1 ( \$ 300 ) ( Ged 6 7539.60, 43%) | why Jours.  |
|   | RECEIVED 1 3 DEC 2018   |
|   |   |
|   |   |
|   |   |
| Date/Time, File Pass to? : Preli. Report          | Days Of Repair:   |
| 1) 13/12 turist : Final Report                    | Resurvey No. of Trip: Survey Fee: 145                               |
| Date/Time, File Return to?                        | Transportation: 50  |
| 2) Add F  |   |
|   | :Interview (\$ ) Photos 60  |
| Report Format:                                    | : Tech. Invs. (\$ ) Others  |
| Lump Sum / I.B.T.: (\$ 3500 )                     | :Weekend (\$ )  |
|   | TOTAL 255   |



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX: (065) 62564315

Your Ref: D18008452MFSH

Date: 13 December 2018

Our Ref: CS/FCI18021568/Uqd3

The Motor Claims Department First Capital Insurance Ltd


Dear Sir/Madam,

### INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 9664B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/12/2018 at the premises of M/s JIN AUTO. and have the following to report:-

| Workshop Estimate Amount | : S\$         | 6,089.60 | <u>)</u>   |  |
|--------------------------|---------------|----------|------------|--|
| Revised Estimate Amount  | : <u>S\$</u>  | 3,500.00 | (Lump Sum) |  |
| "Check" Items Amount     | : <u>S\$</u>  | -        | <u>+</u>   |  |
| Market Value             | : <u>S\$</u>  | -        |            |  |
| LTA Reimbursement Value  | : <u>S</u> \$ | 12       |            |  |
| Nett Value               | : <u>S\$</u>  | -        |            |  |

Description of Damage: The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG Licensed Appraiser



MS First Capital Insurance Limited Co.Reg. No. 195000100C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 069877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

### MOTOR SURVEY ASSIGNMENT

Date

27-11-2018

Our Ref No. D18008452MFSH

Accident Date

25-11-2018

Claim Type. Third Party

Insured Vehicle

SHC8939D

Third Party Vehicle. SJT9664B

Survey Location

BLK 14 #01-410/412 DEFU LANE 10

Contact Person.

CASSANDRA

Contact No.

62898126/0

Fax No. 62870590

Survey Type

WITHOUT PREJUDICE: NOT DISPUTING ON LIABILITY BUT QUANTUM TO

BE AGREED.

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

JIN AUTO SERVICES PTE

Attention. NIL

LTD NA

TP Solicitor Fax No. NA

Officer Incharge

Cc: TP Solicitor

SERENE

### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection. This is a computer generated letter, no signature required.

### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Thursday, 13 December 2018 11:35 AM

To:

'CWS Motor Claims'; assignments

Cc:

'Serene Ler'; SUR

Subject:

RE: SURVEY ASSESSMENT - D18008452MFSH/1

Attachments:

CSFCI18021568Uqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJT 9664B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 29 November 2018 4:09 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18008452MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS.

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 29 November 2018 3:13 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler < Sereneler@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D18008452MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

#### SGCARMART.COM

New Cars Used Cars

ed Cars Sell My

Sell My Car

Price Range

Honda Fit 1.3A G

Directory

Products

∨ Depreciation ∨ 2009

Insurance

Vehicle Type

Articles

Forum

Login Sign up

Submit (

Resources

Advanced Search



VISIT US AT VENUE SGCM Carnival @ Downtown East 1 Pasir Ris Close Singapore 519599

15 - 16 December 2018 10 am to 8 pm





Home » Used Cars » Trust Motor Trading » Honda Fit 1.3A G

Honda Fit

Car Buying
Car Selling
Car Ownership
Car Aftermarket
On The Move

Lifestyle



Ad v

## Planning for a Holiday?

sg.hotels.com

Unlock Secret Prices on selected hotels!

OPEN

Compare

Overview Financial Similar **Photos** Accessories Research Add to Compare Add a Note Report Error Add to Shortlist Car Details \$16,500 Price Depreciation \$8,850 /yr 0 View models with similar depreciation Reg Date 06-Nov-2009 (11mths 1day COE left) 0 Manufactured 2008 Mileage Transmission Auto **Engine Cap** 1.339 cc 0 Road Tax \$590 /yr 73.0 kW (97 bhp) Power View specs of the Honda Fit (2008-2013) **Curb Weight** 1,010 kg 0 Features 1.3L Fuel Efficient I-VTEC Engine, 5 Speed CVT Auto Transmissions, SRS Airbags, Immobilizer, Knockdown Rear Seats. Audio System, Sports Rims, Window Visor, Solar Film, Accessories Reverse Sensors. Well Maintained Condition, Fuel Efficient And Reliable Description Model, Sporty Outlook With Spacious Interior Space. GST Included. Flexible Loan And Trade In Available, Call Now To Viewing The Car. COE \$16,747 0 0 OMV \$16,703 \$16,703 0 ARF Dereg Value 0 \$9,893 as of today (change) No. of Owners Type of Veh Hatchback Category PARF Car Availability Available Add to Shortlist Add to Compare Add a Note Posted on: 01-Dec-2018 | Last Updated on: 03-Dec-2018 Tags: Honda Fit, honda fit, 2009 Honda Fit, 2009 honda fit, Honda, Fit, fit, Used Honda













#### Seller Information

| Company           | Trust Motor Tra<br>» dealer's pricelist |                      |
|-------------------|---|----------------------|
|                   | » 36 vehs sold   22                     |                      |
| Address           | 73 Mackenzie Road<br>Search cars nearby |                      |
| Location          | Mackenzie Used Ca                       | ir Centre            |
| Office No         | 63384472                                |                      |
| Contact Person(s) | Benson Tan<br>Alvin Chea                | 84187320<br>90295022 |

Mr Lim

#### **Useful Services**



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



» more Financial info

Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Upfront Payment

Transfer Fee

\$25

96263081

### SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory


Products

Insurance

Articles

Forum

Resources





FIND OUT MORE



Honda Fit

Price Range

Depreciation V 2009

✓ Vehicle Type

Map

More Actions

Submit (

Home » Used Cars » Car Design Motor » Honda Fit 1.3A G

## Resources Car Buying Car Selling Car Ownership Car Aftermarket On The Move Lifestyle



## Plan Your **Next Trip**

sg.hotels.com

Unlock Secret Prices on selected hotels!

OPEN

#### Honda Fit 1.3A G

| Overview         | Financial        | Accessories                | Similar      | Research | Photo |
|------------------|------------------|----------------------------|--------------|----------|-------|
| Add to Short     | dist Ad          | ld to Compare              | Add a Note   | Report   | Error |
| car pegalis      |                  |                            |              |          |       |
| Price<br>Mashare | \$12,80          | 00                         |              |          |       |
| Depreciation     |                  | /yr<br>iodels with similar | depreciation |          | 0     |
| Reg Date         | 17-Sep<br>(9mths | -2009<br>12days COE left)  |              |          |       |
| Manufacture      | d 2008           |                            |              |          | 0     |
| Mileage          |                  |                            |              |          |       |
| Transmission     | 1 Auto           |                            |              |          |       |
| Engine Cap       | 1,339            | cc                         |              |          |       |
| Road Tax         | \$590 /          | yr                         |              |          | 0     |
| Power            | 73.0 kV          | W (97 bhp)                 |              |          |       |

View specs of the Honda Fit (2008-2013)

1.3L 4 Cylinders Inline 16V I-VTEC Engine, Smooth 5

Speed CVT Auto Transmission, EPS, Dual SRS Airbags,

1,010 kg

DADE Car

Available

Posted on: 13-Nov-2018 | Last Updated on: 29-Nov-2018

ABS, Immobilizer,

Curb Weight Features

> Accessories Sports Rims, Audio System, Reverse Sensors, Upholstery Leather Seats. Cheapest In The Market! Affordable Depreciation, Description Original Paintwork, Smooth Engine, Easy To Maintain Unit, Low Fuel Consumption! Low Maintenance Cost! The Most Spacious Hatchback Among It's Class! Shop With A Peace Of Mind With STVA Accredited Company, A Well Fairness Company And Trustable. Call And Make An Appointment For Viewing Now. Ð \$11,414 COF OMV \$11,564 0 \$11,564 ARF ø Dereg Value \$6,676 as of today (change) Ø No. of Owners Type of Veh Hatchback

> > Add to Compare

Tags: Honda Fit, honda fit, 2009 Honda Fit, 2009 honda fit, Honda, Fit, fit, Used

CAR DESIGN

Share















#### Seller Information

| Company           | Car Design Moto      | r i           |
|-------------------|----------------------|---------------|
|                   | * dealer's pricelist |               |
|                   | * 28 vehs sold   19  | ehs available |
| Address           | 61 Ubi Avenue 2 #0   | 5-05          |
|                   | Search cars nearby t | his location  |
| Location          | Automobile Megama    | rt            |
| Office No         | 67468820             |               |
| Contact Person(s) | David Tan            | 8333836       |

Danson

Vicky

Dion

### **Useful Services**



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Add a Note

Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

Add to Shortlist

Category

Honda

Availability

83186570

85557476

87425596

## > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

| Owner ID Type:                | Company                  |
|-------------------------------|--------------------------|
| Owner ID:                     | 8001G                    |
| Vehicle Details               |                          |
| Vehicle No.:                  | SJT9664B                 |
| Vehicle to be Exported:       | No                       |
| Intended Deregistration Date: | 04 Dec 2018              |
| Vehicle Make:                 | HONDA                    |
| Vehicle Model:                | FIT 1.3G A               |
| Primary Colour:               | Black                    |
| Manufacturing Year:           | 2008                     |
| Engine No.:                   | L13A4079585              |
| Chassis No.:                  | GE61073678               |
| Maximum Power Output:         | 73.0 kW (97 bhp)         |
| Open Market Value:            | \$11,810.00              |
| Original Registration Date:   | 11 Nov 2009              |
| First Registration Date:      | 11 Nov 2009              |
| Transfer Count:               | 1                        |
| Actual ARF Paid:              | \$11,810.00              |
| Intended PARF Rebate Details  |                          |
| PARF Eligibility:             | Yes                      |
| PARF Eligibility Expiry Date: | 10 Nov 2019              |
| PARF Rebate Amount:           | \$5,905.00               |
| Intended COE Rebate Details   |                          |
| COE Expiry Date:              | 10 Nov 2019              |
| COE Category:                 | A - Car (1600cc & below) |
| COE Period(Years):            | 10                       |
| QP Paid:                      | \$16,747.00              |
| COE Rebate Amount:            | \$1,563.00               |
| Total Rebate Amount:          | \$7,468.00               |

The information contained herein is correct as at 04 Dec 2018

ОК

Not Afford L/S \$3500/- 5dy Hollifter repar

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412 Singapore 539195 Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

4/12/2018

M/S MS FIRST CAPITAL INSURANCE

- Auto Consultants hence notify Repairer of the following:
- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|     | AR SIR / M<br>IMATE RE | EPAIR COST FOR SJT9664B (HONDA FIT)           |                      |              |
|-----|------------------------|---|----------------------|--------------|
|     |                        | TO SUPPLY:                                    |                      |              |
| 01) | 1 DC                   | List Items                                    | •                    | 010.10       |
| 01) | 1 PC                   | REAR BOOT LID                                 | \$                   | 810.10       |
| 02) | 1 PC                   | REAR W/S MOULDING                             | \$                   | 74.00        |
| 03) | 1 PC                   | REAR BOOT LID RUBBER Total                    | \$                   | 92.30        |
| 04) | 1 PC                   | REAR BOOT UPPER LOCK ASSY                     | \$<br>\$<br>\$       | 194.00       |
| 05) | 1 PC                   | REAR BOOTLID STRIKER                          | \$                   | 11.20        |
| 06) | 1 PC                   | REAR BOOT" EMBLEM                             | \$                   | 27.20        |
| 07) | 1 PC                   | REAR BOOT INNER TRIMBOARD                     | \$<br>\$             | 123.90 ×     |
| 08) | 1 PC                   | REAR RH LAMP                                  | \$                   | 206.20 △     |
| 09) | 1 PC                   | REARLH LAMP MA                                | \$                   | 206.20 💸     |
| 10) | 1 PC                   | REAR END PANEL                                | \$<br>\$<br>\$<br>\$ | 295.20       |
| 11) | 1 PC                   | REAR END PANEL GARNISH Twy                    | \$                   | 60.80        |
| 12) | 1 PC                   | REAR BUMPER                                   | \$                   | 440.30       |
| 13) | 2 PCS                  | REAR BUMPER SIDE RETAINER                     | \$                   | 37.60        |
| 14) | 1 PC                   | REAR BUMPER LOWER SPOILER 7/ 680              | \$                   | 920.50       |
|     |                        | 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5         | \$                   | 3,499.50     |
|     |                        | LESS20%                                       |                      | (699.90)     |
|     |                        |   | \$                   | 2,799.60     |
|     |                        | SPECIAL NETT                                  |                      | _,, > > 1.00 |
| 15) | 1 PC Sef               | PARKING SENSOR Shift                          | \$                   | 280.00 200   |
| 16) | 1 PC                   | W/S SEALANT Au                                | S                    | 60.00 40     |
| 17) | 1 PC                   | REAR NUMBER PLATE                             | S                    | 40.00 X      |
| 18) | 1SET                   | REAR BUMPER CLIPS                             | \$                   | 40.00 30     |
|     |                        | Labour Charge                                 |                      |              |
| 19) |                        | SENSOR LABOUR DISMATH & 120/004 POVERE SENSOR | \$                   | 80.00        |
| 20) |                        | WIS LABOUR DISMENTED & SEF. X NEAR W- ASSOREM | \$                   | 120.00       |
| 21) |                        | REMOVE INNER GARNISH                          | \$                   | 100.00       |
| 22) |                        | SPRAY PAINTING                                | \$                   | 1,250.00 980 |
|     |                        |   |                      | 100          |

| 23) | LABOUR CHARGE                      | \$ | 1,000.00 600 |
|-----|------------------------------------|----|--------------|
| 24) | TUFF COAT                          | \$ | 90.00 60     |
| 25) | WIRING CHECK                       | \$ | 30.00 2-0    |
| 26) | CUSHION REMOVE & REFIX Report      | \$ | 100.00       |
| 27) | REMOVE AND REFIX BOOTLID MECHANISM | \$ | 100.00       |
|     |                                    | S  | 6,089.60     |
|     |                                    | -  | -1108        |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

| Alga |   | Affiliated to Federation Intern   | ationale Des Experts En Auton    | nobile     |
|------|---|---|----------------------------------|------------|
| MS F | RST CAPITAL IN  | SURANCE LTD   | Ref : CS/FCI180215               | 68/Uqd3n2  |
|      | BINSON ROAD<br>1 CITY HOUSES  | INGAPORE 068877   | Date : 14-12-2018<br>Code : FCI2 |            |
| 1.   |   | Policy Particula  | ers :- THIRD PARTY CLA           | IM         |
|      | Insured Veh.  | SHC 8939D   | Veh. Inspected                   | SJT 9664B  |
|      | Policy No.  |   | Coverage (\$)                    | 0.00       |
|      | Claim No.   | D18008452MFSH   | Excess (\$)                      | 0.00       |
|      | Assign From   | SERENE  | Assign Date                      | 29/11/2018 |
| 2.   |   | Vehicle Pa  | articulars & Condition           |            |
|      | Make & Model  | HONDA FIT (A)   | c.c                              | 1339       |
| 0    | Engine No.  | HIDDEN  | Year of Reg.                     | 2009       |
|      | Chassis No.   | GE61073678  | Colour                           | BLACK      |
|      | Odometer  | 112581  | Steering                         | IN ORDER   |
|      | Brakes  | IN ORDER  | Modification                     | SPORTS RIM |
|      | General   | GOOD  |                                  |            |
| 3.   |   | Con   | ditions of Tyres                 |            |
|      |   | Size  | Make                             | Balance    |
|      | R/H Front Tyre  | 205/50 ZR16   | TOYO                             | 6 mm       |
|      | L/H Front Tyre  | 205/50 ZR16   | тоуо                             | 6 mm       |
|      | R/H Rear Tyre   | 205/50 ZR16   | TOYO                             | 6 mm       |
|      | L/H Rear Tyre   | 205/50 ZR16   | TOYO                             | 6 mm       |
| 4.   |   | Descri  | ption of Damages                 |            |
|      | THE VEHICLE SU  | STAINED DAMAGES AT THE  | REAR PORTION.                    |            |
|      | DAMAGES SEE D   | ETAILS.   |                                  |            |
| 5.   |   |   | eral Information                 |            |
|      | Accident Date   | 25/11/2018  | Inspection Date                  | 04/12/2018 |
|      | Survey held at  | JIN AUTO SERVICES PTE I   | .TD                              |            |
|      | Demokratichen in Constitution (Constitution | BLK 14 DEFU LANE 10<br>#01-412<br>SINGAPORE 539195                            |                                  |            |
| 5a.  |   |   | Remarks                          |            |
|      | B)THE INSPECTION  | NSISTENT TO ACCIDENT REI<br>ON WAS CONDUCTED ON A"<br>CE TO YOUR INSTRUCTIONS | WITHOUT PREJUDICE" BAS           |            |
| 5b.  |   | Estim   | ate Days of Repair               |            |
|      | ESTIMATED NOR   | MAL PERIOD FOR REPAIR:  | 5 Working Da                     | ys         |



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 9664B

| Qty | Description of Parts                  | Condition     | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---------------------------------------|---------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS                  |               |                               |                   |
| 1   | REAR BOOT LID                         | BADLY DENTED  | 810.10                        | 810.10            |
| া   | REAR W/S NOULDING                     | NECESSARY     | 74.00                         | 74.00             |
| 1   | REAR BOOT LID RUBBER                  | TWISTED       | 92.30                         | 92.30             |
| 1   | REAR BOOT UPPER LOCK ASSY             | TWISTED       | 194.00                        | 194.00            |
| 1   | REAR BOOTLID STRIKER                  | NOT NECESSARY | 11.20                         | 174               |
| 1   | REAR BOOT EMBLEM                      | NECESSARY     | 27.20                         | 27.20             |
| 1   | REAR BOOT INNER TRIMBOARD             | NOT NECESSARY | 123.90                        | 92                |
| 1   | REAR RH LAMP                          | NOT NECESSARY | 206.20                        | 135               |
| 1   | REAR LH LAMP                          | NOT NECESSARY | 206.20                        | 9-                |
| 1   | REAR END PANEL                        | DENTED / BENT | 295.20                        | 295.20            |
| 1   | REAR END PANEL GARNISH                | TWISTED       | 60.80                         | 60.80             |
| 1   | REAR BUMPER                           | DEFORMED      | 440.30                        | 440.30            |
| 2   | REAR BUMPER SIDE RETAINER             | BENT          | 37.60                         | 37.60             |
| 1   | REAR BUMPER LOWER SPOILER             | DISTORTED     | 920.50                        | 680.00            |
|     | LESS 20% DISCOUNT                     |               | -699.90                       | -542.30           |
|     |                                       |               | 2,799.60                      | 2,169.20          |
|     | SPECIAL NETT ITEMS                    |               |                               |                   |
| 1   | SET PARKING SENSOR (SN)               | SHORTED       | 280.00                        | 200.00            |
| 1   | W/S SEALANT (SN)                      | NECESSARY     | 60.00                         | 40.00             |
| 1   | REAR NUMBER PLATE (SN)                | NOT NECESSARY | 40.00                         |                   |
| 1   | SET REAR BUMPER CLIPS (SN)            | NECESSARY     | 40.00                         | 30.00             |
|     |                                       |               | 420.00                        | 270.00            |
|     | LABOUR                                |               |                               |                   |
|     | DISMANTLE & REPLACING REVERSE SENSOR. |               | 80.00                         | 50.00             |
|     | DISMANTLE & REFIX REAR WINDSCREEN.    |               | 120.00                        | 120.00            |
|     | REMOVE INNER GARNISH.                 | - 1           | 100.00                        | 60.00             |
|     | SPRAY PAINTING.                       |               | 1,250.00                      | 980.00            |
|     | LABOUR CHARGE.                        |               | 1,000.00                      | 600.00            |
|     | TUFF COAT.                            |               | 90.00                         | 60.00             |
|     | WIRING CHECK                          |               | 30.00                         | 20.00             |

Report Ref No. CS/FCI18021568/Uqd3n2



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

| Qty | Description of Parts  | Condition | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |  |
|-----|---|-----------|-------------------------------|-------------------|--|
|     | CUSHION REMOVE & REFIX. REMOVE AND REFIX BOOTLID MECHANISM. | REPEATED  | 100.00<br>100.00              |                   |  |
|     |   |           | 2,870.00                      | 1,950.00          |  |
|     | GRAND TOTAL   |           | 6,089.60                      | 4,389.20          |  |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 3,500.00 |
|--------------------------------------|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |          |

Report Ref No. CS/FCI18021568/Uqd3n2

CHUA KANG SENG

Licensed Appraiser