

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1265/2018/JT
Date : 8-Nov-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Yang How
Address : 47 Hillview Ave
#01-05 Hllington Green
Singapore 669614
Telephone : HP +65 9632 2413
Type of Claim : Own Damage Claims
Policy No. : 2100453659-02
Vehicle No : **SCP 1269 R**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Feb-16
Engine No : CVN 002306
Chassis No : WAUZZZF42GA024216
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Nov-18
Place of Accident : West Mall Shopping centre

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCP 1269 R.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer LHS front multi lock system and power window devices.	S/N \$ 280.00 ✓
2	To dismantle and renew LHS front door, align to position. Repair LHS sill panel. Reinstall all parts removed.	\$ 1,800.00 1000
3	To respay LHS front and rear doors, door handles, LHS sill panel and LHS rear fender. To carry out stone chip treatments.	\$ 3,200.00 2300 4x555 = 2200 Handle = 100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,472.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCP 1269 R.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT DOOR - LHS <i>dent</i>	\$	2,048.00 ✓
2	FRONT DOOR OUTER SEAL - LHS <i>new</i>	\$	176.00 ✓
3	BONDING AGENT <i>new</i>	\$	43.00 ?
4	CLEANING SOLUTION <i>new</i>	\$	64.00 ?
5	FRONT DOOR ATTACHMENT PARTS - LHS <i>new</i>	\$	432.00 ?
6	FRONT DOOR CATCH - LHS <i>new</i>	\$	92.00 X.
7	FRONT DOOR BAR - LHS <i>new</i>	\$	143.00 +
8	FRONT DOOR HANDLE COVER - LHS <i>new</i>	\$	55.00 +
9	FRONT DOOR SLOT SHIELD - LHS <i>new</i>	\$	265.00 +
10	STONE CHIP <i>new</i>	S/N \$	200.00 ✓
11	SUNDRIES <i>new</i>	\$	300.00 ?
TOTAL SPARE PARTS CHARGES		\$	3,818.00
TOTAL LABOUR CHARGES		\$	5,472.00
GRAND TOTAL		\$	9,290.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lin
Surveyed Date : 29/11/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 0.5 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant