



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SLS9999S

Great American Insurance Company

3 Temasek Avenue #16-01
Centennial Tower
Singapore 039190
Attn: Motor Claims Dept

Vehicle & Document Information

WIP No 26838
Reg No/Reg Date SLS9999S / 13/08/2014
Date In/Mileage 22/11/2018 / 98633
Chassis No WDD2073342F240331
Engine No 27492030099903
Make/Model MB/E 200 2.0 CGI COUPE (C207
Colour/Trim 025 590 Fire Opal / 042 264 Leather Jav

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	14/12/2018/ 12:42	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100382131 // 11/09/2018 DRIVE IN/EXCESS : 13/09/2018 // TP VEH NO GX8225G GAIA DATE IN/DATE SURVEY: 22/11/2018 // TAUFIKH LKK BY/AUTHORIZED ON : DIRECT SETTLEMENT // KELVYNA GAIA				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				480.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
X RADIATOR GRILLE	1.00	742.31	00.00	742.31

Attn: 02 Working Days

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 1,602.31**
1602.31 112.16

Total Payable 1,714.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg