

(1/1/2018)

INS. CASE OWNER:

DANIEL

CC

/III1802

LKK:

IDAC:

Surveyor:

PSC

DOI:

ASSIGNMENT

Date / Time:

10/11/18

Registered in Meriten:

20/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHL 8504A

Name of Insured:

LIM

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

26/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: DANIEL 21

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MOT 18110911

Policy No.:

MEL00015

Make / Model:

1-4MMP1

Place of Accident:

HAPART BMD TRPS T/TAXI

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:Lim
TanINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/R

SS

2,107.75

(2

days)

Reduction:

29

%

Email

Call

FINAL SETTLEMENT

Date/Time:

12/03/19

Confirm with:

RICHARD

Email

Call

Final Liability:

SS

100

(Agreed/ Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

(CONO REPAIR-ENDED TP)

Repair Cost:

(w/60)

SS

2,265.29

Loss of Rental (LOR):

SS

—

(days)

Loss of Use (LOU):

SS

240.00 (55 x 2 days)

- VARIOUS ADDITIONAL

Loss of Income (LOI):

SS

—

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

—

Medical:

SS

—

Disbursement:

SS

—

(e.g. Tow/ Independent)

Legal Cost

SS

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$300.00

Total:

SS

2,525.29

Global Sum \$5:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2,525.29

Name 1:

LIM TAN MOTOR P/R LTD

Payee 2: (Strike if N.A.)

SS

—

Name 2:

—

Payee 3: (Strike if N.A.)

SS

—

Name 3:

—

REF: II

ASSIGNMENT

From: Date: 04-12-2016

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 04E 3797X

at Workshop mis: Lim Tan

of Blk 176 Sin Ming Drive #03-07

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.81 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 04E 3797X Yr Regn: 07 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Alphard Wagon C.C. 2493

Colour: M. Black A/C Insured / Std / NI / NA

Sp. Reading: 215564 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: AGH30 004829K

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 28/11/18 D.O.I. 4/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/12/18 File pass to Cc/term

P/P \$2,107.75
C/Rev. \$896.50 (29%)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

3)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) 3 + RS. 51

) Photo

) Other

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Invs: \$

☐

Weekend: \$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18021595/Khb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 30-11-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8504A	Veh. Inspected	SLE 3797X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/11/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	28/11/2018	Inspection Date	04/12/2018
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721

Tel : 65-64520893 Fax : 65-64589127 Email : sales@ltm.sg

Website : www.ltm.sg

Co.Reg No. : 199307277D GST Reg No. : M2-0119086-0

TP INSURER: India International Insurance Pte Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

04 DEC 2018

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/11/2018
Vehicle Reg. No.:	SLE3797X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	WONG CHEE KIONG		
Make/Model:	TOYOTA ALPHARD, 2.5 (A)	Vehicle Reg. Date:	19/07/2016
Vehicle Colour:	BLACK		
Engine No:	2ARH648054	Chassis No:	AGH300044294
Odometer:	214005 KM		
Paint Type:			<i>Not Authored</i>
List Item Discount:	25.00 %		<i>Refusing B4 paint</i>
Total Loss?	NO		
Est. Duration of Repair (day)	<i>5 days</i>		

Description of Accident/Loss: AT THE MATERIAL DATE AND TIME, I WAS TRAVELLING ALONG AT CHANGI AIRPORT BLVD, SUDDENLY IN FRONT OF ME THERE ARE VEHICLES STOP I JUST FOLLOWING, WHEN I JUST STOPPED, I AM FELT AN IMPACT FRONT MY BEHIND. I NOTICED VEH B FRONT PORTION HIT ON TO MY VEH A REAR PORTION. BECAUSE HIS COULDN'T STOP IN TIME. NOBODY INJURY, THTA'S ALL.

Present Location: LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	2,114.25
Miscellaneous Items	10.00
Labour	380.00
Paintwork Labour	500.00
Towing	0.00
Gross Total (\$\$)	3,004.25
+ GST 7.00% (\$\$)	210.30
Nett Amount (\$\$)	3,214.55

This claim is handled by: ANG WEI GUANG, RICHARD

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Nov 2018)

Parts: M1-MPV TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

04 DEC 2018

Print Code: Lim Tan Motor Pte Ltd/SLE3797X/29/11/2018 17:50

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	Bu *1,776.00 FL ✓
2	2		*REAR BUMPER RETAINER	25.00	0.00	ln *214.00 FL X
3	21		*REAR BUMPER SENSOR	25.00	0.00	ln *762.00 FL X
4	1		*TAILGATE EMBLEM	25.00	0.00	ln *67.00 FL X
Sub Total (S\$)						2,819.00
- List Item Discount on L Items (S\$)						704.75
Total Parts (S\$)						2,114.25

F=Franchise part, L=ListItemDisc.

Lim Tan Motor Pte Ltd/SLE3797X/29/11/2018 17:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

04 DEC 2018

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	10.00 ✓
Sub Total (S\$)			10.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	TO PUTTY AND SPRAY PAINTING	New	500.00 ²⁵⁰
---	-----------------------------	-----	-----------------------

Labour Items

2	TO CHECK REAR WIRING AND REPLACE SENSOR	New	30.00 ✓
3	LABOUR CHARGES	New	200.00 350.00

Gross Labour Cost (S\$) 880.00

Lim Tan Motor Pte Ltd/SLE3797X/29/11/2018 17:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 4499L

Vehicle Details

Vehicle No.: SLE3797X
Vehicle to be Exported: Yes
Intended Deregistration Date: 29 Nov 2018
Vehicle Make: TOYOTA
Vehicle Model: ALPHARD 2.5S A
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: 2ARH648054
Chassis No.: AGH300044294
Maximum Power Output: 134.0 kW (179 bhp)
Open Market Value: \$34,422.00
Original Registration Date: 19 Jul 2016
First Registration Date: 19 Jul 2016
Transfer Count: 0
Actual ARF Paid: \$40,191.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 18 Jul 2026
PARF Rebate Amount: \$30,143.00

Intended COE Rebate Details

COE Expiry Date: 18 Jul 2026
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$57,390.00
COE Rebate Amount: \$43,524.00
Total Rebate Amount: \$73,667.00

The information contained herein is correct as at 29 Nov 2018

OK

Print Received Message

This mail is associated with :

SLE3797X (MCT18110911)
[SHC8504A]
TP
OH LIMOUSINE
Nov 28 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Lim Tan Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 08/03/2019 12:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2525.29) - SLE3797X - Claim Handler: Pooi Chin Han Daniel

Approved:2525.29.

Vehicle Leasing Contract

The agreement is between Oh Limousine, 3 Jalan Kukoh #01-115, Singapore 161003 and Mr. Wong Chee Kiong (S1760081H), address Blk 251 Jurong East Street 24 #09-122, Singapore 600251.

Oh Limousine will lease vehicle SLE 3797X (Black Toyota Alphard 2.5L) to Mr. Wong Chee Kiong from 4th March 2018 onwards. This leasing contract will take effect on 4th March 2018 and terminate on 3rd March 2019.

Oh Limousine and Mr. Wong Chee Kiong agree as follows:

Responsibility of Oh Limousine

1. Provide vehicle insurance and road tax.
2. Perform routine vehicle maintenance.

Responsibility of Mr. Wong Chee Kiong

1. Weekly leasing payment of S\$945 to be made at the beginning of each week to Oh Limousine.
2. In the event of an accident, Mr. Wong Chee Kiong is to reimburse Oh Limousine for any and all costs not covered by liability and collision insurance.
3. Any early termination of contract is not accepted unless one month written notice prior to the termination date should be given to Oh Limousine, or equivalent cash terms in exchange for the notice period.

The agreement is agreed and signed by:


 

Oh Limousine
Oliver Leong
General Manager

Date: 4th March 2018



Mr. Wong Chee Kiong
IC: S1760081H

Date: 4th March 2018



Date: 19 DEC 2018

Your Ref: CC4/III18021595/Khb3

Our ref: LTP112018/098 (SLE 3797 X)

(WITHOUT PREJUDICE)

Attention To : MR VIC ALPEH (From LKK Auto Consultants Pte Ltd)

Insurance Company : INDIA INTERNATIONAL INSURANCE PTE LTD

Dear Sir/Mdm,

IN THE MATTER OF ACCIDENT INVOLVING SLE3797X & SHC8504A ON 28.11.2018

We refer to the above matter.

We are instructed and authorised by our client to quantify, to act and negotiate settlement in related to the above road traffic accident that was caused by your insured.

All supporting documents are enclosed herewith:-

☒ Authorization To Act	☒ Original Tax Invoice no. INV37763
☒ Original Vehicle Leasing Contract	☐ LTA Search Receipt
☐ Letter Of Discharge	☐ _____

Survey was done by Insurance instruction and was surveyed by Mr Kenneth
on 4-Dec-18

As a result of the accident, our client's vehicle was damaged and has been put to loss and Expenses, particulars of which are as follows:-

1] Cost of repair (inclusive of 7% GST)	\$ 2,255.29
2] Loss of Use (\$135.00 x 2 days)	\$ 270.00
Total	<u>\$ 2,525.29</u>

Please acknowledge receipt of this letter within 14 days. If you agreeable to the above, please forward your payment. Payment to be issued directly to LIM TAN MOTOR PTE LTD within 4 weeks. Should there be any injury related to this matter, any settlement agreed is WITHOUT PREJUDICE to the related injury claim.

Your faithfully

Mandy Lim

Email: mandy@ltm.sg

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Website: www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd.

To Whom It May Concern

AUTHORIZATION TO ACT

I/We, OH LIMOUSINE ('the third party Claimant') of 3 JALAN KUKOH #01-115 SINGAPORE 161003 (Address) owner of SLE3797X (vehicle number) hereby authorize LIM TAN MOTOR PTE LTD ('the workshop') to act for me with respect to my/our claim for repair costs and/or rental and/or Loss of use ('claim') for my/our vehicle number SLE3797X that was damaged pursuant to the accident which occurred on 28-Nov-18 (date) along CHANGI AIRPORT BOULEVARD (locate on) involving vehicle number SHC8504A (the accident').

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive Payment further to settlement of my claim with payment cheque/s being made In favour of the workshop.

Dated this 3rd (day) of December (month) 2018 (year)



Signed By ' the third party claimant '



Signed By ' the workshop '

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT18110911

Claimant Ref: LTP112018/098(SLE3797X)

We/I, LIM TAN MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 2,255.29 (repair cost), S\$ 270.00 (loss of use/rental), S\$ --- (search fee), vehicle no. SLE3797X that was damaged pursuant to the accident which occurred on 28/11/2018 (date) at CHANGI AIRPORT BOULEVARD (location) involving vehicle no. SHC8504A (insured vehicle). This is pursuant to the inspection conducted on 04/12/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner OH LIMOUSINE ("the third party claimant") of vehicle no. SLE3797X to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLE3797X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2,525.29 to LIM TAN MOTOR PTE LTD

Dated this 12 day of MARCH 20 19

CLAIMANT:

Signature:


Signed by "the workshop" (with chop)

Name:

LIM TAN MOTOR PTE LTD

NRIC:

199307277D

Address:

BLK 176 SIN MING DRIVE

#03-09 SE 575721

Nationality:

Occupation:

WITNESS:

Signature:


Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANTS PTE LTD

NRIC:

199607198R

Address:

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

Nationality:

Occupation:



LIM TAN MOTOR PTE LTD
林陳摩哆私人有限公司

Company's Registration No. 199307277D
GST Registration No. S42-0119086-0

Branch
(Warranty and Performance) Blk 9 Sector C #01-38/40/42
Sin Ming Industrial Estate, Singapore 575644
Tel: +65 6452 2135 Fax: +65 6452 2159

Blk 17 Sector A #01-65
Sin Ming Industrial Estate, Singapore 575675

Main Office / Workshop
Blk 176 Sin Ming Drive #03-09/10/06
Sin Ming Autocare Singapore 575721

Tel: +65 6452 0893 (24Hrs)

Fax: +65 6458 9127

Email: sales@LTM.sg

WWW.LTM.SG

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-#05 IOB BUILDING
S049711

TAX INVOICE

NO : INV37763

DATE : 18-12-2018

TERMS : CASH

PAGE : 1

ATTN : MOTOR CLAIMS DEPT

TEL :

FAX :

A/C NO. : 3010/005

MILEAGE :

W.O NO. : SO38508

CAR NO. : SLE3797X

MAKE : TOYOTA

MODEL : ALPHARD

DESCRIPTION	QTY	U.PRICE	DIS	AMOUNT
1 TOTAL REPAIR COSTS AS RECOMMENDED BY SURVEYOR	1 UNIT			2,107.75

SINGAPORE DOLLARS : TWO THOUSAND TWO HUNDRED FIFTY FIVE AND TWENTY NINE CENTS ONLY

REMARKS: D.O.A : 28.11.2018
LKK REF : CC4/III18021595/Khb3

TOTAL QTY: 1.00

SUBTOTAL	2,107.75
DISCOUNT	0.00
TOTAL	2,107.75
GST 7 %	147.54
NET	2,255.29
Deposit	0.00
Balance	2,255.29



AUTHORISED SIGNATURE(S)

CUSTOMER NAME / SIGNATURE / DATE

Customer Acknowledgement

I/We confirm that I/We incurred the repair costs herein and will observe my/our Agreement with the repairer. I/We declare the repair for the above vehicle have been completed to my/our satisfaction

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2018 Sendback Est	29 Nov 2018 17:50 \$53,004.25	30 Nov 2018 08:27 Edit Adj Rpt	\$52,107.75 Edit Estimates	\$52,107.75 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	OH LIMOUSINE , Co. Reg. No.: 53284499L								
Vehicle Reg. No.:	SLE3797X	Date of Loss:	28/11/2018 19:00 - :59 [28 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18110911	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHC8504A	Policy No. (Claimant):	5095335108						
		Excess:							
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/12/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (08/03/2019): Alert - Adj Mandate Approved (\$52525.29) - SLE3797X - Claim Handler: Pooi Chin H... - III_SG (14/12/2018): Alert - Adj Mandate Approved (\$50.00) - SLE3797X - Claim Handler: Pooi Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLE3797X (MCT18110911)
[SHC8504A]
TP
OH LIMOUSINE
Nov 28 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Lim Tan Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 11:47	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 17:50	Repairer Estimates	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/02/19 17:10	Odometer Reading	Load JPG	☒
2	21/02/19 17:10	Chassis Number	Load JPG	☒
3	21/02/19 17:11	General View	Load JPG	☒
4	21/02/19 17:11	General View	Load JPG	☒
5	21/02/19 17:11	General View	Load JPG	☒
6	21/02/19 17:11	General View	Load JPG	☒
7	21/02/19 17:11	General View	Load JPG	☒
8	21/02/19 17:11	General View	Load JPG	☒
9	21/02/19 17:11	General View	Load JPG	☒
10	21/02/19 17:11	General View	Load JPG	☒
11	21/02/19 17:11	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/12/18 11:23	Singapore Accident Statement	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/12/18 17:28	TP ESTIMATE- MARKED	Load PDF	
2	25/02/19 14:56	WORKSHOP INVOICE	Load PDF	
3	25/02/19 14:56	LOD	Load PDF	
4	20/03/19 10:52	AUTHORISATION TO ACT FORM	Load PDF	
5	20/03/19 10:52	DISCHARGE VOUCHER	Load PDF	

Linked Accident Report Documents

			View View in Browser	
Video			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 11:47	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 12:22	Accident Statement	Load HTM	

Video			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 11:50	Accident Photo	 Load JPG	☒
2	29/11/18 11:50	Accident Photo	 Load JPG	☒
3	29/11/18 11:50	Accident Photo	 Load JPG	☒
4	29/11/18 11:51	Accident Photo	 Load JPG	☒
5	29/11/18 11:51	Accident Photo	 Load JPG	☒
6	29/11/18 11:51	Accident Photo	 Load JPG	☒
7	29/11/18 11:51	Accident Photo	 Load JPG	☒
8	29/11/18 11:51	Accident Photo	 Load JPG	☒
9	29/11/18 11:52	Accident Photo	 Load JPG	☒
10	29/11/18 11:52	Accident Photo	 Load JPG	☒
11	29/11/18 11:52	Accident Photo	 Load JPG	☒
12	29/11/18 11:52	Accident Photo	 Load JPG	☒
13	29/11/18 11:52	Accident Photo	 Load JPG	☒
14	29/11/18 11:52	Accident Photo	 Load JPG	☒
15	29/11/18 11:52	Accident Photo	 Load JPG	☒
16	29/11/18 11:52	Accident Photo	 Load JPG	☒
17	29/11/18 12:16	Accident Photo	 Load JPG	☒
18	29/11/18 12:16	Accident Photo	 Load JPG	☒
19	29/11/18 12:16	Accident Photo	 Load JPG	☒
20	29/11/18 12:16	Accident Photo	 Load JPG	☒
21	29/11/18 12:16	Accident Photo	 Load JPG	☒
22	29/11/18 12:16	Accident Photo	 Load JPG	☒
23	29/11/18 12:16	Accident Photo	 Load JPG	☒
24	29/11/18 12:16	Accident Photo	 Load JPG	☒
25	29/11/18 12:17	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Lim Tan Motor Pte Ltd (HQ)	Thumbnail	Print
1	29/11/18 11:49	Sketch Plan	 Load TIF	
2	29/11/18 11:49	Sketch Plan #2	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18021595/KHB3Q2

Date: 20/03/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SLE3797X

Insured Vehicle No : SHC8504A

Date of Loss: 28/11/2018

Nature of Claim:

TP

Claim No: MCT18110911

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE3797X

Make & Model: TOYOTA ALPHARD, 2.5 (A)

Reg. Date: 19/07/2016 (Man. Year: 2015)

Colour: Metallic Black

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 2ARH648054

Chassis No: AGH300044294

Odometer: 215564 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Front Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Tyre Size: 235/50 R18

Rear Left Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,114.25	1,617.75	496.50	23.48
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	380.00	230.00	150.00	39.47
Paintwork Labour	500.00	250.00	250.00	50.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,004.25	2,107.75	896.50	29.84
+ GST 7.00/7.00% (S\$)	210.30	147.54	62.76	29.84
Nett Amount (S\$)	3,214.55	2,255.29	959.26	29.84
+ Loss of Use (2.0 x S\$135.00/day) (S\$)		270.00		
Nett Liability (S\$)		2,525.29		

INSPECTION

Date of Assignment: 30/11/2018 Present Location:

Date Inspected: 04/12/2018 Inspected At:

Lim Tan Motor Pte Ltd (HQ)

Lim Tan Motor Pte Ltd (HQ)

Blk 176 Sin Ming Drive #03-09/10, Sin

Ming Auto Care

Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2019)
Parts: M1-MPV	TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE3797X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,776.00 FL	*1,776.00 FL
2	2		*REAR BUMPER RETAINER	Serviceable	214.00 FL	*- FL
3	2		*REAR BUMPER SENSOR	Shorted (1 PCS ONLY)	762.00 FL	*381.00 FL
4	1		*TAILGATE EMBLEM	Not Necessary	67.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,819.00	2,157.00
- List Item Discount on L Items 25.00/25.00% (S\$)	704.75	539.25
Total Parts (S\$)	2,114.25	1,617.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO PUTTY AND SPRAY PAINTING	New	500.00	250.00
<u>Labour Items</u>				
2	TO CHECK REAR WIRING AND REPLACE SENSOR	New	30.00	30.00
3	LABOUR CHARGES	New	350.00	200.00
Gross Labour Cost (S\$)			880.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >