

Lim Tan Motor Pte Ltd

Block 176 Sin Ming Drive # 03-09/10/06 Sin Ming Autocare Singapore 575721 Tel: 65-64520893 Fax: 65-64589127 Email: sales@ltm.sg Website: www.ltm.sg

Co.Reg No.: 199307277D GST Reg No.: M2-0119086-0

TP INSURER:

India International Insurance Pte Ltd (HQ)

COMFORT TRANSPORTATION PTE LTD

Singapore

n 4 DEC 2018

Claimant Insurer:

NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

Policy No:

Date of Loss:

Driveable?

Vehicle Reg. No.: Party At Fault:

SLE3797X

UNKNOWN

Driver (TP):

WONG CHEE KIONG

Make/Model:

TOYOTA ALPHARD, 2.5 (A)

Vehicle Reg. Date:

19/07/2016

28/11/2018

Vehicle Colour:

BLACK

2ARH648054

Chassis No:

AGH300044294

Engine No: Odometer:

214005 KM

Paint Type:

List Item Discount:

25.00 %

Total Loss?

NO

Est. Duration of Repair

(day)

& Iday,

Nos Nothern Resiny B4 pains

Description of Accident/Loss AT THE MATERIAL DATE AND TIME, I WAS TRAVELLING ALONG AT CHANGI AIRPORT BVLD, SUDDENLY IN FRONT OF ME THERE ARE VEHICLES STOP I JUST FOLLOWING, WHEN I JUST STOPPED, I AM FELT AN IMPACT FRONT MY BEHIND. I NOTICED VEH B FRONT PORTION HIT ON TO MY VEH A REAR PORTION, BECAUSE HIS COULDN'T STOP IN TIME, NOBODY INJURY, THTA'S ALL.

Present Location:

LIM TAN MOTOR PTE LTD (HQ)

COST OF CLAIMS		Amount
Parts		2,114.25
Miscellaneous Items		10.00
Labour		380.00
Paintwork Labour		500.00
Towing		0.00
	Gross Total (S\$)	3,004.25
	+ GST 7.00% (S\$)	210.30
	Nett Amount (S\$)	3,214.55

This claim is handled by: ANG WEI GUANG, RICHARD

REPAIR DETAILS Reference Version: 1.0 (Last Synchronised: 29 Nov 2018) Part Source: MRM-SG TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0) M1-MPV Parts: 0 4 DEC 2018 (Price-denominated Standard List) Labour: Repairer's Print Code: Lim Tan Motor Pte Ltd/SLE3797X/29/11/2018 17:50 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity: the END OF ESTIMATES marker on the last estimate page Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

_				_
Ect	imat	00	on	Parts
	ша	=5	()	Falls

No.	Qty Part No.		Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	Bn *1,776.00 FL
2	2		*REAR BUMPER RETAINER	25.00	0.00	*214.00 FL X
3	2		*REAR BUMPER SENSOR	25.00	0.00	√ ×762.00 FL X
4	1		*TAILGATE EMBLEM	25.00	0.00	*67.00 FL X
F=Fr	anchise part. L=ListIt	emDisc.				
			Sub Total (S\$)			2,819.00
			11.44 51 44 14 46 (00)			
			- List Item Discount on L Items (S\$)			704.75

Lim Tan Motor Pte Ltd/SLE3797X/29/11/2018 17:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items No Qty Particulars	0 4 DEC 2018	Amount
Miscellaneous Items		
1 1 OD/TP Case (Insurer)		10.00
	Sub Total (S	10.00
Estimates on Labour		
No Particulars	Lab.Type	Amount
Paintwork Labour		250
1 TO PUTTY AND SPRAY PAINTING Labour Items	New	500.00
2 TO CHECK REAR WIRING AND REPLACE SENSOR	New	30.00
B LABOUR CHARGES	New	2006 350.00
	Gross Labour Cost (S\$)	880.00

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged partis, aug. cresurvey
 Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: