

ASS. REC. BY:

REF: (S/CTU18021596 / Gtbnz

Special Instruction:

SURVAYOR

ASSIGNMENT (Office)

From (Person): Catherine Triga of CTL Date/Time: 30/11/2018 11:20am

Estimated Cost: Bill to:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 3910T Insured: SLC 1762U

at Workshop m/s: World Auto Tel: 6362 1776

of No. 1 Kranji Loop

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 26-11-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time: 30/11/2018 1:30pm Person Contacted: Aimee Vehicle: ☒ IN / ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLM 3910T - x
	SLC 1762U - x
	Finalise COR \$13,940.40 (Red: 9180.40; 39%)
	Reconfirm \$13,556.40 (12 days) (Red: 9564.40; 70%)

Surveyor: VHL

REF: CTi

C4597K

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s World Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$73K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM2990T

Yr Regn: 27 Mar 2017

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle c.c. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 146684 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP 71104095

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 185 / 60 R 15

R: 14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 03-12-18

Survey held at W/S

4pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Net: \$25K.

RECEIVED 25 APR 2019

Date/Time, File Pass to?

☐ : Preli. Report

25/4 Typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS. \$

) Photos

) Others

TOTAL

Report Format : TP

Lump Sum / (B.I.): (\$ 13,556.40)

220

Catherine Chong (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Friday, 30 November, 2018 11:20 AM
To: assignments
Cc: Lucas Lee; worldautopl@yahoo.com.sg
Subject: FW: Request for Third Party Motor Claim Survey (SLM2990T) DOA: 26-11-2018

Dear LKK OIC

Please assist to do PRI on without prejudice basis. We will create in Merimen shortly

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ainee31@worldauto.com.sg [mailto:aine31@worldauto.com.sg]
Sent: Thursday, 29 November, 2018 9:46 AM
To: Lucas Lee <lucas.lee@sg.cntaiping.com>
Cc: worldautopl@yahoo.com.sg; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: Request for Third Party Motor Claim Survey (SLM2990T) DOA: 26-11-2018

DEAR LUCAS

Can please help to assist this PRI

Ainee

**Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250**

From: ainee31@worldauto.com.sg <ainee31@worldauto.com.sg>
Sent: Wednesday, November 28, 2018 9:46 AM
To: 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>
Cc: 'worldautopl@yahoo.com.sg' <worldautopl@yahoo.com.sg>
Subject: Request for Third Party Motor Claim Survey (SLM2990T) DOA: 26-11-2018

Good afternoon,
We would like to request for a Third Party Motor Claim Survey, details as follow;

Our Vehicle: SLM2990T
Your Insured: SLC1762U
DOA: 26-11-2018

Our vehicle is currently in the workshop, address as follow;

World Auto Pte Ltd
No.1, Kranji Loop
Singapore 739535

Please response immediately upon receiving this request, send us your list of Loss Adjustor for our choice within 48 hours.

Kindly note that should you fail to response to us within the above stipulated timeline, we may, at our discretion, appoint our own Loss Adjustor to perform this PRI.

Ainee

**Thanks and Rgds,
World Auto Pte Ltd
Kranji: 63621776
Fax: 63631250**

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Friday, 17 May 2019 2:30 PM
To: tggtan@worldauto.com.sg
Subject: RE: SLM 2990T Our ref: TP/2345/18

Dear Sophia,

confirm finalise COR \$13,556.40 and 12 repair days.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Friday, 17 May 2019 2:28 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: SLM 2990T Our ref: TP/2345/18
Importance: High

Hi Denise

As per our telecon, we confirm finalise COR \$13,556.40 and 12 repair days.

Kindly confirm.

Thanks
Sophia

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, 24 April 2019 10:29 AM
To: tggtan@worldauto.com.sg
Cc: daniel@worldauto.com.sg
Subject: RE: SLM 2990T Our ref: TP/2345/18

Dear All,

Any photograph? Need to finalize with you

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Denise Tay (LKKAUTO)

From: tggtan@worldauto.com.sg
Sent: Wednesday, 24 April 2019 4:57 PM
To: Denise Tay (LKKAUTO)
Subject: RE: SLM 2990T Our ref: TP/2345/18

Hi Denise

Confirmed finalised COR \$13,940.40 and 12 repair days,

Rdgs
Sophia

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, 24 April 2019 2:01 PM
To: tggtan@worldauto.com.sg
Subject: RE: SLM 2990T Our ref: TP/2345/18

Dear Sophia,

Enclosed estimate marking

Part by Part \$13,940.40, 12days.

Please check and get back on confirmation.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg <tggtan@worldauto.com.sg>
Sent: Wednesday, 24 April 2019 1:22 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Subject: RE: SLM 2990T Our ref: TP/2345/18

Hi Denise

Attach for your attention.

Rdgs
Sophia

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Wednesday, 24 April 2019 10:29 AM
To: tggtan@worldauto.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLM2990T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	LEB6305025
Chassis No.:	GP71104095
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,821.00
Original Registration Date:	27 Mar 2017
First Registration Date:	27 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Mar 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$52,600.00
COE Rebate Amount:	\$43,706.00
Total Rebate Amount:	\$47,456.00

The information contained herein is correct as at 04 Dec 2018

OK

china Taipei



Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: G 11359

Date: 26/11/18

Name/Company World Auto
Vehicle No. SLM 2990 T Model shuttle
From Thomson heavy vehicle car park
To 1 kranji loop
Remarks _____

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Time: 08:10 - 08:50 - 09:30

Amount \$60

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

YM 5128T
Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

Received By [Signature]

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

Estimate : ES000411

Date : 28/11/2018

Vehicle Num. : SLM 2990T (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 26/11/2018

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID / BUC		1,350.00
2.	1	REAR NUMBER PLATE LAMP GARNISH / BR		460.00
3.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) /		89.00
4.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) /		89.00
5.	1	REAR WINDSCREEN GLASS MOULDING		250.00
6.	2	REAR BOOT REFLECTOR LAMP / CRA	580.00	1,160.00
7.	1	REAR BOOT WEATHER STRIP /		180.00
8.	1	REAR BOOT INNER TRIM BOARD /		480.00
9.	1	REAR BOOT LOCK ASSY / BT		565.00
10.	1	REAR BOOT HAND GRIP COVER / DIS		85.00
11.	1	REAR BUMPER /		1,150.00
12.	1	REAR END PANEL / BUC		680.00
13.	1	REAR END PANEL TOP GARNISH /		260.00
14.	1	REAR BUMPER TOW COVER /		89.00
15.	1	REAR ANTENNA SENSOR /		180.00
16.	1	SMART BUZZER SENSOR /		180.00
17.	1	REAR FLOOR PANEL /		980.00
18.	1	REAR FLOOR BOARD /		550.00
19.	1	REAR COMPARTMENT BOX / CRA		420.00
20.	1	REAR COMPARTMENT BOX BACK COVER / CRA		160.00
21.	2	REAR BUMPER RETAINER /	89.00	178.00
22.	2	REAR BOOT STOPPER /	42.00	84.00
23.	1	REAR BOOT LOCK CATCH /		158.00
24.	1	REAR EXHAUST MUFFLER /		650.00
25.	1	REAR EXHAUST PIPE /		650.00
26.	1	REAR EXHAUST HEAT SHIELD /		180.00
27.	1	REAR EXHAUST MOUNTING /		50.00
28.	1	REAR BUMPER UNDERDUST COVER /		210.00
29.	2	REAR TAIL LAMP / CRA	580.00	1,160.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

Estimate : ES000411

Date : 28/11/2018

Vehicle Num. : SLM 2990T (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 26/11/2018

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	2	REAR FENDER <i>x repair</i>	817.00	1,634.00
31.	2	REAR BUMPER REFLECTOR GARNISH <i>LH X NN</i>	170.00	340.00
32.	2	REAR BUMPER REFLECTOR LENS <i>RH - CAA</i>	180.00	360.00
33.	2	REAR TAILLAMP LOWER PANEL <i>Buc</i>	215.00	430.00
34.	2	REAR FENDER INNER TRIM BOARD <i>RE</i>	345.00	690.00
35.	2	REAR SIDE COMPARTMENT BOX <i>X NN</i>	120.00	240.00
36.	2	REAR COMPARTMENT SIDE FLOOR BOARD <i>X NN</i>	190.00	380.00
37.	1	REAR BOOT TOOLKIT FOAM BOX <i>CAA</i>		120.00
38.	2	REAR FENDER GLASS MOULDING <i>X NN</i>	140.00	280.00
39.	2	REAR BUMPER INNER FOAM <i>LH - CAA, RH X NN</i>	100.00	200.00
40.	1	HYBRID BATTERY BLOWER MOTOR <i>X</i>		450.00
41.	1	HYBRID BATTERY BLOWER MOTOR AIR DUCT <i>X</i>		160.00
42.	1	HYBRID BATTERY METAL HOUSING <i>X</i>		240.00
List Total S\$:				18,201.00
20.00% Discount S\$:				3,640.20
				14,560.80

SPECIAL NETT ITEMS :

1.	1	REAR NUMBER PLATE LAMP GARNISH CLIP <i>MLC</i>	40.00	20
2.	1	REAR WINDSCREEN SEALANT <i>MLC</i>	100.00	40
3.	1	REAR BOOT INNER TRIM BOARD CLIP <i>MLC</i>	40.00	20
4.	1	REAR NUMBER PLATE W/CASING <i>MLC</i>	40.00	20
5.	1	REAR BUMPER CLIP <i>MLC</i>	40.00	20
6.	1	REAR END PANEL TOP GARNISH CLIPS <i>MLC</i>	40.00	20
7.	1	REVERSE SENSOR <i>Om</i>	280.00	200
8.	2	REAR TAILLAMP CLIPS <i>MLC</i>	40.00	80.00
9.	2	REAR FENDER INNER TRIM BOARD CLIPS <i>MLC</i>	40.00	80.00
10.	2	REAR FENDER GLASS SEALANT <i>X NN</i>	60.00	120.00
11.	1	TOWING CHARGE		60.00
Special Nett Total S\$:				920.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

Estimate : ES000411

Date : 28/11/2018

Vehicle Num. : SLM 2990T (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 26/11/2018

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES

180.00 60

REMOVE & REFIT REAR WINDSCREEN GLASS

180.00 120

LH
RH

REMOVE & REPLACE FENDER 1/4 GLASS

180.00 x } NV

REMOVE & REPLACE FENDER 1/4 GLASS

180.00 x }

TO DISMANTLE REAR DAMAGE PARTS, CUT AND WELD REAR SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.

3,000.00 1700

TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS

2,000.00 1300

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS

180.00 60

TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.

180.00 120

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 250

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 250

COMPUTERISED ALIGNMENT

180.00 x NV

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

CHINA TAIPING INSURANCE PTE LTD

Estimate : ES000411

Date : 28/11/2018

Vehicle Num. : SLM 2990T (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 26/11/2018

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE REAR EXHAUST MUFFLER IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	180.00	60
		REMOVE REAR UPHOLSTERY INCLUDING REAR CAR SEATS, REAR FLOOR PANEL LINING, ROOF INNER LINING, IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	300.00	80
		Labour Total S\$:		7,640.00

12 Days -

~~to be~~

put by put.

before parts photos.

Gino Qiang - 8288 0282

03/12/18.

E. & O.E.

Total S\$:

23,120.80

=====

for WORLD AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021596/GTBN2

Date: 21/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30558418022
Claimant Vehicle No :	SLM2990T	Insured Vehicle No :	SLC1762C
Date of Loss:	26/11/2018	Nature of Claim:	TP
		Claim No:	SNM18D05522C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM2990T	Engine No:	LEB6305025
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71104095
Reg. Date:	27/03/2017 (Man. Year: 2016)	Odometer:	146684 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R16	Rear Tyre Size:	185/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,420.80	9,506.40	5,914.40	38.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	4,050.00	3,650.00	47.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,120.80	13,556.40	9,564.40	41.37
+ GST 7.00/7.00% (S\$)	1,618.46	948.95	669.51	41.37
Nett Amount (S\$)	24,739.26	14,505.35	10,233.91	41.37

INSPECTION

Date of Assignment:	16/05/2019	
Date Inspected:	03/12/2018	Inspected At: World Auto Pte Ltd (HQ) 47 Jln Pemimpin, #01-02/03 Halcyon 2 Singapore 577200
Estimated Period of Repair:	12.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 May 2019)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM2990T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	1,350.00 FL	*1,350.00 FL
2	1		*REAR NUMBER PLATE LAMP GARNISH	Broken	460.00 FL	*460.00 FL
3	1		*REAR BOOT SHUTTLE EMBLEM (SHUTTLE)	Necessary	89.00 FL	*89.00 FL
4	1		*REAR BOOT HYBRID EMBLEM (SHUTTLE)	Necessary	89.00 FL	*89.00 FL
5	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	250.00 FL	*250.00 FL
6	2		*REAR BOOT REFLECTOR LAMP	Cracked	1,160.00 FL	*1,160.00 FL
7	1		*REAR BOOT WEATHER STRIP	Twisted	180.00 FL	*180.00 FL
8	1		*REAR BOOT INNER TRIM BOARD	Not Necessary	480.00 FL	*- FL
9	1		*REAR BOOT LOCK ASSY	Bent	565.00 FL	*565.00 FL
10	1		*REAR BOOT HAND GRIP COVER	Distorted	85.00 FL	*85.00 FL
11	1		*REAR BUMPER	Deformed	1,150.00 FL	*1,150.00 FL
12	1		*REAR END PANEL	Buckled	680.00 FL	*680.00 FL
13	1		*REAR END PANEL TOP GARNISH	Deformed	260.00 FL	*260.00 FL
14	1		*REAR BUMPER TOW COVER	Missing	89.00 FL	*89.00 FL
15	1		*REAR ANTENNA SENSOR	Damaged	180.00 FL	*180.00 FL
16	1		*SMART BUZZER SENSOR	Not Necessary	180.00 FL	*- FL
17	1		*REAR FLOOR PANEL	Buckled	980.00 FL	*980.00 FL
18	1		*REAR FLOOR BOARD	Not Necessary	550.00 FL	*- FL
19	1		*REAR COMPARTMENT BOX	Cracked	420.00 FL	*420.00 FL
20	1		*REAR COMPARTMENT BOX BACK COVER	Cracked	160.00 FL	*160.00 FL
21	2		*REAR BUMPER RETAINER	Necessary	178.00 FL	*178.00 FL
22	2		*REAR BOOT STOPPER	Not Necessary	84.00 FL	*- FL
23	1		*REAR BOOT LOCK CATCH	Bent	158.00 FL	*158.00 FL
24	1		*REAR EXHAUST MUFFLER	Not Necessary	650.00 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	650.00 FL	*- FL
26	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	180.00 FL	*- FL
27	1		*REAR EXHAUST MOUNTING	Not Necessary	50.00 FL	*- FL
28	1		*REAR BUMPER UNDERDUST COVER	Not Necessary	210.00 FL	*- FL
29	2		*REAR TAIL LAMP	Cracked	1,160.00 FL	*1,160.00 FL
30	2		*REAR FENDER	Repair	1,634.00 FL	*- FL
31	1		*REAR BUMPER REFLECTOR GARNISH	O/s Cracked/N/s Not Necessary	340.00 FL	*170.00 FL
32	1		*REAR BUMPER REFLECTOR LENS	O/s Cracked/N/s Not Necessary	360.00 FL	*180.00 FL
33	2		*REAR TAILLAMP LOWER PANEL	Buckled	430.00 FL	*430.00 FL
34	2		*REAR FENDER INNER TRIM BOARD	Deformed	690.00 FL	*690.00 FL
35	2		*REAR SIDE COMPARTMENT BOX	Not Necessary	240.00 FL	*- FL
36	2		*REAR SIDE COMPARTMENT SIDE FLOOR BOARD	Not Necessary	380.00 FL	*- FL
37	1		*REAR BOOT TOOLKIT FOAM BOX	Cracked	120.00 FL	*120.00 FL
38	2		*REAR FENDER GLASS MOULDING	Not Necessary	280.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR BUMPER INNER FOAM	N/s Cracked/O/s Not Necessary	200.00 FL	*100.00 FL
40	1		*HYBRID BATTERY BLOWER MOTOR	Not Necessary	450.00 FL	*- FL
41	1		*HYBRID BATTERY BLOWER MOTOR AIR DUCT	Not Necessary	160.00 FL	*- FL
42	1		*HYBRID BATTERY METAL HOUSING	Not Necessary	240.00 FL	*- FL
43	1		*REAR NUMBER PLATE LAMP GARNISH CLIP	Necessary	40.00 FS	*20.00 FS
44	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
45	1		*REAR BOOT INNER TRIM BOARD CLIP	Necessary	40.00 FS	*20.00 FS
46	1		*REAR NUMBER PLATE W/CASING	Scratched	40.00 FS	*40.00 FS
47	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
48	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
49	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
50	2		*REAR TAILLAMP CLIPS	Necessary	80.00 FS	*20.00 FS
51	2		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*40.00 FS
52	2		*REAR FENDER GLASS SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,061.00	11,773.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,640.20	2,266.60
Total Parts (\$\$)	15,420.80	9,506.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	60.00	50.00
2	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
3	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
4	REMOVE & REPLACE FENDER 1/4 GLASS LH	New	180.00	0.00
5	REMOVE & REPLACE FENDER 1/4 GLASS RH	New	180.00	0.00
6	TO DISMANTLE REAR DAMAGE PARTS,CUT AND WELD REAR SUPPORT PANEL,KNOCK,STRAIGHTEN AND RESHAPE O/S REAR CHASSIS FRAME AND REPLACE RECOMMENDED PARTS	New	3,000.00	1,700.00
7	TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS	New	2,000.00	1,300.00
8	TO CHECK REAR WIRES,CONNECTORS,REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS	New	180.00	60.00
9	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS	New	180.00	120.00
10	DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	250.00
11	PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINTIALISING HV HYBRID SYSTEM FOR POST REPAIRS (HV HYBRID SYSTEM SAFETY PROCEDURES)	New	450.00	250.00
12	COMPUTERISED ALIGNMENT	New	180.00	0.00
13	REMOVE REAR EXHAUST MUFFLER IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	New	180.00	60.00
14	REMOVE REAR UPHOLSTERY INCLUDING REAR CAR SEATS,REAR FLOOR PANEL LINING,ROOF INNER LINING,IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME	New	300.00	80.00
Gross Labour Cost (\$\$)			7,700.00	4,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >