

MS FCIL Insured's Veh No : SHC773S Date of Accident : 29 November 2018

51 Defu Lane 10 Singapore 539216 Tel: 68585151 (24 Hours) Fax: 68580877

GST Regn. No.: M2-8922054-2

Miss Loo Sek Lin (Lu Xueling)

Date: 11 December 2018

Supplementary To Repair SGQ6515U - Mercedes Benz S300L

Chassis No: WDD2211542A097119

| No Quantity | Description | / | Amount |
|--|---|---|--------|
| 01 | LABOUR & MISC. CHARGES To redo paint coating accident affected portion. | \$ | 350.00 |
| | To rego paint coating accident ancested portion. | \$ | 350.00 |
| | Total | \$ | 350.00 |
| | | | |
| | | | |
| | LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed | | |
| | Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer | | |
| | Signature: Date: | | |
| edites jestija kas kaja kaja kaja kaja kaja kaja kaj | | - The second section of the section of | |
| | | | |
| | | | |
| | | | |
| | | | |