

ASS. REC. BY:

REF:

CS/CTI18021619/Dtd3n2

Special Instruction:

Surveyor

Meimien

From (Person):

Ong chin krat

ASSIGNMENT (Office)

of CTI

Date/Time: 30/11/18 @ 8.58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 890L

Insured:

XD 9350P

at Workshop in/s

Chenni Motor

Tel:

6542 5119

of

10 AMK Ind. Park 2A #03-19

Policy No:

DMCVSN1407121804

Claim No:

SNM18D05527C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/11/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9.2am 30/11/18

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SHC 890L - NS/INCL 8003773 / K11bn2

JUA: 20/2/18

XD 3350P-

REF:

ASSIGNMENT

03 July 2021

From:

Date:

Veh No:

SHC 890L

Yr Regn:

July 2013

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Mercedes Benz E220

C.C. 2143

at Workshop m/s

Colour:

White

A/C:

Insured / Std / NI / NA

of

Sp. Reading

870496

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

65192431502802

Policy No.

C/No:

WDD2120022A758330

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / ☒ R/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F:

205/60R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

S

mm

R/Bal.

S

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

S

mm

L/Bal.

S

mm

Est. Repairs:

106 days

Res.: Yes or No

D.O.A.

23/11/2018

D.O.I.

30/11/2018

Lum Sum:

800 %

3 Val.: Yes or No

Survey held at

Chunni AMC

CA / REV / REP. / 24 HRS

Des. of Damages: ☒ Front

Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Taping XD 3350?

17/12/18 finished 1/5 15000/- in 8 days of run
(led 11089.5h, 42%)

RECEIVED 10 DEC 2018

Date/Time, File Pass to?



Prel. Report

1) Mr. Taping



Final Report

Date/Time, File Return to?

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

2)

Add Fee:



Site Insp (\$

) \$ + RS. \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

) TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

15000/-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2018		30 Nov 2018 08:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KAY LIM CONSTRUCTION & TRADING PTE LTD, Co. Reg. No.: 198900654E		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHC890L	Date of Loss:	23/11/2018 00:00 - :59 [63 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05527C02	Policy/Cover Note No.:	DMCVSN1407121804 (Comprehensive) Coverage: 10/03/2018 - 09/03/2019
Vehicle Reg. No. (Insured):	XD3350P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/12/2018]		
Driver/Custodian (Insured):	TAY LIM THIAM (55 / Male), NRIC: S2619000B		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD018152303 / ComfortDelGro Engineering Pte Ltd - Loyal
 ENTRY DATE & TIME: 24/11/2018 12:10
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2018 12:10
Date Of Accident	23/11/2018 20:30
Exact Location Of Accident	SENGKANG EAST RD TWDS JLN KAYU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC890L
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E220

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	YIP HEE FET
NRIC No	S1813274E
Date Of Birth	03/10/1967
Occupation	OUTDOOR
Date Of Driving Pass	28/08/2000
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91112183

Fax Number

Contact Number

Email Address

YIPHEEFET23@GMAIL.COM

Address BLK 175 BOON LAY DRIVE #11-344
Postcode 640175
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: -
GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED / Type Of Accident: 3P REVERSE

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD3350P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver TAY KIM THIAM
NRIC/Passport Number
Contact Number 90280707
Address
Postcode
Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage NO VISIBLE DAMAGE

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 24.11.2018

24/11/18
Jackson Hong
CSO
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/11/2018 at about 2030 hrs, I vehicle A was stationary at Seng Kang East road traffic junction. Vehicle B roll backward and hit vehicle A front portion. No one was injured at that times.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

To Survey by 1 LKK)

DATE : 26.11.2018

TEL : 6542 5119

FAX : 6542 6039

China Tawping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt Dented			\$ 1,890.50 ✓
	Bumper Reinforcement, Frt #2 dntd			\$ 1,458.00 ✓✓
	Bumper Bracket, Frt/LH/RH NH	\$	95.00	\$ 190.00 X
	Bumper Absorber, Frt/LH/RH NH	\$	295.00	\$ 590.00 X
	Bumper Frame, Frt/Centre 2 damaged			\$ 639.00 ✓✓
	Bumper Frame, Frt/LH/RH SVL	\$	75.00	\$ 150.00 X
	Bumper Sponge, Frt/Centre broken			\$ 558.00 ✓✓
	Bumper Inner Clip, Frt HLC			\$ 22.00 ✓
	Head Lamp Assy (LH/RH) mounting broken	\$	2,380.00	\$ 4,760.00 ✓✓
	Head Lamp Bracket (LH/RH) NH	\$	300.00	\$ 600.00 X
	Radiator Top Panel, Frt broken			\$ 330.50 ✓✓
	Radiator Grille broken			\$ 1,620.00 ✓
	Radiator Grille Adjuster Bracket broken			\$ 685.70 ✓
	Bonnet Assy broken			\$ 2,850.60 —
	Bonnet Mercedes Star Logo HLC			\$ 112.00 —
	Bonnet Lock Brace Panel broken			\$ 64.80 —
	Bonnet Air Inlet Grille CRASHED			\$ 269.25 ✓
	Radiator Assy broken			\$ 1,950.00 ✓✓
	Radiator Fan Blower Assy NH			\$ 1,750.00 X
	Radiator Shroud CRASHED			\$ 1,550.00 ✓✓
	Radiator Air Baffle, Top broken			\$ 80.00 ✓X
	Radiator Air Baffle, Lower broken			\$ 125.90 ✓X
	Radiator Dowel Pin broken			\$ 12.00 ✓X
	Radiator Mounting Lower NH			\$ 8.00 X
	Radiator Mounting Top NH			\$ 12.00 X
	Aircon Condenser broken			\$ 1,780.00 ✓✓
	Turbos Charger Air Cooler broken			\$ 1,540.00 ✓✓
	P/Steering Cooling Pipe broken			\$ 556.80 ✓✓
	SUB TOTAL			\$ 26,155.05
	LESS 10%			\$ 2,615.51
	DISCOUNTED TOTAL			\$ 23,539.55
	Labour Charge			
	Panel Beating			\$ 1,000.00 600/-
	Spray Painting Charge			\$ 600.00 400/-
	Wiring Charge			\$ 50.00 30/-
	Towing Charges			\$ 150.00 HH
	Tuff Kote			\$ 50.00 20/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Re-set and Diagnosis			\$ 550.00 HH
	TOTAL LABOUR			\$ 2,550.00
	ESTIMATE TOTAL			\$ 26,089.55

LKK Auto Consultants hence notify
the Repairer of the following:

- * To resurvey before after spray painting
- * To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- * No illegal modification(s) allowed.

Acknowledged by Repairer:
Signature: _____
Date: _____

22637-15
20373.43

1130.00
21563.43
L/S 15 000/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021619/DTD3N2

Date: 21/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1407121804	
Claimant Vehicle No :	SHC890L	Insured Vehicle No :	XD3350P	
Date of Loss:	23/11/2018	Nature of Claim:	TP	Claim No: SNM18D05527C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC890L	Engine No:	65192431502802
Make & Model:	MERCEDES-BENZ E220, 2.1 D CDI BlueEFFICIENCY (A)	Chassis No:	WDD2120022A758330
Reg. Date:	25/07/2013 (Man. Year: 2013)	Odometer:	870496 km
Colour:	White		
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	23,539.54	20,373.43	3,166.11	13.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,130.00	1,420.00	55.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,089.54	21,503.43	4,586.11	17.58
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	26,089.54	15,000.00	11,089.54	42.51
+ GST 7.00/7.00% (S\$)	1,826.27	1,050.00	776.27	42.51
Nett Amount (S\$)	27,915.81	16,050.00	11,865.81	42.51

INSPECTION

Date of Assignment: 30/11/2018

Date Inspected: 30/11/2018 Inspected At:

Chunni Motor Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2018)
Parts:	143	MERCEDES-BENZ E220 2.1 D CDI BlueEFFICIENCY (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC890L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER ASSY,FRT	Dented	1,890.50 FL	*1,890.50 FL
2	1		*BUMPER REINFORCEMENT,FRT	Dented	1,458.00 FL	*1,458.00 FL
3	2		*BUMPER BRACKET,FRT/LH/RH	Not Necessary	190.00 FL	*- FL
4	2		*BUMPER ABSORBER,FRT/LH/RH	Not Necessary	590.00 FL	*- FL
5	1		*BUMPER FRAME,FRT/CENTRE	Deformed	639.00 FL	*639.00 FL
6	2		*BUMPER FRAME,FRT/LH/RH	Serviceable	150.00 FL	*- FL
7	1		*BUMPER SPONGE,FRT/CENTRE	Broken	558.00 FL	*558.00 FL
8	10		*BUMPER INNER CLIP,FRT	Necessary	22.00 FL	*22.00 FL
9	2		*HEAD LAMP ASSY (LH/RH)	Mounting Broken	4,760.00 FL	*4,760.00 FL
10	2		*HEAD LAMP BRACKET (LH/RH)	Not Necessary	600.00 FL	*- FL
11	1		*RADIATOR TOP PANEL,FRT	Bent	330.50 FL	*330.50 FL
12	1		*RADIATOR GRILLE	Broken	1,620.00 FL	*1,620.00 FL
13	1		*RADIATOR GRILLE ADJUSTER BRACKET	Bent	685.70 FL	*685.70 FL
14	1		*BONNET ASSY	Bent	2,850.60 FL	*2,850.60 FL
15	1		*BONNET MERCEDES STAR LOGO	Necessary	112.00 FL	*112.00 FL
16	1		*BONNET LOCK BRACE PANEL	Bent	64.80 FL	*64.80 FL
17	1		*BONNET AIR INLET GRILLE	Cracked	269.25 FL	*269.25 FL
18	1		*RADIATOR ASSY	Bent	1,950.00 FL	*1,950.00 FL
19	1		*RADIATOR FAN BLOWER ASSY	Not Necessary	1,750.00 FL	*- FL
20	1		*RADIATOR SHROUD	Cracked	1,550.00 FL	*1,550.00 FL
21	1		*RADIATOR AIR BAFFLE, TOP	Not Necessary	80.00 FL	*- FL
22	1		*RADIATOR AIR BAFFLE, LOWER	Not Necessary	125.90 FL	*- FL
23	1		*RADIATOR DOWEL PIN	Not Necessary	12.00 FL	*- FL
24	1		*RADIATOR MOUNTING LOWER	Not Necessary	8.00 FL	*- FL
25	1		*RADIATOR MOUNTING TOP	Not Necessary	12.00 FL	*- FL
26	1		*AIRCON CONDENSER	Bent	1,780.00 FL	*1,780.00 FL
27	1		*TURBOR CHARGER AIR COOLER	Punctured	1,540.00 FL	*1,540.00 FL
28	1		*P/STEERING COOLING PIPE	Bent	556.80 FL	*556.80 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	26,155.05	22,637.15
- List Item Discount on L Items 10.00/10.00% (S\$)	2,615.51	2,263.72
Total Parts (S\$)	23,539.54	20,373.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING CHARGE	New	600.00	400.00
3	WIRING CHARGE	New	50.00	30.00
4	TOWING CHARGES	New	150.00	-
5	TUFF KOTE	New	50.00	20.00
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	RE-SET AND DIAGNOSIS	New	550.00	-
Gross Labour Cost (S\$)			2,550.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >