

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 07 Dec 2018

Preliminary Advice

Insured Vehicle No	: SMD6259G	Accident Date	: 23/11/2018
TP Vehicle No	: SGL7998D	Assignment Date	: 29/11/2018
Make	: BMW 535I GT	Est. Duration of Repair	: 3.00
Date of Inspection	: 06/12/2018		
Inspection At	: KUM CHEW MOTOR WORKSHOP (160 SIN MING) (HQ) 160 SIN MING DRIVE, #05-08 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,252.75
Revised Amount	:S\$	3,671.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,671.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.