

ASS. REC. BY:

REF: CS/CT118021624/Rlvds | n2
Special Instruction:

Surveyor:

Rasul
ASSIGNMENT (Office)

From (Person):

Ong chin kiat of CTI Date/Time: 29/11/18 @ 4:49pm.

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 3338G

Insured:

GY 4730K

at Workshop m/s

Yew Tee Automobile

Tel:

6256 2081 / 6765 3373

of

39 woodlands close #01-12

Policy No:

DMCVSN3031361802

Claim No:

SNM1805449C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/11/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:31am @ 30/11/18

Person Contacted:

Vinnie

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLK 3338G-X

GY 4730K-CS/MSG 17021065/K/bn2

D.O.A: 2/11/17

13/12/18

LS \$6450 confirmed by email (Red 4234.60, 409)

NAME *P. Rame*

REF: CT1

5059C

ASSIGNMENT

From: Date: 30/11/18

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 3338G
at Workshop m/s Yew Tee Automobile
of 39 Woodlands close # 01-12

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: After 3pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 3338G Yr Regn: 2017 / JAN

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ C200 C.C. 1991

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 79265 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2050422R 210052

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ FIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/11/18 D.O.I. 30/11/18

Survey held at Yew Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

u/s FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 14 DEC 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) 14/12 - typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS, SI

) Photos:

) Others:

TOTAL

Report Format : merimen

Lump Sum / I.B.I. (\$) 6450/-

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Created	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2018		29 Nov 2018 16:49 Assign				New Assignment Cancel Case

Reference	Claim Details	Documents	Show All						
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SIN SOON HING POULTRY, Co. Reg. No.: 53040422B								
Main Claimant:	KOH KENG HUAT, ID: S2595059C								
Vehicle Reg. No.:	SLK3338G	Date of Loss:	19/11/2018 16:00 - :59 [10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM1805449C02	Policy/Cover Note No.:	DMCVSN3031361802 (Comprehensive) Coverage: 20/04/2018 - 19/04/2019						
Vehicle Reg. No. (Insured):	GY4730K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands, 737856 Woodlands - Tel: 62562533								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/12/2018]								
Driver/Custodian (Insured):	NG PENG HONG (65 / Male), NRIC: S0179833B								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Ong Chin Kiat

From: YT(MG) <info@yewteegroup.com>
Sent: Thursday, 29 November, 2018 10:02 AM
To: Claims Dept of CTI
Cc: YEW TEE GROUP
Subject: Accident involving SLK3338G (NTUC) claiming against GY4730K (China Taiping) on 19.11.2018
Attachments: SLK3338G_19112018.pdf; SLK3338G Estimate.pdf

Hi Motor Claim,

Attached report and estimate.

Kindly arrange PRI at **39 Woodlands Close, #01-12 Mega @ Woodlands S(737856).**

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You 😊

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 13 December 2018 2:51 PM
To: 'info@yewteegroup.com'; SUR
Subject: SLK 3338G-DOA: 19/11/2018

Dear Vinnie,

WITHOUT PREJUDICE

We refer to the above mentioned.

Confirmed Lump Sum \$6450/- @ 5 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1811/011
Policy No:	5087300575-01	Date of Loss:	19/11/2018
Vehicle Reg. No.:	SLK3338G	Driveable?	no
Driver Age:	05/02/1965	Third Party Vehicle No.:	GY4730K
Any Injuries?	no	Contact No:	90279669
Insured/Claimant:	KOH KENG HUAT	Driver:	KOH KENG HUAT

Make/Model:	Mercedes-Benz, C200 Avant	Vehicle Reg. Date:	05/01/2017
	- WDD204		
Vehicle Colour:	BLACK	Engine Number:	27492030731997
Chassis No:	WDD2050422R210052	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION WHILST PARKED
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	8,199.60
Miscellaneous Items	45.00
Labour	1,540.00
Paintwork Labour	900.00
Towing	0.00
Gross Total(\$\$):	10,684.60
GST 7.00%(\$\$):	747.92
Nett Amount(\$\$):	11,432.52

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP RH / SCR 3150	2,625.00	2,625.00	-10.00	2,362.50
2	1	BONNET / DD	2,201.00	2,201.00	-20.00	1,760.80
3	1	BONNET HINGES LH X } su	200.00	200.00	-10.00	180.00
4	1	BONNET HINGES RH X }	200.00	200.00	-10.00	180.00
5	1	BONNET ACTUATOR LH A / Activated	370.00	370.00	-10.00	333.00
6	1	BONNET ACTUATOR RH A / Activated	370.00	370.00	-10.00	333.00
7	1	BONNET LOGO / NEL	86.00	86.00	-10.00	77.40
8	1	FRONT FENDER RH / DD	1,940.00	1,940.00	-20.00	1,552.00
9	1	FRONT BUMPER X Rep-V	1,658.00	1,658.00	-20.00	1,326.40
10	1	FRONT BUMPER SIDE RETAINER RH X NN	105.00	105.00	-10.00	94.50

Total Parts (\$\$) 8,199.60

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS X NN	45.00	45.00	0.00	45.00

Sub Total (\$\$) 45.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Refit Front Bumper Sensor. X M	80.00	80.00	0.00	80.00
3	1	To Computer Reset and Re-program all fault code.	450.00 200	450.00	0.00	450.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	980.00 600	980.00	0.00	980.00

Gross Labour Cost (\$\$) 1,540.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00 40	60.00	0.00	60.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00 750	800.00	0.00	800.00

Gross Labour Cost (\$\$) 900.00

< END OF ESTIMATES >

4/8 PTP 5 days

Resin 64 paint

Rasul
Hp 90010068

4/12/18

30/11/18 @ 1550 hr

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1811/011
Policy No:	5087300575-01	Date of Loss:	19/11/2018
Vehicle Reg. No.:	SLK3338G	Driveable?	no
Driver Age:	05/02/1965	Third Party Vehicle No.:	GY4730K
Any Injuries?	no	Contact No:	90279669
Insured/Claimant:	KOH KENG HUAT	Driver:	KOH KENG HUAT

Make/Model:	Mercedes-Benz, C200 Avant - WDD204	Vehicle Reg. Date:	05/01/2017
Vehicle Colour:	BLACK	Engine Number:	27492030731997
Chassis No:	WDD2050422R210052	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION WHILST PARKED
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	6418.70 8,199.60
Miscellaneous Items	0.00 45.00
Labour	830.00 1,540.00
Paintwork Labour	860.00 900.00
Towing	0.00
Gross Total(S\$):	8108.70 10,684.60
GST 7.00%(S\$):	747.92
Nett Amount(S\$):	11,432.52

This claim is handled by: Sky Toh T C

8108.70
 -20% # 1621.74
 # 6486.96

LIS \$ 6,450.00

(PLS CONFIRM)

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP RH / SCR	2,625.00	2,625.00	-10.00	2,362.50
2	1	BONNET / DD	2,201.00	2,201.00	-20.00	1,760.80
3	1	BONNET HINGES LH X	200.00	200.00	-10.00	180.00
4	1	BONNET HINGES RH X	200.00	200.00	-10.00	180.00
5	1	BONNET ACTUATOR LH A / Activated	370.00	370.00	-10.00	333.00
6	1	BONNET ACTUATOR RH A / Activated	370.00	370.00	-10.00	333.00
7	1	BONNET LOGO / NEC	86.00	86.00	-10.00	77.40
8	1	FRONT FENDER RH / DD	1,940.00	1,940.00	-20.00	1,552.00
9	1	FRONT BUMPER X Repair	1,658.00	1,658.00	-20.00	1,326.40
10	1	FRONT BUMPER SIDE RETAINER RH X NN	105.00	105.00	-10.00	94.50
Total Parts (\$\$)				6418.70		8,199.60

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER CLIPS X NN	45.00	45.00	0.00	45.00
Sub Total (\$\$)				0.00		45.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Refit Front Bumper Sensor. X	80.00	80.00	0.00	80.00
3	1	To Computer Reset and Re-program all fault code.	450.00	200 450.00	0.00	450.00
4	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	980.00	600 980.00	0.00	980.00
Gross Labour Cost (\$\$)				830.00		1,540.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	40 60.00	0.00	60.00
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	750 800.00	0.00	800.00

Gross Labour Cost (\$\$) 860.00 900.00

< END OF ESTIMATES >

Rasul
Hp 90010068
30/11/18 @ 1550 hr
P/P 5 days

Rasul b4 paint

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18021624/R1VD3N2

Date: 17/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3031361802
Claimant Vehicle No :	SLK3338G	Insured Vehicle No :	GY4730K
Date of Loss:	19/11/2018	Nature of Claim:	TP
		Claim No:	SNM1805449C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK3338G	Engine No:	27492030731997
Make & Model:	MERCEDES-BENZ C200, 2.0 (A)	Chassis No:	WDD2050422R210052
Reg. Date:	05/01/2017 (Man. Year: 2016)	Odometer:	79265 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,244.60	6,418.70	1,825.90	22.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,690.00	750.00	30.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,684.60	8,108.70	2,575.90	24.11
Approved Total (Overridden) (\$\$)		6,450.00		
(\$\$)	10,684.60	6,450.00	4,234.60	39.63
+ GST 7.00/7.00% (\$\$)	747.92	451.50	296.42	39.63
Nett Amount (\$\$)	11,432.52	6,901.50	4,531.02	39.63

INSPECTION

Date of Assignment:	29/11/2018	
Date Inspected:	30/11/2018	Inspected At:
		Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2018)
Parts: 143	MERCEDES-BENZ C200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLK3338G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	2,201.00 FL	*2,201.00 FL
2	1		*FRONT FENDER RH	Dented	1,940.00 FL	*1,940.00 FL
3	1		*FRONT BUMPER	Repair	1,658.00 FL	*- FL
4	1		*FRONT HEADLAMP RH	Scratched	2,625.00 FN	*2,625.00 FN
5	1		*BONNET HINGES LH	Serviceable	200.00 FN	*- FN
6	1		*BONNET HINGES RH	Serviceable	200.00 FN	*- FN
7	1		*BONNET ACTUATOR LH	Activated	370.00 FN	*370.00 FN
8	1		*BONNET ACTUATOR RH	Activated	370.00 FN	*370.00 FN
9	1		*BONNET LOGO	Necessary	86.00 FN	*86.00 FN
10	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	105.00 FN	*- FN
11	1		*FRONT BUMPER CLIPS	Not Necessary	45.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (\$\$)	9,800.00	7,592.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,159.80	828.20
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	395.60	345.10
Total Parts (\$\$)	8,244.60	6,418.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	30.00	30.00
2	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	80.00	-
3	TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE	New	450.00	200.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	980.00	600.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	60.00	40.00
6	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	40.00	40.00
7	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	800.00	780.00
Gross Labour Cost (S\$)			2,440.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >