

VANTAGE AUTOMOTIVE LIMITED

(A Sime Darby Motors Company)

Co. Regs. No. 192600045M GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7368
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



SERVICE TAX INVOICE

RE-PRINT

REPAIR ORDER NO. B9 45275	Date IN 05/12/2018 Payment Term 30 Days From Invoice Customer Service Advisor Tan Xunhong Nixon	Invoice Number Invoice Date ?? Invoice By Katherine Chong Fui Poh	Page No. 2 of 2
-------------------------------------	---	---	------------------------

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	4,800.60
Labour Charges	3,210.00	Less Insurance Excess	S\$	500.00
Parts Charges	1,590.60	GST @ 7%	S\$	301.04
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	4,601.64
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	4,601.64

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



Vantage Automotive Limited
305 Alexandra Road S'pore 159942

Date : 29.11.2018

RE: VEHICLE REPAIR QUOTATION

Insurance Company : MSIG Insurance (Singapore) Pte. Ltd.
Vehicle Reg No : SBN10Z
Name of Insured : CHUA HUA ENG DANIEL
Policy Number : A 29090260 QMY
Date of Accident : 26.11.2018
Tyre of Claim : OD CLAIM
Model : MERCEDES-BENZ B200
Chassis No : WDD2462432J177881

6741 2916
C DEN 107
sur @ LKK.00
LKK Auto. com

We are please to submit our estimate of repairs to the above mention vehicle.

1	SUNDRIES	\$ 150.00	20. ✓
2	LABOUR TO REMOVE, RE-ALIGN AND REPLACE FRONT RIGHT DOOR, DOOR HINGE, DOOR HANDLE, FRONT RIGHT FENDER AND ALL AFFECTED AREA	\$ 1,800.00	1200 ✓
3	TO PUTTY AND SPRAY FRONT RIGHT DOOR, FRONT RIGHT FENDER AND ALL AFFECTED AREA	\$ 1,800.00	800 ✓
4	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING	\$ 150.00	70. ✓
5	TRANSFER AND REFIX FRONT RIGHT DOOR FITTING, GLASS AND ALL USABLE MECHANICAL COMPONENT	\$ 300.00	200. ✓
6	TUFF KOTE, ANTI RUST PRESERVATIONS, BODY CAVITY PRESERVATIONS.	\$ 120.00	✓
7	SEALANT FOR BODY PANELS.	\$ 120.00	90. ✓
8	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES	\$ 300.00	✓
9	TO REPLACE FRONT RIGHT DOOR POWER WINDOW MECHANISM AND REGULATOR	\$ 250.00	?

Total (Labour)

\$ 4,990.00

Parts	Qty.	
1 FRONT RIGHT DOOR	1	\$1,424.50 166 ✓
2 Front RH Fender	1	\$ 650.00 Rx ✓
3 Front RH Door Handle	1	\$ 1,300.00 dis ✓
4 Frt RH Door Hinge	2	\$ 216.00 ✓
5 Frt RH Door Window Moulding (cl	1	\$ 176.00 ✓
6 Frt RH Door Window Regulator	1	\$ 510.00 ?
7 Frt RH Window Motor	1	\$ 435.00 ?
8 Frt RH Door Weatherstrip	1	\$ 278.00 ✓
9 Frt RH Door Window Panel	1	\$ 1,030.00 Rx ✓
10 Frt RH Window Glass	1	\$ 195.00 ?

Total (Parts)

\$6,214.50

Sub Total :

\$11,204.50

GST 7%

\$ 784.32

Grand Total :

\$11,988.82

Tanjin 97495749
Ex \$500

Not Authorised Repair

Paint by paint

Resurvey before paint

* For Supplementary, need to take approval
sure (LKK auto. com)
6 days



GOLDENLINK AUTO PTE LTD

TAX INVOICE



Invoice To

VANTAGE AUTOMOTIVE LIMITED W1051
MAIN OFFICE
305 ALEXANDRA ROAD
SINGAPORE 159942
LEVEL 3 PARTS DEPT
TEL: 6477 7363 (ATTN: MR. TEO KIAT TNG)

INVOICE NO: WL443355

DATE: 07-12-2018 11:18

PAGE: 1 / 1

SALESMAN: CHEE WEN SHENG

TERMS: 30 DAYS

PO REF :

SNO	ITEMCODE	DESCRIPTION	QUANTITY	UNITPRICE	AMOUNT
	Remark :	SBN10Z TEO		(SGD)	(SGD)
1	204 760 0270 9999	OUTER HANDLE FRT/RR RH ✓	1	70.00	70.00
2	204 727 1187	DOOR RUBBER FRT/RR LH/RH ✓	1	150.00	150.00
3	246 720 0205	DOOR FRT RH ✓	1	770.00	770.00

PO 2 670828

RO 2 B9 45275

V/N 2 SBN10Z

V/M: MERCEDES BENZ

VANTAGE AUTOMOTIVE LIMITED	
Cost Centre	pg
Verified by	
Approved by	

Products received and checked to be in good condition

Customer's Signature / Company Stamp

This is a computer-generated Invoice. No signature required.

Products purchased are to be installed in accordance to manufacturer's standards and procedures.

SUB-TOTAL 990.00
ADD G.S.T 7% 69.30
TOTAL (SGD) 1,059.30

Cheques to be made payable to GOLDENLINK AUTO PTE LTD.

Any overdue account shall be chargeable with interest at the prevailing prime rate from time to time of DBS Bank Limited. Request for the return of any unused product (in original and good condition) may be considered on a case by case basis and subject to applicable terms and conditions. Such request must be accompanied by the original invoice and lodged within 14 days of delivery of your order.

Goldenlink Auto Pte Ltd

Head Office 8 Changi South Lane #02-01 Singapore 486113

Tel: 6336 4903 (Accounts) 6336 2380 (Supply Chain) Fax: 6339 5618 Co. Reg. No. 199606343K GST Reg. No. 19-9605343-K



bizSAFE₃

www.goldenlink.com.sg



GOLDENLINK AUTO PTE LTD

TAX INVOICE



* I V B P 0 0 1 6 1 2 *

Invoice To

VANTAGE AUTOMOTIVE LIMITED W1051
MAIN OFFICE
305 ALEXANDRA ROAD
SINGAPORE 159942
LEVEL 3 PARTS DEPT
TEL: 6477 7363 (ATTN: MR. TEO KIAT TNG)

INVOICE NO: BP001612

DATE: 11-12-2018 17:23

PAGE: 1 / 1

SALESMAN: CHEE WEN SHENG

TERMS: 30 DAYS

PO REF :

SNO	ITEMCODE	DESCRIPTION	QUANTITY	UNITPRICE	AMOUNT
	Remark :	SBN10Z TEO		(SGD)	(SGD)
1	246 720 1237	TOP HINGE FRT RH ✓	1	58.00	58.00
2	246 720 0437	BTM HINGE FRT RH ✓	1	58.00	58.00
3	246 725 0282	TRIM STRIP FRT RH ✓	1	95.00	95.00
4	246 722 0200 28	TRIM FRT RH. ✓	1	65.00	65.00

PO: 2670915
RO: 89 45275
VIN: SBN10Z
VIN: Mercedes Benz.

VANTAGE AUTOMOTIVE LIMITED	
Cost Centre	P9
Verified by	✓
Approved by	

Product received and checked to be in good condition

Customer's Signature / Company Stamp

This is a computer-generated invoice. No signature required.

Products purchased are to be installed in accordance to manufacturer's standards and procedures.

SUB-TOTAL 276.00

ADD G.S.T 7% 19.32

TOTAL (SGD) 295.32

Cheques to be made payable to GOLDENLINK AUTO PTE LTD.

Any overdue account shall be chargeable with interest at the prevailing prime rate from time to time of DBS Bank Limited. Request for the return of any unused product (in original and good condition) may be considered on a case by case basis and subject to applicable terms and conditions. Such request must be accompanied by the original invoice and lodged within 14 days of delivery of your order.



bizSAFE₃

Goldenlink Auto Pte Ltd

Head Office 8 Changi South Lane #02-01 Singapore 486113

Tel: 6336 4903 (Accounts) 6336 2380 (Supply Chain) Fax: 6339 5618 Co. Reg. No. 199606343K GST Reg. No. 19-9606343-K

www.goldenlink.com.sg



GOLDENLINK AUTO PTE LTD

TAX INVOICE



Invoice To

VANTAGE AUTOMOTIVE LIMITED W1051
MAIN OFFICE
305 ALEXANDRA ROAD
SINGAPORE 159942
LEVEL 3 PARTS DEPT
TEL: 6477 7363 (ATTN: MR. TEO KIAT TNG)

INVOICE NO: WL443491

DATE: 11-12-2018 12:43

PAGE: 1 / 1

SALESMAN: CHEE WEN SHENG

TERMS: 30 DAYS

PO REF :

SNO	ITEMCODE	DESCRIPTION	QUANTITY	UNITPRICE	AMOUNT
	Remark :	SBN10Z TEO		(SGD)	(SGD)
1	166 720 0235	DOOR LOCK FRT RH <i>bt</i>	1	145.00	145.00

PO2670830
RO1B945275
VN2 SBN10Z
VM2 MERCEDES BENZ

VANTAGE AUTOMOTIVE LIMITED	
Cost Centre	<i>p9</i>
Verified by	<i>JS</i>
Approved by	

Products received and checked to be in good condition

Customer's Signature / Company Stamp

This is a computer-generated Invoice. No signature required.

Products purchased are to be installed in accordance to manufacturer's standards and procedures.

SUB-TOTAL 145.00
ADD G.S.T 7% 10.15
TOTAL (SGD) 155.15

Cheques to be made payable to GOLDENLINK AUTO PTE LTD.

Any overdue account shall be chargeable with interest at the prevailing prime rate from time to time of DBS Bank Limited. Request for the return of any unused product (in original and good condition) may be considered on a case by case basis and subject to applicable terms and conditions. Such request must be accompanied by the original invoice and lodged within 14 days of delivery of your order.

Goldenlink Auto Pte Ltd

Head Office 8 Changi South Lane #02-01 Singapore 486113

Tel: 6336 4903 (Accounts) 6336 2380 (Supply Chain) Fax: 6339 5618 Co. Reg. No. 199606343K GST Reg. No. 19-9606343-K



bizSAFE₃

www.goldenlink.com.sg



GOLDENLINK AUTO PTE LTD

TAX INVOICE



Invoice To

VANTAGE AUTOMOTIVE LIMITED W1051
MAIN OFFICE
305 ALEXANDRA ROAD
SINGAPORE 159942
LEVEL 3 PARTS DEPT
TEL: 6477 7363 (ATTN: MR. TEO KIAT TNG)

INVOICE NO: BP001623

DATE: 14-12-2018 17:57

PAGE: 1 / 1

SALESMAN: CHEE WEN SHENG

TERMS: 30 DAYS

PO REF :

SNO	ITEMCODE	DESCRIPTION	QUANTITY	UNITPRICE	AMOUNT
	Remark :	SBN10Z TEO		(SGD)	(SGD)
1	204 766 1425 9761	TRIM RING ,RHF DOOR <i>new</i>	1	35.00	35.00

PDZ 671142

RO: W9 45275

VN = SBN10Z

V/M - Mercedes Benz

VANTAGE AUTOMOTIVE LIMITED	
Cost Centre	PM
Verified by	<i>[Signature]</i>
Approved by	

Products received and checked to be in good condition

Customer's Signature / Company Stamp

This is a computer-generated Invoice. No signature required.

Products purchased are to be installed in accordance to manufacturer's standards and procedures.

SUB-TOTAL 35.00
ADD G.S.T 7% 2.45
TOTAL (SGD) 37.45

Cheques to be made payable to GOLDENLINK AUTO PTE LTD.

Any overdue account shall be chargeable with interest at the prevailing prime rate from time to time of DBS Bank Limited. Request for the return of any unused product (in original and good condition) may be considered on a case by case basis and subject to applicable terms and conditions. Such request must be accompanied by the original invoice and lodged within 14 days of delivery of your order.

Goldenlink Auto Pte Ltd

Head Office 8 Changi South Lane #02-01 Singapore 486113

Tel: 6336 4903 (Accounts) 6336 2380 (Supply Chain) Fax: 6339 5618 Co. Reg. No. 199606343K GST Reg. No. 19-9606343-K



bizSAFE₃

www.goldenlink.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Nov 2018		30 Nov 2018 17:07 Edit Adj Rpt	S\$4,400.60 Edit Estimates	S\$4,400.60 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHUA HUA ENG DANIEL, ID: S0336993E, Tel: +6590278269		
Vehicle Reg. No.:	SBN10Z	Date of Loss:	26/11/2018 16:00 - :59 [63 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 577383	Policy/Cover Note No.:	A29090260QMY (Comprehensive) Coverage: 01/08/2018 - 31/07/2019
		Excess:	S\$500.00
Repairer:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre, 159942 Alexandra - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 30/12/2018]		
Driver/Custodian:	CHUA ZI EN RUTH (33 / Female), NRIC: S8510576J, Tel: +6597561978 Email: RUTHZIENCHUA@GMAIL.COM		
Adj Asg. Remarks:	Car in, Survey & revert. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (09/04/2019): Alert - Adj Mandate Approved (S\$4400.60) - SBN10Z - Claim Handler: Clara Milah Y...
- MSIG_SG (05/12/2018): Alert - Adj Mandate Approved (S\$5046.60) - SBN10Z - Claim Handler: Clara Milah Y...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBN10Z (577383)
OD
Nov 26 2018 4:00PM
[CHUA HUA ENG DANIEL]
Vantage Automotive Limited

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Vantage Automotive Limited (Ubi)		Thumbnail	Print
1	27/11/18 10:21	Accident Statement	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/18 13:52	Adjuster Immediate Advice	1	Load HTM	
2	04/12/18 17:28	Adjuster Immediate Advice	1	Load HTM	
3	05/12/18 12:02	Adjuster Immediate Advice	1	Load HTM	
4	02/04/19 17:28	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/12/18 13:43	General View	1	Load JPG	☒
2	04/12/18 13:43	General View	1	Load JPG	☒
3	04/12/18 13:43	General View	1	Load JPG	☒
4	04/12/18 13:43	General View	1	Load JPG	☒
5	04/12/18 13:43	General View	1	Load JPG	☒
6	04/12/18 13:43	General View	1	Load JPG	☒
7	04/12/18 13:43	General View	1	Load JPG	☒
8	04/12/18 13:43	General View	1	Load JPG	☒
9	04/12/18 13:43	General View	1	Load JPG	☒
10	04/12/18 13:43	General View	1	Load JPG	☒
11	04/12/18 13:43	General View	1	Load JPG	☒
12	04/12/18 13:43	General View	1	Load JPG	☒
13	04/12/18 13:43	General View	1	Load JPG	☒
14	04/12/18 13:43	General View	1	Load JPG	☒
15	04/12/18 13:43	General View	1	Load JPG	☒
16	04/12/18 13:43	General View	1	Load JPG	☒
17	04/12/18 13:43	General View	1	Load JPG	☒
18	04/12/18 13:43	General View	1	Load JPG	☒
19	04/12/18 13:43	General View	1	Load JPG	☒
20	04/12/18 13:43	General View	1	Load JPG	☒
21	04/12/18 13:43	General View	1	Load JPG	☒
22	04/12/18 13:43	General View	1	Load JPG	☒
23	04/12/18 13:43	General View	1	Load JPG	☒
24	04/12/18 13:43	General View	1	Load JPG	☒
25	04/12/18 13:43	General View	1	Load JPG	☒
26	04/12/18 13:43	General View	1	Load JPG	☒
27	04/12/18 13:43	General View	1	Load JPG	☒
28	04/12/18 13:43	General View	1	Load JPG	☒
29	04/12/18 13:43	General View	1	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
30	04/12/18 13:43	General View	 Load JPG	☒
31	04/12/18 13:43	General View	 Load JPG	☒
32	04/12/18 13:43	General View	 Load JPG	☒
33	04/12/18 13:43	General View	 Load JPG	☒
34	04/12/18 13:43	General View	 Load JPG	☒
35	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
36	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
37	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
38	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
39	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
40	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
41	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
42	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
43	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
44	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
45	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
46	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
47	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
48	02/04/19 14:18	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/11/18 13:23	Email from w/shop to request survey	 Load PDF	
2	30/11/18 13:23	Repair Estimate	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 13:41	estimate	 Load PDF	
2	04/12/18 17:30	ESTIMATE AFTER PARTS 25%	 Load PDF	
3	05/12/18 12:04	cost plus estimate	 Load PDF	
4	02/04/19 14:16	supplementary	 Load PDF	
5	02/04/19 17:30	ESTIMATE	 Load PDF	
6	09/04/19 13:54	PARTS INVOICE	 Load PDF	

Linked Accident Report Documents

View View In Browser

Assessment Reports			1 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
1	27/11/18 10:21	Accident Statement	 Load HTM	

Photos/Images

			3 per page	☒
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
1	27/11/18 10:20	MILEAGE	 Load JPG	☒
2	27/11/18 10:20	CHASSIS NUMBER	 Load JPG	☒
3	27/11/18 10:20	FRONT VIEW	 Load JPG	☒
4	27/11/18 10:20	LEFT SIDE VIEW	 Load JPG	☒
5	27/11/18 10:20	REAR VIEW	 Load JPG	☒
6	27/11/18 10:20	RIGHT VIEW	 Load JPG	☒
7	27/11/18 10:20	RH FRT DOOR DAMAGE	 Load JPG	☒
8	27/11/18 10:20	DAMAGE AREA	 Load JPG	☒
9	27/11/18 10:20	DAMAGE DOOR CLOSE	 Load JPG	☒
10	27/11/18 10:20	DAMAGE DOOR CLOSE 1	Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
11	27/11/18 10:20	DOOR HANDLE	 Load JPG	✓
12	27/11/18 10:20	DAMAGE DOOR	 Load JPG	✓
13	27/11/18 10:20	DAMAGE DOOR	 Load JPG	✓
14	27/11/18 10:20	DAMAGE DOOR	 Load JPG	✓
15	27/11/18 10:20	DAMAGE DOOR	 Load JPG	✓
16	27/11/18 10:20	DAMAGE DOOR CLOSED	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Vantage Automotive Limited (Ubi)	Thumbnail	Print
1	27/11/18 10:17	CI NOTE	 Load JPG	✓
2	27/11/18 10:17	DRIVER LICENSE & IC	 Load JPG	✓
3	27/11/18 10:17	OWNER IC	 Load JPG	✓
4	27/11/18 10:18	Sketch Plan	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18021669/T1TBS2
Date: 09/04/2019

REFERENCE

Insured/Claimant:	CHUA HUA ENG DANIEL	Policy No:	A29090260QMY	
Date of Loss:	26/11/2018	Nature of Claim:	OD	Claim No: 577383

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBN10Z	Engine No:	27091030195881
Make & Model:	MERCEDES-BENZ B200, 1.6 ABS (A)	Chassis No:	WDD2462432J177881
Reg. Date:	01/08/2013 (Man. Year: 2013)	Odometer:	73511 km
Colour:	Silver		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,730.60	1,710.60	2,020.00	54.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,720.00	2,690.00	2,030.00	43.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,450.60	4,400.60	4,050.00	47.93
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	7,950.60	3,900.60	4,050.00	50.94
+ GST 7.00/7.00% (S\$)	556.54	273.04	283.50	50.94
Nett Amount (S\$)	8,507.14	4,173.64	4,333.50	50.94

INSPECTION

Date of Assignment:	30/11/2018	
Date Inspected:	03/12/2018 Inspected At:	Vantage Automotive Limited (Alexandra) 305 Alexandra Road #02-01, Vantage Automotive Centre Singapore 159942
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2019)
Parts:	144	MERCEDES-BENZ B200 1.6 ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBN10Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT DOOR (WCP)	Bent	770.00 F	*770.00 F
2	1		*FRONT RH FENDER (WCP)	Repair	350.00 F	*- F
3	1		*FRONT RH DOOR HANDLE (WCP)	Distorted	70.00 F	*70.00 F
4	2		*FRT RH DOOR HINGE (WCP)	Bent	116.00 F	*116.00 F
5	1		*FRT RH DOOR WINDOW MOULDING (WCP)	Deformed	95.00 F	*95.00 F
6	1		*FRT RH DOOR WINDOW REGULATOR (WCP)	Not Necessary	275.00 F	*- F
7	1		*FRT RH WINDOW MOTOR (WCP)	Not Necessary	235.00 F	*- F
8	1		*FRT RH DOOR WEATHERSTRIP (WCP)	Necessary	150.00 F	*150.00 F
9	1		*FRT RH DOOR WINDOW PANEL (WCP)	Repair	555.00 F	*- F
10	1		*FRT RH WINDOW GLASS (WCP)	Not Necessary	105.00 F	*- F
11	1		*SUNDRIES	Necessary	150.00 FS	*30.00 FS
12	1		*SEALANT FOR BODY PANELS	Necessary	120.00 FS	*90.00 FS
13	1		*FRONT RH DOOR CYLINDER LOCK (WCP)	Not Necessary	180.00 F	*- F
14	1		*FRONT RH DOOR LOCK MECHANISM (WCP)	Bent	145.00 F	*145.00 F
15	1		*FRONT DOOR PLASTIC MOULDING (BLACK) (WCP)	Necessary	65.00 F	*65.00 F
16	1		*FRONT RH DOOR LOCK COVER (WCP)	Cut	35.00 F	*35.00 F

F=Franchise part, S=SpcNett.

Sub Total (S\$)	3,416.00	1,566.00
+ Margin on L,N Items 10.00/10.00% (S\$)	314.60	144.60
Total Parts (S\$)	3,730.60	1,710.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE, RE-ALIGN AND REPLACE FRONT RIGHT DOOR, DOOR HINGE, DOOR HANDLE, FRONT RIGHT FENDER AND ALL AFFECTED AREA.	New	1,800.00	1,200.00
2	TO PUTTY AND SPRAY FRONT RIGHT DOOR, FRONT RIGHT FENDER AND ALL AFFECTED AREA.	New	1,800.00	800.00
3	ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.	New	150.00	70.00
4	TRANSFER AND REFIX FRONT RIGHT DOOR FITTING, GLASS AND AL USABLE MECHANICAL COMPONENT.	New	300.00	200.00
5	TUFF KOTE, ANTI RUST PRESERVATIONS, BODY CAVITY PRESERVATIONS.	New	120.00	120.00
6	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULTY CODES.	New	300.00	300.00
7	TO REPLACE FRONT RIGHT DOOR POWER WINDOW MECHANISM AND REGULATOR.	New	250.00	0.00
Gross Labour Cost (\$\$)			4,720.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >