



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGF8018H

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT  
50 Raffles Place #05-01/06  
Singapore Land Tower  
Singapore 048623  
64616555

### Vehicle & Document Information

WIP No **28793**  
Reg No/Reg Date **SGF8018H / 19/01/2018**  
Date In/Mileage **03/12/2018 / 19170**  
Chassis No **WDD2462422J459817**  
Engine No **27091031400030**  
Make/Model **MB/B 180 SEDAN (W246) "STYLE**  
Colour/Trim **027 787 Mountain Gr/ 041 111 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	17/01/2019/ 17:53	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 1800001629 // 24.11.18 DRIVE IN/EXCESS : 26.11.18 // TP CAR NO.SKQ6140U=SOMPO INS DATE IN/DATE SURVEY: 03.12.18 // 03.12.18 TAUFIKH -LKK 14:00PM DIRECT SETTLEMENT: GNOH PAU LOONG-SOMPO // 27.11.18				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPLACE ON REAR BUMPER				960.00
A BPIRES RESPRAY ON REAR BUMPER				600.00
X FOOTPLATE	1.00	185.64	00.00	185.64
X REAR BUMPER	1.00	1429.51	00.00	1429.51

Finalization

3 days

Confirmed & accepted by

Nett **3,555.15**  
7% GST on **3555.15** **248.86**  
**Total Payable 3,804.01**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany