

ASS. REC. BY:

REF: CS/CTUS021677/KH012

Special Instruction:

Surveyor
Munim

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTL

Date/Time:

30/11/2018 5:15pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 7611E

Insured:

GBG 2675D

at Workshop m/s

BH Auto

Tel:

of

Bik 1 sin ming Ind 1st #01-115

Policy No:

DMCVGN 1747921801

Claim No:

SNM18D055211C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/11/2018

CA / REV / REP. / REV 24 HRS 'wp'

11am

H.O.D. Endorsement:

Date/Time: 03/12/2018 10am

Person Contacted:

Jacelyn

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate:

SJH 7611E - X

GBG 2675D - X

lump sum \$39501 (Red: 5427.81; 57%)

REF:

CTL

ASSIGNMENT

From:

Date: 03-12-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

STH 7611E

at Workshop m/s

BH Auto

of

Bk 1 Sin Ming Ind Est #01-116

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

8/28

Person Contacted:

Vehicle: IN / OUT

Veh No:

STH 7611E

Yr Regn:

08 08

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

N/S

A) 4/1/18

G.C.

1498

Colour:

M. Gold

A/C.

Insured / Std / NI / NA

Sp. Reading

175354

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1BAA G11 Z 010 6501

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/85R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

24/11/18

D.O.I.

3/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

8/18

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12 File pass to Corbin

RECEIVED 15 JAN 2019

Date/Time, File Pass to?

1) 15/1 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) TP

39507

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

) TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2018		30 Nov 2018 17:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	[Created by insurer]		
Main Claimant:	PETER LIM AH BENG		
Vehicle Reg. No.:	SJH7611E	Date of Loss:	24/11/2018 13:00 - :59
Claim Type:	TP / SNM18D05524C02	Policy/Cover Note No.:	DMCVSN1747921801
Vehicle Reg. No. (Insured):	GBG2675D	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/12/2018]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

500+ dealers
competed to
buy my car!



Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Golf GT Selling Cheaper Than Polo! Best Short Term!



Full Agent Records Since Day 1!
80k Km Mileage Only! Tip Top!
View To Believe!
Direct Owner - StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

2 vehicles

Nissan Sylphy

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Sylphy		Any	Any	2008	Any	Any	Any	Available
	Nissan Sylphy	Nissan Sylphy 1.5A (New 5-yr COE)	\$29,800	\$5,960 /yr	28-Nov-2008	1,498 cc	-	Sedan	Available
10 Years COE Renewal For \$44,800. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And...									
Classic Credit Pte Ltd									
Posted: 24-Nov-2018 Tags: 2008 Nissan Sylphy, 2008 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									
	Nissan Sylphy	Nissan Sylphy 1.5A (New 5-yr COE)	\$27,800	\$5,560 /yr	04-Nov-2008	1,498 cc	127,000 km	Sedan	Available
AA Trust Certified Quality Pre-Owned Vehicle! Stunning Pearl White Nissan Sylphy Available Now For COE Renewal At An Affordable Price! Compact On The Outside Yet Luxurious On The Inside! Perfect For W...									
AA Trust Automotive									
Posted: 04-Nov-2018 Tags: 2008 Nissan Sylphy, 2008 nissan sylphy, Nissan Sylphy, nissan sylphy, Nissan, Sylphy, sylphy, Used Nissan									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Nissan Sylphy, Nissan Sylphy Singapore, used Nissan Sylphy Singapore, used Nissan Sylphy, used vehicles Singapore or even buy used Nissan Sylphy Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2018 sgCarMart. All rights reserved.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

3406B

Vehicle Details

Vehicle No.:

SJH7611E

Vehicle to be Exported:

No

Intended Deregistration Date:

26 Nov 2018

Vehicle Make:

NISSAN

Vehicle Model:

SYLPHY 1.5 4AT

Primary Colour:

Beige

Manufacturing Year:

2008

Engine No.:

HR15360838A

Chassis No.:

JN1BAAG11Z0106501

Maximum Power Output:

80.0 kW (107 bhp)

Open Market Value:

\$17,774.00

Original Registration Date:

22 Aug 2008

First Registration Date:

22 Aug 2008

Transfer Count:

1

Actual ARF Paid:

\$17,774.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

21 Aug 2028

COE Category:

A - Car (1600cc & below)

COE Period(Years):

10

PQP Paid:

\$34,197.00

COE Rebate Amount:

\$33,296.00

Total Rebate Amount:**\$33,296.00**

The information contained herein is correct as at 26 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2018 16:25
Date Of Accident	24/11/2018 13:20
Exact Location Of Accident	PTE TOWARDS SIM AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH7611E
Insured/Policyholder	
Name Of Registered Owner	PETER LIM AH BENG
NRIC No	S1373406B
Email Address	POWERFIT9988@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-90059202
Alternative Phone No	OFFICE-90059202

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.5 4AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA257547/1
Cover Note Number	

Driver

Name of Driver	LIM SWAY HONG
NRIC No	S1396766J
Date Of Birth	14/07/1959
Occupation	INDOOR
Date Of Driving Pass	11/04/1988
Driving Experience	30 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91460759
Fax Number	
Contact Number	
Email Address	BBLESS139@GMAIL.COM

Address	BLK 26 TANGLIN HALT ROAD #05-64
Postcode	141026
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DAUGHTER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG1968R
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KOH ZHISHENG, JONAS
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG2675D
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

4 田田田田

A 53H76UE
B GB01762R
C GB02670D

P1E towards Sim Ave

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car ^{was} coming to a halt when suddenly ~~the~~ an oncoming vehicle bumped my car from the back. My car swerved forward and knocked onto the front van that was already stationary.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature _____

Date & Time

24/11/98 14:00, 2000

Driver's Signature _____

(if driver is not the policyholder)

Date & Time: 24/10/18 16:00pm

Reporting Centre Personnel's Signature _____

Name: _____

NRIC/FIN No.:

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL : 6389 6111 FAX :-

DATE : 27/11/2018
PAGE : 1 OF 3

Not Notwork
L1 Bump & ?
Resuming After Paint

ACCIDENT REPAIR ON : SJH7611E
MODEL : NISSAN SYLPHY 1.5
POLICY NO : GA257547/1
CHASSIS NO : JN1BAAG11Z0106501
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 24/11/2018@13:20HRS
LOCATION : ALONG PTE TOWARDS SIM AVE
THIRD PARTY VEHICLE NO : GBG2675D

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT	
1	FRONT HEADLAMP LH	1	\$m	\$ 507.30	X
2	FRONT HEADLAMP RH	1	\$m	\$ 507.30	X
3	FRONT GRILLE	1	\$m	\$ 364.50	74
4	FRONT GRILLE "LOGO" EMBLEM	1	\$m	\$ 65.70	74
5	FRONT BUMPER	1	\$m	\$ 566.20	74
6	FRONT BUMPER TOW HOOK COVER	1	\$m	\$ 21.20	X
7	FRONT BUMPER FOG LAMP LH	1	\$m	\$ 321.60	X
8	FRONT BUMPER FOG LAMP RH	1	\$m	\$ 321.60	X
9	FRONT BUMPER FOG LAMP GARNISH LH	1	\$m	\$ 124.70	X
10	FRONT BUMPER FOG LAMP GARNISH RH	1	\$m	\$ 124.70	X
11	FRONT BUMPER LOWER GARNISH	1	\$m	\$ 75.00	X
12	FRONT BUMPER INNER SPONGE	1	\$m	\$ 231.00	74
13	FRONT BUMPER REINFORCEMENT	1	\$m	\$ 563.70	74
14	REAR BOOTLID	1	\$m	\$ 796.70	✓
15	REAR BOOTLID "LOGO" EMBLEM	1	\$m	\$ 46.10	✓
16	REAR BOOTLID OUTER CHROME MOULDING TOP	1	\$m	\$ 270.60	✓
17	REAR BOOTLID NUMBER PLATE LAMP LH	1	\$m	\$ 78.40	X
18	REAR BOOTLID NUMBER PLATE LAMP RH	1	\$m	\$ 78.40	X
19	REAR BOOTLID OUTER HANDLE	1	\$m	\$ 100.00	X
20	REAR BOOTLID OUTER CHROME MOULDING LOWER	1	\$m	\$ 152.70	74
21	REAR BOOTLID REFLECTOR LAMP LH	1	\$m	\$ 120.90	✓
22	REAR BOOTLID REFLECTOR LAMP RH	1	\$m	\$ 120.90	✓
23	REAR BOOTLID MECHANISM LOCK	1	\$m	\$ 118.00	X
24	REAR BOOTLID INNER TRIM BOARD	1	\$m	\$ 148.90	X
25	REAR BOOTLID HINGE LH	1	\$m	\$ 93.00	X
26	REAR BOOTLID HINGE RH	1	\$m	\$ 93.00	X
27	REAR BOOTLID WEATHERSTRIP	1	\$m	\$ 106.30	508.20
28	REAR TAILLAMP LH	1	\$m	\$ 241.80	✓
29	REAR TAILLAMP RH	1	\$m	\$ 241.80	✓
30	REAR TAILLAMP LOWER BRACKET LH	1	\$m	\$ 32.70	74
31	REAR TAILLAMP LOWER BRACKET RH	1	\$m	\$ 32.70	74
32	REAR BUMPER	1	\$m	\$ 660.60	✓
33	REAR BUMPER SIDE RETAINER LH	1	\$m	\$ 35.00	✓
34	REAR BUMPER SIDE RETAINER RH	1	\$m	\$ 35.00	✓
TOTAL CARRY DOWN				\$ 7,398.00	

ACCIDENT REPAIR ON : SJH7611E
MODEL : NISSAN SYLPHY 1.5
POLICY NO : GA257547/1
CHASSIS NO : JN1BAAG11Z0106501
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 24/11/2018@13:20HRS
LOCATION : ALONG PTE TOWARDS SIM AVE
THIRD PARTY VEHICLE NO : GBG2675D

DATE : 27/11/2018
PAGE : 2 OF 3

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
		TOTAL BRING DOWN		\$ 7,398.00
35	REAR BUMPER REVERSE SENSOR LH	1		\$ 182.00
36	REAR BUMPER REVERSE SENSOR RH	1		\$ 182.00
37	REAR BUMPER OUTER MOULDING	1		\$ 168.60
38	REAR BUMPER REFLECTOR LH	1		\$ 55.00
39	REAR BUMPER REFLECTOR RH	1		\$ 55.00
40	REAR BUMPER LOWER SPOILER	1		\$ 588.00
41	REAR BUMPER IMPACT BRACKET LH	1		\$ 50.40
42	REAR BUMPER IMPACT BRACKET RH	1		\$ 50.40
43	REAR END PANEL	1		\$ 438.70
44	REAR END PANEL INNER LOCK STRIKER	1		\$ 57.40
45	REAR END PANEL INNER TOP GARNISH	1		\$ 242.80
		SUB TOTAL		\$ 9,468.30
		LESS 30%		\$ (2,840.49)
		PARTS TOTAL		\$ 6,627.81

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT GRILLE CLIPS	4	\$ 5.00	\$ 20.00
2	FRONT BUMPER CLIPS	10	\$ 5.00	\$ 50.00
3	FRONT BUMPER NUMBER PLATE WITH HOLDER	1		\$ 50.00
4	REAR BOOTLID OUTER CHROME MOULDING TOP CLIPS	4	\$ 5.00	\$ 20.00
5	REAR BOOTLID NUMBER PLATE WITH HOLDER	1		\$ 50.00
6	REAR BOOTLID INNER TRIM BOARD CLIPS	8	\$ 5.00	\$ 40.00
7	REAR BUMPER CLIPS	10	\$ 5.00	\$ 50.00
8	REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 5.00	\$ 20.00
		PARTS TOTAL		\$ 300.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCIDENT REPAIR ON : SJH7611E
MODEL : NISSAN SYLPHY 1.5
POLICY NO : GA257547/1
CHASSIS NO : JN1BAAG11Z0106501
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 24/11/2018@13:20HRS
LOCATION : ALONG PTE TOWARDS SIM AVE
THIRD PARTY VEHICLE NO : GBG2675D

DATE : 27/11/2018
PAGE : 3 OF 3

LABOUR CHARGES FOR FRONT AND REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,200.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 1,000.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00
4	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
5	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00
LABOUR TOTAL		\$ 2,450.00

900/ ✓
✓
60/ ✓
40/ ✓

TOTAL PARTS & LABOUR	\$ 9,377.81
GST 7%	\$ 656.45
GRAND TOTAL	\$ 10,034.26
ESTIMATE REPAIR DURATION	8 DAYS

✓

YOURS SINCERELY,


ESTIMATOR : KIT
TEL : 8405 4058
FAX : 6269 2404
EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	CKK
DATE	3/12/18
TIME	10.45am
TEL	96910663
EMAIL	

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

DATE : 27/11/2018

PAGE : 1 OF 3

3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL : 6389 6111 FAX : -

Not Authorized
L1 Pmp @ 3950h
Resurvey After Repair

ACCIDENT REPAIR ON : SJH7611E
MODEL : NISSAN SYLPHY 1.5
POLICY NO : GA257547/1
CHASSIS NO : JN1BAAG11Z0106501
YEAR OF MANUFACTURE : 2008
DATE / TIME OF ACCIDENT : 24/11/2018@13:20HRS
LOCATION : ALONG PTE TOWARDS SIM AVE
THIRD PARTY VEHICLE NO : GBG2675D

8 days

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT HEADLAMP LH	1	\$m	\$ 507.30
2	FRONT HEADLAMP RH	1	\$m	\$ 507.30
3	FRONT GRILLE	1	\$m	\$ 364.50
4	FRONT GRILLE "LOGO" EMBLEM	1	\$m	\$ 65.70
5	FRONT BUMPER	1	\$m	\$ 566.20
6	FRONT BUMPER TOW HOOK COVER	1	\$m	\$ 21.20
7	FRONT BUMPER FOG LAMP LH	1	\$m	\$ 321.60
8	FRONT BUMPER FOG LAMP RH	1	\$m	\$ 321.60
9	FRONT BUMPER FOG LAMP GARNISH LH	1	\$m	\$ 124.70
10	FRONT BUMPER FOG LAMP GARNISH RH	1	\$m	\$ 124.70
11	FRONT BUMPER LOWER GARNISH	1	\$m	\$ 75.00
12	FRONT BUMPER INNER SPONGE	1	\$m	\$ 231.00
13	FRONT BUMPER REINFORCEMENT	1	\$m	\$ 563.70
14	REAR BOOTLID	1	\$m	\$ 796.70
15	REAR BOOTLID "LOGO" EMBLEM	1	\$m	\$ 46.10
16	REAR BOOTLID OUTER CHROME MOULDING TOP	1	\$m	\$ 270.60
17	REAR BOOTLID NUMBER PLATE LAMP LH	1	\$m	\$ 78.40
18	REAR BOOTLID NUMBER PLATE LAMP RH	1	\$m	\$ 78.40
19	REAR BOOTLID OUTER HANDLE	1	\$m	\$ 100.00
20	REAR BOOTLID OUTER CHROME MOULDING LOWER	1	\$m	\$ 152.70
21	REAR BOOTLID REFLECTOR LAMP LH	1	\$m	\$ 120.90
22	REAR BOOTLID REFLECTOR LAMP RH	1	\$m	\$ 120.90
23	REAR BOOTLID MECHANISM LOCK	1	\$m	\$ 118.00
24	REAR BOOTLID INNER TRIM BOARD	1	\$m	\$ 148.90
25	REAR BOOTLID HINGE LH	1	\$m	\$ 93.00
26	REAR BOOTLID HINGE RH	1	\$m	\$ 93.00
27	REAR BOOTLID WEATHERSTRIP	53.155m	\$m	\$ 106.30
28	REAR TAILLAMP LH	1	\$m	\$ 241.80
29	REAR TAILLAMP RH	1	\$m	\$ 241.80
30	REAR TAILLAMP LOWER BRACKET LH	1	\$m	\$ 32.70
31	REAR TAILLAMP LOWER BRACKET RH	1	\$m	\$ 32.70
32	REAR BUMPER	1	\$m	\$ 660.60
33	REAR BUMPER SIDE RETAINER LH	1	\$m	\$ 35.00
34	REAR BUMPER SIDE RETAINER RH	1	\$m	\$ 35.00
TOTAL CARRY DOWN				\$ 7,398.00

LKK Auto Consultants hence is the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCIDENT REPAIR ON : SJH7611E
 MODEL : NISSAN SYLPHY 1.5
 POLICY NO : GA257547/1
 CHASSIS NO : JN1BAAG11Z0106501
 YEAR OF MANUFACTURE : 2008
 DATE / TIME OF ACCIDENT : 24/11/2018@13:20HRS
 LOCATION : ALONG PTE TOWARDS SIM AVE
 THIRD PARTY VEHICLE NO : GBG2675D

DATE : 27/11/2018
 PAGE : 2 OF 3

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT
		TOTAL BRING DOWN		\$ 7,398.00
35	REAR BUMPER REVERSE SENSOR LH	1		\$ 182.00
36	REAR BUMPER REVERSE SENSOR RH	1		\$ 182.00
37	REAR BUMPER OUTER MOULDING	1		\$ 168.60
38	REAR BUMPER REFLECTOR LH	1		\$ 55.00
39	REAR BUMPER REFLECTOR RH	1		\$ 55.00
40	REAR BUMPER LOWER SPOILER	1		\$ 588.00
41	REAR BUMPER IMPACT BRACKET LH	1		\$ 50.40
42	REAR BUMPER IMPACT BRACKET RH	1		\$ 50.40
43	REAR END PANEL	1		\$ 438.70
44	REAR END PANEL INNER LOCK STRIKER	1		\$ 57.40
45	REAR END PANEL INNER TOP GARNISH	1		\$ 242.80
SUB TOTAL				\$ 9,468.30
LESS 30%				\$ (2,840.49)
PARTS TOTAL				\$ 6,627.81

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT
1	FRONT GRILLE CLIPS	4	\$ 5.00	\$ 20.00
2	FRONT BUMPER CLIPS	10	\$ 5.00	\$ 50.00
3	FRONT BUMPER NUMBER PLATE WITH HOLDER	1		\$ 50.00
4	REAR BOOTLID OUTER CHROME MOULDING TOP CLIPS	4	\$ 5.00	\$ 20.00
5	REAR BOOTLID NUMBER PLATE WITH HOLDER	1		\$ 50.00
6	REAR BOOTLID INNER TRIM BOARD CLIPS	8	\$ 5.00	\$ 40.00
7	REAR BUMPER CLIPS	10	\$ 5.00	\$ 50.00
8	REAR END PANEL INNER TOP GARNISH CLIPS	4	\$ 5.00	\$ 20.00
PARTS TOTAL				\$ 300.00

3568.80

PARTS : \$ ~~3818.88~~ - 30% =
 \$ ~~2673.16~~ 2498.16

S/NETT : \$ ~~135.00~~ 388.15

LABOUR : \$ ~~2000.00~~ 2050

TOTAL : \$ 4808.16 - 20%
 = \$ 3846.52

R = \$ ~~3840.00~~
3950.00

ACCIDENT REPAIR ON : SJH7611E

MODEL : NISSAN SYLPHY 1.5

POLICY NO : GA257547/1

CHASSIS NO : JN1BAAG11Z0106501

YEAR OF MANUFACTURE : 2008

DATE / TIME OF ACCIDENT : 24/11/2018@13:20HRS

LOCATION : ALONG PTE TOWARDS SIM AVE

THIRD PARTY VEHICLE NO : GBG2675D

DATE : 27/11/2018

PAGE : 3 OF 3

LABOUR CHARGES FOR FRONT AND REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 1,200.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 1,000.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00
4	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
5	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00
LABOUR TOTAL		\$ 2,450.00

TOTAL PARTS & LABOUR	\$ 9,377.81
GST 7%	\$ 656.45
GRAND TOTAL	\$ 10,034.26
ESTIMATE REPAIR DURATION	8 DAYS

YOURS SINCERELY,

ESTIMATOR : KIT

TEL : 8405 4058

FAX : 6269 2404

EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	CKK
DATE	3/12/18
TIME	10.45am
TEL	96910663
EMAIL	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118021677/KTBN2
Date: 16/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1747921801	
Claimant Vehicle No :	SJH7611E	Insured Vehicle No :	GBG2675D	
Date of Loss:	24/11/2018	Nature of Claim:	TP	Claim No: SNM18D05524C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH7611E	Engine No:	HR15360838A
Make & Model:	NISSAN SYLPHY, 1.5 4AT (A)	Chassis No:	JN1BAAG11Z0106501
Reg. Date:	22/08/2008 (Man. Year: 2008)	Odometer:	175354 km
Colour:	Metallic Gold		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,927.81	2,886.31	4,041.50	58.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	2,050.00	400.00	16.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,377.81	4,936.31	4,441.50	47.36
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	9,377.81	3,950.00	5,427.81	57.88
+ GST 7.00/7.00% (S\$)	656.45	276.50	379.95	57.88
Nett Amount (S\$)	10,034.26	4,226.50	5,807.76	57.88

INSPECTION

Date of Assignment:	30/11/2018
Date Inspected:	03/12/2018 Inspected At:

BH Auto Services Pte Ltd (Sin Ming)
Blk 1 Sin Ming Industrial Estate Sector
C, #01/111/113/115/117
Singapore 575636

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2019)
Parts:	143	NISSAN SYLPHY 1.5 4AT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH7611E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Serviceable	507.30 FL	*- FL
2	1		*FRONT HEADLAMP RH	Serviceable	507.30 FL	*- FL
3	1		*FRONT GRILLE	Serviceable	364.50 FL	*- FL
4	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	65.70 FL	*- FL
5	1		*FRONT BUMPER	Serviceable	566.20 FL	*- FL
6	1		*FRONT BUMPER TOW HOOK COVER	Serviceable	21.20 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP LH	Serviceable	321.60 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP RH	Serviceable	321.60 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP GARNISH LH	Serviceable	124.70 FL	*- FL
10	1		*FRONT BUMPER FOG LAMP GARNISH RH	Serviceable	124.70 FL	*- FL
11	1		*FRONT BUMPER LOWER GARNISH	Serviceable	75.00 FL	*- FL
12	1		*FRONT BUMPER INNER SPONGE	Serviceable	231.00 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Repair	563.70 FL	*- FL
14	1		*REAR BOOTLID	Bent	796.70 FL	*796.70 FL
15	1		*REAR BOOTLID LOGO EMBLEM	Necessary	46.10 FL	*46.10 FL
16	1		*REAR BOOTLID OUTER CHROME MOULDING TOP	Cracked	270.60 FL	*270.60 FL
17	1		*REAR BOOTLID NUMBER PLATE LAMP LH	Serviceable	78.40 FL	*- FL
18	1		*REAR BOOTLID NUMBER PLATE LAMP RH	Serviceable	78.40 FL	*- FL
19	1		*REAR BOOTLID OUTER HANDLE	Serviceable	100.00 FL	*- FL
20	1		*REAR BOOTLID OUTER CHROME MOULDING LOWER	Serviceable	152.70 FL	*- FL
21	1		*REAR BOOTLID REFLECTOR LAMP LH	Cracked	120.90 FL	*120.90 FL
22	1		*REAR BOOTLID REFLECTOR LAMP RH	Cracked	120.90 FL	*120.90 FL
23	1		*REAR BOOTLID MECHANISM LOCK	Repair	118.00 FL	*- FL
24	1		*REAR BOOTLID INNER TRIM BOARD	Serviceable	148.90 FL	*- FL
25	1		*REAR BOOTLID HINGE LH	Repair	93.00 FL	*- FL
26	1		*REAR BOOTLID HINGE RH	Repair	93.00 FL	*- FL
27	1		*REAR TAILLAMP LH	Cracked	241.80 FL	*241.80 FL
28	1		*REAR TAILLAMP RH	Mtg Cracked	241.80 FL	*241.80 FL
29	1		*REAR TAILLAMP LOWER BRACKET LH	Repair	32.70 FL	*- FL
30	1		*REAR TAILLAMP LOWER BRACKET RH	Repair	32.70 FL	*- FL
31	1		*REAR BUMPER	Buckled	660.60 FL	*660.60 FL
32	1		*REAR BUMPER SIDE RETAINER LH	Distorted	35.00 FL	*35.00 FL
33	1		*REAR BUMPER SIDE RETAINER RH	Distorted	35.00 FL	*35.00 FL
34	1		*REAR BUMPER OUTER MOULDING	Necessary	168.60 FL	*168.60 FL
35	1		*REAR BUMPER REFLECTOR LH	Serviceable	55.00 FL	*- FL
36	1		*REAR BUMPER REFLECTOR RH	Serviceable	55.00 FL	*- FL
37	1		*REAR BUMPER LOWER SPOILER	Cracked	588.00 FL	*588.00 FL
38	1		*REAR BUMPER IMPACT BRACKET LH	Repair	50.40 FL	*- FL
39	1		*REAR BUMPER IMPACT BRACKET RH	Repair	50.40 FL	*- FL
40	1		*REAR END PANEL	Repair	438.70 FL	*- FL
41	1		*REAR END PANEL INNER LOCK STRIKER	Repair	57.40 FL	*- FL
42	1		*REAR END PANEL INNER TOP GARNISH	Cracked	242.80 FL	*242.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR BOOTLID WEATHERSTRIP (50%)	Dented/Distorted	74.41 FS	*53.15 FS
44	1		*REAR BUMPER REVERSE SENSOR LH }	Dented	127.40 FS	*200.00 FS
45	1		*REAR BUMPER REVERSE SENSOR RH }	Dented	127.40 FS	*- FS
46	4		*FRONT GRILLE CLIP	Not Necessary	20.00 FS	*- FS
47	10		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*FRONT BUMPER NUMBER PLATE WITH HOLDER	Dented	50.00 FS	*45.00 FS
49	4		*REAR BOOTLID OUTER CHROME MOULDING TOP CLIPS	Necessary	20.00 FS	*20.00 FS
50	1		*REAR BOOTLID NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
51	8		*REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS
52	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
53	4		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
					Sub Total (\$\$)	9,627.21 3,956.95
					- List Item Discount on L Items 30.00/30.00% (\$\$)	2,699.40 1,070.64
					Total Parts (\$\$)	6,927.81 2,886.31

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,200.00	900.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	1,000.00	1,000.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	50.00	50.00
4	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS	New	80.00	60.00
5	DISCONNECT,CHECK,RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING,HARNESS,WIRE SOCKETS AND ETC.REMOVE AND REINSTALL DAMAGED PARTS.TEST AND RECTIFY FOR PROPER FUNCTIONING	New	120.00	40.00
Gross Labour Cost (S\$)			2,450.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >