



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGU1739C
Make & Model : TOYOTA, WISH 1.8 CVT, JTDGG20WX0J003850
Year of Manufacture : 2016

Estimation No. : E18110018
DOA : 26/11/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper <i>X Repair</i>	1.00	565.80	565.80
2	Front bumper retainer (LH) <i>X NN</i>	1.00	80.40	80.40
3	Front bumper retainer (RH) <i>— NN</i>	1.00	80.40	80.40
4	Fog lamp (RH) <i>X NN</i>	1.00	422.50	422.50
5	Head lamp (RH) <i>— SCR</i>	1.00	1,045.00	1,045.00
6	Front fender (RH) <i>— Bue</i>	1.00	980.00	980.00
7	Front fender inner shield (RH) <i>— ee.</i>	1.00	214.70	214.70
8	Front wheel rim <i>— Cut</i>	1.00	0.00	0.00
9	Front absorber (RH)	1.00	520.00	520.00
10	Front absorber top mounting (RH)	1.00	0.00	0.00
11	Front knuckle arm (RH)	1.00	651.30	651.30
12	Front lower arm (RH)	1.00	640.00	640.00
13	Front linkage (RH)	1.00	0.00	0.00
14	Front wheel rim cap (RH)	1.00	0.00	0.00
15	Front knuckle bearing (RH)	1.00	599.10	599.10

-25%
Amt S\$ 5,799.20
Discount (0.00%) S\$ 0.00
Subtotal S\$ 5,799.20

65.2

687.2

189.6

1987

1490.25

Section: Special Nett Items

16	Front bumper clip set <i>—</i>	1.00	45.00	45.00
17	front fender inner shield clip set (RH) <i>—</i>	1.00	45.00	45.00
18	Front tyre (RH) <i>X NN</i>	1.00	220.00	220.00

30

30

60

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGU1739C
Make & Model : TOYOTA, WISH 1.8 CVT, JTDGG20WX0J003850
Year of Manufacture : 2016
Estimation No. : E18110018
DOA : 26/11/2018

No	Description	Qty	U/P	Amt
				Amt S\$ 310.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 310.00

Section: Labour Items

19	To check wiring & lighting system	1.00	60.00	60.00	30
20	To focus head lamp assy	1.00	50.00	50.00	X NN
21	To apply undercoating on affected areas	1.00	60.00	60.00	40
22	To R&R front wheel rim, tyre and balancing	1.00	60.00	60.00	30
23	To conduct wheel alignment before and after	1.00	150.00	150.00	60
24	To R&R front under-carriage damage parts	1.00	300.00	300.00	X NN
25	To repair, replace & realign damage areas	1.00	1,000.00	1,000.00	400
26	To spray painting on affected areas	1.00	800.00	800.00	400.
				Amt S\$ 2,480.00	960
				Discount (0.00%) S\$ 0.00	
				Subtotal S\$ 2,480.00	

4 Days.

Lump sum repair.

After repair photos.

Eno Qianf - 82880282

05/12/18.

2510.25
20%: 2000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

List Items Subtotal	S\$ 5,799.20
Special Nett Items Subtotal	S\$ 310.00
Labour Items Subtotal	S\$ 2,480.00
Total	S\$ 8,589.20