

ASS. REC. BY:

REF:

TM1/ CC3/TML18021689/Ksbnz

zhu wei

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SLS 481A

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S110 99735

Yr Regn:

06, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

719031

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1 ABL15AUC 278270

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/11/18

D.O.I.

30/11/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/12 File pass to Catherine

S110 99735 - NA/INC15006208/02

SLS 481A - X

DCA: 0504205

11/12 878501

10/12/18 Confirmed HS \$ 7,950/- @ 5 days with Kenneth (\$32,771.77 Rd - 81%)

RECEIVED 14 DEC 2018

Date/Time, File, Page to?

14/12/18



: Prell. Report



: Final Report

1)

Type

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

10

: Factors

: Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 7,950/- HS)

TOTAL

260

Shirley Hiew (LKK Auto)

From: Zhe Wei <zhewei.kek@transcab.com.sg>
Sent: Thursday, 13 December 2018 1:38 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'SUR'
Subject: RE: TCS REF: AAD1811-272--Accident involving SHD 9973S & SLS 482A on 29.11.18

Hi Shirley,

We confirm finalized repair cost @ \$7950 before GST and 5 days repair.

Please wait while I retrieve the before-paint photos.

Thank you.

Best Regards,
Kek Zhewei
Claims Officer



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, December 10, 2018 2:00 PM
To: zhewei.kek@transcab.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: TCS REF: AAD1811-272--Accident involving SHD 9973S & SLS 482A on 29.11.18

Hi Zhe Wei,

Please confirm final fig of \$7,950.00 (lump sum) @ 5 days of repairs before GST.

Kindly provide us the before paint photo.

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 4 December 2018 2:50 PM
To: 'Motor Claims'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 29/11/2018 , SHD 9973S (TP Vehicle), SLS 482A (OI Vehicle)
Attachments: TP GIA REPORT .pdf; ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9973S at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 30/11/2018

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

11/29/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9973S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Nov 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001559
Chassis No.:	VF1ABL15AUC278270
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	05 Jun 2014
First Registration Date:	05 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	04 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$57,338.00
COE Rebate Amount:	\$25,203.00
Total Rebate Amount:	\$34,576.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/11/2018 17:44
Date Of Accident	29/11/2018 16:45
Exact Location Of Accident	KEPPEL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9973S
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	LEE KOK PENG
NRIC No	S78308071
Date Of Birth	18/10/1978
Occupation	OUTDOOR
Date Of Driving Pass	14/10/2000
Driving Experience	18 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96817554
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 109 BUKIT BATOK WEST AVENUE 6 #07-18
Postcode	650109
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : DHANESH VYAS GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 29/11/2018 AT ABOUT 1645HRS, I WAS STATIONARY ALONG LANE 2 OF KEPPEL ROAD DUE TO RED TRAFFIC LIGHT. SUDDENLY I FELT AN IMPACT FROM THE REAR OF MY TAXI. VEHICLE B(SLS482A) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

Details of Witness 1

Name	DHANESH VYA
Phone Number	98296412
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS482A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Keppel Road.

Diagram illustrating a sequence of events on a track:

- A car labeled 'B' is shown moving from left to right.
- A car labeled 'A' is shown moving from left to right.
- Three empty rectangular boxes are shown, representing a sequence of events or positions.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9973S**AAD1811-272***Not Authorized
C/Smp & 78506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9973S

VF1ABL15AUC278270

RENAULT

LATITUDE

29.11.2018

TOKIO MARINE**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>pd/d.1</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>dit</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sm</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Bz</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CR</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Sm</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>Sm</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1811-272**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 99735

30	1 TAILLAMP LH	\$	552.55 X
31	1 TAILLAMP PANEL LH	\$	986.70 X
32	1 TAILLAMP RH	\$	552.55 X
33	1 TAILLAMP PANEL RH	\$	986.70 X
34	1 OUTER PANEL REAR (End Panel)	\$	1,471.77 ✓
35	1 OUTER PANEL REAR (End Panel)TRIM	\$	404.56 ✓
36	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	2,189.88 X
37	1 SPARE WHEEL PANEL TRIM	\$	612.21 X
38	1 EXHAUST REAR	\$	7,489.05 X
39	1 EXHAUST CAP REAR	\$	230.49 X

TOTAL	\$	26,840.83
10%	\$	2,684.08
	\$	24,156.75

Special Nett

1	1SET PARKING AID	\$	700.00 ✓
2	1SET REAR BUMPER CLIP	\$	66.00 ✓
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00 ✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00 X
5	1SET BUMPER RETAINER RH CLIP RR	\$	20.00 X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00 X
7	1SET BUMPER RETAINER CLIP LH RR	\$	20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	17.82 X
11	1SET BOOT FINISHER CLIP	\$	24.20 X
12	1 BOOT STICKER "Trans-cab"	\$	30.00 ✓
13	1 BOOT STICKER "6555-3333"	\$	30.00 ✓
14	1 BOOT INNER TRIM CLIP	\$	45.00 X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	35.00 X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00 X
17	1 FENDER INNER TRIM CLIP LH	\$	28.00 X
18	1 FENDER INNER TRIM CLIP LH	\$	28.00 X
19	1 TAILLAMP CLIP RH	\$	5.00 X
20	1 TAILLAMP CLIP LH	\$	5.00 X
21	2 REAR WINDSCREEN SELANT	\$	80.00 X
22	1 WINDSCREEN MOULDING	\$	100.00 X

Trans-cab Auto Services Pte Ltd**AAD1811-272**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 99735

23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>NN</i> 100.00 X
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sm</i> 385.00 X
25	1 SPARE TYRE	\$	<i>Sm</i> 330.00 X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 26,381.77****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 <i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>60</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60</i>
To repair and realign rear exhaust pipe.	\$	<i>NN</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>NN</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>60</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>NN</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>NN</i> 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1811-272**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 99735

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ *NN* 380.00 *X*

To transfer of rear windscreen fittings and conduct water seepage test.

\$ *NN* 170.00 *X*

To check steering geometry and computer wheel alignment

\$ *NN* 220.00 *X*

To transfer of rear door fittings, attachment and perform water seepage test.

\$ *NN* 380.00 *X***TOTAL \$ 14,340.00****Over All Total \$ 40,721.77****(LUMP SUM)****Repair Days***41101.76*
20 DAYS*5 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18021689/KSBN2

Date: 21/12/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT105075
Claimant Vehicle No :	SHD9973S	Insured Vehicle No :	SLS482A
Date of Loss:	29/11/2018	Nature of Claim:	TP
		Claim No:	M1806201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9973S	Engine No:	M9R8839C001559
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC278270
Reg. Date:	05/06/2014 (Man. Year: 2014)	Odometer:	719031 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	26,381.76	8,440.23	17,941.53	68.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,720.00	1,500.00	13,220.00	89.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,101.76	9,940.23	31,161.53	75.82
Approved Total (Overridden) (S\$)		7,950.00		
(S\$)	41,101.76	7,950.00	33,151.76	80.66
+ GST 7.00/7.00% (S\$)	2,877.12	556.50	2,320.62	80.66
Nett Amount (S\$)	43,978.88	8,506.50	35,472.38	80.66

INSPECTION

Date of Assignment:	05/12/2018	
Date Inspected:	30/11/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2018)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9973S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Distorted	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Buckled	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Serviceable	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
31	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
32	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
33	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
34	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
35	1		*OUTER PANEL REAR (END PANEL) TRIM	Dented	404.56 FL	*404.56 FL
36	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
37	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
38	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
39	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
40	1		*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
41	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
42	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
44	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
45	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
46	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
47	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
48	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
49	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
50	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
51	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
52	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
53	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
54	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
55	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
56	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
57	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
58	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
59	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
60	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
61	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
62	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
63	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
64	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	29,065.84	9,286.37
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,684.08	846.14
Total Parts (\$\$)	26,381.76	8,440.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
Gross Labour Cost (S\$)			14,720.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >