

INS. CASE OWNER:

RA

CC4, Asm 180 2695, KKa3s2

LKK:  
IDAC:

85115

Surveyor:

Kenneth

DOI:

ASSIGNMENT

30/11/18  
(Kil)

Date/Time:

30/11/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 54482

Claim No.:

S8m014up

Name of Insured:

The bus etc

Policy No.:

Insured Tel No.:

HP:

(km)

Make / Model:

Excess Sec II :SS

5,000.00

D.O.A.:

29/11/2018

Place of Accident:

Alexander Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 54482

SLG 9246U

SPX 785L

SLP 3389S



INSRS:

WSP:

Tel:

Liability:

RMKS:

u



INSRS:

WSP:

Tel:

Liability:

RMKS:

COLE

Bradden

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.

28 (Acc. 001000) NO or B 28, Ass. Lia: 100%

Repair Cost:

SS

25600.00

Loss of Rental (LOR):

SS

2370.00

(30 days)

x \$77

Loss of Use (LOU):

SS

-

(\$)

x days

Loss of Income (LOI):

SS

-

(\$)

x days

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.49

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS

27992.49

Global Sum SS: 27900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

27900.00

Name 1:

Comfortable Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

COPY SENT

ASS. REC. BY:

REF:

AA/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/12

File pass to Catherine

15 \$ 24K (Red \$ 13495.24/369)

24 + 1 PRS + 4 sum + 1 PH = 30

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + FS. SI

Fix/PS

Others

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

4597K

#### Vehicle Details

Vehicle No:

SLG9246U

Vehicle to be Exported:

No

Intended Deregistration Date:

29 Nov 2018

Vehicle Make:

HONDA

Vehicle Model:

SHUTTLE HYBRID 1.5 A

Primary Colour:

Black

Manufacturing Year:

2016

Engine No.:

LEB4260597

Chassis No.:

GP71041185

Maximum Power Output:

101.0 kW (135 bhp)

Open Market Value:

\$20,820.00

Original Registration Date:

18 Oct 2016

First Registration Date:

18 Oct 2016

Transfer Count:

1

Actual ARF Paid:

\$5,000.00

#### Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

17 Oct 2026

PARF Rebate Amount:

\$3,750.00

#### Intended COE Rebate Details

COE Expiry Date:

17 Oct 2026

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$49,156.00

COE Rebate Amount:

\$38,743.00

**Total Rebate Amount:**

**\$42,493.00**

The information contained herein is correct as at 29 Nov 2018

OK



**GET THE BEST PRE-OWNED CAR DEALS**

WIDE RANGE OF QUALITY JAPANESE CARS

- FREE Grooming & Servicing
- After Sales Warranty By In-House Workshop
- Bank / In-house Finance Available



**SGCARMART CARNIVAL**

15-16 DEC 2018 @ DOWNTOWN EAST

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

2017 Toyota Camry at \$102,800

Original Beautiful Condition  
StarA4



**HIN LUNG AUTO**

Ho Bee Group

**One Stop Car Hub**

Finance, Insurance, Workshop  
New and Used Cars

**30 years**  
of car sale

Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

honda shuttle

Advanced Search

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

honda shuttle

Any

Any

2016

Any

Any

Any

Available



Honda Shuttle 1.5A G

\$64,800

\$8,020 /yr

27-Jul-2016

1,496 cc

29,000 km

Stationwagon

Available

Not A Grab Car, One Owner, Low Downpayment Of \$6,480. Very Well Maintained, Low Mileage, Neat Interior And No Further Repairs Needed. Accident Free, Spacious Inner Cabin & Big Boot Space. Powerful, Fuel...

Posted: 01-Dec-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$66,800

\$8,010 /yr

27-Sep-2016

1,496 cc

46,800 km

Stationwagon

Available

One Owner Honda Shuttle, Down Payment \$9,800 Monthly \$835 Only, In-House Loan Or Bank Loan Welcome.

Posted: 29-Nov-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G (OPC)

\$49,500

\$6,000 /yr

29-Jun-2016

1,496 cc

26,000 km

Stationwagon

Available

1 Owner, Full Servicing Records Available. 3 Years Warranty From Date Of Purchase. Loans Up To 85% With Interest Rates As Low As 1.98%. Viewing Is Strictly By Appointment Only So Call Now To Book!

Posted: 23-Nov-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$59,800

\$7,590 /yr

17-May-2016

1,496 cc

-

Stationwagon

Available

\$0 Down Payment Available! S Pass, EP Or LTV Pass Welcome To Loan! In-House Loan Or Bank Loan Available! Balloon Scheme Available! Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Vie...

88 Motor Trading

Posted: 23-Nov-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Fit Shuttle goes on sale in Japan

Honda has announced the launch of the much-awaited Fit Shuttle in Japan, which was delayed due to problems arising from the Japanese earthquake in March

Read this article



Honda Shuttle 1.5A G

\$63,800

\$7,990 /yr

25-May-2016

1,496 cc

42,000 km

Stationwagon

Available

Down Payment 10% Easy Approval! Well Kept Lady Owner. Huge Boot Space To Wagon, With Recent Service And Regularly Maintained, Flawless And Mint Condition. Great Fuel Efficiency. Accident Free Condition...

Car Buyers Automotive Pte Ltd

Posted: 10-Nov-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$59,800

\$7,430 /yr

16-May-2016

1,496 cc

-

Stationwagon

Available

Owner Upgrade To MPV, Excellent Condition, Accident Free, Elegance White Orchid Pearl, Pioneer DVD Player With Bluetooth, Parking Sensor/Camera & Dashboard View Cam. Super Fuel Consumption, Low Mainte...

Posted: 08-Nov-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda



Honda Shuttle 1.5A G

\$85,000

\$10,530 /yr

28-Jul-2016

1,496 cc

400,000 km

Stationwagon

Available

Pearl White Color, Front Bumper Paint Peel, LED Front Lights, No Agents, No Consignment.

Posted: 02-Nov-2018

Tags: 2016 Honda Shuttle, 2016 honda shuttle, Honda Shuttle, honda shuttle, Honda, Shuttle, shuttle, Used Honda

Compare

Direct Owner

Compare



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLG9246UMake & Model : HONDA SHUTTLE HYB 1.5 AYear of Manufacture : 2016Chassis No. : GP71041185

Engine No. : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

Ins Company : AIG / AXA

Excess : \_\_\_\_\_

Date of Accident : 29/11/2018

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

Case Owner : Andrew

Signature : \_\_\_\_\_

**Repair Estimate**Parts (a) Cost / List Price Items S 32,607.30Plus/Less 20% S 6,521.46Total of Cost / List S 26,085.84(b) Nett Price Items S -Less S -Total of Nett Item S -(c) Special Nett Items S 560.00Total Parts Cost (Appendix A) S 26,645.84Labour (Appendix B) S 10,800.00Total Repair Cost S 37,445.84

The above total will be subjected to 7% G.S.T.

Contact No  
**Frt Counter Operation**  
 6383 7466 - Patrick Tin  
 6383 7730 - Brenda Ng  
 6383 7890 - Rohani  
[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)

Workshop Operation  
 63837656 - Ngo Toh Wee  
 63837362 - Andrew Goh  
 63838115 - William Wang

**Spark Car Care Consultants** hence notify  
 the Repairer of the following:  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Name of Surveyor : \_\_\_\_\_  
 Company : \_\_\_\_\_  
 Survey conducted on : \_\_\_\_\_ at \_\_\_\_\_

**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : \_\_\_\_\_ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

**Spare Parts**

Vehicle No : SLG9246U Case Owner : Andrew  
 Make & Model : HONDA SHUTTLE HYB 1.0 Year Manufacture : 2016  
 Chassis No : GP71041185 Engine No : 0  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description                                 | QTY | Cost Price | List Price  | Nett Price | S/N      | Disposition By Surveyor |
|------|--------------------------------------------------|-----|------------|-------------|------------|----------|-------------------------|
| 1    | Front number plate with casing <i>CFA</i>        | 1   |            |             |            |          |                         |
| 2    | Front bumper <i>BT</i>                           | 1   |            | \$ 1,050.50 |            | \$ 45.00 |                         |
| 3    | Front bumper lower grille <i>DIS</i>             | 1   |            | \$ 140.00   |            |          |                         |
| 4    | Front bumper grille LH <i>DIS</i>                | 1   |            | \$ 45.00    |            |          |                         |
| 5    | Front bumper grille RH <i>SVC</i>                | 1   |            | \$ 45.00    | X          |          |                         |
| 6    | Front bumper tow cover <i>SVC</i>                | 1   |            | \$ 25.00    | X          |          |                         |
| 7    | Front bumper side retainer LH <i>DIS</i>         | 1   |            | \$ 15.40    |            |          |                         |
| 8    | Front bumper side retainer RH <i>DIS</i>         | 1   |            | \$ 15.40    |            |          |                         |
| 9    | Front bumper clips <i>Nec</i>                    | 10  |            | \$ 39.00    |            |          |                         |
| 10   | Radiator grille <i>CRA</i>                       | 1   |            | \$ 395.00   |            |          |                         |
| 11   | Radiator grille outer chrome moulding <i>CRA</i> | 1   |            | \$ 302.80   |            |          |                         |
| 12   | Radiator grille lower chrome moulding <i>CRA</i> | 1   |            | \$ 220.70   |            |          |                         |
| 13   | Radiator grille emblem logo H <i>Nec</i>         | 1   |            | \$ 27.40    |            |          |                         |
| 14   | Radiator grille base bracket                     | 1   | <i>CM</i>  | \$ 65.00    |            |          |                         |
| 15   | Radiator grille top bracket LH                   | 1   |            | \$ 38.00    | X          |          |                         |
| 16   | Radiator grille top bracket RH                   | 1   |            | \$ 38.00    | X          |          |                         |
| 17   | Headlamp LH <i>Mtg CRA</i>                       | 1   |            | \$ 2,250.00 |            |          |                         |
| 18   | Headlamp RH <i>Mtg CRA</i>                       | 1   |            | \$ 2,250.00 |            |          |                         |
| 19   | Headlamp lower bracket LH <i>DIS</i>             | 1   |            | \$ 48.00    |            |          |                         |
| 20   | Headlamp lower bracket RH                        | 1   |            | \$ 48.00    |            |          |                         |
| 21   | Bonnet <i>BUC</i>                                | 1   |            | \$ 920.80   |            |          |                         |
| 22   | Bonnet hinge LH <i>DIS</i>                       | 1   |            | \$ 45.00    |            |          |                         |
| 23   | Bonnet hinge RH <i>DIS</i>                       | 1   |            | \$ 45.00    |            |          |                         |
| 24   | Bonnet lock <i>BT</i>                            | 1   |            | \$ 135.00   |            |          |                         |
| 25   | Bonnet lock cable                                | 1   | <i>B</i>   | \$ 75.00    | X          |          |                         |
| 26   | Bonnet insulator                                 | 1   | <i>B</i>   | \$ 140.00   | X          |          |                         |
| 27   | Bonnet rubber seal LH                            | 1   | <i>B</i>   | \$ 27.40    | X          |          |                         |
| 28   | Bonnet rubber seal RH <i>SVC</i>                 | 1   |            | \$ 27.40    | X          |          |                         |
| 29   | LH front fender <i>BUC</i>                       | 1   |            | \$ 435.10   |            |          |                         |
| 30   | LH front fender inner shield                     | 1   | <i>B</i>   | \$ 110.50   | X          |          |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

Page 2

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U

Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB I.

Year Manufacture : 2016

Chassis No : GP71041185

Engine No : 0

Sales Order : 0

Supplier : 0

Order By : 0

Type of Claim : TP

| S/No | Part Description                               | QTY | Cost Price | List Price  | Nett Price | S/N      | Disposition By Surveyor |
|------|------------------------------------------------|-----|------------|-------------|------------|----------|-------------------------|
| 31   | LH front fender inner shield clips <i>Nec</i>  | 10  |            | \$ 39.00    |            |          |                         |
| 32   | LH front fender emblem HYBRID <i>Nec</i>       | 1   |            | \$ 65.80    |            |          |                         |
| 33   | RH front fender <i>Buc</i>                     | 1   |            | \$ 435.10   |            |          |                         |
| 34   | RH front fender inner shield <i>sc</i>         | 1   |            | \$ 110.50   |            |          |                         |
| 35   | RH front fender inner shield clips <i>NV</i>   | 10  |            | \$ 39.00    |            |          |                         |
| 36   | RH front fender emblem HYBRID <i>Nec</i>       | 1   |            | \$ 65.80    |            |          |                         |
| 37   | Front bumper reinforcement <i>BT</i>           | 1   |            | \$ 420.90   |            |          |                         |
| 38   | Front support panel (complete) <i>Buc</i>      | 1   |            | \$ 786.00   |            |          |                         |
| 39   | Front support panel top cover <i>DIS</i>       | 1   |            | \$ 48.30    |            |          |                         |
| 40   | Front support panel top cover clips <i>Nec</i> | 10  |            | \$ 39.00    |            |          |                         |
| 41   | Front bumper bracket LH <i>BT</i>              | 1   |            | \$ 48.00    |            |          |                         |
| 42   | Front bumper bracket RH <i>RM</i>              | 1   |            | \$ 48.00    |            |          |                         |
| 43   | Radiator <i>BT</i>                             | 1   |            | \$ 1,540.40 |            |          |                         |
| 44   | Condenser <i>BT/PM</i>                         | 1   |            | \$ 985.00   |            |          |                         |
| 45   | Coolant <i>Nec</i>                             | 1   |            | \$ 40.10    |            |          |                         |
| 46   | Fan shroud                                     | 1   | <i>h</i>   | \$ 115.00   | <i>X</i>   |          |                         |
| 47   | Radiator fan LH                                | 1   | <i>h</i>   | \$ 78.00    | <i>X</i>   |          |                         |
| 48   | Radiator fan RH                                | 1   | <i>h</i>   | \$ 78.00    | <i>X</i>   |          |                         |
| 49   | Radiator fan motor LH                          | 1   | <i>h</i>   | \$ 329.10   | <i>X</i>   |          |                         |
| 50   | Radiator fan motor RH                          | 1   | <i>h</i>   | \$ 308.00   | <i>X</i>   |          |                         |
| 51   | Breather tube PVC                              | 1   | <i>h</i>   | \$ 25.00    | <i>X</i>   |          |                         |
| 52   | Rear number plate with casing <i>BT</i>        | 1   |            |             |            | \$ 45.00 |                         |
| 53   | Rear bumper                                    | 1   |            | \$ 1,150.60 |            |          |                         |
| 54   | Rear bumper side retainer LH <i>DIS</i>        | 1   |            | \$ 32.60    |            |          |                         |
| 55   | Rear bumper side retainer RH <i>DIS</i>        | 1   |            | \$ 32.60    |            |          |                         |
| 56   | Rear bumper clips <i>Nec</i>                   | 10  |            | \$ 39.00    |            |          |                         |
| 57   | Rear bumper cover LH <i>DIS</i>                | 1   |            | \$ 45.00    |            |          |                         |
| 58   | Rear bumper cover RH <i>DIS</i>                | 1   |            | \$ 45.00    |            |          |                         |
| 59   | Rear bumper reflector LH <i>CRA</i>            | 1   |            | \$ 45.60    |            |          |                         |
| 60   | Rear bumper reflector RH <i>sc</i>             | 1   |            | \$ 45.60    |            |          |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

30/11/2018

3:56 PM

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1.4 Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/N | Part Description                         | QTY | Cost Price | List Price  | Nett Price | S/N       | Disposition By Surveyor |
|-----|------------------------------------------|-----|------------|-------------|------------|-----------|-------------------------|
| 61  | Rear bumper tow cover <i>MIS</i>         | 1   |            | \$ 17.40    |            |           |                         |
| 62  | Rear bumper sponge LH                    | 1   | <i>in</i>  | \$ 56.50    | <i>X</i>   |           |                         |
| 63  | Rear bumper sponge RH                    | 1   | <i>in</i>  | \$ 56.50    | <i>X</i>   |           |                         |
| 64  | Tailgate <i>BT</i>                       | 1   |            | \$ 1,193.00 |            |           |                         |
| 65  | Tailgate glass <i>STP/H/200</i>          | 1   |            | \$ 1,210.30 |            |           |                         |
| 66  | Tailgate glass moulding upper <i>Nic</i> | 1   |            | \$ 31.20    |            |           |                         |
| 67  | Tailgate glass moulding lower <i>"</i>   | 1   |            | \$ 80.00    |            |           |                         |
| 68  | Tailgate glass moulding LH <i>"</i>      | 1   |            | NA          |            |           |                         |
| 69  | Tailgate glass moulding RH <i>"</i>      | 1   |            | NA          |            |           |                         |
| 70  | Tailgate glass sealant <i>"</i>          | 1   |            |             |            | \$ 40.00  |                         |
| 71  | Tailgate glass inner seal <i>"</i>       | 1   |            |             |            | \$ 30.00  |                         |
| 72  | Private Hire Sticker <i>MIS</i>          | 1   |            |             |            | \$ 120.00 | <i>405N</i>             |
| 73  | Tailgate weatherstrip <i>Pcl/MIS</i>     | 1   |            | \$ 168.50   |            |           |                         |
| 74  | Tailgate pocket handle                   | 1   | <i>in</i>  | \$ 25.00    | <i>✓</i>   |           |                         |
| 75  | Tailgate striker                         | 1   | <i>in</i>  | \$ 27.10    | <i>X</i>   |           |                         |
| 76  | Tailgate lock <i>Jam</i>                 | 1   |            | \$ 151.80   |            |           |                         |
| 77  | Tailgate chrome moulding <i>CRA</i>      | 1   |            | \$ 383.10   |            |           |                         |
| 78  | Tailgate emblem HYBRID <i>Nic</i>        | 1   |            | \$ 80.10    |            |           |                         |
| 79  | Tailgate emblem SHUTTLE <i>"</i>         | 1   |            | \$ 55.00    |            |           |                         |
| 80  | Tailgate emblem logo H <i>"</i>          | 1   |            | \$ 38.00    |            |           |                         |
| 81  | Tailgate lamp LH <i>CRA</i>              | 1   |            | \$ 340.80   |            |           |                         |
| 82  | Tailgate lamp RH <i>MIS CRA</i>          | 1   |            | \$ 340.80   |            |           |                         |
| 83  | Tailgate inner trim board <i>Buc</i>     | 1   |            | \$ 320.00   |            |           |                         |
| 84  | Tailgate wiper arm                       | 1   |            | \$ 95.50    |            |           |                         |
| 85  | Tailgate wiper arm cover                 | 1   |            | \$ 15.10    |            |           |                         |
| 86  | Tailgate wiper motor                     | 1   |            | \$ 490.00   |            |           |                         |
| 87  | Tailgate strut LH                        | 1   |            | \$ 120.00   |            |           |                         |
| 88  | Tailgate strut RH                        | 1   |            | \$ 120.00   |            |           |                         |
| 89  | Tailgate hinge LH                        | 1   |            | \$ 40.00    |            |           |                         |
| 90  | Tailgate hinge RH                        | 1   |            | \$ 40.00    |            |           |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

Page 4

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew  
Make & Model : HONDA SHUTTLE HYB 1.0 Year Manufacture : 2016  
Chassis No : GP71041185 Engine No : 0  
Sales Order : 0 Supplier : 0  
Order By : 0 Type of Claim : TP

| S/No | Part Description                              | QTY | Cost Price  | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|-----------------------------------------------|-----|-------------|------------|------------|-----|-------------------------|
| 91   | Tailgate stopper                              | 2   | \$ 25.80    |            | X          |     |                         |
| 92   | Taillamp LH <i>CKH</i>                        | 1   | \$ 520.50   |            |            |     |                         |
| 93   | Taillamp RH <i>CKH</i>                        | 1   | \$ 520.50   |            |            |     |                         |
| 94   | Taillamp clips <i>NRC</i>                     | 4   | \$ 16.80    |            |            |     |                         |
| 95   | Taillamp panel LH                             | 1   | \$ 210.50   |            |            |     |                         |
| 96   | Taillamp panel RH                             | 1   | \$ 210.50   |            |            |     |                         |
| 97   | Rear end panel <i>BT</i>                      | 1   | \$ 560.30   |            |            |     |                         |
| 98   | Rear end panel top garnish <i>DCL</i>         | 1   | \$ 155.60   |            |            |     |                         |
| 99   | Rear cargo top cover                          | 1   | \$ 350.00   |            | X          |     |                         |
| 100  | Rear cargo tray                               | 1   | \$ 295.50   |            |            |     |                         |
| 101  | Rear cargo tray end cover                     | 1   | \$ 85.60    |            |            |     |                         |
| 102  | Rear tools tray                               | 1   | \$ 165.00   |            |            |     |                         |
| 103  | Rear end floor panel <i>P/B</i>               | 1   | \$ 956.00   |            | X          |     |                         |
| 104  | LH rear fender inner trim                     | 1   | \$ 455.00   |            |            |     |                         |
| 105  | LH rear fender inner trim top board           | 1   | \$ 215.00   |            | X          |     |                         |
| 106  | RH rear fender inner trim                     | 1   | \$ 455.00   |            |            |     |                         |
| 107  | RH rear fender inner trim top board           | 1   | \$ 215.00   |            |            |     |                         |
| 108  | LH rear fender air vent                       | 1   | \$ 38.40    |            |            |     |                         |
| 109  | LH rear fender air vent top bracket           | 1   | \$ 38.70    |            |            |     |                         |
| 110  | RH rear fender air vent                       | 1   | \$ 38.40    |            |            |     |                         |
| 111  | RH rear fender air vent top bracket           | 1   | \$ 38.70    |            |            |     |                         |
| 112  | Duct assy IPU                                 | 1   | \$ 155.00   |            |            |     |                         |
| 113  | Tube joint comm IPU                           | 1   | \$ 86.50    |            |            |     |                         |
| 114  | Tube assy IPU                                 | 1   | \$ 235.00   |            |            |     |                         |
| 115  | LH rear fender <i>R</i>                       | 1   | \$ 1,010.90 |            | X          |     |                         |
| 116  | LH rear fender glass <i>MM</i>                | 1   | \$ 478.10   |            | X          |     |                         |
| 117  | LH rear fender glass moulding upper <i>MM</i> | 1   | \$ 31.20    |            | X          |     |                         |
| 118  | LH rear fender glass moulding side <i>MM</i>  | 1   | \$ 31.20    |            | X          |     |                         |
| 119  | LH rear fender glass moulding lower <i>MM</i> | 1   | \$ 34.70    |            | X          |     |                         |
| 120  | RH rear fender <i>RUC</i>                     | 1   | \$ 1,010.90 |            | X          |     |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1. Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/No | Part Description                               | QTY | Cost Price | List Price | Nett Price  | S/N       | Disposition By Surveyor |
|------|------------------------------------------------|-----|------------|------------|-------------|-----------|-------------------------|
| 121  | RH rear fender glass                           | 1   | <i>su</i>  | \$ 478.10  | X           |           |                         |
| 122  | RH rear fender glass moulding upper <i>nee</i> | 1   |            | \$ 31.20   |             |           |                         |
| 123  | RH rear fender glass moulding side <i>nee</i>  | 1   |            | \$ 31.20   |             |           |                         |
| 124  | RH rear fender glass moulding lower <i>nee</i> | 1   |            | \$ 34.70   |             |           |                         |
| 125  | Exhaust silencer box                           | 1   |            | \$ 588.60  | <i>su x</i> |           |                         |
| 126  | Exhaust silencer pipe inner                    | 1   |            | \$ 700.80  |             |           |                         |
| 127  | Exhaust silencer pipe gasket                   | 1   |            | \$ 33.90   |             |           |                         |
| 128  | Exhaust silencer pipe O ring                   | 1   |            |            |             |           |                         |
| 129  | Exhaust pipe mounting                          | 2   |            | \$ 34.20   |             |           |                         |
| 130  | Rear end panel buzzer                          | 1   |            | \$ 80.50   |             |           |                         |
| 131  | Rear antenna control                           | 1   |            | \$ 58.70   |             |           |                         |
| 132  | Reverse sensor <i>pd.</i>                      | 1   |            |            |             | \$ 280.00 | <i>280.00</i>           |
| 133  | LH rear rim cover <i>su</i>                    | 1   |            | \$ 150.00  | X           |           |                         |
| 134  | RH rear rim cover <i>su</i>                    | 1   |            | \$ 150.00  | X           |           |                         |
| 135  | 0                                              | 0   |            |            |             |           |                         |
| 136  | 0                                              | 0   |            |            |             |           |                         |
| 137  | 0                                              | 0   |            |            |             |           |                         |
| 138  | 0                                              | 0   |            |            |             |           |                         |
| 139  | 0                                              | 0   |            |            |             |           |                         |
| 140  | 0                                              | 0   |            |            |             |           |                         |
| 141  | 0                                              | 0   |            |            |             |           |                         |
| 142  | 0                                              | 0   |            |            |             |           |                         |
| 143  | 0                                              | 0   |            |            |             |           |                         |
| 144  | 0                                              | 0   |            |            |             |           |                         |
| 145  | 0                                              | 0   |            |            |             |           |                         |
| 146  | 0                                              | 0   |            |            |             |           |                         |
| 147  | 0                                              | 0   |            |            |             |           |                         |
| 148  | 0                                              | 0   |            |            |             |           |                         |
| 149  | 0                                              | 0   |            |            |             |           |                         |
| 150  | 0                                              | 0   |            |            |             |           |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spark Car Care**  
**ComfortDelGro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

**Labour**

Vehicle No. : SLG9246U Case Owner : Andrew  
 Make & Model : ONDA SHUTTLE HYB 1.5 A Year of Manufacture : 2016

| S/No | Labour Description                                                                                                                                    | Esimated Price | Adjusted Price |
|------|-------------------------------------------------------------------------------------------------------------------------------------------------------|----------------|----------------|
| 1    | To remove and replace rear windscreen                                                                                                                 | \$ 120.00      |                |
| 2    | To remove and refit cushions and upholstery to facilitate repairs                                                                                     | \$ 280.00      | 120            |
| 3    | To transfer tailgate parts and mechanisms to new tailgate                                                                                             | \$ 250.00      | 80             |
| 4    | To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure                                                     | \$250.00       |                |
| 5    | To remove and replace air con parts, vacuum & recharge gas                                                                                            | \$120.00       | 100            |
| 6    | To remove, reinstall Hybrid Electronic Module connection and to reset and sychronization the electronic system                                        | \$ 550.00      | 240            |
| 7    | Labor charges to panel beat, repair LH front door and replace Front portion affected damages                                                          | \$ 1,440.00    | 960            |
| 8    | Labor charges to panel beat, repair and replace Rear bumper, Rear end panel, Taillamp panel LH, Taillamp panel RH, and affected areas                 | \$ 2,400.00    | 2160           |
| 9    | To check wiring functions                                                                                                                             | \$ 120.00      | 40             |
| 10   | To install reverse sensor                                                                                                                             | \$ 120.00      | 80             |
| 11   | To putty and spray paint Front bumper, Bonnet, LH front fender, RH front fender, Front support panel, LH front door, RH front door and affected areas | \$ 2,000.00    | 1250           |
|      |                                                                                                                                                       |                |                |
|      |                                                                                                                                                       |                |                |
|      |                                                                                                                                                       |                |                |

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*

Tel: 63837168 / 63837466 Fax:62844284,62815767

Andrew  
2016

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLG9246UMake & Model : HONDA SHUTTLE HYB 1.5 AYear of Manufacture : 2016Chassis No. : GP71041185Ins Company : AIG / AXA

Engine No. : \_\_\_\_\_

Excess : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Date of Accident : 29/11/2018

Time of Accident : \_\_\_\_\_

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 280.00

Total Parts Cost (Appendix A) \$ 280.00

Labour (Appendix B) \$ 10,800.00

Total Repair Cost \$ 11,080.00

Contact No

**Frt Counter Operation**

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell\_cr@sparkcarcare.com

**Workshop Operation**

63837656 - Ngo Toh Wee

**63837362 - Andrew Goh**

63838115 - William Wang

braddell\_operation@sparkcarcare.com

*Not Authorized*  
*61 Ramp 87, 1.B.1*  
*Resurvey After Paint*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : LKKSurvey conducted on : 30/11/18 at \_\_\_\_\_**Remarks By Surveyor**(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 24 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : De Date: 30/11/18

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1. Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description                                 | QTY | Cost Price | List Price | Nett Price | S/N      | Disposition By Surveyor |
|------|--------------------------------------------------|-----|------------|------------|------------|----------|-------------------------|
| 1    | Front number plate with casing <i>CMA</i>        | 1   |            |            |            | \$ 45.00 | ✓                       |
| 2    | Front bumper <i>B</i>                            | 1   |            |            |            |          | ✓                       |
| 3    | Front bumper lower grille <i>D11</i>             | 1   |            |            |            |          | ✓                       |
| 4    | Front bumper grille LH <i>D11</i>                | 1   |            |            |            |          | ✓                       |
| 5    | Front bumper grille RH <i>Sm</i>                 | 1   |            |            |            |          | X                       |
| 6    | Front bumper tow cover <i>Sm</i>                 | 1   |            |            |            |          | X                       |
| 7    | Front bumper side retainer LH <i>D11</i>         | 1   |            |            |            |          | ✓                       |
| 8    | Front bumper side retainer RH <i>D11</i>         | 1   |            |            |            |          | ✓                       |
| 9    | Front bumper clips <i>Ac</i>                     | 10  |            |            |            |          | ✓                       |
| 10   | Radiator grille <i>CMA</i>                       | 1   |            |            |            |          | ✓                       |
| 11   | Radiator grille outer chrome moulding <i>Ac</i>  | 1   |            |            |            |          | ✓                       |
| 12   | Radiator grille lower chrome moulding <i>CMA</i> | 1   |            |            |            |          | ✓                       |
| 13   | Radiator grille emblem logo H <i>m</i>           | 1   |            |            |            |          | ✓                       |
| 14   | Radiator grille base bracket                     | 1   |            |            |            |          | ✓                       |
| 15   | Radiator grille top bracket LH                   | 1   |            |            |            |          | ✓                       |
| 16   | Radiator grille top bracket RH                   | 1   |            |            |            |          | ✓                       |
| 17   | Headlamp LH <i>mg</i>                            | 1   |            |            |            |          | ✓                       |
| 18   | Headlamp RH <i>mg</i>                            | 1   |            |            |            |          | ✓                       |
| 19   | Headlamp lower bracket LH <i>D11</i>             | 1   |            |            |            |          | ✓                       |
| 20   | Headlamp lower bracket RH                        | 1   |            |            |            |          | ✓                       |
| 21   | Bonnet <i>Bu</i>                                 | 1   |            |            |            |          | ✓                       |
| 22   | Bonnet hinge LH <i>D11</i>                       | 1   |            |            |            |          | ✓                       |
| 23   | Bonnet hinge RH <i>D11</i>                       | 1   |            |            |            |          | ✓                       |
| 24   | Bonnet lock <i>B</i>                             | 1   |            |            |            |          | ✓                       |
| 25   | Bonnet lock cable                                | 1   |            |            |            |          | ✓                       |
| 26   | Bonnet insulator                                 | 1   |            |            |            |          | ✓                       |
| 27   | Bonnet rubber seal LH                            | 1   |            |            |            |          | ✓                       |
| 28   | Bonnet rubber seal RH <i>Sm</i>                  | 1   |            |            |            |          | X                       |
| 29   | LH front fender <i>Bu</i>                        | 1   |            |            |            |          | ✓                       |
| 30   | LH front fender inner shield                     | 1   |            |            |            |          | ✓                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1. Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/N | Part Description                             | QTY | Cost Price | List Price | Nett Price | S/N      | Disposition By Surveyor |
|-----|----------------------------------------------|-----|------------|------------|------------|----------|-------------------------|
| 31  | LH front fender inner shield clips <i>M</i>  | 1   |            |            |            |          | ✓                       |
| 32  | LH front fender emblem HYBRID <i>M</i>       | 0   |            |            |            |          | ✓                       |
| 33  | RH front fender <i>Bu</i>                    | 1   |            |            |            |          | ✓                       |
| 34  | RH front fender inner shield <i>Sn</i>       | 1   |            |            |            |          | X                       |
| 35  | RH front fender inner shield clips <i>nn</i> | 1   |            |            |            |          | X                       |
| 36  | RH front fender emblem HYBRID <i>M</i>       | 0   |            |            |            |          | ✓                       |
| 37  | Front bumper reinforcement <i>B</i>          | 1   |            |            |            |          | ✓                       |
| 38  | Front support panel (complete) <i>Bu</i>     | 1   |            |            |            |          | ✓                       |
| 39  | Front support panel top cover <i>D11</i>     | 1   |            |            |            |          | ✓                       |
| 40  | Front support panel top cover clips <i>M</i> | 1   |            |            |            |          | ✓                       |
| 41  | Front bumper bracket LH <i>B</i>             | 0   |            |            |            |          | ✓                       |
| 42  | Front bumper bracket RH                      | 0   |            |            |            |          | ✓                       |
| 43  | Radiator <i>B</i>                            | 1   |            |            |            |          | ✓                       |
| 44  | Condenser <i>B1/Pu</i>                       | 1   |            |            |            |          | ✓                       |
| 45  | Coolant <i>M</i>                             | 1   |            |            |            |          | ✓                       |
| 46  | Fan shroud                                   | 1   |            |            |            |          | ✓                       |
| 47  | Radiator fan LH                              | 1   |            |            |            |          | ✓                       |
| 48  | Radiator fan RH                              | 1   |            |            |            |          | ✓                       |
| 49  | Radiator fan motor LH                        | 1   |            |            |            |          | ✓                       |
| 50  | Radiator fan motor RH                        | 1   |            |            |            | \$ 45.00 | ✓                       |
| 51  | Breather tube PVC                            | 1   |            |            |            |          | ✓                       |
| 52  | Rear number plate with casing <i>Red</i>     | 1   |            |            |            |          | ✓                       |
| 53  | Rear bumper <i>B</i>                         | 1   |            |            |            |          | ✓                       |
| 54  | Rear bumper side retainer LH <i>D11</i>      | 1   |            |            |            |          | ✓                       |
| 55  | Rear bumper side retainer RH <i>D11</i>      | 1   |            |            |            |          | ✓                       |
| 56  | Rear bumper clips <i>M</i>                   | 10  |            |            |            |          | ✓                       |
| 57  | Rear bumper cover LH <i>D11</i>              | 1   |            |            |            |          | ✓                       |
| 58  | Rear bumper cover RH <i>D11</i>              | 1   |            |            |            |          | ✓                       |
| 59  | Rear bumper reflector LH <i>CM</i>           | 1   |            |            |            |          | ✓                       |
| 60  | Rear bumper reflector RH <i>Sn</i>           | 1   |            |            |            |          | X                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1.0 Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/No | Part Description                        | QTY | Cost Price | List Price | Nett Price | S/N       | Disposition By Surveyor |
|------|-----------------------------------------|-----|------------|------------|------------|-----------|-------------------------|
| 61   | Rear bumper tow cover <i>Mr</i>         | 1   |            |            |            |           | ✓                       |
| 62   | Rear bumper sponge LH                   | 1   |            |            |            |           | ✓                       |
| 63   | Rear bumper sponge RH                   | 1   |            |            |            |           | ✓                       |
| 64   | Tailgate <i>Mr</i>                      | 1   |            |            |            |           | ✓                       |
| 65   | Tailgate glass <i>Shattered</i>         | 1   |            |            |            |           | ✓                       |
| 66   | Tailgate glass moulding upper <i>Mr</i> | 1   |            |            |            |           | ✓                       |
| 67   | Tailgate glass moulding lower <i>Mr</i> | 1   |            |            |            |           | ✓                       |
| 68   | Tailgate glass moulding LH <i>Mr</i>    | 1   |            |            |            | \$ 40.00  | ✓                       |
| 69   | Tailgate glass moulding RH <i>Mr</i>    | 1   |            |            |            | \$ 30.00  | ✓                       |
| 70   | Tailgate glass sealant <i>Mr</i>        | 1   |            |            |            | \$ 120.00 | <i>Posn</i>             |
| 71   | Tailgate glass inner seal <i>Mr</i>     | 1   |            |            |            |           | ✓                       |
| 72   | Private Hire Sticker <i>Mr</i>          | 1   |            |            |            |           | ✓                       |
| 73   | Tailgate weatherstrip <i>Odior</i>      | 1   |            |            |            |           | ✓                       |
| 74   | Tailgate pocket handle                  | 1   |            |            |            |           | ✓                       |
| 75   | Tailgate striker                        | 1   |            |            |            |           | ✓                       |
| 76   | Tailgate lock <i>Mr</i>                 | 1   |            |            |            |           | ✓                       |
| 77   | Tailgate chrome moulding <i>CM</i>      | 1   |            |            |            |           | ✓                       |
| 78   | Tailgate emblem HYBRID <i>Mr</i>        | 1   |            |            |            |           | ✓                       |
| 79   | Tailgate emblem SHUTTLE <i>Mr</i>       | 1   |            |            |            |           | ✓                       |
| 80   | Tailgate emblem logo H <i>Mr</i>        | 1   |            |            |            |           | ✓                       |
| 81   | Tailgate lamp LH <i>CM</i>              | 1   |            |            |            |           | ✓                       |
| 82   | Tailgate lamp RH <i>Mr CM</i>           | 1   |            |            |            |           | ✓                       |
| 83   | Tailgate inner trim board <i>Mr</i>     | 1   |            |            |            |           | ✓                       |
| 84   | Tailgate wiper arm                      | 1   |            |            |            |           | ✓                       |
| 85   | Tailgate wiper arm cover                | 1   |            |            |            |           | ✓                       |
| 86   | Tailgate wiper motor                    | 1   |            |            |            |           | ✓                       |
| 87   | Tailgate strut LH                       | 1   |            |            |            |           | ✓                       |
| 88   | Tailgate strut RH                       | 1   |            |            |            |           | ✓                       |
| 89   | Tailgate hinge LH                       | 1   |            |            |            |           | ✓                       |
| 90   | Tailgate hinge RH                       | 1   |            |            |            |           | ✓                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1. Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/No | Part Description                      | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|---------------------------------------|-----|------------|------------|------------|-----|-------------------------|
| 91   | Tailgate stopper                      | 2   |            |            |            |     | ?                       |
| 92   | Taillamp LH CM                        | 1   |            |            |            |     | —                       |
| 93   | Taillamp RH CM                        | 1   |            |            |            |     | —                       |
| 94   | Taillamp clips M                      | 4   |            |            |            |     | —                       |
| 95   | Taillamp panel LH                     | 1   |            |            |            |     | ?                       |
| 96   | Taillamp panel RH                     | 1   |            |            |            |     | ?                       |
| 97   | Rear end panel B                      | 1   |            |            |            |     | —                       |
| 98   | Rear end panel top garnish RJ         | 1   |            |            |            |     | —                       |
| 99   | Rear cargo top cover                  | 1   |            |            |            |     | ?                       |
| 100  | Rear cargo tray                       | 1   |            |            |            |     | ?                       |
| 101  | Rear cargo tray end cover             | 1   |            |            |            |     | ?                       |
| 102  | Rear tools tray                       | 1   |            |            |            |     | ?                       |
| 103  | Rear end floor panel B1/B2            | 1   |            |            |            |     | ✓                       |
| 104  | LH rear fender inner trim             | 1   |            |            |            |     | ?                       |
| 105  | LH rear fender inner trim top board   | 1   |            |            |            |     | ?                       |
| 106  | RH rear fender inner trim             | 1   |            |            |            |     | ?                       |
| 107  | RH rear fender inner trim top board   | 1   |            |            |            |     | ?                       |
| 108  | LH rear fender air vent               | 1   |            |            |            |     | ?                       |
| 109  | LH rear fender air vent top bracket   | 1   |            |            |            |     | ?                       |
| 110  | RH rear fender air vent               | 1   |            |            |            |     | ?                       |
| 111  | RH rear fender air vent top bracket   | 1   |            |            |            |     | ?                       |
| 112  | Duct assy IPU                         | 1   |            |            |            |     | ?                       |
| 113  | Tube joint comm IPU                   | 1   |            |            |            |     | ?                       |
| 114  | Tube assy IPU                         | 1   |            |            |            |     | ?                       |
| 115  | LH rear fender R                      | 1   |            |            |            |     | X                       |
| 116  | LH rear fender glass M                | 1   |            |            |            |     | X                       |
| 117  | LH rear fender glass moulding upper M | 1   |            |            |            |     | X                       |
| 118  | LH rear fender glass moulding side M  | 1   |            |            |            |     | X                       |
| 119  | LH rear fender glass moulding lower M | 1   |            |            |            |     | X                       |
| 120  | RH rear fender B                      | 1   |            |            |            |     | ✓                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**Spark Car Care**  
**ComfortDelGro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

**Spare Parts**

Vehicle No : SLG9246U Case Owner : Andrew

Make & Model : HONDA SHUTTLE HYB 1.: Year Manufacture : 2016

Chassis No : GP71041185 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

| S/No | Part Description                              | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|------|-----------------------------------------------|-----|------------|------------|------------|-----|-------------------------|
| 121  | RH rear fender glass                          | 1   |            |            |            |     | ?                       |
| 122  | RH rear fender glass moulding upper <i>me</i> | 1   |            |            |            |     | —                       |
| 123  | RH rear fender glass moulding side <i>me</i>  | 1   |            |            |            |     | —                       |
| 124  | RH rear fender glass moulding lower <i>me</i> | 1   |            |            |            |     | —                       |
| 125  | Exhaust silencer box                          | 1   |            |            |            |     | ?                       |
| 126  | Exhaust silencer pipe inner                   | 1   |            |            |            |     | ?                       |
| 127  | Exhaust silencer pipe gasket                  | 1   |            |            |            |     | ?                       |
| 128  | Exhaust silencer pipe O ring                  | 1   |            |            |            |     | ?                       |
| 129  | Exhaust pipe mounting                         | 2   |            |            |            |     | ?                       |
| 130  | Rear end panel buzzer                         | 1   |            |            |            |     | ?                       |
| 131  | Rear antenna control                          | 1   |            |            |            |     | ?                       |
| 132  | Reverse sensor <i>Not</i>                     | 1   |            |            |            |     | ✓                       |
| 133  | LH rear rim cover <i>Sm</i>                   | 1   |            |            |            |     | X                       |
| 134  | RH rear rim cover <i>Sm</i>                   | 1   |            |            |            |     | X                       |
| 135  | 0                                             | 0   |            |            |            |     |                         |
| 136  | 0                                             | 0   |            |            |            |     |                         |
| 137  | 0                                             | 0   |            |            |            |     |                         |
| 138  | 0                                             | 0   |            |            |            |     |                         |
| 139  | 0                                             | 0   |            |            |            |     |                         |
| 140  | 0                                             | 0   |            |            |            |     |                         |
| 141  | 0                                             | 0   |            |            |            |     |                         |
| 142  | 0                                             | 0   |            |            |            |     |                         |
| 143  | 0                                             | 0   |            |            |            |     |                         |
| 144  | 0                                             | 0   |            |            |            |     |                         |
| 145  | 0                                             | 0   |            |            |            |     |                         |
| 146  | 0                                             | 0   |            |            |            |     |                         |
| 147  | 0                                             | 0   |            |            |            |     |                         |
| 148  | 0                                             | 0   |            |            |            |     |                         |
| 149  | 0                                             | 0   |            |            |            |     |                         |
| 150  | 0                                             | 0   |            |            |            |     |                         |

*Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.*

## Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

### Labour

Vehicle No. : SLG9246U Case Owner : Andrew  
 Make & Model : ONDA SHUTTLE HYB 1.5 A Year of Manufacture : 2016

| S/No | Labour Description                                                                                                                                    | Estimated Price | Adjusted Price           |
|------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|--------------------------|
| 1    | To remove and replace rear windscreen                                                                                                                 | \$ 120.00       | ✓                        |
| 2    | To remove and refit cushions and upholstery to facilitate repairs                                                                                     | \$ 280.00       | 1201                     |
| 3    | To transfer tailgate parts and mechanisms to new tailgate                                                                                             | \$ 250.00       | 801                      |
| 4    | To mount vehicle on black hawk floor bench in order to re-align chassis members or body structure                                                     | \$250.00        | ✓                        |
| 5    | To remove and replace air con parts, vacuum & recharge gas                                                                                            | \$120.00        | 1001                     |
| 6    | To remove, reinstall Hybrid Electronic Module connection and to reset and synchronization the electronic system                                       | \$ 550.00       | 2401                     |
| 7    | Labor charges to panel beat, repair LH front door and replace Front portion affected damages                                                          | \$ 1,440.00     | 9601                     |
| 8    | Labor charges to panel beat, repair and replace Rear bumper, Rear end panel, Taillamp panel LH, Taillamp panel RH, and affected areas                 | \$ 2,400.00     | 21601                    |
| 9    | To check wiring functions                                                                                                                             | \$ 120.00       | 401                      |
| 10   | To install reverse sensor                                                                                                                             | \$ 120.00       | 801                      |
| 11   | To putty and spray paint Front bumper, Bonnet, LH front fender, RH front fender, Front support panel, LH front door, RH front door and affected areas | \$ 2,000.00     | <del>9601</del><br>12501 |
|      |                                                                                                                                                       |                 |                          |
|      |                                                                                                                                                       |                 |                          |
|      |                                                                                                                                                       |                 |                          |

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*

205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62844284, 62815767

|              |                                 |                     |                 |
|--------------|---------------------------------|---------------------|-----------------|
| Vehicle No.  | : <u>SLG9246U</u>               | Case Owner          | : <u>Andrew</u> |
| Make & Model | : <u>ONDA SHUTTLE HYB 1.5 A</u> | Year of Manufacture | : <u>2016</u>   |

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |  |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| <p><b>LKK Auto Consultants</b> hence <b>notify the Repairer of the following:</b></p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• <u>Supplementary item(s) must be resurveyed and</u><br/>is subject to final approval from Insurance Company</li> </ul> |  |
| <b>Acknowledged by Repairer</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |  |
| <b>Signature:</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |  |
| <b>Date:</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |  |

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*



## Service Request Details

Claim

S8M014UP

Reference

None 

Loss Date

November 29, 2018

Request Date

November 30, 2018

Due Date

December 7, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

30-11-2018 @ 10:45am  
Andrew veh in  
Kenneth

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLG9246U

Make

TPVD HONDA

Model

SHUTTLE HYBRID 1.5 A

Service Address

---

...

Primary Contact/Insured

---

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

---

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)

---

[New Message](#)

**Catherine Chong (LKK Auto)**

---

**From:** CDGE Braddell Private Cars Crash Repair Operation  
<braddell\_operation@sparkcarcare.com>  
**Sent:** Thursday, 29 November, 2018 5:16 PM  
**To:** LOW Garnet; NGUETTE Kadi; SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** Denis Teo Chin Chye; CDGE Braddell Private Cars Crash Repair Operation  
**Subject:** LCR \_ SLG9246U claim against SHC5448Z \_ DOA 29.11.2018 \_ (AIG / AXA)  
**Attachments:** SLG9246U \_ SAS.pdf; SLG9246U \_ Estimate.pdf  
  
**Categories:** Santosh

Dear Sir / Madam

Please advice on the liability of the accident.

And to arrange for survey the car at CDGE, Braddell.

Car in workshop ready for survey.

Andrew

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)