



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打噴漆，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.
Date: 03/12/2018

EQ Insurance Company Limited
22 Gemmill Lane, Singapore 069257
Tel: (65) 6223 9433
Fax: (65) 6224 3903
DDI: (65) 6496 9032

TPEQ

Xiao Tony

- To display the repaired parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Dear Sir / Madam

Estimate Cost repair Bill To Isuzu NHR 85 Lorry YM 7054 J & XD 6311 H on 28/11/2018/2018 @15:30 PM.

To Supply :-

1pc	Front Panel	Distorted	\$	660.00	✓
1pc	Front "ISUZU" Plate	3pc	\$	105.00	✓
1pc	Front "NHR" Sticker		\$	35.00	✓
1pc	Front Side Panel Fender RH	cracked	\$	255.00	✓
1pc	Front Side Mirror Cover	cracked	\$	55.00	✓
1pc	Front Grille	cracked	\$	376.00	✓
2pcs	Head Lamp LH & RH	2pc cracked, LH cracked	\$	708.00	✓
2pcs	Side Lamp LH & RH	2pc cracked, LH NHR	\$	342.00	✓
1pc	Front Windscreen Top Moulding	new	\$	103.00	✓
1pc	Front Bumper	Distorted	\$	597.00	✓
1pc	Front Number Plate	Best	\$	45.00	✓
1pc	Front wiper garnish	new	\$	395.00	✓
1pc	Rear Boot Cover	Distorted	\$	1,480.00	✓
1pc	Rear Boot Cover "ISUZU" Sticker	3pc	\$	127.00	✓
1pc	Rear Boot Cover "60km/h" Sticker		\$	45.00	✓
1pc	Rear Boot Cover "6pax" Sticker		\$	45.00	✓
2pcs	Rear Lamp LH & RH	2pc x \$197	\$	394.00	✓
1pc	Rear Number Plate Lamp	missing Replaced	\$	257.00	✓
1pc	Rear Bumper	Best	\$	780.00	✓
1pc	Rear Boot Member	Distorted	\$	1,180.00	✓
1pc	Spare Tyre Bracket	new	\$	380.00	✓
1pc	Rear Door Aluminium Panel	Best	\$	900.00	✓
1pc	Floor Aluminium Panel	Best	\$	1,580.00	✓
1pc	Rear Number Plate Lamp	cracked	\$	45.00	✓
1pc	ERP Sticker	for new	\$	45.00	✓
1pc	Windscreen Sealant	new	\$	75.00	✓

To dismantle and replace of the accident damaged parts, including heat/weld, cut-off, knocking, straighten, repair, adjust and reshape of same.

To putty, apply primer & spray paint on the affected portion.

To check wiring functions.

To remove dashboard

labour charge to remove windscreen.

2800

Adrian hwy
1/5 03/12/18
10 Days

7.5K

total 9417.60
1/5 7.5K