

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/1382/2018/NK  
**Date** : 03-Dec-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**

Your insured vehicle is : **SCQ 929 X**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Joseph Leung Wah Chau  
**Address** : Blk 47 Jalan Tiga  
# 15-38  
Singapore 390047  
**Telephone** : (HP) 96372601  
**Type of Claim** : Third Party Claim  
**Policy No.** :  
**Vehicle No** : **SGJ 433 Z**  
**Model Code** : AUDI A3 1.4 SEDAN TFSI  
**Model / Year** : Mar-15  
**Engine No** : CZC 232941  
**Chassis No** : WAUZZZ8V3F1093033  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 01-Dec-18  
**Place of Accident** : Jurong Town Hall Road Towards AYE

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGJ 433 Z

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid.check function.	S/N	\$ 280.00	/
2	To dismantle and renew rear bumper. Reorganise crash managements components. Reinstall all parts removed.		\$ 900.00	500
3	To respray rear bumper		\$ 800.00	550
4	To carry out diagnostic check.	S/N	\$ 192.00	/
<b>TOTAL LABOUR CHARGES - FRONT</b>			<b>: \$ 2,172.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No.SGJ 433 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / DC	\$	1,619.00
2	REAR BUMPER FIXING SETS / NBC	\$	166.00
3	REAR BUMPER GUIDE SECTION-LH/RH X	2 \$	28.00
4	REAR BUMPER LOCKING MECHANISM X	2 \$	50.00
5	REAR LIGHT REFLECTOR-LH/RH X	2 \$	52.00
6	REAR SPOILER-DOUBLE PIPE X	\$	206.00
7	REAR REINFORCEMENT ?	\$	501.00
8	REAR BUMPER BRACKET LH / RH X	2 \$	22.00
9	REAR BUMPER GUIDE SECTION-LH/RH X	2 \$	114.00
10	REAR BUMPER SENSOR INNER/ OUTER X	2 \$	421.00
11	REAR BUMPER SENSOR SEAL RING / NBC	4 \$	14.00
12	SUNDRIES ?	\$	300.00
<b>TOTAL SPARE PARTS CHARGES</b>		<b>:</b>	<b>\$ 3,493.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,172.00</b>
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 5,665.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Gao Qiy  
Surveyed Date :  
Authorised Date : 07/12/18  
Excess Cost :  
Liability : 3 Days -  
Remarks : before paint photos

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant