

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1382/2018/NK
Date : 03-Dec-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle is : **SCQ 929 X**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Joseph Leung Wah Chau
Address : Blk 47 Jalan Tiga
15-38
Singapore 390047
Telephone : (HP) 96372601
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SGJ 433 Z**
Model Code : AUDI A3 1.4 SEDAN TFSI
Model / Year : Mar-15
Engine No : CZC 232941
Chassis No : WAUZZZ8V3F1093033
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 01-Dec-18
Place of Accident : Jurong Town Hall Road Towards AYE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGJ 433 Z

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and reinstall rear parking aid.check function.	S/N	\$ 280.00	
2	To dismantle and renew rear bumper. Reorganise crash managements components. Reinstall all parts removed.		\$ 900.00	
3	To respray rear bumper		\$ 800.00	
4	To carry out diagnostic check.	S/N	\$ 192.00	
TOTAL LABOUR CHARGES - FRONT			: \$ 2,172.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGJ 433 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$	1,619.00
2	REAR BUMPER FIXING SETS	\$	166.00
3	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	28.00
4	REAR BUMPER LOCKING MECHANISM	2 \$	50.00
5	REAR LIGHT REFLECTOR-LH/RH	2 \$	52.00
6	REAR SPOILER-DOUBLE PIPE	\$	206.00
7	REAR REINFORCEMENT	\$	501.00
8	REAR BUMPER BRACKET LH / RH	2 \$	22.00
9	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	114.00
10	REAR BUMPER SENSOR INNER/ OUTER	2 \$	421.00
11	REAR BUMPER SENSOR SEAL RING	4 \$	14.00
12	SUNDRIES	\$	300.00
	TOTAL SPARE PARTS CHARGES	:	\$ 3,493.00
	TOTAL LABOUR CHARGES	:	\$ 2,172.00
	GRAND TOTAL	:	\$ 5,665.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant