

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBG3802Y  
 Accident Date : 19-Nov-2018

No. : 05889

Date : 21-Nov-2018

Our Ref : 218194 (AXA) / CHAN

PAGE : 1

TAN BEE KIM  
 43 JALAN LEMBAH THOMSON  
 Singapore 577513

*Not Authorized  
 Putty B4 paint*

ESTIMATED COST OF REPAIR FOR MAZDA 3 HATCHBACK SGE6662R  
 =====

1 pc Rear bumper fascia		<i>Bu/nd</i> 1,080.10	✓
1 pc Rear bumper reinforcement		587.30	✓
1 pc Rear end panel		<i>n</i> 590.10	X
1 pc Front bumper fascia		955.10	✓
1 pc Front bumper reinforcement		<i>n</i> 464.40	X
1 pc Radiator grille		129.60	✓
2 pcs Radiator grille side chrome	@ S\$186.00	372.00	✓
1 pc Radiator grille logo		45.20	✓
6 pcs Front bumper top rivet	@ S\$ 9.00	54.00	✓
		-----	
		4,277.80	
	Less 20% :	855.56	
		-----	
			3,422.24

To rewire damaged parts and refocus headlamp beam.		20.00	<i>15/</i>
To remove roof lining, front and rear seats, trim board and carpet		<i>na</i> 120.00	X
To apply undersealing		<i>na</i> 60.00	X
To putty and spray replaced parts		1,000.00	<i>660/</i>
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts		1,200.00	<i>550/</i>
		-----	
	Total :	S\$ 5,822.24	
		=====	

Singapore Dollars Five Thousand Eight Hundred and Twenty Two and Cents Twenty Four Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_