

22/03/2002

ASS. REC. BY:

REF: CS/FCU8021713 / Krbn2

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

WS Karen Tan

of

FCL

Date/Time: 03/12/2018 4:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SMF 3269L

Insured:

SHC 1426M

at Workshop m/s

Cheng Hwe

Tel:

67556142

of

Bik YONG Yishun Ind Park A #07-374

Policy No:

Claim No:

D18008540MFSH

Sum Insured:

Excess:

D.O.A. 01-12-2018

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS '03'

Date/Time: 03-12-2018 4:30pm

Person Contacted:

Jure

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMF 3269L - X

SHC 1426M - CS/FCU8021713 / Rlgdbn2

D.O.A. 23082018

4/12/18

Email preli revised to FCL

ASS. REC. BY:

REF:

P021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: R83k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8-14 days Res.: Yes or NoLum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMF 32092 Yr Regn: 11, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle Wagon C.C. 1496Colour: N. Grey A/C: Insured / Std / NI / NASp. Reading: 11177 T/Radio: Insured / Std / NI / NAEng/No: _____ C/No: GP7 1217045Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 185/60R15
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 1/12/18

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 3/12/18Des. of Damages: Frt Rear O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12 File pass to Catherine

12/3/19 8 6305.56 Customer Edward (Red 2535.04, 29%)

RECEIVED 12 MAR 2019

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 12/3 - typist

Days Of Repair: 8Resurvey No. of Trip: 3Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + P.S. \$

Fees

Others

TOTAL

Report Format:

CWS

Lump Sum / I.B.I. (\$)

6305.56

160

50

50 + 50 + 50

35

395



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18008540MFSH

Our ref: CS/FCI18021713/Kvb

Date : 4/12/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMF 3269L


We thank for your instruction on 3/12/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/12/2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$8,759.60
Revised Estimate Amount	: S\$4,628.16
"Check" Items Amount	: S\$3,014.96
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	03-12-2018	Our Ref No. D18008540MFSH
Accident Date	01-12-2018	Claim Type. Third Party
Insured Vehicle	SHC1426M	Third Party Vehicle. SMF3269L
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	EFEEDA	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 4 December 2018 2:15 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008540MFSH/1, SMF 3269L
Attachments: SMF 3269L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SMF 3269L
Date of survey: 3/12/2018
Number of days : 8-11 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 3 December 2018 4:34 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008540MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 3 December, 2018 4:14 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008540MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0750E
Vehicle Details	
Vehicle No.:	SMF3269L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Dec 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	LEB6560717
Chassis No.:	GP71217045
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,766.00
Original Registration Date:	01 Nov 2018
First Registration Date:	01 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$12,473.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2028
PARF Rebate Amount:	\$9,354.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$33,420.00
COE Rebate Amount:	\$26,736.00
Total Rebate Amount:	\$36,090.00

The information contained herein is correct as at 01 Dec 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMF3269L
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 01/12/2018

TP Veh Reg No: SHC1426M

Estimate No: ES1891361/YISHUN

Date: 01 Dec 2018

Policy No: 5105159121

Veh Reg No: SMF3269L

Make/Model: HONDA SHUTTLE
HYBRID 1.5 AUTO

Chassis No: GP71217045

Engine No: LEB6560717

Reg. Date: 01/11/2018

Not Notion

Resurvey by painting

8-10 days

Estimate Repair Cost to Vehicle No :SMF3269L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	1,150.60	1 PC	1,150.60	✓
2 REAR BUMPER RH REFLECTOR	45.00	1 PC	45.00	X
3 REAR BUMPER RH REFLECTOR GARNISH	45.90	1 PC	45.90	X
4 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
5 REAR SPARE TYRE COMPARTMENT	986.10	1 PC	986.10	X
6 REAR TAILGATE	1,193.20	1 PC	1,193.20	✓
7 TAILGATE OUTER MOULDING	383.10	1 PC	383.10	X
8 TAILGATE LOGO	38.10	1 PC	38.10	✓
9 TAILGATE EMBLEM (SHUTTLE)	55.30	1 PC	55.30	✓
10 TAILGATE EMBLEM (HYBRID)	80.10	1 PC	80.10	✓
11 TAILGATE INNER LOCK	157.50	1 PC	157.50	✓
12 TAILGATE INNER RUBBER	186.50	1 PC	186.50	✓
13 TAILGATE INNER BOARD	330.30	1 PC	330.30	✓
14 TAILGATE INNER OPEN CAP	39.80	1 PC	39.80	✓
15 REAR WINDSCREEN GLASS MOULDING	161.20	1 SET	161.20	✓
16 REAR PANEL	560.80	1 PC	560.80	✓
17 REAR PANEL TOP INNER GARNISH	155.50	1 PC	155.50	✓
18 REAR PANEL INNER SIDE GARNISH	88.10	1 PC	88.10	X
19 REAR TOOL BOX	295.60	1 PC	295.60	✓
20 REAR SPARE TYRE TOP BOARD	655.00	1 PC	655.00	X 320.20 ✓
21 REAR BUMPER TOW COVER	20.10	1 PC	20.10	✓
22 REAR SMART KEY SENSOR	85.80	1 PC	85.80	X
			6,737.00	
			Less 20%	1,347.40
				5,389.60

RH Tailamp panel

#101-25 B1 ✓

Special Net

- 23 REVERSE SENSOR 200.00 1 SET CMA 200.00 ✓
24 REAR WINDSCREEN GLASS SEALANT 40.00 1 PC Ne 40.00 ✓

240.00 240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 01/12/2018

TP Veh Reg No: SHC1426M

Estimate No: ES1891361/YISHUN

Date: 01 Dec 2018

Policy No: 5105159121

Veh Reg No: SMF3269L

Make/Model: HONDA SHUTTLE
HYBRID 1.5 AUTO

Chassis No: GP71217045

Engine No: LEB6560717

Reg. Date: 01/11/2018

Estimate Repair Cost to Vehicle No :SMF3269L

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
25 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
26 REMOVE & REFIX RR BUMPER ASSY,REFLECTORS,TAILLAMPS,TAILGATE,RR WIPER ASSY,RR REFLECTORS,SPOILER,CUT,WELD & RENEW RR CENTRE PANEL,RR SPARE ATYRE COMPARTMENT,KNOCK & REPAIR TAILLAMP PANLE,RR COMPARTMENT LOWER MEMBERS,REAR FENDERS & REALIGN THE SAME	1,380.00	1 LA	1,380.00	9501
27 REMOVE & REFIX SEAT,CARPET,GARNISH,TOP ROOF LINING,ETC	120.00	1 LA	120.00	100
28 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
29 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR FENDERS,TAILGATE,REAR PANEL,REAR BUMPER & REAR AFFECTED AREAS	1,100.00	1 LA	1,100.00	1000
30 REMOVE & REFIX REAR UNDER CARRIAGE,EXHAUST PIPE & CONDUCT COMPUTERIZED WHEEL ALIGNMENT & CHECK LEAKING	280.00	1 LA	280.00	X
31 RUSTPROOFING	90.00	1 LA	90.00	60
	8840.60		3,130.00	3,130.00
			Total	S\$ 8,759.60
			Add GST @ 7%	613.17
			Total Amount Payable	S\$ 9,372.77

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18021713/Kvbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-03-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1426M	Veh. Inspected	SMF 3269L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008540MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	03/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP71217045	Colour	METALLIC GREY	
Odometer	11177	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	9 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2018	Inspection Date	03/12/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 3269L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT	1,150.60	1,150.60
1	REAR BUMPER RH REFLECTOR	SERVICEABLE	45.00	-
1	REAR BUMPER RH REFLECTOR GARNISH	SERVICEABLE	45.90	-
6	REAR BUMPER CLIPS @\$3.90	NECESSARY	23.40	23.40
1	REAR SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	986.10	-
1	REAR TAILGATE	BENT	1,193.20	1,193.20
1	TAILGATE OUTER MOULDING	SERVICEABLE	383.10	-
1	TAILGATE LOGO	NECESSARY	38.10	38.10
1	TAILGATE EMBLEM (SHUTTLE)	NECESSARY	55.30	55.30
1	TAILGATE EMBLEM (HYBRID)	NECESSARY	80.10	80.10
1	TAILGATE INNER LOCK	DENTED	157.50	157.50
1	TAILGATE INNER RUBBER	DENTED / DISTORTED	186.50	186.50
1	TAILGATE INNER BOARD	BUCKLED	330.30	330.30
1	TAILGATE INNER OPEN CAP	DENTED	39.80	39.80
1	SET REAR WINDSCREEN GLASS MOULDING	NECESSARY	161.20	161.20
1	REAR PANEL	BENT	560.80	560.80
1	REAR PANEL TOP INNER GARNISH	DENTED	155.50	155.50
1	REAR PANEL INNER SIDE GARNISH	SERVICEABLE	88.10	-
1	REAR TOOL BOX	DEFORMED	295.60	295.60
1	REAR BUMPER TOW COVER	DENTED	20.10	20.10
1	REAR SMART KEY SENSOR	SERVICEABLE	85.80	-
1	RH TAILLAMP PANEL	BENT	101.25	101.25
1	REAR SPARE TYRE TOP BOARD	DENTED / DISTORTED	655.00	320.20
	LESS 20% DISCOUNT		-1,367.65	-973.89
			5,470.60	3,895.56
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSOR (SN)	CRACKED	200.00	200.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
			240.00	240.00
	LABOUR			
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		100.00	100.00
	REMOVE & REFIX RR BUMPER ASSY, REFLECTORS, TAILLAMPS, TAILGATE, RR WIPER ASSY, RR REFLECTORS, SPOILER, CUT, WELD & RENEW RR CENTRE PANEL, RR SPARE TYRE COMPARTMENT, KNOCK & REPAIR TAILLAMP PANEL, RR COMPARTMENT LOWER MEMBERS, REAR FENDERS & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE COMPARTMENT.		1,380.00	950.00
	REMOVE & REFIX SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC.		120.00	100.00
	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM.		60.00	60.00
	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, TAILGATE, REAR PANEL, REAR BUMPER & REAR AFFECTED AREAS.		1,100.00	900.00
	REMOVE & REFIX REAR UNDER CARRIAGE, EXHAUST PIPE & CONDUCT COMPUTERIZED WHEEL ALIGNMENT & CHECK LEAKING.	NOT NECESSARY	280.00	-
	RUSTPROOFING.		90.00	60.00
			3,130.00	2,170.00
GRAND TOTAL			8,840.60	6,305.56
RECOMMENDED COST OF REPAIRS				6,305.56

Report Ref No. CS/FCI18021713/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.