

ASS. REC. BY:

REF: CS/SM018021715/Ugbn2

Special Instruction:

Survivor:

merimen

ASSIGNMENT (Office)

From (Person):

Agnes Chan

of

SMO

Date/Time:

13/12/2018 4:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKL 2956K

Insured:

GBE 97350

at Workshop m/s

Fastech Auto

Tel:

67465405

of

Blk 1 Kaki Bukit Ave 6 #01-46

Policy No:

D18MTPEVE00490

Claim No:

CMTD1805313

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03.12.2018

CA / REV / REP. / REV 24 HRS WP

04.12.2018

H.O.D. Endorsement:

Date/Time:

03.12.2018 4:55pm

Person Contacted:

Nancy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKL 2956K x

GBE 97350 x

05/12/18 @ 4:40pm informed Shawn Ngo, we are pending estimate from repairer.
 04/11/19 @ 11:52am revised to Agnes Chan via Merimen.

REF: 8MO

ASSIGNMENT

From:

Date: 4/12/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKL 2956K

at Workshop m/s

Fastech Auto

of

Ikaki Bkt Ave 6 #01-46

Insured:

Policy No.

6BC9735D

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

65%

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

lup

LTA-3688

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKL 2956K

Yr Regn:

10 / 13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Volkswagen

Touran

c.c.

1390

Colour:

white

A/C:

Insured / Std / NI / NA

Sp Reading:

66411

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WV6222172DW041007

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Bin / STD A/Rim or

Tyre Size:

F:

205/55-216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/12/18

D.O.I.

4/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/1/19

have h/19 4hrs. 10 min. 27/11/18 11311
4/5 11.000 confirmed with Alan.
(red 6 71467.20, 66%)

RECEIVED 04 JAN 2019

Date/Time: File Pass to?



: Preli. Report

11/04/19 typist



: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation

450

) S + RS \$

10

) Photos

) Others

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format: MER-7P

Lump Sum / I.D.I. (\$) 11000

TOTAL

460

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 04 Jan 2019

Preliminary Advice

Insured Vehicle No	: GBE9735D	Accident Date	: 03/12/2018
TP Vehicle No	: SKL2956K	Assignment Date	: 03/12/2018
Make	: VOLKSWAGEN TOURAN (A)	Est. Duration of Repair	: 6
Date of Inspection	: 04/12/2018		
Inspection At	: FASTECH AUTO		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	32,469.90
Revised Amount	:S\$	14,326.14
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,326.14
Lump Sum Repair	:S\$	11,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Dec 2018		03 Dec 2018 16:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	SENG HUP SECOND HAND AUTO PARTS, Co. Reg. No.: 29250100E								
Main Claimant:	HENDRA CAKRA								
Vehicle Reg. No.:	SKL2956K	Date of Loss:	03/12/2018 00:00 - :59						
Claim Type:	TP / CMTD1805313	Policy/Cover Note No.:	D18MTPCVE001490 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBE9735D	Policy No. (Claimant):							
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/12/2018]								
Adj Asg. Remarks:	- PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 5 December 2018 4:40 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SKL 2956K (YOUR REF: CMTD1805313)

This mail is associated with :

***SKL2956K (CMTD1805313)**

[GBE9735D]

TP

HENDRA CAKRA

Dec 3 2018 12:00AM

[SENG HUP SECOND HAND AUTO PARTS]

Fastech Auto Pte Ltd

Dear Shawn,

Please be informed that we have inspected the vehicle SKL 2956K on 03/12/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



FREE **Car Search REWARDS MEMBERSHIPS**
Get at least **10% DISCOUNT** on car services from repair, warranty & servicing, grooming to car accessories [Learn more](#)



Volkswagen Touran

Price Range

Depreciation

2013

Vehicle Type



Submit

Advanced Search

Home » Used Cars » SD Motors Pte Ltd » Volkswagen Touran Sport 1.4A TSI

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Plan Your Next Trip

sg.hotels.com

Unlock Secret Prices on selected hotels!

OPEN

Compare

Volkswagen Touran Sport 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$63,500****Depreciation**

\$11,690 /yr

View models with similar depreciation

Reg Date

18-Apr-2013

(4yrs 4mths 13days COE left)

Manufactured

2013

Mileage

100,000 km (17.8k /yr)

Transmission

Auto

Engine Cap

1,390 cc

Road Tax

\$620 /yr

Power

125.0 kW (167 bhp)

View specs of the Volkswagen Touran Sport (2008-2009)

Curb Weight

1,567 kg

Features

140 Bhp, 220 Nm Powerful 1.4 Turbocharged TSI Engine With 7 Speed DSG Gearbox, 6 Airbags, ISOFIX System For Rear Seats. Robust And Functional Car.

Accessories

Reverse Sensors, Removable Rear Seats, 2 Zone Climatic Aircon System. Auto Headlights.

Description

Extremely Well Maintained By Previous Owner, Routinely Serviced! Gearbox And Clutch Just Changed With Agent. Wear And Tears Done Up! Owner Looking To Upgrade Therefore The Sale! Have A Worry Free Drive With This Purchase! Up To 80% Financing Possible! Trade In Welcome! Call/SMS Today To Arrange A Viewing! Viewing Strictly By Appointment Only!

COE

\$78,301

OMV

\$29,868

ARF

\$24,868

Dereg Value

\$51,624 as of today (change)

No. of Owners

3

Type of Veh

MPV

Category

PARF Car, Premium Ad Car

Availability

Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 28-Nov-2018 | Last Updated on: 28-Nov-2018

Tags: Volkswagen Touran, volkswagen touran, 2013 Volkswagen Touran, 2013 volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen



Location Map

Seller Information

Company

SD Motors Pte Ltd

» dealer's pricelist

» 4 vehs sold | 10 vehs available

Address

3C River Valley Road #01-10

Search cars nearby this location

Location

The Cannery

Contact Person(s)

Damien

94563061

Rey

86669749

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation



LOOKING FOR AN
INDEPENDENT SPECIALIST?

Find the specialty Workshops for your vehicle.

Volkswagen Touran

Price Range

Depreciation

2013

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Automate » Volkswagen Touran Sport 1.4A TSI Sunroof

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Ad

You
Need a
Break

sg.hotels.com

Unlock
Secret
Prices on
selected
hotels!

OPEN

Compare

Volkswagen Touran Sport 1.4A TSI Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$62,900**

Depreciation \$10,460 /yr

View models with similar depreciation

Reg Date 24-Jul-2013
(4yrs 7mths 19days COE left)

Manufactured 2013

Mileage 114,556 km (21.3k /yr)

Transmission Auto

Engine Cap 1,390 cc

Road Tax \$620 /yr

Power 125.0 kW (167 bhp)
View specs of the Volkswagen Touran Sport (2008-2009)

Curb Weight 1,567 kg

Features 140 Bhp, 220 Nm Powerful 1.4 Turbocharged TSI Engine With 7 Speed DSG Gearbox, 6 Airbags, ISOFIX System For Rear Seats. Robust And Functional Car.

Accessories Reverse Sensors, Removable Rear Seats, 2 Zone Climatic Aircon System. Auto Headlights.

Description Road Tune To 200Bhp. Park Assist, Engine And Gearbox Overhauled. Water Pump Replaced. All 4 Tyres Replaced 3 Months Ago. Full Service History. Buy With No Worries. Warranty On Engine For The Next 10k KM. Wonderfully Maintained By Owner And Services Routinely For Optimal Condition. High Paper Value. Call Us Now To Arrange Viewing.

COE \$73,989

OMV \$29,868

ARF \$28,816

Dereg Value \$54,470 as of today (change)

No. of Owners 2

Type of Veh MPV

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 25-Sep-2018 | Last Updated on: 28-Nov-2018

Tags: Volkswagen Touran, volkswagen touran, 2013 Volkswagen Touran, 2013 volkswagen touran, Volkswagen, Touran, touran, Used Volkswagen



Location Map

Seller Information

Company

Automate

* dealer's pricelist
* 7 vehs sold | 12 vehs available

Address

7 Toh Guan Road East #01-04
Search cars nearby this location

Location

Alpha Industrial Building

Office No

69093096

Contact Person(s)

Sam	96782525
Jenelle	96703396
Queenie	96340787

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2387D
Vehicle Details	
Vehicle No.:	SKL2956K
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TOURAN 1.4 TSI AT 1T32B4
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	CTH018836
Chassis No.:	WVGZZZ1TZDW041007
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,706.00
Original Registration Date:	24 Oct 2013
First Registration Date:	24 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$17,389.00 <i>8694</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Oct 2023
PARF Rebate Amount:	\$12,172.00
Intended COE Rebate Details	
COE Expiry Date:	23 Oct 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$85,000.00
COE Rebate Amount:	\$41,517.00
Total Rebate Amount:	\$53,689.00

The information contained herein is correct as at 04 Dec 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/12/2018 14:32
Date Of Accident	03/12/2018 09:00
Exact Location Of Accident	JCT OF COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL2956K
Insured/Policyholder	
Name Of Registered Owner	HENDRA CAKRA
NRIC No	S7482387D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96996609
Alternative Phone No	OTHERS-96996609

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	TOURAN 1.4 TSI AT 1T32B4
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1434800
Cover Note Number	

Driver

Name of Driver	CHEW LAY SI
NRIC No	S7438698I
Date Of Birth	22/11/1974
Occupation	INDOOR
Date Of Driving Pass	31/01/1994
Driving Experience	24 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94567473
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	23 MEYAPPA CHETTIAR ROAD #05-01 SPORE 358463
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	POTONG PASIR NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 142 POTONG PASIR AVENUE 3 , POSTCODE: 350142 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2829999 - FAX NO: 62815964
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE9735D
Vehicle Make/Model/Colour	TOYOTA DYNA 150 MANUAL
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHEW LAY SI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKL2956K

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available *forensic*.

5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the claims) and as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *L. L. L.*
NIC/FID No: *970417211*

Sketch Plan #2

SKETCH PLAN

A - SKL 2411R
B - GRETTSD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: *abu ni*
NRIC/ID No: *5203714*

Police Report



**SINGAPORE
POLICE FORCE**



Report No. 100-012150-040

Police Station Of Origin
Potong Pasir NPP
142 Potong Pasir Avenue 3 #01 240
SINGAPORE 350142
Tel No 1800-2829999

Report No. 100-012150-040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made
03/12/2018 13:01

Video Report No.

Police Station No.
11

Informant's Particulars

Name of Informant CHEW LAY SI	Address 23 MEYAPPA CHESTNUT ROAD #05-01 SINGAPORE 110003		
ID Type / ID No NRIC NO / S7438698	Contact No	Mobile 94567471	
Nationality SINGAPORE CITIZEN	Email		
Sex Female	Age 44	Date of Birth 22/11/1974	Type of Informant Driver
Race Chinese	Language English		Institution / School Name
Occupation MANAGER	Driving Licence Information Class 3		Date of Expiry

General Information of the Accident

Type of Accident	Injury Others	Drink Drive No	Date/Time of Accident 03/12/2018 09:00	Type of Location X Junction
Location: Along Road 1 COMMONWEALTH AVENUE WEST				
Towards Jurong near to the junction of Clement Ave 3 within the yellow box				
Weather: Clear	Road Surface Dry		Road Speed Limit	
Traffic Flow: One Way	Traffic Control Traffic Light - Working		Traffic Volume Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
GBE9735D	Lorry			Blue	Slightly Damaged	0
SKL2958K	Car	VOLKSWAGO N	TOURAN	White	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

Police Report



**SINGAPORE
POLICE FORCE**



T/20181203/2056

2 of 3

Report No: T/20181203/2056

Police Station Of Origin:
Potong Pasir NPP
142 Potong Pasir Avenue 3 #01-240
SINGAPORE 350142
Tel No: 1800-2829999

CONTINUATION OF REPORT

Driver		ID No	
Name	LIM TECK HENG	ID No	S0132804B
Related Vehicle	GBE9735D (Lorry)	Contact No	62881061
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver		ID No	
Name	CHEW LAY SI	ID No	ST4386961
Related Vehicle	SKL2955K (Car)	Contact No	94567473
Hospital/Clinic	THE FAMILY PRACTICE - POTONG PASIR	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	03/12/2018	Date Discharge	03/12/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details

On 03/12/2018 at around 0900hrs, I was traveling on lane 2 of a 4-lane road along Commonwealth Ave West towards Jurong. As I was passing by the cross junction of Commonwealth Ave West and Clementi Ave 3, I suddenly realized there was a blue coloured lorry which was along Clementi Ave 3 and it had turned left abruptly into Commonwealth Ave West. I could not stop in time as such the front left side of my car had hit onto the right side of the lorry. We then exchanged particulars and took photos of each others vehicles. The lorry then left.

My car had to be towed away. The damages to my car are as follows:

- 1) Front bumper came off
- 2) Front left headlight broken
- 3) Front left passenger door unable to be opened
- 4) Severe dent to the front left side of my car

The damages to the said lorry are as follows:-

- 1) Scratches and slight dents to the right side of his lorry

Due to the accident, I felt pain on my neck and back area (right side) as well as my right elbow. I went to seek medical treatment and was given 3 days MC.

Police Report



SINGAPORE
POLICE FORCE



1720181203/2056

Police Station Of Origin
Police Station Pasir NPP
142 Potong Pasir Avenue 3 #01-240
SINGAPORE 350142
Tel No: 1800-2829999

Report No: 1720181203/2056

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report
E /
Sr Staff Sgt JAMADIL BIN DOL MAT

Signature Of Interpreter
Not applicable

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt MOHAMAD ZULFAZEL BIN
SIL 057
Contact No: 65476204
Authentication Stamp
NP105

SIGNATURE

Signature Of Informant

Date/Time
03/12/2016 13:01

Classification Of Case

not Authorized
2/1/11
2/5 @ 11.000
6 day.
H. M. 18

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

VEHICLE NO: SKL 2956K

QTY	PARTICULAR			
1 PCS	FRONT BUMPER	1105	Dis	\$1,415.10
1 PCS	FRONT BUMPER CENTRE GRILLE		See	\$611.20 X
2 PCS	FRONT BUMPER SIDE RETAINERS @\$105.00	66 x 2 = 132	See	\$210.00
1 SET	FRONT BUMPER CLIPS		See	\$50.00
1 PCS	FRONT BUMPER SPONGE	182.00	See	\$288.00
1 PCS	FRONT BUMPER REINFORCEMENT		See	\$615.30 X
1 PCS	FRONT BUMPER SIDE SPONGE N/S	85	See	\$105.00
1 PCS	FRONT GRILLE	687.00	See	\$715.00
1 PCS	FRONT GRILLE LOGO		See	\$108.00 X
2 PCS	HEADLAMPS @\$2200.00	1450	MS 320	\$4,400.00 1PC
1 PCS	HEADLAMP TOP PANEL N/S	188.50	See	\$311.00
1 PCS	FRONT SUPPORT PANEL	941.00	See	\$945.00
1 PCS	FRONT SUPPORT PANEL TOP GARNISH		See	\$320.00 X
1 PCS	BONNET	1319.00	See	\$1,805.00
2 PCS	BONNET HINGES @\$118.00	105 x 2 = 210	See	\$236.00
1 PCS	BONNET LOCK	315	See	\$399.00
1 PCS	BONNET INSULATOR		See	\$360.00 X
1 SET	BONNET INSULATOR CLIPS		See	\$50.00 X
2 PCS	FRONT FENDERS @\$850.00	765.25	0/52 MS 320	\$1,700.00 1PC
1 PCS	FRONT FENDER INNER SHIELD N/S	182	See	\$305.00
1 SET	FRONT FENDER INNER SHIELD CLIPS N/S		See	\$50.00
1 PCS	FRONT FENDER INNER SIDE BRACKET N/S	105	See	\$122.00
1 PCS	FRONT FENDER INNER PANEL N/S	915.00	See	\$988.00
1 PCS	FRONT FENDER QUARTER GLASS N/S		See	\$620.00 X
1 PCS	BONNET INNER RUBBER BEADING		See	\$65.00
1 PCS	FRONT WHEEL HOUSING PANEL N/S		See	\$1,220.00 X
1 PCS	AIR CLEANER BOX ASSY	685	See	\$708.00
1 PCS	FUSE BOX TOP COVER		See	\$199.00
1 PCS	FUSE BOX BOTTOM		See	\$680.00 X
1 PCS	FRONT SHOCK ABSORBER N/S	466.50	See	\$650.00
1 PCS	FRONT KNUCKLE ARM N/S	746.00	See	\$915.00
1 PCS	FRONT SHOCK ABSORBER TOP MOUNTING N/S		See	\$215.00
1 PCS	FRONT KNUCKLE ARM BEARING N/S	366.00	See	\$425.00
1 PCS	FRONT LOWER ARM N/S	504.00	See	\$718.00
1 PCS	FRONT DRIVESHAFT N/S		See	\$1,150.00 X
1 PCS	FRONT STEERING RACK ASSY		See	\$1,866.30 X
1 PCS	FRONT TYRE N/S		See	\$200.00 60% 1205. N
1 PCS	FRONT SPORT RIM N/S 16 INCH		See	\$680.00 4005. N
1 PCS	AIR CON CONDENSER		See	\$1,220.00 X

1192228
1132613

	\$27,639.90	
LABOUR CHARGES:		
TOWING CHARGE	\$120.00	60
TO CHECK WIRING	\$80.00	30
TO CONDUCT WHEEL ALIGNMENT	\$120.00	60
TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	\$280.00	150
TO SPRAY RUST PROOFING	\$100.00	80
TO REFILL AIR CON GAS	\$150.00	100
TO MOUNT VEHICLE ON CAR O-LINER	\$380.00	x
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,800.00	1000
TO PUTTY & SPRAY PAINTING	\$1,800.00	1000
TOTAL	\$32,469.90	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18021715/UQBN2

Date: 08/01/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE001490
Claimant Vehicle No :	SKL2956K	Insured Vehicle No :	GBE9735D
Date of Loss:	03/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805313

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL2956K	Engine No:	CTH018836
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI 1T32B4 (A)	Chassis No:	WVGZZZ1TZDW041007
Reg. Date:	24/10/2013 (Man. Year: 2012)	Odometer:	66411 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,639.90	11,846.14	15,793.76	57.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	2,480.00	2,350.00	48.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,469.90	14,326.14	18,143.76	55.88
Approved Total (Overridden) (\$\$)		11,000.00		
(\$\$)	32,469.90	11,000.00	21,469.90	66.12
+ GST 7.00/7.00% (\$\$)	2,272.89	770.00	1,502.89	66.12
Nett Amount (\$\$)	34,742.79	11,770.00	22,972.79	66.12

INSPECTION

Date of Assignment:	03/12/2018	
Date Inspected:	04/12/2018	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2019)
Parts:	M1-MPV	VOLKSWAGEN TOURAN 1.4 TSI 1T32B4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL2956K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,415.10 F	*1,105.00 FL
2	1		*FRONT BUMPER CENTRE GRILLE	Serviceable	611.20 F	*- FL
3	2		*FRONT BUMPER SIDE RETAINERS	Bent	210.00 F	*132.00 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT BUMPER SPONGE	Torn	288.00 F	*182.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Repair	615.30 F	*- FL
7	1		*FRONT BUMPER SIDE SPONGE N/S	Torn	105.00 F	*85.00 FL
8	1		*FRONT GRILLE	Cracked	715.00 F	*681.00 FL
9	1		*FRONT GRILLE LOGO	Not Necessary	108.00 F	*- FL
10	1		*HEADLAMPS	N/s Broken	4,400.00 F	*1,450.00 FL
11	1		*HEADLAMP TOP PANEL N/S	Bent	311.00 F	*188.50 FL
12	1		*FRONT SUPPORT PANEL	Cracked	945.00 F	*941.00 FL
13	1		*FRONT SUPPORT PANEL TOP GARNISH	Not fitted	320.00 F	*- FL
14	1		*BONNET	Dented/Buckled	1,805.00 F	*1,319.00 FL
15	2		*BONNET HINGES	Bent/Twisted	236.00 F	*210.00 FL
16	1		*BONNET LOCK	Twisted/Jammed	399.00 F	*315.00 FL
17	1		*BONNET INSULATOR	Not Necessary	360.00 F	*- FL
18	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
19	1		*FRONT FENDERS	N/s Distorted/O/s Repair	1,700.00 F	*765.25 FL
20	1		*FRONT FENDER INNER SHIELD N/S	Torn	305.00 F	*182.00 FL
21	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
22	1		*FRONT FENDER INNER SIDE BRACKET N/S	Bent	122.00 F	*105.00 FL
23	1		*FRONT FENDER INNER PANEL N/S	Dented/Buckled	988.00 F	*915.00 FL
24	1		*FRONT FENDER QUARTER GLASS N/S	Not Necessary	620.00 F	*- FL
25	1		*BONNET INNER RUBBER BEADING	Necessary	65.00 F	*65.00 FL
26	1		*BONNET WHEEL HOUSING PANEL N/S	Repair	1,220.00 F	*- FL
27	1		*AIR CLEANER BOX ASSY	Cracked	708.00 F	*685.00 FL
28	1		*FUSE BOX TOP COVER	Cracked	199.00 F	*199.00 FL
29	1		*FUSE BOX BOTTOM	Not Necessary	680.00 F	*- FL
30	1		*FRONT SHOCK ABSORBER N/S	Bent	650.00 F	*466.50 FL
31	1		*FRONT KNUCKLE ARM N/S	Bent	915.00 F	*746.00 FL
32	1		*FRONT SHOCK ABSORBER TOP MOUNTING N/S	Twisted	215.00 F	*215.00 FL
33	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	425.00 F	*366.00 FL
34	1		*FRONT LOWER ARM N/S	Bent	718.00 F	*504.00 FL
35	1		*FRONT DRIVESHAFT N/S	Serviceable	1,150.00 F	*- FL
36	1		*FRONT STEERING RACK ASSY	Serviceable	1,866.30 F	*- FL
37	1		*AIR CON CONDENSER	Not Necessary	1,220.00 F	*- FL
38	1		*FRONT TYRE N/S (60%)	Punctured	200.00 FS	*120.00 FS
39	1		*FRONT SPORT RIM N/S 16 INCH	Bent	680.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	27,639.90
					12,442.25	
					- List Item Discount on L Items 0.00/5.00% (S\$)	0.00
						596.11
					Total Parts (S\$)	27,639.90
						11,846.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE	New	120.00	60.00
2	TO CHECK WIRING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	New	280.00	150.00
5	TO SPRAY RUST PROOFING	New	100.00	80.00
6	TO REFILL AIR CON GAS	New	150.00	100.00
7	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	-
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800.00	1,000.00
9	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,000.00
Gross Labour Cost (\$\$)			4,830.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >