

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163

Company Registration Number: 200505706E


Quotation

DATE: 26/11/18
 VEHICLE NO: PA5662L
 DRIVER: SHARUDIN BIN SAMSUDIN
 ATTENTION TO:
 PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
 Q REF No: Q18/11/956
 DEPARTMENT: WTS Bus Department
 ACCIDENT DATE: 23/11/18
 REF No: JW-1118-76

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	FRONT BUMPER	1	1025.6	1,025.60
2	FRONT LHS SIGNAL LAMP	1	201.75	201.75
3	EXCURSION BUS STICKER	1	10	10.00
4	FRONT RHS GRILLE.	1	94	94.00
Labour Costs				
1	TO REMOVE AND RE-INSTALL FRONT DASHBOARD AND WIRING TO ASSIST REPAIR FRONT PANEL DENTED. TO REMOVE AND RE-INSTALL WINDSCREEN GLASS TO ASSIST REPAIR FRONT PANEL. 3 MAN DAY X \$400.00	1	1200	1,200.00
2	TO PANEL BEAT FRONT PANEL LHS DENTED, TO PANEL BEAT FRONT LHS SIDE BODY LOWER PANEL, TO REMOVE AND REPLACE FRONT BUMPER.FRONT GRILLE. 3 MAN DAY X 400 = \$1200.00	1	1200	1,200.00
3	SUPPLY LABOUR AND REPLACE WTS STICKER AND LOGO.	1	250	250.00
4	TO CHECK WIRING AND REPLACE FRONT LHS SIGNAL LAMP	1	120	120.00
Spray Paint				
1	Spray Painting TO PUTTY AND SPRAY PAINTING FRONT BUMPER. FRONT PANEL AND LHS SIDE BODY PANEL.	1	2000	2,000.00
TOTAL:				6,101.35
Total Amount				SGD 6,101.35


Remarks:



Signature of Workshop Dpt



Signature of Department Head



Signature of Claim Department