

INS. CASE OWNER:

CC 4,601 180

LKK:
IDAC:

Surveyor:

DOI

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 50

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle / 009

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strive L'N')

S\$

Name 2:

Payee 3: (Strive L'N')

S\$

Name 3:

Visit No: EU 1385 Yr Reqn: 2016 APR

Type M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf 1.4 CC 1395
Colour: Beona A/C: Insured / Std / NI / NA
Sp. Reading: 30243 T/Radio: Insured / Std / NI / NA

Eng/No:

CIN: WVWZZZANZGW081134

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

3pm

N/S	O/S	

Tyre Size F: 225/35R18
R: 18"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 29/11/18 D.O.I. 04/12/18

Survey held at Volkswagen Mexicana

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee:	<input type="checkbox"/>	Site Insp	\$
	<input type="checkbox"/>	Interview	\$
	<input type="checkbox"/>	Tech. Invs	\$
	<input type="checkbox"/>	Weekend	\$

Lump Sum / I.B.I.: (\$

Figure 1



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQ118021758/R1ea3

Date: 06/12/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

EU 138S

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04/12/2018 at the premises of M/s Volkswagen Centre Singapore have the following to report:-

Workshop Estimate Amount	: S\$	20,393.87
Revised Estimate Amount	: S\$	14,549.18
"Check" Items Amount	: S\$	39.97
Total (Including Check Items)	: S\$	14,589.15
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 11.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

SKADING ANNE
10 ANSON ROAD
#49-08
Singapore, 079903
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV017634
Quote No. SER/QUO/1802025
QuoteDate 29/11/18
Salesperson Xiao Li Na Helena
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 R-Line 110 (DSG)	26,734	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
EU138S	WVWZZZAUZGW081134	01/04/16	Xiao Li Na Helena
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZD 345082	5G14NZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	R&R RIM & BALANCE	1	Labor		50.00
P B&P ALEX LABOUR	LABOUR	8	Labor		6,720.00
P B&P ALEX PAINT	SPRAY PAINT	5	Labor		4,000.00
P B&P TYRE SALES	TYRE N-V	1	Pieces		680.00
	PURCHASE OF TIRE				
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT -NETT	1			360.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				12,570.00
P 311601361	RUBBER VALVE <i>new</i>	1	Pieces		2.28
	Use Predecessor 281601361				
P 5G0073149A FZZ	ALLOY WHEELS 19" TWINSPOKE <i>See</i>	1	Pieces		2,055.92
P 5G0810971D	WHEEL HOUSING LINER-REAR <i>out</i>	1	Pieces		181.23
	Use Predecessor 5G0810971C				
P 5G0837205Q GRU	LHR DOOR HANDLE <i>repair</i>	1	Pieces		552.72
P 5G0919491	SENSOR BRACKET <i>XNN</i>	1	Pieces		15.49
P 5G0919491	SENSOR BRACKET <i>XNN</i>	1	Pieces		15.49
P 5G0919491A	SENSOR BRACKET <i>XNN</i>	1	Pieces		15.49
P 5G0919492A	SENSOR BRACKET <i>XNN</i>	1	Pieces		15.49
P 5G4809843	SECTION/LHR FENDER <i>new</i>	1	Pieces		1,350.18
P 5G4833055AB	DOOR LHR <i>new</i>	1	Pieces		1,650.63
	Use Predecessor 5G4833055AA				
P 5G6807393	BUMPER BRACKET LH <i>new</i>	1	Pieces		39.97
Sum carried forward					18,464.89

Payments to: - BBN - Acc.-No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6735B
Vehicle Details	
Vehicle No.:	EU1385
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Dec 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF 1.4 TSI R-LINE AT SR
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	CZD345082
Chassis No.:	WVWZZZAUZGW081134
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$25,089.00
Original Registration Date:	01 Apr 2016
First Registration Date:	01 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$17,125.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2026
PARF Rebate Amount:	\$12,843.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,970.00
COE Rebate Amount:	\$34,381.00
Total Rebate Amount:	\$47,224.00

The information contained herein is correct as at 05 Dec 2018

OK

78,500
47,224

30,776
//

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Friday, 30 November 2018 2:25 PM
To: assignments
Subject: FW: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18
Attachments: 30112018133107-0001.pdf

3.16pm @ 30/11/18
charmaine
vNI

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 30 November 2018 1:56 PM
To: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18

Without Prejudice

Dear Charmaine

We will appoint LKK to survey your client's vehicle.
Liability is unclear as our insured has not reported this accident.

Dear LKK

Please assist with this PRS.
Our insured has not reported this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 7 December, 2018 10:15 AM
To: 'Joel Goh'
Cc: Admin A; CS A Team; Asher Sng (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18
Attachments: TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf

Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

EQI ref: TBA
LKK REF: CC4/EQI18021758/R1ea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: EU 138S

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 3 December, 2018 9:33 AM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18

Dear Nivitha

Attached both accident reports for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 7 December 2018 3:29 PM
To: 'Kong, Charmaine (VWG Singapore)'; Rasul (LKKAuto)
Cc: Wong, MeiY (VWG Singapore); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore)
Subject: RE: ACCIDENT INVOLVING EU1385 AND YN9985D (EQ) ON 29/11/18 *** LKK REF: CC4/EQI18021758/ea3
Attachments: OI SKETCH PLAN.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sirs,

We refer to the above matter.

Please be informed that liability is unclear for this matter. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>
Sent: Thursday, 6 December 2018 10:59 AM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Wong, MeiY (VWG Singapore) <meiy.wong@vw.com.sg>; Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>
Subject: RE: ACCIDENT INVOLVING EU1385 AND YN9985D (EQ) ON 29/11/18 *** LKK REF: CC4/EQI18021758/ea3

Dear Asher,

Understand that your insured had already reported. Please kindly revert on liability & repair limit asap.


Thanks.

Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: Kong, Charmaine (VWG Singapore)
Sent: Wednesday, 5 December, 2018 2:41 PM
To: 'Asher Sng (LKKAUTO)'
Cc: Wong, Mely (VWG Singapore) (mely.wong@vw.com.sg); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore)
Subject: FW: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18 *** LKK REF: CC4/EQI18021758/ea3

Dear Asher,

Please revert on liability.

Thanks.


Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd

247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Wednesday, 5 December, 2018 2:26 PM
To: Kong, Charmaine (VWG Singapore); Joel Goh; Admin A; Asher Sng (LKKAuto)
Cc: Wong, Mei (VWG Singapore); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore); CS A Team
Subject: RE: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18 *** LKK REF: CC4/EQ118021758/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

OI reported.

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>
Sent: Wednesday, 5 December, 2018 2:10 PM
To: Joel Goh <joel.goh@eginsurance.com.sg>; Admin A <admin-a@lkkauto.com>
Cc: Wong, Mei (VWG Singapore) <meiy.wong@vw.com.sg>; Cheong, Pearlyn (VWG Singapore)

<Pearlyn.cheong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>

Subject: RE: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18

Hi,

Has your insured reported?

Thanks.

Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]

Sent: Friday, 30 November, 2018 1:56 PM

To: Kong, Charmaine (VWG Singapore)

Cc: Admin A

Subject: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18

Without Prejudice

Dear Charmaine

We will appoint LKK to survey your client's vehicle.
Liability is unclear as our insured has not reported this accident.

Dear LKK

Please assist with this PRS.
Our insured has not reported this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 9 April 2019 10:50 AM
To: Joel Goh
Subject: RE: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18 *** LKK REF: CC4/EQ18021758/ea3

Hi Joel,

We refer to the above matter.

We were informed by TP workshop that claimant do not come back to their workshop for repair up to date.

In view of the above, we will proceed to close file and submit our w/p report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]
Sent: Friday, 30 November, 2018 1:56 PM
To: Kong, Charmaine (VWG Singapore)
Cc: Admin A
Subject: ACCIDENT INVOLVING EU138S AND YN9985D (EQ) ON 29/11/18

Without Prejudice

Dear Charmaine

We will appoint LKK to survey your client's vehicle.
Liability is unclear as our insured has not reported this accident.

Dear LKK

Please assist with this PRS.
Our insured has not reported this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



A handwritten signature in black ink, appearing to be "De" or similar, with a long horizontal stroke extending to the right.

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18021758/R1ea3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 17-04-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 9985D	Veh. Inspected	EU 138S
Policy No.	DMCPHQ18-007190	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	30/11/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF 1.4	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WWWZZZAUZGW081134	Colour	BROWN
Odometer	30243	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/35 R18	PIRELLI	6 mm
L/H Front Tyre	225/35 R18	PIRELLI	6 mm
R/H Rear Tyre	225/35 R18	PIRELLI	6 mm
L/H Rear Tyre	225/35 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/11/2018	Inspection Date	04/12/2018
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EU 138S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TYRE (SN)	NOT NECESSARY	680.00	-
1	RUBBER VALVE (SN)	NECESSARY	2.28	2.28
1	ALLOY WHEELS 19 TWINSPOKE (SN)	SCRATCHED	2,055.92	2,055.92
1	WHEEL HOUSING LINER -REAR (SN)	CUT	181.23	181.23
1	LHR DOOR HANDLE (SN)	TO REPAIR SEE LABOUR	552.72	-
1	SENSOR BRACKET (SN)	NOT NECESSARY	15.49	-
1	SENSOR BRACKET (SN)	NOT NECESSARY	15.49	-
1	SENSOR BRACKET (SN)	NOT NECESSARY	15.49	-
1	SENSOR BRACKET (SN)	NOT NECESSARY	15.49	-
1	SECTION /LHR FENDER (SN)	BUCKLED	1,350.18	1,350.18
1	DOOR LHR (SN)	BENT	1,650.63	1,650.63
1	BUMPER BRACKET LH (SN)	* CHECK	39.97	-
1	BUMPER GUIDE LH (SN)	NOT NECESSARY	39.97	-
1	REAR BUMPER COVER (SN)	TO REPAIR SEE LABOUR	889.74	-
1	DOOR SEAL (SN)	NECESSARY	109.43	109.43
1	INOXSPRAY (SN)	NECESSARY	67.97	67.97
1	2KADHESIV (SN)	NECESSARY	286.20	286.20
1	2KADHESIVE (SN)	NOT NECESSARY	89.84	-
1	DOOR INSULATOR (SN)	NECESSARY	46.22	46.22
1	SEALANT (SN)	NECESSARY	77.38	77.38
1	2K FOAM (SN)	NECESSARY	157.96	157.96
1	BONDAGENT (SN)	NOT NECESSARY	64.27	-
			8,403.87	5,985.40
LABOUR				
	R&R RIM & BALANCE.		50.00	50.00
	LABOUR INCLUSIVE OF THE REPAIR OF LHR DOOR HANDLE AND REAR BUMPER COVER.		6,720.00	5,040.00
	SPRAY PAINT.		4,000.00	2,400.00
	B&P WHEEL ALIGNMENT.		360.00	360.00

Report Ref No. CC4/EQI18021758/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC .		480.00	480.00
	CHECK WIRE HARNESS ,ECU,S.		280.00	280.00
			11,890.00	8,610.00
GRAND TOTAL			20,293.87	14,595.40
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$39.97 NETT)				14,595.40

Report Ref No. CC4/EQ118021758/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Monday, 6 May 2019 2:51 PM
To: 'Joel Goh'
Cc: 'ashersng@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving YN 9985D (OI) and EU 138S (TP) on 29/11/2018
Attachments: EMAIL.pdf; LKK REPORT & PHOTO.pdf

Dear Sir/Madam,

We refer to our email dated 09.04.2019, which is self-explanatory.

We enclose herewith our without prejudice report and relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933