

Summary - Dec 5, '18 @ 4 pm / Nov 22, '18 / SPH 88005



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



INDIA INTERNATIONAL INSURANCE PTE LTD		NAME : Mr Cheong Chee Kong		WIP : 35837	
64 CECIL STREET		ADDRESS : 725 Ang Mo Kio Avenue 6		EXCESS :	
#04-00 & #05-00 IOB BUILDING		#17-4142		DATE: 23-Nov-18	
SINGAPORE 049711		Singapore 560725			
ATTN. : MOTOR CLAIMS		TEL : 96747207		Dec 5, '18	
FAX :					
VEH NO :	SJM632P	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BN22A8J0188324	MILEAGE :	11802	TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	12-Jan-18	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER / RE	1	MBPD8-50-221ABB \$ 1,074.80
2	BRACKET CENTER X NN	1	MKD53-50-251 \$ 5.10
3	RETAINER, SENSOR MCL	4	MKD47-67-UC5A53 \$ 69.20
4	SENSOR CENTER, ULTRASONIC ?	2	MGMK6-67-UC1 53 \$ 344.40
5	SENSOR SIDE, ULTRASONIC X NN	2	MKD47-67-UC1 53 \$ 387.80
6	TAPE PROTECTOR, SENSOR MCL	3	MGS1D-50-EM1A \$ 24.30
7	REAR REINFORCEMENT ?	1	MB45A-50-260 \$ 537.30
8	RIVET, REAR BUMPER	4	MBBM4-50-355 \$ 16.80
9	GROMMET, REAR BUMPER	4	MBHN1-50-021A \$ 10.00
10	GROMMET, REAR BUMPER	2	M9991-00-501 \$ 5.60
11	FASTENER, REAR BUMPER MCL	4	MB45A-56-146A \$ 11.20
12	CLIP, REAR BUMPER	2	MGJ21-50-049 \$ 6.40
13	GASKET LHS, TAILLAMP	1	MBHN1-51-163 \$ 20.90
14	GASKET RHS, TAILLAMP	1	MBHN1-51-153 \$ 20.90
TOTAL PARTS			\$ 2,534.70
LESS 10%			\$ 253.47
TOTAL PARTS COST			\$ 2,281.23

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660 \$ 1,320.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630 \$ 1,260.00
3	MZ-BR-REVSAN	TO TRANSFER REVERSE SENSORS.	330 \$ 660.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. NN	X \$ 250.00

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$	250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$	350.00
7		TO SUPPLY BRILA PREMIUM COATING.	180	NETT	\$ 800.00
8	MZ-BR-SUNDRI	SUNDRIES.	10	NETT	\$ 100.00
			TOTAL LABOUR	\$ -	\$ 4,990.00
			TOTAL PARTS	\$ -	\$ 2,281.23
			TOTAL	\$ -	\$ 7,271.23
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

3 Days.

before paint photos.

Euro Qian 82880282

05/12/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: