

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

SHD3291R

ESTIMATE

DATE : 3.12.2018

VEHICLE NO : SKT1244X

MAKE/MODEL : VW GOLF

ACC DATE : 30.11.2018

not approved
2018
h/s \$11,200/r
Take photo After rep
4/12/18
Sdy.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR TAILGATE EMBLEM GOLF	94.35	94.35
2	1 REAR TAILGATE EMBLEM TSI	82.95	82.95
3	1 REAR TAILGATE RUBBER	323.85	323.85
4	1 REAR TAILGATE LOCK	361.25	361.25
5	1 REAR TAILGATE LOCK CATCH	46.05	46.05
6	1 REAR BUMPER	1,132.65	1,132.65
7	2 REAR BUMPER PDC SENSOR <i>225x2=450</i>	299.15	598.30
8	2 REAR BUMPER NUMBER PLATE LAMP	29.25	58.50
9	1 REAR BUMPER LOWER LID	400.90	400.90
10	1 REAR BUMPER CENTRE GUIDE	145.05	145.05
11	1 REAR BUMPER REINFORCEMENT	606.05	606.05
12	2 REAR BUMPER SIDE RETAINER RH/LH	48.15	96.30
13	1 REAR EXHAUST BOX	1,073.10	1,073.10
14	2 REAR EXHAUST BOX MOUTNING	48.00	96.00
15	1 REAR END PANEL	970.80	970.80
16	1 REAR END PANEL GARNISH	161.05	161.05
17	2 FRONT HEADLAMP RH/LH	681.25	1,362.50
18	2 FRONT HEADLAMP PANEL RH/LH	95.60	191.20
19	1 FRONT GRILLE	622.30	622.30
20	1 FRONT GRILLE EMBLEM LOGO	153.70	153.70
21	1 FRONT BUMPER	1,203.75	1,203.75
22	1 FRONT BUMPER TOW COVER	38.95	38.95
23	2 FRONT BUMPER PDC SENSOR <i>215x2=430</i>	299.15	598.30
24	1 FRONT BUMPER LOWER CENTRE GRILLE	433.15	433.15
25	2 FRONT BUMPER FOG LAMP RH/LH	204.65	409.30
26	2 FRONT BUMPER FOG LAMP COVER RH/LH	145.75	291.50
27	2 FRONT BUMPER FOAM RH/LH	69.95	139.90
28	1 FRONT BUMPER REINFORCEMENT	731.30	731.30
29	1 FRONT BUMPER BEAM	206.45	206.45
30	2 FRONT BUMPER SIDE RETAINER RH/LH <i>48.15x2=96.30</i>	155.15	310.30

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
31	1 FRONT SUPPORT PANEL	1,146.05	1,146.05
32	1 FRONT BRACE PANEL	114.30	114.30
33	1 AIR CON CONDENSOR	865.15	865.15
34	1 RADIATOR	805.65	805.65
35	1 INTER COOLER	714.65	714.65
36	1 FRONT INTAKE AIR DUCT	116.80	116.80
			16,702.35
		LESS 10%	1,670.24
			15,032.12

SPECIAL NETT ITEMS

1	1 (SET) REAR BUMPER PLATE WITH CASING	50.00	50.00
2	1 (SET) REAR BUMPER CLIP	35.00	35.00
3	1 REAR BUMPER LOWER SPOILER	680.00	680.00
4	1 (SET) FRONT NUMBER PLATE WITH CASING	50.00	50.00
5	1 (SET) FRONT BUMPER CLIP	45.00	45.00
6	1 FRONT BUMPER LOWER SPOILER	680.00	680.00
7	1 RADIATOR COOLANT	25.00	25.00
8	1 AIR CON OIL	45.00	45.00
			1,610.00

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT / WELD REAR PANEL, REPLACE FRONT SUPPORT AND ACCIDENT PARTS.	1,400.00
2	TO SPRAY PAINTING AND ACCIDENT PORTION	1,600.00
3	TO CHECK FRONT AND REAR WIRING	50.00
4	TO REMOVE AND REPLACE CONDENSOR AND REFILL GAS	100.00
5	TO REMOVE AND REFIX CUSHION AND INNER TRIM	120.00
6	TO REMOVE AND REPLACE REAR EXHAUST BOX	120.00
7	TO TUFF KOTE	100.00
		3,490.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 20,132.12

2910