


Surveyor: 1022 DOI: ASSIGNMENT 2/2/2018 Date/Time: 30/11/2018
 Registered in Merimen: 31/12/18

Pre-assign / CCU / FTE: SHB 40140
 Insured Vehicle No.: CTP2 Claim No.: _____
 Name of insured: _____ Policy No.: _____
 Insured Tel No.: _____ HP: _____ Make / Model: _____
 Excess Sec II :SS _____ D.O.A: 30/11/2018 Place of Accident: Lower Rd > Ave
 Is driver the owner? (YES / NO) Name of Accident: _____
 If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No



Date/Time	STAGE	DATE / PIC
18/11/18	Non-Reporting ltr (1st)	
18/11/18	Non-Reporting ltr (2nd)	
18/11/18	Non-Reporting ltr (Final)	
11/11/18	Notification ltr (if non-pickup)	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	FIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:		Confirm by: <u>Kenneth</u>	
Repair Cost:	<u>46</u>	\$S 10,800.00	(12 days)	Reduction:	<u>25,464</u>	40 % 21	
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email:	Call:		
Final Liability:	%	<u>100</u>	(Agreed / Assessed)	BOLA S/N No.:		<u>28</u>	
Repair Cost:	(W/GST)	\$S	<u>11,556.00</u>				
Loss of Rental (LOR):	\$S	-	(days)				
Loss of Use (LOU):	\$S	<u>280.00</u>	(80 x 16 days)				
Loss of Income (LOI):	\$S	-	(3 x days)				
LOR only	<input type="checkbox"/>	LOU only	<input checked="" type="checkbox"/>	LOR + LOU	<input type="checkbox"/>	LOR + LOI	<input type="checkbox"/>
GIA/LTA Search	\$S	<u>29.00</u>					
Medical:	\$S	-					
Disbursement:	\$S	-	(e.g. Tow/Independent)				
Legal Cost:	\$S	-					
Total:	\$S	<u>12,865.00</u>	Global Sum \$S:				
FINAL PAYMENT		Date/Time:	Confirm with:	Email:	Call:		
Payee 1:	\$S	<u>12,865.00</u>	Name 1:	<u>Elite Automotive Pte Ltd</u>			
Payee 2: (Strike if N.A.)	\$S		Name 2:				
Payee 3: (Strike if N.A.)	\$S		Name 3:				

COPY SENT 25/11/19

ASS. REC. BY:

REF: TU /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no's Chang Hoo

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8.73k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 70 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 01/10 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SOA 6020A Yr Regn: 03, 90

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Bmw 520 c.c. 1991

Colour: h. Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 134556 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WBADM 22090BR 57551

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modl: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 225/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 30/11/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/12 File pass to Catherine, eh not ready

Repair can not more than 811k.

MV: 8.73k
Rebate: ~~1.5k~~ \$2700
NV: ~~1.5k~~ \$10,000

45 \$10,800 - (Red = \$20, 964.40 / 71%)

* 12 repair days + 2 PRS + 2 Sundays = 16 days

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee: _____
Transportation: _____
Fuel: _____
Others: _____
TOTAL: _____

Report Format : _____
Lump Sum / L.B.I: (\$ _____)

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SDA 6020A

Vehicle Model : BMW 520I

Chassis Number : WBADM22090BR57551

*Not Authorized
USing &?
Resony After Paint*

Estimated Repair Cost

S/N	Parts Description	Qty	List Price	
1	BOOT LID	1	\$ 1863.81	X
2	BOOT LID LOCK	1	\$ 398.94	✓
3	BOOT LID "BMW" LOGO	1	\$ 89.06	✓
4	BOOT LID "520I" EMBLEM	1	\$ 83.63	✓
5	BOOT LID WEATHERSTRIP	1	\$ 214.63	X
6	BOOT LID INNER TRIM	1	\$ 178.31	X
7	BOOT LID HINGES (LH & RH)	2	\$ 100.75	✓
8	BOOT LID FLOOR COMPARTMENT	1	\$ 728.06	X
9	TAIL LAMP (LH & RH)	2	\$ 632.75	X
10	REAR BUMPER	1	\$ 1504.88	✓
11	REAR BUMPER CLIPS	10	\$ 50.00	✓
12	REAR BUMPER TOWING CAP	1	\$ 42.50	X
13	REAR BUMPER REINFORCEMENT	1	\$ 605.44	X
14	REAR BUMPER RETAINER (LH & RH)	2	\$ 95.00	X
15	REAR BUMPER LOWER COVER CLIPS	10	\$ 50.00	X
16	REAR BUMPER CHROME MOULDING	3	\$ 222.06	✓
17	REAR BUMPER MOULDING (BLACK)	1	\$ 275.38	✓ 91-79
18	END PANEL	1	\$ 941.88	✓
19	END PANEL UPPER GARNISH	1	\$ 538.56	X
20	REAR FENDER LHS INNER TRIM	1	\$ 365.56	✓
21	REAR FENDER RHS INNER TRIM	1	\$ 365.56	X
22	REAR FENDER (LH & RH)	2	\$ 5385.62	✓
23	EXHAUST PIPE	1	\$ 1792.81	✓
24	EXHAUST MOUNTING	2	\$ 144.88	X
25	FRONT BONNET	1	\$ 3334.88	✓
26	FRONT BUMPER	1	\$ 1634.75	✓
27	HEADLAMP LH & RH	2	\$ 2545.88	✓
28	RADIATOR	1	\$ 895.75	X
29	A/C CONDENSER	1	\$ 653.94	X
30	FRONT GRILLE	1	\$ 278.76	✓
31	FRONT GRILLE INNER BRACKET	1	\$ 145.88	X
32	FRONT BUMPER CHROME MOULDING (3PCS)	3	\$ 321.56	✓
33	FRONT BUMPER MOULDING (BLACK)	2	\$ 187.13	✓ 124-75
34	TOWING CAP	1	\$ 50.31	X
35	HEADLAMP UPPER RUBBERSTRIP (LH & RH)	2	\$ 80.12	✓
36	HEADLAMP LOWER GARNISH (LH & RH)	2	\$ 154.26	X
37	FRONT BUMPER LOWER CENTRE GRILLE	1	\$ 155.88	X

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

38	FOG LAMP LH & RH	2	\$	<i>Sen</i>	766.88	<i>X</i>
39	FRONT BUMPER REINFORCEMENT	1	\$	<i>NH</i>	599.19	<i>X</i>
40	SUPPORT PANEL	1	\$	<i>R</i>	1254.63	<i>X</i>
			\$		<u>29729.87</u>	
	Discount Less	10%	\$		<u>2972.99</u>	
	List Prices Total		\$		<u>26,756.88</u>	

S/N	<i>PT</i>	Special Nett Items:	Qty			
1	REAR	NUMBER PLATE WITH HOLDER	1 SET	\$	<i>B</i> 60.00	<i>451a</i>
2		REVERSE SENSORS	1 SET	\$	1767.52	<i>X NH</i>
		Special Nett Total		\$	<u>1827.52</u>	
		Spare Part's Total Price		\$	<u>28584.40</u>	

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number :SDA 6020A
Vehicle Model : BMW 520I
Chassis Number : WBADM22090BR57551

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIRS BOOT FLOOR PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 <i>1000</i>
2	TO SPRAY PAINTING ON BOOT LID, REAR BUMPER, BOTH REAR FENDER, END PANEL, FLOOR PANEL.	\$ 1800.00 <i>1000</i>
3	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTION.	\$ 50.00 <i>20</i>
4	TO REMOVE & REPLACE REAR EXHAUST AND ALIGN SAME.	\$ 100.00 <i>60</i>
5	TO DRILL 4 PCS SENSORS HOLES AND REPLACE SENSORS AND TEST FUNCTIONS.	\$ 120.00 <i>60</i>
6	TO REMOVE & INSTALL BOOT COMPARTMENT TRIMMINGS & FITTINGS TO ENABLE REPAIRS.	\$ 100.00 <i>80</i>
7	TO CHECK & RESET E.C.U AFTER ACCIDENT REPAIRS AND REMOVE FAULT CODES.	<i>no</i> \$ 280.00 <i>X</i>
8	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIR FRONT END PANELLINGS, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 1800.00 <i>550</i>
9	TO SPRAY PAINTING ON FRONT BUMPER, FRONT PANELLINGS, BONNET (INNER, OUTER)	\$ 1500.00 <i>600</i>
10	TO REMOVE & REPLACE HEADLAMP, CHECK LIGHTINGS & FOCUS HEADLIGHTS.	\$ 100.00 <i>20</i>

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

- | | | | | |
|----|---|-------------|--------|------------|
| 11 | TO REMOVE & REPLACE HEADLAMP WIPER JET C/W MOTOR, RE-ALIGN & TEST FUNCTION. | \$ | 80.00 | <i>201</i> |
| 12 | TO REMOVE & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS. | <i>✓</i> \$ | 250.00 | <i>X</i> |

Labour Total \$ 8180.00

Parts & Labour Total \$ 36764.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before *after* spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1280I
Vehicle Details	
Vehicle No.:	SDA6020A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Nov 2018
Vehicle Make:	B.M.W.
Vehicle Model:	520IA
Primary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	37632167206S4
Chassis No.:	WBADM22090BR57551
Maximum Power Output:	-
Open Market Value:	\$44,509.00
Original Registration Date:	01 Mar 2000
First Registration Date:	01 Mar 2000
Transfer Count:	2
Actual ARF Paid:	\$62,313.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$18,484.00
COE Rebate Amount:	\$2,216.00
Total Rebate Amount:	\$2,216.00

The information contained herein is correct as at 30 Nov 2018

OK

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SDA 6020A

Vehicle Model : BMW 520I

Chassis Number : WBADM22090BR57551

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	FAN COWLING	1	159.00
2	FRONT FENDER LH & RH	2	1545.60
			1704.60
		Discount Less 10%	\$ 170.46
		List Prices Total	\$ 1,534.14

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 30 November, 2018 3:58 PM
To: Catherine Chong (LKK Auto)
Cc: Efeeda (Cheng Hoe -Yishun); Mekavathanan Sarangapani; Pooi Chin Han Daniel
Subject: RE: Repair Survey (Single Joint Expert) - SDA6020A

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SDA6020A and let us have your report urgently.

This claim will be handled by MR Daniel.

*Kindly upload this survey request email to merimen.

*03122018 @ 11:01am
Efeeda vch in*

Thank You.

Joel Nah
Motor Claims Department
India International Insurance Pte Ltd
64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 206 Fax: 6224 4174

-----Original Message-----

From: Efeeda (Cheng Hoe -Yishun) [mailto:chmotor@singnet.com.sg]
Sent: Friday, 30 November, 2018 3:53 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Chmotor <chmotor@singnet.com.sg>
Subject: Re: Repair Survey (Single Joint Expert) - SDA6020A

Dear Sir,

Our selection as below:

- LKK Auto Consultants Pte Ltd

Thank you.

Rgds
Efeeda
Cheng Hoe Motor PL
Tel:67556142
Fax:67557719

-----Original Message-----

From: Motor Claim - III

Sent: Friday, November 30, 2018 2:42 PM

To: Cheng Hoe Motor Pte Ltd (Yishun-June)

Subject: RE: Repair Survey (Single Joint Expert) - SDA6020A

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Joel Nah

Motor Claims Department

India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building

Singapore 049711

Tel: 6347 6100 Ext 206 Fax: 6224 4174

-----Original Message-----

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]

Sent: Friday, 30 November, 2018 2:40 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Chmotor <chmotor@singnet.com.sg>

Subject: Repair Survey (Single Joint Expert) - SDA6020A

Dear Sir,

OUR CLIENT – SDA6020A

DOA : 30/11/2018 @ 0830HRS

YR INSURED : SHB4014D

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

Efedda

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and

outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 10 December 2018 4:21 PM
To: Elite Automotive; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Pooi Chin Han Daniel
Subject: RE: Accident Involving Of Vehicle No: SDA 6020A & SHB 4014D
Attachments: 10122018133330.pdf

4:33pm @ 10/12/18
vehicle in
Christy
agreed survey on 11/12/18

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SDA6020A and let us have your report urgently.

This claim will be handled by Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Elite Automotive [mailto:elite.automotive13@gmail.com]
Sent: 10 December, 2018 2:29 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Accident Involving Of Vehicle No: SDA 6020A & SHB 4014D

Hi,

Good day! We noted that your emailed and agreed to appoint LKK, kindly to advise liability on this case.
Thanks!

Regards,

Christy

On Mon, 10 Dec 2018 at 14:07, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Elite Automotive [mailto:elite.automotive13@gmail.com]
Sent: 10 December, 2018 1:34 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Accident Involving Of Vehicle No: SDA 6020A & SHB 4014D

Hi,

Good day! Kindly to arrange pre-repair inspection for vehicle no: SDA 6020A. Thanks!

Regards,

Christy

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

--

Regards,

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 12 December 2018 1:23 PM
To: 'Elite Automotive'; Mei Kwan (LKKAuto)
Cc: Admin A; assignments
Subject: RE: Estimate For Vehicle No: SDA 6020A *** LKK REF: CC4/III18021762/fa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/III18021762/fa3
Your Ref : SDA 6020A

Dear Christy,

We refer to above matter and our tele conversation.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

Print Received Message

This mail is associated with :

***SDA6020A (MCT18110916)**
[SHB4014D]
TP
KOH JIA HAO
Nov 30 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Elite Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 12/12/2018 10:22 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SDA6020A - Claim Handler: Pooi Chin Han Daniel

Approved:0.00.

Poh Kin (LKKAuto)

From: Elite Automotive <elite.automotive13@gmail.com>
Sent: Monday, 17 December 2018 12:10 PM
To: Poh Kin (LKKAuto)
Subject: Supplementary Item For Vehicle No: SDA 6020A
Attachments: 17122018120908.pdf

Categories: Red- Do Something plz

Hi Poh Kin,

Good day! Kindly to inform Kenneth about the supplementary item and pass to him for marking.

Please noted that on the estimate item no 19, 22, this 2 parts got damaged and adjust the labour and the spray panting (add in front both fender). Thanks!

Regards,

Christy

View Received Message

This mail is associated with :

***SDA6020A (MCT18110916)**
[SHB4014D]

TP
KOH JIA HAO
Nov 30 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Elite Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/12/2019 14:23 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13185.00) - SDA6020A - Claim Handler: Pool Chin Han Daniel

Approved:13185.00.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2018 Edit Reg		30 Nov 2018 00:00 Edit Adj Rpt	S\$10,800.00 Edit Estimates	S\$10,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	KOH JIA HAO , ID: S91112801								
Vehicle Reg. No.:	SDA6020A	Date of Loss:	30/11/2018 08:00 - :59 [224 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18110916	Policy/Cover Note No.:	MCCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHB4014D	Policy No. (Claimant):	5094610933-01						
Repairer:	Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands, 757322 Woodlands - Tel: 9388 2885/8136 4741/63397378								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/12/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> • III_SG (10/12/2019): Alert - Adj Mandate Approved (S\$13185.00) - SDA6020A - Claim Handler: Pool Chin ... • III_SG (06/12/2019): Alert - Adj Mandate Approved (S\$13185.00) - SDA6020A - Claim Handler: Pool Chin ... • III_SG (29/11/2019): Alert - Adj Mandate Maintained - SDA6020A - Claim Handler: Pool Chin Han Daniel • III_SG (12/12/2018): Alert - Adj Mandate Approved (S\$0.00) - SDA6020A - Claim Handler: Pool Chin Han ... 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDA6020A (MCT18110916)**
[SHB4014D]
TP
KOH JIA HAO
Nov 30 2018 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Elite Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser
Video				1 per page <input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 08:53	Video - Accident MCT18110916 SHB4014D 30-11-2018 FAF	Load MP4	<input type="checkbox"/>
Photos/Images				3 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
2	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
15	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
16	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
17	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
18	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
19	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
20	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
21	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
22	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
23	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
24	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
25	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
26	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
27	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
28	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
29	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
30	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
31	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
32	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
33	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
34	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
35	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
36	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
37	17/10/19 12:01	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	03/12/18 21:36	ACKNOWLEDGEMENT EMAIL TO III DD 03.12.2018		Load PDF
2	11/12/18 11:50	NOTIFICATION FROM WKSP - ELITE		Load PDF
3	11/12/18 17:21	TP GIA REPORT		Load PDF
4	17/12/18 11:35	TP ESTIMATE - MARKED		Load PDF
5	17/10/19 12:00	LOD AND OTHER DOCUMENTS		Load PDF
6	26/11/19 12:02	GIA SEARCH		Load PDF
7	26/11/19 12:02	LOD		Load PDF
8	24/12/19 11:17	WORKSHOP INVOICE		Load PDF
9	24/12/19 11:17	AUTHORISATION TO ACT FORM		Load PDF
10	24/12/19 11:17	DISCHARGE VOUCHER		Load PDF
11	24/12/19 11:17	GIROFORM		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/12/18 08:40	Singapore Accident Statement		Load PDF
2	04/12/18 11:40	Email from Workshop - Client withdrawing claim and will engaged another workshop		Load PDF
3	27/11/19 08:53	Singapore Accident Statement TP SDA6020A		Load PDF
4	27/11/19 08:53	Singapore Accident Statement TP SJV657X		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18021762/KGA3N2

Date: 24/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant	Insured Vehicle No :	SHB4014D
Vehicle No : SDA6020A		
Date of Loss: 30/11/2018	Nature of Claim:	TP Claim No: MCT18110916

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDA6020A	Engine No:	37632167206S4
Make & Model:	BMW 520i, 2.0 (A)	Chassis No:	WBADM22090BR57551
Reg. Date:	01/03/2000 (Man. Year: 2000)	Odometer:	134556 km
Colour:	Metallic Silver		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R16	Rear Tyre Size:	225/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,584.40	11,832.13	16,752.27	58.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,180.00	3,410.00	4,770.00	58.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,764.40	15,242.13	21,522.27	58.54
Approved Total (Overridden) (S\$)		10,800.00		
(S\$)	36,764.40	10,800.00	25,964.40	70.62
+ GST 7.00/7.00% (S\$)	2,573.51	756.00	1,817.51	70.62
Nett Amount (S\$)	39,337.91	11,556.00	27,781.91	70.62
+ Loss of Use (16.0 x S\$80.00/day) (S\$)		1,280.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		12,865.00		

INSPECTION

Date of Assignment:	30/11/2018	
Date Inspected:	03/12/2018 Inspected At:	Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands Singapore 757322
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2019)
Parts: 143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDA6020A)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,863.81 FL	*- FL
2	1		*BOOT LID LOCK	Repair	398.94 FL	*- FL
3	1		*BOOT LID BMW LOGO	Necessary	89.06 FL	*89.06 FL
4	1		*BOOT LID 520i EMBLEM	Necessary	83.63 FL	*83.63 FL
5	1		*BOOT LID WEATHERSTRIP	Serviceable	214.63 FL	*- FL
6	1		*BOOT LID INNER TRIM	Serviceable	178.31 FL	*- FL
7	2		*BOOT LID HINGES (LH & RH)	Repair	100.75 FL	*- FL
8	1		*BOOT LID FLOOR COMPARTMENT	Repair	728.06 FL	*- FL
9	2		*TAIL LAMP (LH & RH)	Service Item	632.75 FL	*- FL
10	1		*REAR BUMPER	Buckled	1,504.88 FL	*1,504.88 FL
11	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
12	1		*REAR BUMPER TOWING CAP	Serviceable	42.50 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Not Necessary	605.44 FL	*- FL
14	2		*REAR BUMPER RETAINER (LH & RH)	Serviceable	95.00 FL	*- FL
15	10		*REAR BUMPER LOWER COVER CLIPS	Not Necessary	50.00 FL	*- FL
16	3		*REAR BUMPER CHROME MOULDING	Dented	222.06 FL	*222.06 FL
17	1		*REAR BUMPER MOULDING (BLACK) (3 PCS)	Dented (1 PCS ONLY)	275.38 FL	*91.79 FL
18	1		*END PANEL	Bent	941.88 FL	*941.88 FL
19	1		*END PANEL UPPER GARNISH	Serviceable	538.56 FL	*- FL
20	1		*REAR FENDER LHS INNER TRIM	Serviceable	365.56 FL	*- FL
21	1		*REAR FENDER RHS INNER TRIM	Serviceable	365.56 FL	*- FL
22	2		*REAR FENDER (LH & RH)	Repair	5,385.62 FL	*- FL
23	1		*EXHAUST PIPE	Bent	1,792.81 FL	*1,792.81 FL
24	2		*EXHAUST MOUNTING	Serviceable	144.88 FL	*- FL
25	1		*FRONT BONNET	Bent	3,334.88 FL	*3,334.88 FL
26	1		*FRONT BUMPER	Buckled	1,634.75 FL	*1,634.75 FL
27	2		*HEADLAMP LH & RH	Mtg Cracked	2,545.88 FL	*2,545.88 FL
28	1		*RADIATOR	Not Necessary	895.75 FL	*- FL
29	1		*A/C CONDENSER	Not Necessary	653.94 FL	*- FL
30	1		*FRONT GRILLE	Cracked	278.76 FL	*278.76 FL
31	1		*FRONT GRILLE INNER BRACKET	Repair	145.88 FL	*- FL
32	1		*FRONT BUMPER CHROME MOULDING (3 PCS)	Necessary	321.56 FL	*321.56 FL
33	1		*FRONT BUMPER MOULDING (BLACK) (3 PCS)	Dented (2 PCS ONLY)	187.13 FL	*124.75 FL
34	1		*TOWING CAP	Serviceable	50.31 FL	*- FL
35	2		*HEADLAMP UPPER RUBBERSTRIP (LH & RH)	Necessary	80.12 FL	*80.12 FL
36	2		*HEADLAMP LOWER GARNISH (LH & RH)	Serviceable	154.26 FL	*- FL
37	1		*FRONT BUMPER LOWER CENTRE GRILLE	Serviceable	155.88 FL	*- FL
38	2		*FOG LAMP LH & RH	Serviceable	766.88 FL	*- FL
39	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	599.19 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SUPPORT PANEL	Repair	1,254.63 FL	*- FL
41	1		*SET FRT NUMBER PLATE WITH HOLDER	Bent	60.00 FS	*45.00 FS
42	1		*SET REVERSE SENSORS	Not Necessary	1,767.52 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	31,557.39	13,141.81
- List Item Discount on L Items 10.00/10.00% (S\$)	2,972.99	1,309.68
Total Parts (S\$)	28,584.40	11,832.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS TO CUT & WELD WHERE NECESSARY ,TO STRAIGHTEN & REPAIRS BOOT FLOOR PANEL ,TO REPLACE DAMAGED PARTS AS LISTED ABOVE	New	2,000.00	1,000.00
2	TO SPRAY PAINTING ON BOOT LID ,REAR BUMPER ,BOTH REAR FENDER ,END PANEL,FLOOR PANEL	New	1,800.00	1,000.00
3	TO CHECK ELECTRICAL WIRING & REAR LIGHTS FUNCTION	New	50.00	20.00
4	TO REMOVE & REPLACE REAR EXHAUST AND ALIGN SAME	New	100.00	60.00
5	TO DRILL 4 PCS SENSORS HOLES AND REPLACE SENSORS AND TEST FUNCTIONS	New	120.00	60.00
6	TO REMOVE & INSTALL BOOT COMPARTMENT TRIMMINGS & FITTINGS TO ENABLE REPAIRS	New	100.00	80.00
7	TO CHECK & RESET E.C.U AFTER ACCIDENT REPAIRS AND REMOVE FAULT CODES	New	280.00	0.00
8	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS ,TO STRAIGHTEN & REPAIR FRONT AND PANELLINGS ,TO REPLACE DAMAGED PARTS AS LISTED ABOVE	New	1,800.00	550.00
9	TO SPRAY PAINTING ON FRONT BUMPER ,FRONT PANELLING ,BONNET (INNER OUTER)	New	1,500.00	600.00
10	TO REMOVE & REPLACE HEADLAMP ,CHECK LIGHTINGS & FOCUS HEADLIGHTS	New	100.00	20.00
11	TO REMOVE & REPLACE HEADLAMP WIPER JET C/W MOTOR ,RE-ALIGN & TEST FUNCTION	New	80.00	20.00
12	TO REMOVE & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS	New	250.00	0.00
Gross Labour Cost (\$\$)			8,180.00	3,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >