

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 777B**AAD1811-276**

Not Authorized
Resurvey B4 paint @ 11499.23

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 777B
 VF1ABL15AUC283310
 RENAULT
 LATITUDE
 24.11.2018
TOKIO MARINE

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>Bt</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Bt</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>D11</i> 113.47 ✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$	<i>Bt</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>D11</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bt</i> 225.95 ✓
13	1 BOOT REAR	\$	<i>Bt</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>CM</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>nd</i> 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>nd</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>nd</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81

Trans-cab Auto Services Pte Ltd

AAD1811-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 777B

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
31	1 WHEELARCH REAR LH	\$	Sn	543.47	X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
33	1 FUEL FLAG	\$	Sn	343.57	X
34	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	X
35	1 CHASSIS PANEL REAR LH L70Y	\$	R	3,766.43	X
36	1 TAILLAMP RH	\$	ngcm Sn	552.55	✓
37	1 TAILLAMP PANEL RH	\$	R	986.70	X
38	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	DI	404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
42	1 EXHAUST REAR	\$	R	7,489.05	X
43	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	38,607.73
10%	\$	3,860.77
	\$	34,746.95

Special Nett

1	1SET PARKING AID	\$	shon	700.00	Goosa
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X

Trans-cab Auto Services Pte Ltd**AAD1811-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 777B

18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	✓
20	1 TAILLAMP CLIP LH	\$	nn	5.00	} X
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	
22	1 WINDSCREEN MOULDING	\$	nn	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	} X
25	1 SPARE TYRE	\$	nn	330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 36,971.97****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	7001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1811-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 777B

To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i>	380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i>	170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>

TOTAL \$ 14,340.00**Over All Total \$ 51,311.97****(PART-BY-PART)****Repair Days****20 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: