

ASS. REC. BY:

REF:

TMI/

CC3/TMI18021765/Kvbz

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SID 777B

Yr Regn:

08, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c.

1895

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

301030

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFI ABLISAUC 283310

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size:

F: Giti 215/60R18

R: M&amp;H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

24/11/18

D.O.I.

3/12/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/12

File pass to Catherine

1/4 PP. 23

(Red)

39,810.74, 779

SID 777B - CC3 / FCL13009391 / Kvbz

STF 9878A - NA / INC10024136 / S

DA: 06032013

DA: 08112010

4/12/18

Email GIA to TMI

RECEIVED 04 DEC 2018

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

4/12 - typist

Days Of Repair:

5

Resurvey No. of Trlp:

-

Survey Fee:

Transportation:

250

10

S + RS. SI

Fixt/OS

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Merimen

Lump Sum / I.B.I. (\$

11,499.33

TOTAL

260

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Nov 2018		04 Dec 2018 14:35 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>						
Insured:	<b>SYC MULTI SERVICES</b> , Co. Reg. No.: 53365104B								
Main Claimant:	<b>TRANS CAB</b>								
Vehicle Reg. No.:	<b>SHD777B</b>	Date of Loss:	24/11/2018 04:00 - :59						
Claim Type:	<b>TP / M1806067</b>	Policy/Cover Note No.:	MJ000837 (Comprehensive) Coverage: 22/06/2018 - 24/06/2019						
Vehicle Reg. No. (Insured):	<b>SJF9878A</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>Trans-cab Auto Services Pte Ltd (Ang Mo Kio)</b> 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Dillen Senthilan so Selvarajoo</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 13/12/2018]</b>								
Driver/Custodian (Insured):	TOH ZHIQIANG JASON (), NRIC: S8720946F, Tel: +6581429839								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 4 December 2018 1:57 PM  
**To:** motorclaims@tokiomarine.com.sg; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 24/11/2018 , SHD 777B (TP Vehicle), SJF 9878A (OI Vehicle)  
**Attachments:** EST.pdf; GIA.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 777B at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 3/12/2018

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Tuesday, 4 December 2018 3:34 PM  
**To:** Ng Wai Yin; 'calvin.er'  
**Cc:** jasminetan@transcab.com.sg; SUR  
**Subject:** SHD 777B-DOA: 24/11/18 (TOKIO MARINE TP)  
**Attachments:** EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Please submit final amount \$11,499.23 @ 5 working days.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHD777B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Nov 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003221
Chassis No.:	VF1ABL15AUC283310
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Aug 2016
First Registration Date:	31 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2024
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	30 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$41,215.00
COE Rebate Amount:	\$29,609.00
<b>Total Rebate Amount:</b>	<b>\$44,607.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/11/2018 10:28
Date Of Accident	24/11/2018 04:00
Exact Location Of Accident	BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD777B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	LUM CHEE KWAI
NRIC No	S1248732J
Date Of Birth	06/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	15/03/1978
Driving Experience	40 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90295158
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 10B BOON TIONG ROAD #26-533
Postcode	164010
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN - 91904082 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2369999 - FAX NO: 62268438
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20181129/2130

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJF9878A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH ZHIQIANG, JASON
NRIC/Passport Number	S8720946F
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

LUM CHEE KWAI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD777B

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN

Sketch Plan

A- SHD 777B

B- SJF 9878A

Bukit Timah Road

Sketch Plan

A- SHD 777B

B- SJF 9878A

Bukit Timah Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20181129/2130

1 of 3

Report No. T/20181129/2130

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 29/11/2018 19:43	Vide Report No.:	Station Diary No.: 135
--	------------------	---------------------------

<b>Informant's Particulars</b>			
Name of Informant: LUM CHEE KWAI		Address: APT BLK 10B BOON TIONG ROAD #26-533 SINGAPORE 164010	
ID Type / ID No.: NRIC NO / S1248732J		Contact No.: Home/Office: Mobile: 90295158	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 61	Date of Birth: 06/03/1957	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: taxi driver		Driving Licence Information: Class: 3,4 Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 24/11/2018 04:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 BUKIT TIMAH ROAD BUKIT BATOK ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SHD777B	Car				Seriously Damaged	1
SJF9878A	Car					0

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20181129/2130

2 of 3

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

Report No. T/20181129/2130

## CONTINUATION OF REPORT

Driver			
Name	LUM CHEE KWAI	ID No.	S1248732J
Related Vehicle	NIL	Contact No.	90295158
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 24/11/2018, I was involved in a traffic accident involving SHD777B, which was my taxi and SJF9878A, which was the deft. I was with a passenger during the time of the accident.

I was driving along Bukit Timah Rd and when the traffic light turned red, I stopped at the stop line. After being at a complete stop for about 10-12 sec, I felt an impact on the rear of my vehicle. I came out to see that the vehicle SJF9878A had knocked onto my rear. As I did not think that I was injured at the time, we exchanged particulars and left. However after I went home, I felt something wrong with my body, so I went to SGH to see a doctor. The doctor diagnosed me with Cervical spondylosis and severe canal stenosis.

I am lodging this report as advised by the traffic IO.



**SINGAPORE  
POLICE FORCE**



T/20181129/2130

3 of 3

Report No. T/20181129/2130

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

## CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

A /  
Sgt 2 PANG LIN TONG

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
29/11/2018 19:43

Officer In Charge Of Case:  
TP / AEIT /  
Sr Staff Sgt MOHAMAD ZULFAZDLI BIN  
ABDULLAH  
Contact No.: 65476204

Classification Of Case:

Authentication Stamp  
NP168

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD 777B****AAD1811-276**

*Not Authored*  
*Resurvey B4 paint* @ 11499.23

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

**SHD 777B**

VF1ABL15AUC283310

RENAULT

LATITUDE

24.11.2018

**TOKIO MARINE****PART****LIST**

1	1 BUMPER COVER REAR	\$	B7 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	B7 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	D11 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	Sh 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	Sh 44.99	X
6	1 BUMPER REFLECTOR RH	\$	Sh 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	Sh 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	Sh 44.99	X
9	1 BUMPER REFLECTOR LH	\$	CM 43.61	✓
10	1 BUMPER BEAM REAR	\$	B7 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	D11 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	B7 225.95	✓
13	1 BOOT REAR	\$	B7 2,872.68	✓
14	1 BOOT FINISHER	\$	Sh 470.06	X
15	1 BOOT WHEATERSTRIP	\$	CM 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	Sh 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	nd 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	Sh 225.36	✓
19	1 BOOT BADGE	\$	Sh 225.36	✓
20	1 BOOT STRUT LH	\$	Sh 276.08	} X
21	1 BOOT STRUT RH	\$	Sh 276.08	
22	1 BOOT HINGE LH	\$	R 367.84	
23	1 BOOT HINGE RH	\$	R 367.84	
24	1 BOOT INNER TRIM	\$	Sh 586.45	
25	1 BOOT SWITCH	\$	Sh 168.13	
26	1 BOOT LOCK	\$	R 202.67	
27	1 BOOT LOCK CATCH	\$	R 74.40	}
28	2 LICENCE PLATE LAMP	\$	Sh 50.52	
29	2 BOOT RUBBER PLUG	\$	Sh 221.81	

**Trans-cab Auto Services Pte Ltd****AAD1811-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 777B**

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
31	1 WHEELARCH REAR LH	\$	Sn	543.47	X
32	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
33	1 FUEL FLAG	\$	Sn	343.57	X
34	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	X
35	1 CHASSIS PANEL REAR LH L70Y	\$	R	3,766.43	X
36	1 TAILLAMP RH	\$	Mjcm Sn	552.55	✓
37	1 TAILLAMP PANEL RH	\$	R	986.70	X
38	1 OUTER PANEL REAR (End Panel)	\$	Ry	1,471.77	✓
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	D11	404.56	✓
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
42	1 EXHAUST REAR	\$	R	7,489.05	X
43	1 EXHAUST CAP REAR	\$	R	230.49	X

<b>TOTAL</b>	<b>\$</b>	<b>38,607.73</b>
<b>10%</b>	<b>\$</b>	<b>3,860.77</b>
	<b>\$</b>	<b>34,746.95</b>

**Special Nett**

1	1SET PARKING AID	\$	Shon	700.00	Goosa
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1811-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 777B**

18	1 FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
19	1 TAILLAMP CLIP RH	\$	nn	5.00	✓
20	1 TAILLAMP CLIP LH	\$	nn	5.00	} X
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	
22	1 WINDSCREEN MOULDING	\$	nn	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
25	1 SPARE TYRE	\$	nn	330.00	

**TOTAL \$ 2,225.02****TOTAL PARTS \$ 36,971.97****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	7001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X

**Trans-cab Auto Services Pte Ltd****AAD1811-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 777B**To supply and re-do rear luggage floor panel  
insulation padding.\$ *na* 380.00 XTo transfer of rear fender fittings, attachment and  
perform water seepage test.\$ *na* 380.00 XTo transfer of rear windscreen fittings and conduct  
water seepage test.\$ *na* 170.00 XTo check steering geometry and computer wheel  
alignment\$ *na* 220.00 XTo transfer of rear door fittings, attachment and  
perform water seepage test.\$ *na* 380.00 X**TOTAL \$ 14,340.00****Over All Total \$ 51,311.97***51691.96***(PART-BY-PART)****Repair Days***20 DAYS**5 days*LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI18021765/KVBN2

Date: 13/12/2018

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ000837
Claimant		Insured Vehicle No :	SJF9878A
Vehicle No :	SHD777B	Nature of Claim:	TP
Date of Loss:	24/11/2018	Claim No:	M1806067

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD777B		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003221
Reg. Date:	31/08/2016 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC283310
Colour:	Metallic White/Red	Odometer:	301030 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	36,971.96	9,679.23	27,292.73	73.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,720.00	1,820.00	12,900.00	87.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>51,691.96</b>	<b>11,499.23</b>	<b>40,192.73</b>	<b>77.75</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>3,618.44</b>	<b>804.95</b>	<b>2,813.49</b>	<b>77.75</b>
<b>Nett Amount (\$\$)</b>	<b>55,310.40</b>	<b>12,304.18</b>	<b>43,006.22</b>	<b>77.75</b>

### INSPECTION

Date of Assignment:	04/12/2018	
Date Inspected:	03/12/2018	Inspected At:
		Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 13 Dec 2018)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD777B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR	Bent	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR	Distorted	113.47 FL	*113.47 FL
4	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1	*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1	*BUMPER BEAM BRACKET LH REAR	Distorted	225.95 FL	*225.95 FL
12	1	*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1	*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1	*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP	Cut	323.05 FL	*323.05 FL
16	1	*BOOT REFLECTOR LAM LH	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAM RH	Dented	493.35 FL	*493.35 FL
18	1	*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1	*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1	*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1	*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1	*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1	*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1	*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1	*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1	*BOOT LOCK	Repair	202.67 FL	*- FL
27	1	*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2	*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	2	*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
31	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
32	1	*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
33	1	*FUEL FLAG	Serviceable	343.57 FL	*- FL
34	1	*WHEEL HOUSING PANEL REAR LH	Repair	4,682.09 FL	*- FL
35	1	*CHASSIS PANEL REAR LH L70Y	Repair	3,766.43 FL	*- FL
36	1	*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL
37	1	*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
38	1	*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
39	1	*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	*404.56 FL
40	1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
41	1	*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
42	1	*EXHAUST REAR	Repair	7,489.05 FL	*- FL
43	1	*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
44	1	*SET PARKING AID	Shorted	700.00 FS	*600.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
46	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
47	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
48	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
49	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
50	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
51	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
52	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
53	1	*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
54	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1	*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
56	1	*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
57	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
58	1	*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
59	1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
60	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
61	1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
62	1	*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
63	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
64	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
65	1	*WINDSCREEN MOULDING	Serviceable	100.00 FS	*- FS
66	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
67	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
68	1	*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>40,832.73</b>	<b>10,662.48</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	3,860.77	983.25
<b>Total Parts (S\$)</b>	<b>36,971.96</b>	<b>9,679.23</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	880.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	700.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	-
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	-
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	-
11	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	-
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
14	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	-
Gross Labour Cost (\$\$)			14,720.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >