

CC3/MSU18021766/Risber

REF:

CC3/MSU18021766/Risber

5362K

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured: **SKA 6969E**

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **SHF 1852** Yr Regn: **2017** **ML**  
Type: M.Car / M.Cycle / Bus / Van / Lorry **(C)** Prime Mover /  
Truck / Trailer or

Make: **TOYOTA PRIMS 1.8A** c.c. **1798**

Colour: **MARON** A/C Insured / Std / NI / NA

Sp. Reading: **103155** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **JTDKBFU903578997**

Gen. Cond: Good / **(C)** Fair / Poor / Burnt

Steering: **(C)** In order / Jammed / Leaked / Burnt or

Brake: **(C)** In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **175/65R15**  
R: **175/65R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Fallen**

Front

Rear

R/Bal. **5** mm R/Bal. **5** mm

L/Bal. **5** mm L/Bal. **5** mm

D.O.A. **28/11/18** D.O.I. **30/11/18**

Survey held at **SMAR**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

**O/S RGR**

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	SHF 1852 - NS/INC17006618 / Klg3m2 DCA:3103707 11/18/2128
	SKA 6969E - X
05/12/18	@ 11:46 am. revised IA to Muhl Ashik B madi NS16 via merimer.
17/01/19	Confirmed P/P \$ 3,096.05 @ 8 days with Rasul. SKA 6969E (\$ 8,378.76 Rd - 73%)

RECEIVED 17 JAN 2019

Date/Time File Pass to? ☐ : Preli. Report

1) **17/01/19** ☒ : Final Report

Date/Time File Return to?

2)

Days Of Repair: **8**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Invs (\$

☐ Weekend (\$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$ **3,096.05 P/P**)

TOTAL

200

10

210

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks

(Incorporated with limited liability)

Unique Entity Number: 200721148H

✓ **HEAD OFFICE**

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

**Branch:** 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

✓ **HEAD OFFICE**

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓: (65) 65355905 (Litigation)  
E-mail : yvonnelim@visionlawllc.com

**BRANCH**

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
SELWYN TAN YINGXIAN

**WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER**

**Our Ref** : SLW 5707 Z (PM)  
**Your Ref** : SGT 979 M

03 December 2018

**BY EMAIL ONLY**

**MSIG INSURANCE (SG) PTE LTD**  
4 Shenton Way  
#21-01 SGX Centre  
Singapore 068807  
[Attention : Motor Claim Department]

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SLW 5707 Z & SGT 979 M ON 29 NOVEMBER 2018  
ALONG ORCHARD BOULEVARD TO PATERSON ROAD BESIDE ION ORCHARD AT ABOUT 1910  
HOURS  
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

**Messrs Derrick Motor Works**  
Blk 9002 Tampines St 93  
#01-72, Tampines Ind Park A  
Singapore 528836  
Attention: Mr Jeromy – HP 9633 3593

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

  
DIANE ANG  
(HEAD OFFICE)

cc: SLW 5707 Z – By email only

**FOR SURVEYOR**

Please initial here after completion of pre-repair inspection. Thank you.

 Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

**CONFIDENTIALITY**

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## Shirley Hiew (LKK Auto)

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
<YeoPohsuan@smrt.com.sg>  
**Sent:** Thursday, 17 January 2019 9:27 AM  
**To:** Rasul (LKKAuto)  
**Cc:** SUR; CS A Team  
**Subject:** RE: SHF185Z

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]  
Sent: Thursday, 17 January 2019 9:18 AM  
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
Cc: SUR; CS A Team  
Subject: RE: SHF185Z

Hi Poh Suan,

Finalised amount of \$ 3,096.05 / 8 days part by part is confirmed

Best Regards,  
Rasul | Assessor  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) [mailto:YeoPohsuan@smrt.com.sg]  
Sent: Wednesday, 16 January, 2019 6:31 PM  
To: Rasul (LKKAuto)  
Cc: SUR; CS A Team  
Subject: SHF185Z

Hi Rasul,

Attached herewith the repair estimate of SHF 185Z having Case No: TAX/11/18/2128.

There is no change to the approved amount of \$3,096.05 @ 8 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Sent: Wednesday, 16 January 2019 5:52 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Subject: Scan Data from FX-D421D6

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 05 Dec 2018

**Preliminary Advice**

Insured Vehicle No	: SKA6969E	Accident Date	: 28/11/2018
TP Vehicle No	: SHF185Z	Assignment Date	: 04/12/2018
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 6 days
Date of Inspection	: 30/11/2018		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,461.17
Revised Amount	:S\$	2,768.63
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,768.63

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Tuesday, 4 December 2018 3:15 PM  
**To:** 'Muhd Ashik B Madi'; eileen\_ang@sg.msiga-asia.com  
**Cc:** KKLau; Accounts (LKKAuto); SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICE PTE LTD, DOA: 28/11/2018 , SHF 185Z (TP VEHICLE), SKA 6969E (OI VEHICLE)  
**Attachments:** TP GIA REPORT.pdf

Dear Ashik/Eileen,

Please be informed that we had inspected the vehicle SHF 185Z M/s: SMRT AUTOMOTIVE SERVICE PTE LTD, 60 WOODLANDS INDUSTRIAL PARK E4, SINGAPORE 757705 on 30/11/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	29/11/2018 11:11
Date Of Accident	28/11/2018 04:00
Exact Location Of Accident	ORCHARD ROAD TOWARDS CUSCADEN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF185Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	TANG CHEK FONG
NRIC No	S1769381F
Date Of Birth	12/07/1966
Occupation	OUTDOOR
Date Of Driving Pass	14/11/1991
Driving Experience	27 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG ORCHARD ROAD AND WAS TURNING RIGHT TOWARDS CUSCADEN ROAD. I SIGNALLLED MY INTENTION TO TURN RIGHT. WHILST I WAS TURNING RIGHT I FELT AN IMPACT AT THE RIGHT PORTION OF MY TAXI. A VEHICLE SKA6969E DID NOT STOP AT THE STOP LINE TO GIVE WAY TO MY TAXI AND HAD COLLIDED ONTO THE RIGHT PORTION OF MY TAXI. AFTER WHICH THIRD PARTY FLED THE SCENE. I WENT AFTER THIRD PARTY AND ONLY MANAGED TO STOP HIM QUITE A DISTANCE AWAY AT WHEEL LOCK PLACE CAR PARK.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SKA6969E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ABDUL HADI RASHID
NRIC/Passport Number	S8702424E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date &amp; Time:

唐澤封

Driver's Signature

(If driver is not the policyholder)

Date & Time:

28/11/2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

唐澤林

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

26/11/2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Case Details

Case Reference Number : TAX/11/18/2128  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHF185Z

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-4747-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : MSIG Insurance (S) Pte Ltd  
 Accident Date and Time : 27/11/2018 08:00 PM  
 Vehicle Age(In Months) : 11

## Documents / Photographs











[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Xsu Not Give
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	mc Replace
One Time Key In	Main			PILLAR, CENTER BODY, OUTER RH	1	313.40	313.40	25.00	235.05	Replace	1	0	R Repair
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR, RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	870.73 932.93	gt Replace
One Time Key In	Main			WEATHERSTRIP, REAR DOOR, NO.2, RH	1	33.20	33.20	25.00	24.90	Replace	1	23.24 24.90	mc Replace
One Time Key In	Main			CHECK ASSY, REAR DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Xsu Not Give
One Time Key In	Main			WEATHERSTRIP, REAR DOOR RH	1	174.40	174.40	25.00	130.80	Replace	1	122.03 130.80	mc Replace
One Time Key In	Main			BOARD SUB-ASSY, REAR DOOR TRIM, RH	1	566.60	566.60	25.00	424.95	Replace	0	0	Xsu Check
Total Spare Part Cost									7,564.17	Surveyor Total 1,268.63			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0			
Final Spare Part Cost									7,564.17	Final Sur Total 1,268.63			

SMRT Recommendation												Surveyor Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			DOOR LOCK REAR , RH	1	544.70	544.70	10.00	490.23	Replace	0	0	 Not Give
One Time Key In	Main			HINGE ASSY, REAR DOOR , UPPER RH	1	83.30	83.30	25.00	62.47	Replace	0	0	 Check
One Time Key In	Main			HINGE ASSY, REAR DOOR , LOWER RH	1	73.30	73.30	25.00	54.97	Replace	0	0	 Check
One Time Key In	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1	200.70	200.70	25.00	150.52	Replace	0	0	 Check
One Time Key In	Main			REAR DOOR SPEAKER ASSY, RADIO RH & LH	1	985.70	985.70	10.00	887.13	Replace	0	0	 Not Give
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	1	0	R Repair
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	R Repair
One Time Key In	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	0	0	 Not Give
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	 Not Give
One Time Key In	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	R Repair
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	R Repair
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	 Not Give
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	 Not Give
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120	 Replace
Total Spare Part Cost									7,564.17		Surveyor Total	1,268.63	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									7,564.17		Final Sur Total	1,268.63	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR RH PORTION	845.00	600	
Total:		845.00	600.00	

Spray Cost Detail



S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO RESPRAY FRONT DOOR RH	378.00	0	
2	TO RESPRAY RH REAR DOOR	378.00	200 /	
3	TO RESPRAY ROCKER PANEL MOULDING	180.00	100 /	
4	TO RESPRAY REAR FENDER RH	378.00	100 2w	
5	TO RESPRAY CENTRE PILLAR RH	180.00	100 /	
6	TO REPSRAY REAR BUMPER	378.00	100 2w	
7	TO RESPRAY RIM	180.00	50 /	
8	TO RESPRAY FILLER RR BUMPER RH	180.00	0 X	
Total:		2,232.00	650.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40 /	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60 /	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60 /	
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30 /	
5	TO TRANSFER DOOR MECHANISM	120.00	60 /	
6	TO REMOVE AND REFIT WIRE HARDESS	120.00	0 /	
Total:		820.00	250.00	



S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	TO REPLACE SUNDRY PARTS	100.00	0	
8	TO WASH AND VACUUM	60.00	0	
Total:		820.00	250.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	7,564.17	1,268.63
Total Labour Cost	845.00	600.00
Total Spray Painting	2,232.00	650.00
Other	820.00	250.00
Overall Total	11,461.17	2,768.63
Lump Sum Repair Option		
Lump Sum Total	0.00	2,768.63
Surveyor Approved Amount		2,768.63
No of Repair Days*	6	6
Remarks		P/P resurvey before paint
Surveyor Name		Rasul
Signature		
Survey Date	30/11/2018	<div>SaveClear</div>



## Section A - Accident Details

Registration Number	SHF185Z
Case Reference Number	TAX/11/18/2128
Registration Date	19/12/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TANG CHEK FONG
Type of Accident	Head To Side
Accident Date and Time	28/11/18 4:00 AM
Accident Reported Date and Time	28/11/18 4:27 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098994
Special Instruction to ARC, if any	TP
Prepared Date and Time	29/11/18 1:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,045.00	\$700.00
Total Spray Cost	\$2,432.00	\$950.00
Total Spare Part Cost	\$7,177.81	\$1,196.05
Total Other Cost	\$820.00	\$250.00
<b>TOTAL COST</b>	<b>\$11,474.81</b>	<b>\$3,096.05 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	8.0
Prepared / Adjusted By	Kim Ming Chin	RASUL (LKK) / MSIG
ARC / Surveyor Sign Off Date	07/12/2018 7:20 AM	07/12/2018 7:48 PM
Signature		
Remarks	Initial = 6 days Request number of days to extend 2 days P/P resurvey before paint	



## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1901-0154	Invoice Number	
Quotation Date	09.01.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$600.00
TO REPAIR SILL MEMBER RH	\$200.00	\$100.00 (S) A
<b>Total Labour</b>	<b>\$1,045.00</b>	<b>\$700.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY CENTRE PILLAR RH	\$180.00	\$100.00
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY SILL MEMBER PANEL RH	\$200.00	\$100.00 (S) A
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$2,432.00</b>	<b>\$950.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$820.00</b>	<b>\$250.00</b>

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given A
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		61311470 50	PILLAR, CENTER BODY, OUTER RH	1.00	\$313.40	100.00	\$0.00	Replace	Repair K
		67003472 10	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,243.90	30.00	\$870.73	Replace	Replace

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705  
FAX Number : 63985592  
Estimator Telephone Number : 68062623  
Accident Reporting Number : 68062672

Date Generated : 15/01/2019

User ID : PohSuan

6789547010	WEATHERSTRIP, REAR DOOR, NO.2, RH	1.00	\$33.20	30.00	\$23.24	Replace	Replace	X
6863047050	CHECK ASSY, REAR DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given	X
6787147051	WEATHERSTRIP, REAR DOOR RH	1.00	\$174.40	30.00	\$122.08	Replace	Replace	X
6763047500C1	BOARD SUB-ASSY, REAR DOOR TRIM, RH	0.00	\$566.60	0.00	\$0.00	Replace	Check	X
6905052250	DOOR LOCK REAR, RH	0.00	\$544.70	0.00	\$0.00	Replace	Not Given	X
6875020122	HINGE ASSY, REAR DOOR, UPPER RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X
6877052031	HINGE ASSY, REAR DOOR, LOWER RH	0.00	\$73.30	0.00	\$0.00	Replace	Check	X
6980347020	DOOR REAR WINDOW REGULATOR SUB-ASSY,	0.00	\$200.70	0.00	\$0.00	Replace	Check	X
861600R140	REAR DOOR SPEAKER ASSY, RADIO RH & LH	0.00	\$985.70	0.00	\$0.00	Replace	Not Given	X
7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair	X
8160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$824.80	100.00	\$0.00	Replace	Repair	X
6563747060	LINER, REAR FENDER, RH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
4261147450	WHEEL, DISC	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair	X
5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair	X
5256547900	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X
<b>Total</b>			<b>\$9,617.24</b>		<b>\$1,196.05</b>			

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

1196.05  
+ 700.00  
+ 1200.00  
3096.05  
8 days

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Nov 2018		04 Dec 2018 15:37 <a href="#">Edit Adj Rpt</a>	<b>S\$3,096.05</b> <a href="#">Edit Estimates</a>	<b>S\$3,096.05</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>ABDUL HADI BIN RASHID</b> , ID: S8702424E, Tel: +6582294138, Email: hardyrashid@gmail.com									
Main Claimant: <b>SMRT TAXIS PTE LTD</b> , Co. Reg. No.: 198905369K									
Vehicle Reg. No.: <b>SHF185Z</b>		Date of Loss: 28/11/2018 04:00 - :59 [11 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 577500</b>		Policy/Cover Note No.: A29085660MPQ(COMP) (Comprehensive) Coverage: 13/06/2018 - 12/06/2019							
Vehicle Reg. No. (Insured): <b>SKA6969E</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>SMRT Automotive Services Pte Ltd (Woodlands)</b> 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 03/01/2019]									
Driver/Custodian (Insured): ABDUL HADI BIN RASHID (31 / Male), NRIC: S8702424E, Tel: +6582294138									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHF185Z (577500)  
[SKA6969E]  
TP  
SMRT TAXIS PTE LTD  
Nov 28 2018 4:00AM  
[ABDUL HADI BIN RASHID]  
SMRT Automotive Services Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	04/12/18 15:33	<b>Accident Statement</b> From: SC - Reg. No: SKA6969E, Claimant: ABDUL HADI BIN RASHID		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	05/12/18 11:46	<b>Adjuster Immediate Advice</b>		Load HTM
<b>Photos/Images</b>			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	17/01/19 10:08	<b>Odometer Reading</b>		Load JPG <input checked="" type="checkbox"/>
2	17/01/19 10:08	<b>Chassis Number</b>		Load JPG <input checked="" type="checkbox"/>
3	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
4	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
5	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
6	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
7	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
8	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
9	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
10	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
11	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
12	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
13	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
14	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
15	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
16	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
17	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
18	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
19	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
20	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
21	17/01/19 10:08	<b>General View</b>		Load JPG <input checked="" type="checkbox"/>
22	17/01/19 10:09	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
23	17/01/19 10:09	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
24	17/01/19 10:09	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
25	17/01/19 10:09	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
26	17/01/19 10:09	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>
27	17/01/19 10:09	<b>Reinspection Photo</b>		Load JPG <input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
----------------------------	-----------------------	----------------------	-----------------------

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18021766/R1SBE2

Date: 21/01/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29085660MPQ(COMP)

Claimant Vehicle No : SHF185Z

Insured Vehicle No : SKA6969E

Date of Loss: 28/11/2018

Nature of Claim: TP

Claim No: 577500

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF185Z

Make &amp; Model: TOYOTA PRIUS TAXI, 1.8 (A)

Engine No: 2ZR8281124

Reg. Date: 19/12/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU903578997

Colour: Maroon

Odometer: 103155 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,677.24	1,196.05	8,481.19	87.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,297.00	1,900.00	2,397.00	55.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>13,974.24</b>	<b>3,096.05</b>	<b>10,878.19</b>	<b>77.84</b>

### INSPECTION

Date of Assignment: 04/12/2018

Date Inspected: 30/11/2018 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
<b>Parts:</b>	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHF185Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY, REAR DOOR, RH (DISC 30%)	Bent	1,243.90 F	*870.73 F
2	1		*WEATHERSTRIP, REAR DOOR, NO.2, RH (DISC 30%)	Necessary	33.20 F	*23.24 F
3	1		*WEATHERSTRIP, REAR DOOR RH (DISC 30%)	Necessary	174.40 F	*122.08 F
4	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
6	1		*PANEL SUB-ASSY, FRONT DOOR RH	Serviceable	1,249.60 F	*- F
7	1		*CHECK ASSY, REAR DOOR	Serviceable	153.50 F	*- F
8	1		*BOARD SUB-ASSY, REAR DOOR TRIM, RH	Serviceable	566.60 F	*- F
9	1		*DOOR LOCK REAR, RH	Serviceable	544.70 F	*- F
10	1		*HINGE ASSY, REAR DOOR, UPPER RH	Serviceable	83.30 F	*- F
11	1		*HINGE ASSY, REAR DOOR, LOWER RH	Serviceable	73.30 F	*- F
12	1		*DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	Serviceable	200.70 F	*- F
13	1		*REAR DOOR SPEAKER ASSY, RADIO RH & LH	Serviceable	985.70 F	*- F
14	1		*LINER, REAR FENDER, RH	Serviceable	135.80 F	*- F
15	1		*FILLER, RR BUMPER, RH	Serviceable	119.90 F	*- F
16	1		*RETAINER, RR BUMPER, RH	Serviceable	112.70 F	*- F
17	1		*TYRE	Not Necessary	126.74 F	*- F
18	1		*PILLAR, CENTER BODY, OUTER RH	Repair	313.40 F	*- F
19	1		*MOULDING ASSY, BODY ROCKER PANEL, RH	Repair	576.00 F	*- F
20	1		*PANEL SUB-ASSY, FENDER REAR RH	Repair	824.80 F	*- F
21	1		*WHEEL, DISC	Repair	1,555.10 F	*- F
22	1		*COVER, RR BUMPER ASSY	Repair	423.90 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>9,677.24</b>	<b>1,196.05</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	1,045.00	700.00
2	SPRAY PAINT	New	2,432.00	950.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	40.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	60.00
5	TO DO WHEEL ALIGNMENT / TYRE BALANCING	New	120.00	60.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
7	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
8	TO REMOVE AND REFIT WIRE HARDESS	New	120.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
10	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			<b>4,297.00</b>	<b>1,900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >