

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 03 NOVEMBER 2018

Third Party Insurer: AIG

Vehicle No: SLQ7142X

Third Party Veh No: SKX768L

Model: VOLKSWAGEN GOLF 1.4 TSI AT

Date of Accident: 02/12/2018

Chassis: VVVZZZAUZHWO71040

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		\$2,164.20
2	REAR TAILGATE INNER REFLECTOR LAMP	1		\$293.58
3	REAR TAILGATE 230 TSI EMBLEM	1		\$98.48
4	REAR BUMPER	1		\$1,269.93
5	REAR BUMPER SIDE RETAINER RH	1		\$57.15
6	REAR BUMPER TOW HOOK COVER	1		\$28.28
7	REAR BUMPER REFLECTOR LAMP RH	1		\$80.23
8	REAR BUMPER REVERSE SENSOR	1		\$250.00
9	REAR BUMPER REINFORCEMENT	1		\$670.93
10	REAR END PANEL	1		\$939.73
SUB TOTAL				\$5,852.48
LESS 10%				-\$585.25
PARTS TOTAL				\$5,267.23

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER			\$120.00
S/N TOTAL				\$120.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$800.00
TO TUFF KOTE / ANTI-RUST	\$80.00
TO CHECK WIRING AND WATER LEAK TEST	\$60.00
TO REMOVE & REINSTALL REAR WINDSCREEN AND TO PERFORM WATER LEAKAGE TEST	\$180.00
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00

TO PERFORM WATER LEAKAGE

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL

\$2,200.00

TOTAL

\$7,587.23

AZMAN

Acknowledged by Repairer

Signature:

Date:

Not Authorized
Penny B4paim
4-6day

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 03 NOVEMBER 2018

Third Party Insurer: AIG

Vehicle No: SLQ7142X

Third Party Veh No: SKX768L

Model: VOLKSWAGEN GOLF 1.4 TSI AT

Date of Accident: 02/12/2018

Chassis: WVVZZZAUZHWO71040

*Not Notified
Repair B4 paint
4-6 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>R</i> \$2,164.20 <i>X</i>
2	REAR TAILGATE INNER REFLECTOR LAMP	1		<i>R</i> \$293.58 <i>✓</i>
3	REAR TAILGATE 230 TSI EMBLEM	1		<i>R</i> \$98.48 <i>✓</i>
4	REAR BUMPER	1		<i>R</i> \$1,269.93 <i>✓</i>
5	REAR BUMPER SIDE RETAINER RH	1		<i>R</i> \$57.15 <i>✓</i>
6	REAR BUMPER TOW HOOK COVER	1		<i>R</i> \$28.28 <i>✓</i>
7	REAR BUMPER REFLECTOR LAMP RH	1		\$80.23 <i>?</i>
8	REAR BUMPER REVERSE SENSOR	1		<i>R</i> \$250.00 <i>✓</i>
9	REAR BUMPER REINFORCEMENT	1		\$670.93 <i>?</i>
10	REAR END PANEL	1		\$939.73 <i>?</i>
SUB TOTAL				\$5,852.48
LESS 10%				-\$585.25
PARTS TOTAL				\$5,267.23

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER			<i>R</i> \$120.00 <i>400ml</i>
S/N TOTAL				\$120.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,000.00 <i>?</i>
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$800.00 <i>600ml</i>
TO TUFF KOTE / ANTI-RUST	\$80.00 <i>?</i>
TO CHECK WIRING AND WATER LEAK TEST	\$60.00 <i>200ml</i>
TO REMOVE & REINSTALL REAR WINDSCREEN AND TO PERFORM WATER LEAKAGE TEST	\$180.00 <i>1200ml</i>
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$80.00 <i>600ml</i>

LABOUR TOTAL \$2,200.00

AZMAN

TOTAL \$7,587.23