

ASS. REC. BY:

REF: CS/FCI 18021760/K1+d3ⁿ²

Special Instruction:

Surveyor:

Kalvin

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 10:14am @ 4/12/18

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 6381A

Insured:

SH 9988Z

at Workshop m/s

Premier Automotive

Tel:

G544 6689 / 6544 6671

of

23 Changi South Ave 2 #01-02

Policy No:

Claim No:

D1800851SMFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/11/18

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:19am @ 4/12/18

Person Contacted:

Gum

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 6381A - NA / CFI 17024021 / h4

D.O.A: 18/12/17

SH 9988Z - CC3 / CFI 17010137 / K1wb3n2

D.O.A: 27/15/2017

7/12 @ 2:57pm

Revised preli advise via email

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6381A Yr Regn: 6 Feb, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KTA optima c.c. 1600Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 369986 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1KNA6M414MF5578017

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 30/11/8 D.O.I. 4/12/8Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/12/8	Checked up \$2600 / 4 P. (Red. 2054.40 / 44%) FCI
	4.
RECEIVED 14 DEC 2018	

Date/Time, File Pass to? ☐ : Prel. Report1) 1312 Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

135

50

50

36

271

Report Format: TPLump Sum / I.B.I: (\$ 2600F)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18008515MFSH

Date: 7/12/2018

Our Ref: CS/FCI18021780/K1td3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6381A

Please be informed that we had conducted the inspection of the abovementioned vehicle
22/11/2018 at the premises of M/s Premier Automotive have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,654.40</u>
Revised Estimate Amount	: S\$ <u>3,245.10</u>
"Check" Items Amount	: S\$ <u>130.00</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kalvin

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	30-11-2018	Our Ref No. D18008515MFSH
Accident Date	30-11-2018	Claim Type. Third Party
Insured Vehicle	SH9988Z	Third Party Vehicle. SHC6381A
Survey Location	23 CHANGI SOUTH AVE 2, #01-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 7 December 2018 2:57 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D18008515MFSH/1
Attachments: PRELI ADVISED SHC 6381A.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6381A**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 4 December 2018 11:59 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18008515MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 4 December 2018 10:14 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18008515MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	06 Feb 2015 / 09:21:33	Receipt No.:	AACCK001-AX239-150206-000008
Asset Type:	Vehicle	Transaction Amount:	\$66,712.00
Asset ID:	SHC6381A	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150206092133373825		

Vehicle No.:	SHC6381A
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	06 Feb 2015
Original Registration Date:	06 Feb 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5578017

Engine No.:	D4FDEH313286
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1564
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-

Manufacturing Year:	2014
Open Market Value:	\$20,834.00
Minimum PARF Benefit:	\$8,200.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	06 Feb 2015 09:21:33
COE No.:	2015020601001516Z
COE Expiry Date:	05 Feb 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$52,904.00
Lifespan Expiry Date:	05 Feb 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

3-Dec-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6381 A

1 pc	Rear bumper <i>Rebuilt</i>	\$	696.00
1 pc	Rear bumper lower cover <i>can</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>95/- can o/s x su</i>	\$	58.00 <i>29</i>
1 pc	Rear bumper inner sponge <i>tm</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>can</i>	\$	607.00
1 pc	Rear bumper stay - o/s <i>x su</i>	\$	53.00
2 pcs	Rear bumper reinforcement lower bracket <i>3/5 - can o/s x su</i>	\$	36.00 <i>18</i>
2 pcs	Rear bumper reinforcement upper bracket <i>n/s - can o/s x su</i>	\$	36.00 <i>18</i>
1 pc	Rear bumper n/s reflector <i>can</i>	\$	46.00
1 pc	End panel <i>Bundled</i>	\$	250.00
1 pc	End panel inner garnish <i>x su</i>	\$	74.00
		\$	2,176.00
		\$	217.60
		\$	1,958.40
S/NETT 1 set Rear bumper clips <i>can</i> 1 set Reverse sensor <i>sltd</i> 1 pc Rear n/s fender sticker <i>x an</i> 1 pc End panel inner garnish clips <i>x m</i> Sundry <i>REC</i> To dismantle / replace reverse sensor to new bumper and reset to the same To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. To labour charge for dismantle and renew the accident damaged parts. To heat/cut the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc To putty and spray painting on rear bumper, rear n/s fender, end panel, floorboard compartment To apply rustproofing on the repaired and replaced panels.			
		\$	48.00
		\$	280.00 <i>200</i>
		\$	60.00
		\$	38.00
		\$	50.00 <i>20</i>
		\$	120.00 <i>20</i>
		\$	180.00 <i>50</i>
		\$	1,000.00 <i>600</i>
		\$	800.00 <i>500</i>
		\$	120.00 <i>20</i>
		\$	4,654.40

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Signature: *K. L. K.*
Date: *4/12/18*

4 Days
After Repair photo

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18021780/K1td3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9988Z	Veh. Inspected	SHC 6381A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18008515MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	04/12/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5578017	Colour	SILVER	
Odometer	369986	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/11/2018	Inspection Date	04/12/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6381A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	N/S CRACKED / O/S SERVICEABLE	58.00	29.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
1	REAR BUMPER STAY-O/S	SERVICEABLE	53.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET	N/S CRACKED / O/S SERVICEABLE	36.00	18.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET	N/S CRACKED / O/S SERVICEABLE	36.00	18.00
1	REAR BUMPER N/S REFLECTOR	CRACKED	46.00	46.00
1	END PANEL	BUCKLED	250.00	250.00
1	END PANEL INNER GARNISH	SERVICEABLE	74.00	-
	LESS 10% DISCOUNT		-217.60	-198.40
			1,958.40	1,785.60
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR N/S FENDER STICKER (SN)	NOT NECESSARY	60.00	-
1	END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	38.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			476.00	268.00
LABOUR				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	30.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/CUT THE END PANEL INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF		1,000.00	600.00

Report Ref No. CS/FCI18021780/K1td3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, END PANEL, FLOORBOARD COMPARTMENT.		800.00	540.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
			2,220.00	1,250.00
GRAND TOTAL			4,654.40	3,303.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CS/FCI18021780/K1td3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.