

Not Authorized
 Lm
 2/5 #9500/
 4/12/18
 bdy.

FASTECH AUTO PTE LTD
 1 KAKI BUKIT AVENUE 6
 #01-46/48/50
 SINGAPORE 417883

VEHICLE NO:GBC 3702Z

QTY	PARTICULAR			
1 PCS	FRONT PANEL		2	\$1,245.10 X
1 PCS	FRONT PANEL 'DYNA' EMBLEM		ner	\$66.20
1 PCS	FRONT GRILLE	466.05	cur/cm	\$867.92
1 PCS	FRONT GRILLE LOGO		ner	\$56.90
1 PCS	HEADLAMP N/S	781.45	one	\$899.10
1 PCS	HEADLAMP RUBBER N/S		Torn	\$32.50
1 PCS	FRONT BUMPER	456.81	Dis	\$898.90
1 PCS	FRONT CORNER PANEL N/S	311.20	Dis	\$405.10
1 PCS	FRONT CORNER PANEL TOP GARNISH N/S(BLACK)		cur	\$166.50
1 PCS	FRONT CORNER TOP GARNISH N/S	184.20	cur	\$311.10
1 PCS	FRONT DOOR N/S	1455.10	Body	\$1,655.10
2 PCS	FRONT DOOR HINGES N/S @ \$165.00	101 x 2 = 202	But	\$330.00
1 PCS	FRONT DOOR CHECKER N/S	89.90	cur	\$105.00
1 PCS	FRONT DOOR INNER LOCK N/S	315.30	cur/cm	\$366.50
1 PCS	FRONT DOOR INNER TRIM BOARD N/S	581.10	De/cm	\$645.10
1 SET	FRONT DOOR INNER TRIM BORAD CLIPS		ner	\$50.00
1 PCS	FRONT DOOR INNER RUBBER N/S	245.50	Torn	\$299.50
1 PCS	FRONT DOOR GLASS REGULATOR N/S		11	\$233.20 X
1 PCS	FRONT DOOR GLASS REGULATOR MOTOR N/S		11	\$450.10 X
1 PCS	FRONT DOOR OUTER PILLAR N/S	899.10	Body	\$1,299.10
1 PCS	FRONT DOOR VIEW MIRROR BRACKET N/S		But/cm	\$645.50
1 PCS	FRONT DOOR INNER LOWER RUBBER N/S		Torn	\$199.20
1 PCS	FRONT DOOR WHEEL ARCH PANEL N/S	545.10	But	\$655.10
1 PCS	FRONT DOOR WHEEL ARCH PANEL TOP GARNISH N/S		De	\$266.50
1 PCS	FRONT DOOR WHEEL ARCH INNER PANEL N/S		Body	\$365.10
1 PCS	AIR CON CONDENSER	1245.30	But/cm	\$1,899.10
1 PCS	AIR CON FAN ASSY		wage/cm	\$641.50
1 PCS	FRONT STEP PANEL N/S		But	\$299.50
1 PCS	FRONT STEP GARNISH N/S		one	\$241.10
1 PCS	FRONT FLOOR PANEL		2	\$1,650.10 X
1 PCS	FRONT LOWER ARM N/S		11	\$688.20 X
1 PCS	FRONT SHOCK ABSORBER N/S		11	\$195.30 X
1 PCS	FRONT WHEEL HUB N/S		one	\$845.10 X
1 PCS	FRONT KNUCKLE ARM N/S	506.32	But	\$822.50
1 PCS	FRONT KNUCKLE ARM BEARING N/S		Body	\$295.00
1 PCS	FRONT BALL JOINT N/S		11	\$211.30 X
1 PCS	FRONT CROSS MEMBER		11	\$1,150.20 X
1 PCS	FRONT MUDFLAP N/S	299.30	cur	\$341.10
				\$21,794.32

15h

1509.27
 8931.95

	S.NETT ITEM		
1 SET	FRONT DOOR ROC STICKER N/S	Net \$50.00	305.2
1 PCS	FRONT STEEL RIM N/S	cur/rel \$100.00	505.2
1 PCS	FRONT TYRE N/S	src \$200.00	X
	LABOUR CHARGES:		
	TO CHECK WIRING	\$50.00	-20
	TO CONDUCT WHEEL ALIGNMENT	\$100.00	-60
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	\$180.00	-120
	TO SPRAY RUST PROOFING	\$150.00	-80
	TO DISMANTLE & REFIX FRONT WINDSCREEN	\$150.00	-100
	TO REFILL AIR CON GAS	\$120.00	-100
	TO DISMANTLE & REFIX FRONT DASHBOARD	\$280.00	-200
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN	\$1,500.00	-1100
	& REPLACING PARTS		
	TO PUTTY & SPRAY PAINTING	\$1,500.00	1080
	TOTAL	\$26,174.32	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Pa. is not subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: