

INSURANCE CASE OWNER:

CC 4, ASM 180

2794, T1 f3382

LKK:
IDAC:

85129

Surveyor:

1941Kh

DOI:

ASSIGNMENT

17/12/2018

Date / Time:

Registered in Merimen:

30/11/2018

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SBF 500T



INSRS:

WSP: Wgurnes.

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/12/18
4/12SBF 500T - X; SLM 730 - X
GIVE. Sent out 1st letter

4/12/18

Spoke to OI (Mr. Adnan bin) / confirmed accident details, OI
reversing and collided into TP vehicle. Informing TP claim and
HED. Since OI agree to settle and more HED will be affected
Send letter to OI.
pending finalise

Need before print photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 14/12/18

After call ltr to OI: 19/12/2018

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

13/3/2019

Sent By:

LPK

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 54,982.00

(8

days)

Reduction: 28.58

%

Email

Call

FINAL SETTLEMENT

Date/Time:

4/12/18

Confirm with:

Subtotal

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

H11

If NO or B 28, Ass. Lia:

OI collided into parked
Vehicle

Repair Cost:

(w/loss)

SS 58,830.74

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

1800.00

(\$ 180.00 x 10

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350.00

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS 60,630.74

Global Sum SS:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS 60,630.74

Name 1:

Wearnes Automotive Pte Ltd

Payee 2: (Strike if N/A)

SS

Name 2:

Payee 3: (Strike if N/A)

SS

Name 3:

Tayfhi

REF:

AXIA

2794 171 (P)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

9440K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8 days

Res.: Yes or No

Lum Sum:

1002 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Devek.

Veh No:

SLF500T

Yr Regn:

2014 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Bentley Continental GT c.c 3993

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

34987

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SCBFN63W7EC090237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/40R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

17/12/18

Survey held at

Wanau

Alexandre

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Plp id 54,982.00 (p.d. \$: 22,000.90 / 28.58%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

✓
in 571218

SERVICE ESTIMATE

77926 - C00001
Mr Gay Chee Cheong
16 Garlick Avenue

SL: SERVICE SALES - PC

GST Reg.No: H28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 30/11/2018

WIP No. : 40939

Veh.In/Out: 29/11/2018

*Tel.No. : Mobile: 81832222

Reg.No. : SBF500T

Reg.date : 15/07/2014

Mileage : 0

Chassis No: SCBFN63W7EC090237

Singapore 279647

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Gay Chee Cheong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
302	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT LOWER SPOILER, FRT LH FENDER, FRT RH FENDER, FRT GRILL, ETC	1400 0	8400.00	0		8,400.00	S
300	TO PUTTY SPRAY PAINT ON FRT GRILL, FRT LH & RH FENDER, FRT BUMPER, ETC	0	5500.00	0		5,500.00	S
R06	TO INSTALL FRONT NUMBER PLATE	0	60.00	0		60.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	1750.00	0		1,750.00	S
	B3W3807217RGRU/BUMPE	1.0 EA	7638.60			7,638.60	S
	FRONT SPLITTER V8	1.0 EA	8009.10			8,009.10	S
	GRILLE CTR	1.0 EA	602.60			602.60	S
	BUMPER BEAM FRT	1.0 EA	2560.80			2,560.80	S
	BRACKET FOR DISTANCE	1.0 EA	72.20			72.20	S
	BRACKET FOR DISTANCE	1.0 EA	72.20			72.20	S

5600 .

4400 .

car ✓

✓

car ✓

car ✓

car ? X m

? X m

car ✓

car ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanghin 97495749
28 days

17/12/18 e 1045 WP

* Repairing before paint

sure the auto. w.m.

SERVICE ESTIMATE

77926 - C00001 SL: SERVICE SALES - PC

Mr Gay Chee Cheong
16 Garlick Avenue

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 2

Inv.date: 30/11/2018

WIP No. : 40939

Veh.In/Out: 29/11/2018

*Tel.No. : Mobile: 81832222

Reg.No. : SBF500T

Reg.date: 15/07/2014

Mileage : 0

Chassis No: SCBFN63W7EC090237

Singapore 279647

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Gay Chee Cheong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	GUIDE PROFILE	1.0 EA	131.50			131.50	S ne ✓
	GUIDE PROFILE	1.0 EA	131.50			131.50	S ne ✓
	GUIDE PROFILE	1.0 EA	11.00			11.00	S ne ✓
	GUIDE PROFILE	1.0 EA	17.10			17.10	S ne ✓
	GUIDE PROFILE	1.0 EA	109.50			109.50	S ne ✓
	GUIDE PROFILE	1.0 EA	109.50			109.50	S ne ✓
	B3W3853651BGRU/RADIA	1.0 EA	3802.40			3,802.40	S Cna ✓
	B3W3853667/GRILLE FI	1.0 EA	1831.60			1,831.60	S Cna ✓
	SEAL	1.0 EA	278.50			278.50	S ne ✓
	RADIATOR GRILLE	1.0 EA	2992.80			2,992.80	S Cna ✓
	STRIKER PLATE	1.0 EA	281.20			281.20	S 7 XAM ✓
	B3W3807277A/SECURING	1.0 EA	219.50			219.50	S ne ✓
	BADGE (SELF-ADHESIVE	1.0 EA	145.90			145.90	S ne ✓
	BADGE WING	1.0 EA	915.80			915.80	S ne ✓
	BADGE SEAL	1.0 EA	106.30			106.30	S ne ✓
	ADHESIVE SEALER FL2	1.0 EA	549.10			549.10	S ne ✓
	WING LHF	1.0 EA	14656.30			14,656.30	S bt ✓

SERVICE ESTIMATE

77926 - C00001 SL: SERVICE SALES - PC

Mr Gay Chee Cheong
16 Garlick Avenue

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date: 30/11/2018

WIP No. : 40939

Singapore 279647

Veh.In/Out: 29/11/2018

*Tel.No. : Mobile: 81832222

Reg.No. : SBF500T

Closed by : Derek Oh Siong Wee

Reg.date: 15/07/2014

Svc Consultant :

Mileage : 0

Remarks : Mr Gay Chee Cheong

Chassis No: SCBFN63W7EC090237

Op.No	Description	Hech Qty	Price	Disc%	PKg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

WING RHF	1.0 EA	14656.30				14,656.30	S R X
HEADLIGHT TRIM OUTER	1.0 EA	330.50				330.50	S ns
HEADLIGHT TRIM OUTER	1.0 EA	330.50				330.50	S ns
HEADLIGHT TRIM	1.0 EA	355.30				355.30	S ns
HEADLIGHT TRIM INNER	1.0 EA	355.30				355.30	S ns

Gross Total. 76,982.90

Labour Total	15,710.00
Parts Total	61,272.90
Package Total	0.00

Net.....	76,982.90
GST @ 7.0%	5,388.80
Total.....	82,371.70
Paid.....	0.00
Please Pay..	82,371.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - A00005	SL: AXA INSURANCE PTE LTD	GST Reg.No:M28920628X
AXA INSURANCE PTE LTD		Inv.No. . : B&P 0 Page 1
8 SHENTON WAY,		Inv.date. : 11/01/2019
#27-01 AXA TOWER,		WIP No. . : 40939
SINGAPORE 068811		Veh.In/Out: 17/12/2018 11/01/2019

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Gay Chee Cheong

*Tel.No. . : 6338 7288
 Reg.No. . : SBF500T
 Reg.date . : 15/07/2014
 Mileage .. : 33,858
 Chassis No: SCBFN63W7EC090237

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT LOWER SPOLIER,FRT LH FENDER,FRT RH FENDER,FRT GRILL,ETC	0	5600.00	0		5,600.00	S
800	TO PUTTY SPRAY PAINT ON FRT GRILL,FRT LH & RH FENDER,FRT BUMPER,ETC	0	4400.00	0		4,400.00	S
R06	TO INSTALL FRONT NUMBER PLATE	0	60.00	0		60.00	S
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	1750.00	0		1,750.00	S
	B3W3807217RGRU/BUMPE ①	1.0 EA	7638.60			7,638.60	S ✓
	FRONT SPLITTER V8 ②	1.0 EA	8009.10			8,009.10	S ✓
	BRACKET FOR DISTANCE ③	1.0 EA	72.20			72.20	S ✓
	BRACKET FOR DISTANCE ④	1.0 EA	72.20			72.20	S ✓
	GUIDE PROFILE ⑤	1.0 EA	131.50			131.50	S ✓
	GUIDE PROFILE ⑥	1.0 EA	131.50			131.50	S ✓

SERVICE ESTIMATE

0 - A00005 SL: AXA INSURANCE PTE LTD
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

GST Reg.No:M28920628X
 0 Page 2
 Inv.No. : B&P
 Inv.date. : 11/01/2019
 WIP No. : 40939
 Veh.In/Out: 17/12/2018 11/01/2019
 *Tel.No. : 6338 7288
 Reg.No. : SBF500T
 Reg.date. : 15/07/2014
 Mileage : 33,858
 Chassis No: SCBFN63W7EC090237

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Gay Chee Cheong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	GUIDE PROFILE ⁽⁹⁾	1.0 EA	11.00			11.00 S	/
	GUIDE PROFILE ⁽¹⁰⁾	1.0 EA	17.10			17.10 S	/
	GUIDE PROFILE ⁽¹¹⁾	1.0 EA	109.50			109.50 S	/
	GUIDE PROFILE ⁽¹²⁾	1.0 EA	109.50			109.50 S	/
	B3W3853651BGRU/RADIA ⁽¹⁵⁾	1.0 EA	3802.40			3,802.40 S	/
	B3W3853667/GRILLE FI ⁽¹⁴⁾	1.0 EA	1831.60			1,831.60 S	/
	SEAL ⁽¹³⁾	1.0 EA	278.50			278.50 S	/
	RADIATOR GRILLE ⁽¹¹⁾	1.0 EA	2992.80			2,992.80 S	/
	BADGE (SELF-ADHESIVE ⁽¹⁹⁾	1.0 EA	145.90			145.90 S	/
	BADGE WING ⁽²⁰⁾	1.0 EA	915.80			915.80 S	/
	BADGE SEAL ⁽²¹⁾	1.0 EA	106.30			106.30 S	/
	ADHESIVE SEALER FL2 ⁽²²⁾	1.0 EA	549.10			549.10 S	/
	WING LHF ⁽²⁴⁾	1.0 EA	14656.30			14,656.30 S	/
	HEADLIGHT TRIM OUTER ⁽²⁵⁾	1.0 EA	330.50			330.50 S	/
	HEADLIGHT TRIM OUTER ⁽²⁶⁾	1.0 EA	330.50			330.50 S	/
	HEADLIGHT TRIM ⁽²⁷⁾	1.0 EA	355.30			355.30 S	/
	HEADLIGHT TRIM INNER ⁽²⁸⁾	1.0 EA	355.30			355.30 S	/

SERVICE ESTIMATE

0 - A00005
 AXA INSURANCE PTE LTD
 8 SHENTON WAY,
 #27-01 AXA TOWER,
 SINGAPORE 068811

SL: AXA INSURANCE PTE LTD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 3

Inv.date. : 11/01/2019

WIP No. : 40939

Veh.In/Out: 17/12/2018 11/01/2019

*Tel.No. : 6338 7288

Reg.No. : SBF500T

Reg.date. : 15/07/2014

Mileage : 33,858

Chassis No: SCBFN63W7EC090237

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Gay Chee Cheong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SECURING STRIP (18)	1.0 EA	219.50			219.50	S✓

Labour Total 11,810.00
 Parts Total 43,172.00
 Package Total 0.00

Gross Total. 54,982.00

Net..... 54,982.00

GST @ 7.0% 3,848.74

Total..... 58,830.74

Paid..... 0.00

Please Pay.. 58,830.74

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

◀ Service Request Details

Claim

S8M014Z6

Reference

None 

Loss Date

November 28, 2018

Request Date

November 30, 2018

Due Date

December 7, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SBF500T

Make

TPVD BENTLEY

30-11-2018 @ 1-39pm
Dark wh not in

Model
FLYING SPVR

Service Address

...

Primary Contact/Insured

LIM LEONG SENG ADRIAN
60 SPRINGSIDE WALK, #03-06 THE BROOKS 1, 786020, Singapore

SKNIGHT_88@YAHOO.COM.SG

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions
NON REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Derek Oh Siong Wee <derek.oh@wearnes.com>
Sent: Friday, 30 November, 2018 10:50 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Richmond Ho
Subject: DIRECT SETTLEMENT FOR SBF500T AND SLM73D
Attachments: 1798_001.pdf

Importance: High
Categories: Pragati

Hi

Please refer to the above attachment and check if possible for direct settlement

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6430 4895 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 12/12/2018 14:47
Date Of Accident 28/11/2018 18:55
Exact Location Of Accident AT DELTA HOUSE 2 ALEXANDRA ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM73D
Insured/Policyholder
Name Of Registered Owner LIM LEONG SENG ADRIAN
NRIC No S7318622F
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97212002
Alternative Phone No OFFICE-97212002

Vehicle Particulars

Manufacturer AUDI
Model A5-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken REPORTING ONLY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number GA156743
Cover Note Number

Driver

Name of Driver LIM LEONG SENG ADRIAN
NRIC No S7318622F
Date Of Birth 01/06/1973
Occupation INDOOR
Date Of Driving Pass 25/11/1993
Driving Experience 25 YEARS AND 0 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97212002
Fax Number
Contact Number OFFICE-97212002
Email Address NOEMAIL



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

04 December, 2018

LIM LEONG SENG ADRIAN
60 SPRINGSIDE WALK
#03-06 THE BROOKS 1
SINGAPORE 86020

Dear Sir,

OUR REF : CC4/ASM18021794/fa3 // S8M014Z6
YOUR REF : SLM 73D
ACCIDENT INVOLVING SLM 73D AND SBF 500T ON 28/11/2018 ALONG/AT
HABITAT 34 BOON LEAT TERRACE

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Friday, 14 December 2018 1:01 PM
To: 'Derek Oh Siong Wee'
Cc: Richmond Ho; Admin A; assignments
Subject: RE: DIRECT SETTLEMENT FOR SBF500T AND SLM73D DOA: 28/11/2018 *** LKK REF: CC4/ASM18021794/fa3

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/ASM18021794/fa3
Your Ref: SBF 500T

Dear Sirs,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, kindly arrange TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.


In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not

(PAYMENT BREAKDOWN)

Vehicle No	:	88F 5007-	(Insd veh)	Model	:	BENTLEY GT.V8
	:	8LM73D	(TP veh)			
Date of Accident	:	28/11/2018				

Global Sum Settlement	:	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
Liability	:	100	% (Agreed/Assessed)

Repair Estimate	:	\$82371.70	
Final Repair Cost	:	\$58830.74	
Loss of Use	:	\$ 2500	10 days at \$ 250 per day
Rental (if any)	:	\$	days at \$ (incl of GST) per day
Others	:	\$	
	:	\$	
	:	\$	
	:	\$	
Final Settlement Sum	:	\$61330.74	

Remarks: _____

Payment Instruction: Payee's Breakdown		
1)	WATKINS AUTOMOTIVE PTY LTD	: \$ 58830.74.
2)	GAT CHEE CHONG	: \$ 2500
3)		: \$
4)		: \$

Poh Kin (LKKAUTO)

From: Suhaimi Saidi <suhaimitaidi8069@gmail.com>
Sent: Thursday, 4 April 2019 11:27 AM
To: Poh Kin (LKKAUTO)
Subject: Re: SBF500T / SLM73D DOA 28.11.18

Hi Poh Kin,

We confirmed acceptance, dv please.

Regards

Suhaimi Saidi
Hp:93865752
For Wearnes Automotive Pte Ltd

On Wed, 3 Apr 2019 at 14:19, Poh Kin (LKKAUTO) <pohkin@lkkauto.com> wrote:

WITHOUT PREJUDICE

SAVE AS TO COSTS

Our Ref: CC4/ASM18021794/T1fa3
Your Ref: SBF 500T

Dear Sir/Madam,

We refer to above matter and your letter of demand.

Please be informed we just receive mandate approval from our principal.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 58,830.74
2. Loss of Use (\$180.00 x 10 days)	<u>S\$ 1,800.00</u>
	<u>S\$ 60,630.74</u>

kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Wednesday, 3 April 2019 2:19 PM
To: 'Suhaيمي Saidi'; 'Christine Yow'
Cc: Admin A
Subject: RE: SBF500T / SLM73D DOA 28.11.18

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Our Ref: CC4/ASM18021794/T1fa3
Your Ref: SBF 500T

Dear Sir/Madam,

We refer to above matter and your letter of demand.

Please be informed we just receive mandate approval from our principal.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 58,830.74
2. Loss of Use (\$180.00 x 10 days)	<u>S\$ 1,800.00</u>
	<u>S\$ 60,630.74</u>

kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

Total: \$60630.74

Reply



RE: Pls comment on what is the 'Wing LHF'

Type

🔔 Question

Message

Dear Peter, We refer to the above matter and our tele-conversation, please be informed that our surveyor had conformed the parts for Wing LHF is Wing Left front Fender (with headlight). and refer into Page 6 (whole page) in LKK survey photo. Hope above information clarify. Thank you. Pohkin-03/04/2019

Reply



Pls comment on what is the 'Wing LHF'

ender

Type

🔔 Question

Message

Hi Poh Kin, based on your survey photos, it appeared to be the front fender portion with the headlight (pg 6 of survey photos). Please confirm on this matter before we give mandate approval.

Reply

6897, 6898 ✓, 6899 ✓, 6900.



<S8M014Z6> IA Mandate uploaded

Type

🔗 Question

Message

Dear Cynthia, Liability: Insured collided into third party vehicle (parked). Liability is down against our insured. We did clarify with insured (Mr Adrian Lim) the nature of the accident and he agree to settle, aware that NCD (if any) is affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Wearnes Automotive Pte Ltd" is as follows: - 1)COR(w/gst) : \$58,830.74 + 2) Loss of Use (10daysx\$180.00): \$1,800.00 = Total: \$60,630.74. **08days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 13/03/2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 13/3/2019

Survey Details:

Date of loss	28-Sep-18
Date of appointment	30-Nov-18
Date of survey	17-Dec-18
Location of survey	WEARNES AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SBF 500T
Make and Model	BENTLEY CONTINENTAL GT V8
Date of registration	15-Jul-14
Parf Rebate	
Market Value	\$ 440,000.00
Parf Rebate	\$ 256,009.00
Nett Loss	\$ 183,991.00

Repair details:

Initial Estimate	76,982.90
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 43,172.00
Check items (estimate)	\$ -
Labour	\$ 11,810.00
Total	\$ 54,982.00
Lump Sum(if applicable)	\$ -

Number of days for repair	8 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	58,830.74	(\$54,982.00 x 10 days)
Loss of use	\$	1,800.00	(\$180.00 x 10 days)
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	-	
Others	\$	-	
Proposed Total	\$	60,630.74	

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM 73D (Insd veh)	Model:	BENTLEY CONTINENTAL GT
	SBF 500T (TP veh)		
Date of Accident:	28/11/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	82,371.70
Final Repair Cost	:	\$	58,830.74
Loss of Use	:	\$	1,800.00
Rental (if any)	:	\$	10 days at \$180.00 per day
LTA / GIA Search Fee	:	\$	days

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	60,630.74

Is Third Party Workshop GIA Registered?		<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
		__NIL__		
BOLA Liability: ____100____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	WEARNES AUTOMOTIVE PTE. LTD.	:	\$ 60,630.74

NUR SHAQILAH BTE ABDOL
WAHAB

17/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18021794/T1fa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: PETER WANG

Date : 17-04-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 73D	Veh. Inspected	SBF 500T
Policy No.	GA156743	Coverage (\$)	0.00
Claim No.	S8M014Z6	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	30/11/2018

2. Vehicle Particulars & Condition

Make & Model	BENTLEY CONTINENTAL GT	c.c	3993
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	SCBFN63W7EC090237	Colour	BLUE
Odometer	34987	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/40R20	PIRELLI	6 mm
L/H Front Tyre	275/40R20	PIRELLI	6 mm
R/H Rear Tyre	275/40R20	PIRELLI	6 mm
L/H Rear Tyre	275/40R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/11/2018	Inspection Date	17/12/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBF 500T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	B3W3807217RGRU/BUMPE (SN) (CONSISTENT)	CRACKED	7,638.60	7,638.60
1	FRONT SPLITTER V8 (SN) (CONSISTENT)	CRACKED	8,009.10	8,009.10
1	GRILLE CTR (SN) (CONSISTENT)	NOT NECESSARY	602.60	-
1	BUMPER BEAM FRT (SN) (CONSISTENT)	NOT NECESSARY	2,560.80	-
1	BRACKET FOR DISTANCE (SN) (CONSISTENT)	NECESSARY	72.20	72.20
1	BRACKET FOR DISTANCE (SN) (CONSISTENT)	NECESSARY	72.20	72.20
1	GUIDE PROFILE (SN) (CONSISTENT)	NECESSARY	131.50	131.50
1	GUIDE PROFILE (SN) (CONSISTENT)	NECESSARY	131.50	131.50
1	GUIDE PROFILE (SN) (CONSISTENT)	NECESSARY	11.00	11.00
1	GUIDE PROFILE (SN) (CONSISTENT)	NECESSARY	17.10	17.10
1	GUIDE PROFILE (SN) (CONSISTENT)	NECESSARY	109.50	109.50
1	GUIDE PROFILE (SN) (CONSISTENT)	NECESSARY	109.50	109.50
1	B3W3853651BGRU/RADIA (SN) (CONSISTENT)	CRACKED	3,802.40	3,802.40
1	B3W3853667/GRILLE FI (SN) (CONSISTENT)	CRACKED	1,831.60	1,831.60
1	SEAL (SN) (CONSISTENT)	NECESSARY	278.50	278.50
1	RADIATOR GRILLE (SN) (CONSISTENT)	CRACKED	2,992.80	2,992.80
1	STRIKER PLATE (SN) (CONSISTENT)	NOT NECESSARY	281.20	-
1	B3W3807277A/SECURING (SN) (CONSISTENT)	NECESSARY	219.50	219.50
1	BADGE (SELF-ADHESIVE) (SN) (CONSISTENT)	NECESSARY	145.90	145.90
1	BADGE WING (SN) (CONSISTENT)	NECESSARY	915.80	915.80
1	BADGE SEAL (SN) (CONSISTENT)	NECESSARY	106.30	106.30
1	ADHESIVE SEALER FL2 (SN) (CONSISTENT)	NECESSARY	549.10	549.10
1	WING LHF (SN) (CONSISTENT)	BENT	14,656.30	14,656.30
1	WINF RHF (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	14,656.30	-
1	HEADLIGHT TRIM OUTER (SN) (CONSISTENT)	NECESSARY	330.50	330.50
1	HEADLIGHT TRIM OUTER (SN) (CONSISTENT)	NECESSARY	330.50	330.50
1	HEADLIGHT TRIM (SN) (CONSISTENT)	NECESSARY	355.30	355.30
1	HEADLIGHT TRIM INNER (SN) (CONSISTENT)	NECESSARY	355.30	355.30
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CRACKED	60.00	60.00
			61,332.90	43,232.00

Report Ref No. CC4/ASM18021794/T1fa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT LOWER SPOILER, FRT LH FENDER, FRT RH FENDER, FRT GRILL, ETC. INCLUSIVE OF THE REPAIR OF WINF RHF.		8,400.00	5,600.00
	TO PUTTY SPRAY PAINT ON FRT GRILL, FRT LH & RH FENDER, FRT BUMPER, ETC.		5,500.00	4,400.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		1,750.00	1,750.00
			15,650.00	11,750.00
	GRAND TOTAL		76,982.90	54,982.00
RECOMMENDED COST OF REPAIRS				54,982.00

Report Ref No. CC4/ASM18021794/T1fa3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.