

SERVICE ESTIMATE

77926 - C00001

SL: SERVICE SALES - PC

Mr Gay Chee Cheong

16 Garlick Avenue

Singapore 279647

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Gay Chee Cheong

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 30/11/2018

WIP No. . : 40939

Veh.In/Out: 29/11/2018

*Tel.No. . : Mobile: 81832222

Reg.No. . : SBF500T

Reg.date : 15/07/2014

Mileage .. : 0

Chassis No: SCBFN63W7EC090237

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	------	-----	-------	-------	-----	--------	---

802	TO REPLACE FRONT BUMPER,FRT	1400	0	8400.00	0		8,400.00	S
-----	-----------------------------	------	---	---------	---	--	----------	---

BRACKET,FRT LOWER SPOLIER,FRT

LH FENDER,FRT RH FENDER,FRT

GRILL,ETC

800	TO PUTTY SPRAY PAINT ON FRT	0	0	5500.00	0		5,500.00	S
-----	-----------------------------	---	---	---------	---	--	----------	---

GRILL,FRT LH & RH FENDER,FRT

BUMPER,ETC

R06	TO INSTALL FRONT NUMBER PLATE	0	0	60.00	0		60.00	S
-----	-------------------------------	---	---	-------	---	--	-------	---

280	TO CHECK WIRING INCLUDE	0	0	1750.00	0		1,750.00	S
-----	-------------------------	---	---	---------	---	--	----------	---

RESETTING OF ALL ELECTRICAL

MODULES

B3W3807217RGRU/BUMPE

1.0 EA 7638.60

7,638.60 S

FRONT SPLITTER V8

1.0 EA 8009.10

8,009.10 S

GRILLE CTR

1.0 EA 602.60

602.60 S

BUMPER BEAM FRT

1.0 EA 2560.80

2,560.80 S

BRACKET FOR DISTANCE

1.0 EA 72.20

72.20 S

BRACKET FOR DISTANCE

1.0 EA 72.20

72.20 S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

2.8 days

17/12/18 e 1045 WP

* Repairing before paint

Sur @ 11h45.00

SERVICE ESTIMATE

77926 - C00001 SL: SERVICE SALES - PC
 Mr Gay Chee Cheong
 16 Garlick Avenue

Singapore 279647

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Gay Chee Cheong

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 2
 Inv.date. : 30/11/2018
 WIP No. . : 40939
 Veh.In/Out: 29/11/2018
 *Tel.No. . : Mobile: 81832222
 Reg.No. . : SBF500T
 Reg.date. : 15/07/2014
 Mileage . : 0
 Chassis No: SCBFN63W7EC090237

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

GUIDE PROFILE	1.0 EA	131.50				131.50	S <i>ner</i>
GUIDE PROFILE	1.0 EA	131.50				131.50	S <i>ner</i>
GUIDE PROFILE	1.0 EA	11.00				11.00	S <i>ner</i>
GUIDE PROFILE	1.0 EA	17.10				17.10	S <i>ner</i>
GUIDE PROFILE	1.0 EA	109.50				109.50	S <i>ner</i>
GUIDE PROFILE	1.0 EA	109.50				109.50	S <i>ner</i>
B3W3853651BGRU/RADIA	1.0 EA	3802.40				3,802.40	S <i>ner</i>
B3W3853667/GRILLE FI	1.0 EA	1831.60				1,831.60	S <i>ner</i>
SEAL	1.0 EA	278.50				278.50	S <i>ner</i>
RADIATOR GRILLE	1.0 EA	2992.80				2,992.80	S <i>ner</i>
STRIKER PLATE	1.0 EA	281.20				281.20	S <i>ner</i>
B3W3807277A/SECURING	1.0 EA	219.50				219.50	S <i>ner</i>
BADGE (SELF-ADHESIVE	1.0 EA	145.90				145.90	S <i>ner</i>
BADGE WING	1.0 EA	915.80				915.80	S <i>ner</i>
BADGE SEAL	1.0 EA	106.30				106.30	S <i>ner</i>
ADHESIVE SEALER FL2	1.0 EA	549.10				549.10	S <i>ner</i>
WING LHF	1.0 EA	14656.30				14,656.30	S <i>bt</i>

SERVICE ESTIMATE

77926 - C00001 SL: SERVICE SALES - PC
 Mr Gay Chee Cheong
 16 Garlick Avenue

Singapore 279647

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Gay Chee Cheong

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 30/11/2018
 WIP No. . : 40939
 Veh.In/Out: 29/11/2018
 *Tel.No. . : Mobile: 81832222
 Reg.No. . : SBF500T
 Reg.date. : 15/07/2014
 Mileage . : 0
 Chassis No: SCBFN63W7EC090237

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

WING RHF	1.0 EA	14656.30	14,656.30	S	R X	
HEADLIGHT TRIM OUTER	1.0 EA	330.50	330.50	S	ng	
HEADLIGHT TRIM OUTER	1.0 EA	330.50	330.50	S	ue	
HEADLIGHT TRIM	1.0 EA	355.30	355.30	S	ue	
HEADLIGHT TRIM INNER	1.0 EA	355.30	355.30	S	ue	

	Gross Total.	76,982.90
Labour Total	15,710.00	Net..... 76,982.90
Parts Total	61,272.90	GST @ 7.0% 5,388.80
Package Total	0.00	Total..... 82,371.70
		Paid..... 0.00
		Please Pay.. 82,371.70

GST: S=StdRated; O=OutOfScope; Z=ZeroRated