

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

03 DEC 2018

ESTIMATE

Estimate No. : b1 49317
Date Estimated : 03/12/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ong Li Ping (Wang LiPing)
66 Phoenix Road
#10-05

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 668201

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF1949X	EB36520	30/10/2018	X2 sDrive18i	0

DESCRIPTION

To replace rear bumper & attachments including to make good rear boot lid and to knock out dented area caused by the accident

1770 2,550.00

To respray rear bumper and boot lid

1730 1,923.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To recoat rear boot lid and rear bumper after paint

? 300.00

- Customer Comments:

Signed up grooming package (Revol)

Any invoice before accident?

Sundries.

? 80.00

Total Labour 1: 5,030.00

DESCRIPTION

REAR BUMPER LH SIDE INNER GUIDE
REAR BUMPER RH SIDE INNER GUIDE
REAR BUMPER CARRIER
MOUNTING SMART OPENER (M)
REAR BUMPER PANEL PRIMED (M PDC/ICA)
Bumper trim
LETTERING X2
PLAQUE 74MM
GROMMET
LETTERING S DRIVE 18i
EXPANDING RIVET

QTY	PRIC	VALUE
1	61.50	? 61.50
1	61.50	? 61.50
1	482.20	? 482.20
1	45.30	? 45.30
1	1,123.30	de 1,123.30
1	468.75	de 468.75
1	64.10	ne 64.10
1	71.25	ne 71.25
2	0.75	ne 1.50
1	96.15	ne 96.15
30	1.35	ne 40.50

Total Parts : 2,516.05

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 49317**
Date Estimated : **03/12/2018**
Prepared By : **Han Kwan Yong**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMF1949X	EB36520	30/10/2018	X2 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date&Time 12/12/18 21:27pm Excess S\$ _____
Surveyor's Name Tanpin Sign [Signature]
Surveyor's Tel 97495745 Authorised Yes / No
Authorised Date wp Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail tanpin@thelink.com
No. of Working Days Recommend 4 days - 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,030.00
Parts	:	2,516.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	528.22
Grand Total	:	8,074.27

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **