

15/5/2018

INS. CASE OWNER:

CC / AXA1802

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$:

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Email

Call

Repair Cost:

\$:

(S - x - days)

Loss of Rental (LOR):

\$:

(S - x - days)

Loss of Use (LOU):

\$:

(S - x - days)

Loss of Income (LOI):

\$:

(S - x - days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

\$:

Medical:

\$:

Disbursement:

\$:

(e.g. Tow/ Independent)

Legal Cost

\$:

Total:

\$:

Global Sum \$:

\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

\$:

Name 1:

Name 2:

Payee 2: (Strike if N.A.)

\$:

Name 2:

Payee 3: (Strike if N.A.)

\$:

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$:

REF: ASM(AXA)

4557K

ASSIGNMENT

From: _____ Date: 04/20/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 9LE 5993H

at Workshop m/s

of

Insured:

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 71K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 19 days Res.: Yes or No

Lum Sum: 20. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE5993H Yr Regn: 2016 July

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel 1.5X CVT c.c. 1498

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 189615 T/Radio: Insured / Std / NI / NA

Eng/No: _____

Ct/No: RN1201466

Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Romstone

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 01/12/18 D.O.I. 04/12/18

Survey held at Vermogen

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

05/12/18 refer to email
 US \$ 165W Credit \$ 46639.04 / 74%
 19 + 3Sun + 1PH = 23 days

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

) S + RS: \$

) Photos

) Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18021806/R1pb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 04-12-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLD 4042P	Veh. Inspected	SLE 5993H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/12/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2018	Inspection Date	04/12/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



SLE5993H

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 1/12/2018

Vehicle Reg. No. : SLE5993H
Vehicle Reg. Date: 27-Jul-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4401468
Chassis No. : RU11201466

COST OF CLAIMS

Parts Cost / List Items : \$ 58,636.30
Plus/Less 20% \$ 11,727.26
Total Cost / List : \$ 46,909.04
Special Nett Items : \$ 2,220.00
Total Parts Amount : \$ 49,129.04
Total Labour Amount : \$ 14,010.00
Gross Total : \$ 63,139.04 *63389.04*
GST % : 7% \$ 4,419.73
Nett Amount : \$ 67,558.77

Surveyor Name and Company :

Rasul CLKK7
Date of survey : 06/12/18 @ 1740
Part by Part / Lump Sum 19 days
Resurvey Before Paint After Paint
Authorize/Not Authorize/Without Prejudice
Email : rasul@clkks.com
Fax No : _____
HP No : 90010068

This claim is handled by : MINOKO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No.: **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No.: **L15B4401468**

Chassis No.: **RU11201466**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear number plate lamp LH/RH	X <i>guc</i>	\$ 250.00	X	
2	1	Tailgate	<i>guc</i> /	\$ 1,860.00	<i>11 88</i>	
3	1 set	Tailgate outer garnish	<i>CR</i> /	\$ 285.00		
4	1set	Tailgate outer garnish clips	<i>ne</i> /	\$ 40.00		
5	1	Tailgate logo	<i>ne</i> /	\$ 52.00		
6	1	Tailgate emblem "VEZEL"	<i>ne</i> /	\$ 56.20		
7	2	Tailgate lamp LH/RH (<i>752 each</i>)	<i>CR</i> /	\$ 980.00	<i>504</i>	
8	2set	Tailgate lamp clips	<i>ne</i> /	\$ 50.00		
9	1	Tailgate outer handle switch	X <i>g</i>	\$ 180.00	X	
10	2	Tailgate damper LH/RH	X / <i>ne</i>	\$ 424.00		
11	1	Tailgate wiper motor	X	\$ 250.00	X	
12	1	Tailgate wiper blade	X	\$ 75.00	X	
13	1	Tailgate buzzer	X <i>CR</i> /	\$ 150.00		
14	1	Tailgate inner handle	X <i>guc</i>	\$ 74.00	X	
15	1	Tailgate inner lock	<i>BT</i> /	\$ 245.00		
16	1	Tailgate lock sensor	X <i>CR</i> /	\$ 220.00		
17	1	Tailgate striker	<i>BT</i> /	\$ 32.00		
18	1 set	Tailgate trimboard	<i>DE</i> /	\$ 295.00		
19	1set	Tailgate trimboard clips	<i>ne</i> /	\$ 45.00		
20	1 set	Tailgate weatherstrip	<i>ne</i> /	\$ 145.00		
21	1	Tailgate windscreen moulding	<i>ne</i> /	\$ 164.00		
22	1	Tailgate hinge LH/RH	X <i>guc</i>	\$ 100.00	X	
23	2	Tail lamp LH/RH (<i>460 each</i>)	LH- <i>CR</i> / RH- <i>CR</i> /	\$ 978.00	<i>920</i>	
24	1set	Tail lamp clips	<i>ne</i> /	\$ 36.00		
25	<i>1 set</i>	Tail lamp panel LH/RH (<i>155 each</i>)	LH- <i>BT</i> / RH- <i>Rm</i> /	\$ 1,100.00	<i>50 155</i>	
26	1	Rear bumper	<i>DE</i> /	\$ 950.00	<i>680</i>	
27	1set	Rear bumper clips	<i>ne</i> /	\$ 50.00		
28	<i>1 set</i>	Rear bumper retainer LH/RH	LH- <i>ne</i> / RH- <i>X</i> /	\$ 144.00	<i>72</i>	
29	<i>1 set</i>	Rear bumper bracket LH/RH	LH- <i>ne</i> / RH- <i>X</i> /	\$ 116.00	<i>58</i>	
30	<i>1 set</i>	Rear bumper reflector LH/RH	LH- <i>DE</i> / RH- <i>X</i> /	\$ 334.00	<i>45 131</i>	
31	<i>1 set</i>	Rear bumper cover LH/RH	LH- <i>DE</i> / RH- <i>X</i> /	\$ 420.00	<i>245 198</i>	
32	<i>1 set</i>	Rear bumper cover clips	LH- <i>ne</i> / RH- <i>X</i> /	\$ 100.00	<i>50</i>	
33	<i>1 set</i>	Rear bumper cover retainer LH/RH	LH- <i>ne</i> / RH- <i>X</i> /	\$ 84.00	<i>42</i>	
34	1	Rear end panel outer	<i>guc</i> /	\$ 585.00	<i>price?</i>	<i>415</i>
35	1	Rear end panel inner	X <i>guc</i>	\$ 396.00		
36	1	Rear end panel top garnish	<i>DE</i> /	\$ 184.00		
37	1set	Rear end panel top garnish clips	<i>ne</i> /	\$ 25.00		
38	1	Spare tyre panel	<i>Repair</i> /	\$ 1,230.00		
39	1	Spare tyre panel insulator	X <i>ne</i>	\$ 240.00	X	
40	1	Spare tyre panel top board	<i>DE</i> /	\$ 420.00	<i>306</i>	

6705.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre tool tray	CR4	\$ 430.00	215	
42	1pc	Rear fender panel LH/RH	LH-Repair/RH-Repair	\$ 1,900.00	950	
43	2	Rear fender lower inner trim LH/RH	DE	\$ 480.00		
44	2	Rear fender lower inner trim clip LH/RH	na	\$ 100.00		
45	1pc	Rear fender arch garnish LH/RH	LH-Repair/RH-X	\$ 330.00	165	
46	2set	Rear fender arch garnish clips	LH-Repair/RH-X	\$ 80.00	40	
47	2	Rear fender inner water shield LH/RH	X	\$ 320.00		
48	2set	Rear fender inner water shield clips	X	\$ 100.00		
49	1pc	Rear fender Air duct LH/RH	na LH-X/RH-X	\$ 150.00	75 X	
50	1	Exhaust muffler	X	\$ 855.00		
51	1	Exhaust muffler mounting	X	\$ 79.50		
52	1	Exhaust muffler heat shield	X	\$ 165.00		
53	1	Rear number plate with frame	M	\$ 55.00	35	
54	1	Tailgate windscreen sealant	na	\$ 80.00	80/100	
55	1	Tailgate windscreen inner seal	na	\$ 80.00	60	
56	1	Rear end panel sealant	na	\$ 80.00	60	
57	1	Reverse sensor	na	\$ 300.00	200	
58	1	Spare tyre panel sealant	X	\$ 80.00	X	
59	1	Spare tyre panel padding	X	\$ 80.00	X	
60	1	Sundries	na	\$ 80.00	40	
61	1	Reverse camera	X	\$ 300.00		
62	1pc	Rear door	LH-Repair/RH-X	\$ 2,084.00		
63	2	Rear door front rubber	X	\$ 80.00		
64	2	Rear door bottom rubber	X	\$ 80.00		
65	2	Rear door back rubber	X	\$ 64.00		
66	2	Rear door sticker	X	\$ 92.00		
67	2	Rear door moulding	X	\$ 170.00		
68	2	Rear door weather strip	X	\$ 190.00		
69	2	Rear door regulator	X	\$ 954.00		
70	2	Rear door lock mechanism	X	\$ 754.00		
71	1	Rear door lock catch	X	\$ 66.00		
72	1	Bonnet	na	\$ 1,130.00	819	
73	2	Bonnet hinge LH/RH	X	\$ 124.00		
74	1	Front tow hook cover	X	\$ 62.00		
75	1	Bonnet insulator	X	\$ 160.00		
76	1set	Bonnet insulator clips	na	\$ 50.00		
77	2	Bonnet rubber side	na	\$ 66.80		
78	1	Bonnet rubber centre	na	\$ 35.20		
79	1	Bonnet lock mechanism	X	\$ 75.00		
80	1	Bonnet lock mechanism cable	X	\$ 36.00		

2921.00

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	1	Front grille base	CRA /	\$ 250.00		
82	1	Front grille garnish	CRA /	\$ 285.00		
83	1	Front grille chrome	X gm	\$ 1,150.00		
84	1	Front grille side bracket	CRA /	\$ 279.00		
85	1	Front grille centre bracket	CRA /	\$ 139.50		
86	1set	Front grille clips	AM /	\$ 50.00		
87	1	Front grille logo	AM /	\$ 28.20		
88	1	Front support panel	repair	\$ 576.20		
89	1	Front support panel top garnish	X	\$ 185.00		
90	1set	Front support panel top garnish clips	X	\$ 35.00		
91	1	Front support lower panel	X	\$ 422.20		
92	1	Air intake duct	X AM	\$ 115.00		
93	1	Washer tank	X	\$ 120.00		
94	1	Washer tank motor	X	\$ 59.60		
95	2	Headlamp LH/RH	CRA /	\$ 5,080.00	7568	
96	2	Headlamp lower bracket LH/RH	CRA /	\$ 140.00		
97	1	Front bumper	DE /	\$ 927.50	801	
98	1	Front bumper lower rubber	X AM	\$ 200.00		
99	1set	Front bumper clips	AM /	\$ 50.00		
100	2	Front bumper retainer LH/RH	AM /	\$ 92.00		
101	1	Front bumper reinforcement	BT /	\$ 321.00	290	
102	2	Front bumper reinforcement garnish	X AM	\$ 60.00		
103	1	Front bumper lower lip	AM /	\$ 351.00	195	
104	1set	Front bumper lower lip clips	AM /	\$ 50.00		
105	2	Front bumper fog lamp garnish LH/RH	at /	\$ 180.00		
106	2	Front bumper fog lamp LH/RH	X	\$ 775.40		
107	2	Front lower splash cover LH/RH	X	\$ 210.00		
108	1set	Front lower splash cover clips	X AM	\$ 50.00		
109	1	Front lower splash cover centre	X	\$ 249.00		
110	1set	Front lower splash cover centre clips	X	\$ 30.00		
111	2	Radiator side garnish LH/RH	X	\$ 150.00		
112	1	A/C Condenser	BT /	\$ 538.50		
113	1	A/C fan assy	X AM	\$ 392.00		
114	1	Radiator	? BT /	\$ 1,220.00		
115	1	Radiator fan assy	X	\$ 483.00		
116	1	Radiator spare tank	X	\$ 55.00		
117	1	Air resonator	X AM	\$ 173.00		
118	2	Front door	X	\$ 2,284.00		
119	1	Horn	X	\$ 64.00		
120	2	Front fender inner shield LH/RH	X	\$ 302.00		

8156.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 4

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
121	2	Front fender inner shield clips	X	\$ 80.00	X	
122	2	Front fender arch garnish LH/RH	X	\$ 330.00	X	
123	2	Front fender arch garnish clips	X	\$ 80.00	X	
124	2	Front fender LH/RH	X	\$ 1,320.00	X	
125	2	Rear fender inner upper trim	X	\$ 146.00	X	
126	1	Roof lining	X	\$ 1,250.00	X	
127	1	Radiator coolant	ne		\$ 80.00	60
128	1	Front number plate with casing	CRA		\$ 55.00	35
129	1	Top up gas	ne		\$ 150.00	100
130	2	Rear chassic member	Repair	\$ 1,440.00	X	
131	2	Rear wheel house LH/RH	X	\$ 1,396.40	X	
132	2	Rear floor side panel LH/RH	repair	\$ 320.00	X	
133	1	Rear tow hook panel center	X	\$ 95.00	X	
134	1	Rear crossmember	X	\$ 250.00	X	
135	1	EDCL MODULE	X	\$ 1,043.30	X	
136	1	TAILGATE WINDSCREEN	X	\$ 1,150.10	X	
137	1	TAILGATE SPOILER	X	\$ 430.20	X	
138	1	THIRD BRAKE LIGHT	X	\$ 280.00	X	
139	1	ROOF PANEL	X	\$ 915.40	X	
140	2	REAR SEAT CUSHION	X		\$ 800.00	an
141	2	REAR SEAT BELT	X	\$ 1,360.00	X	
142	2	SIDE SKIRT	X	\$ 755.00	X	
143	2SET	SIDE SKIRT CLIPS	X	\$ 70.00	X	
144	2	ROCKEL PANEL	X	\$ 1,321.20	X	
145	1	TAILGATE WIRE HARNESS	X	\$ 891.10	X	
146	1	REAR WIRE HARNESS	X	\$ 963.80	X	
147	0	0				
148	0	0				
149	0	0				
150	0	0				
151	0	0				
152	0	0				
153	0	0				
154	0	0				
155	0	0				
156	0	0				
157	0	0				
158	0	0				
159	0	0				
160	0	0				

1358.00

195

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion. TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER X2, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL X2, RR FENDER X2, RR DOOR X2, RR WHEEL HOUSE X2, REAR FLOOR SIDE PANEL X2, RR CROSSMEMBER.	\$ 3,500.00	1400 1800
2	To putty, respray painting and polish accident area. Rear Portion. TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER X2, RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL X2, REAR FENDER X2, RR DOOR X2, RR WHEEL HOUSE X2, RR FLOOR SIDE PANEL X2, RR CROSSMEMBER, RR CHASSIS MEMBER X2	\$ 2,600.00	1600
3	To remove and transfer tailgate components.	\$ 180.00	80
4	To remove and refit tailgate windscreen.	\$ 180.00	120
5	To remove and refit reverse sensor.	\$ 150.00	60
6	To rust proof affected areas.	\$ 300.00	150
7	To check and rectify wiring after disconnect and connect.	\$ 180.00	60
8	To remove and refit interior parts to give way the repair.	\$ 180.00	80
9	To remove and aligned exhaust pipe.	\$ 180.00	X X M
10	To mount vehicle on chassis member (plate)	\$ 350.00	150
11	To remove and transfer Rear door LH components.	\$ 180.00	X M
12	To straighten and panel beating accident area. Front Portion. BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL, FRT FENDER LH/RH.	\$ 2,400.00	600

4929

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: 27/7/2016

Make / Model : H. VEZEL 1.5X CVT

Engine No. : L15B4401468

Chassis No. : RU11201466

PAGE 2

Estimates on Labour

[illegible]

LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver

Signature: _____

Date:

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLE5993H
Vehicle Reg. Date:	27/7/2016
Make / Model :	H. VEZEL 1.5X CVT
Engine No. :	L15B4401468
Chassis No. :	RU11201466

Supplementary Estimates on Labour

[illegible]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: LKK-RASUL
Surveyor Name and Company

Date of Accident : 1/12/2018

BILL TO: AXA

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SLE5993H

Make / Model : H. VEZEL 1.5X CVT

COST OF CLAIMS

Parts Cost / List : \$ 17,943.70

Supp. Parts : \$ -

Special Nett : \$ 630.00

Total Parts : \$ 14,984.96

Total Labour : \$ 5,650.00

TOTAL REPAIR COST : \$ 20,634.96

Total Parts Cost/List :	\$ 17,943.70
Plus / Less : 20%	\$ 3,588.74
Total :	\$ 14,354.96

Lump Sum Discount : 20%	\$ 4,126.99
Lump Sum Amount:	\$ 16,507.97

Final Lump Sum Amount : \$ 16,500.00

Submitted by / Date : MINOKO

No. of Repair Days: 19

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**
Vehicle Reg. Date: **27/7/2016**
Make / Model : **H. VEZEL 1.5X CVT**
Engine No. : **L15B4401468**
Chassis No. : **RU11201466**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear number plate lamp LH/RH		\$ 250.00		
2	1	Tailgate		\$ 1,860.00		\$ 1,860.00
3	1 set	Tailgate outer garnish		\$ 285.00		\$ 285.00
4	1set	Tailgate outer garnish clips		\$ 40.00		\$ 40.00
5	1	Tailgate logo		\$ 52.00		\$ 52.00
6	1	Tailgate emblem "VEZEL"		\$ 56.20		\$ 56.20
7	2	Tailgate lamp LH/RH		\$ 980.00		\$ 980.00
8	2set	Tailgate lamp clips		\$ 50.00		\$ 50.00
9	1	Tailgate outer handle switch		\$ 180.00		
10	2	Tailgate damper LH/RH		\$ 424.00		
11	1	Tailgate wiper motor		\$ 250.00		
12	1	Tailgate wiper blade		\$ 75.00		
13	1	Tailgate buzzer		\$ 150.00		\$ 150.00
14	1	Tailgate inner handle		\$ 74.00		
15	1	Tailgate inner lock		\$ 245.00		\$ 245.00
16	1	Tailgate lock sensor		\$ 220.00		\$ 220.00
17	1	Tailgate striker		\$ 32.00		\$ 32.00
18	1 set	Tailgate trimboard		\$ 295.00		\$ 295.00
19	1set	Tailgate trimboard clips		\$ 45.00		\$ 45.00
20	1 set	Tailgate weatherstrip		\$ 145.00		\$ 145.00
21	1	Tailgate windscreen moulding		\$ 164.00		\$ 164.00
22	1	Tailgate hinge LH/RH		\$ 100.00		
23	2	Tail lamp LH/RH		\$ 978.00		\$ 978.00
24	1set	Tail lamp clips		\$ 36.00		\$ 36.00
25	2	Tail lamp panel LH/RH		\$ 1,100.00		\$ 550.00
26	1	Rear bumper		\$ 950.00		\$ 950.00
27	1set	Rear bumper clips		\$ 50.00		\$ 50.00
28	2	Rear bumper retainer LH/RH		\$ 144.00		\$ 72.00
29	2	Rear bumper bracket LH/RH		\$ 116.00		\$ 58.00
30	2	Rear bumper reflector LH/RH		\$ 334.00		\$ 167.00
31	2	Rear bumper cover LH/RH		\$ 420.00		\$ 210.00
32	2set	Rear bumper cover clips		\$ 100.00		\$ 50.00
33	2	Rear bumper cover retainer LH/RH		\$ 84.00		\$ 42.00
34	1	Rear end panel outer		\$ 585.00		\$ 585.00
35	1	Rear end panel inner		\$ 396.00		
36	1	Rear end panel top garnish		\$ 184.00		\$ 184.00
37	1set	Rear end panel top garnish clips		\$ 25.00		\$ 25.00
38	1	Spare tyre panel		\$ 1,230.00		
39	1	Spare tyre panel Insulator		\$ 240.00		\$ 240.00
40	1	Spare tyre panel top board		\$ 420.00		\$ 420.00

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre tool tray		\$ 430.00		\$ 430.00
42	2	Rear fender panel LH/RH		\$ 1,900.00		\$ 950.00
43	2	Rear fender lower inner trim LH/RH		\$ 480.00		\$ 480.00
44	2	Rear fender lower inner trim clip LH/RH		\$ 100.00		\$ 100.00
45	2	Rear fender arch garnish LH/RH		\$ 330.00		\$ 165.00
46	2set	Rear fender arch garnish clips		\$ 80.00		\$ 40.00
47	2	Rear fender inner water shield LH/RH		\$ 320.00		
48	2set	Rear fender inner water shield clips		\$ 100.00		
49	2	Rear fender Air duct LH/RH		\$ 150.00		\$ 75.00
50	1	Exhaust muffler		\$ 855.00		
51	1	Exhaust muffler mounting		\$ 79.50		
52	1	Exhaust muffler heat shield		\$ 165.00		
53	1	Rear number plate with frame			\$ 35.00	
54	1	Tailgate windscreen sealant			\$ 50.00	
55	1	Tailgate windscreen inner seal			\$ 50.00	
56	1	Rear end panel sealant			\$ 60.00	
57	1	Reverse sensor			\$ 200.00	
58	1	Spare tyre panel sealant			\$ -	
59	1	Spare tyre panel padding			\$ -	
60	1	Sundries			\$ 40.00	
61	1	Reverse camera			\$ -	
62	2	Rear door		\$ 2,084.00		
63	2	Rear door front rubber		\$ 80.00		
64	2	Rear door bottom rubber		\$ 80.00		
65	2	Rear door back rubber		\$ 64.00		
66	2	Rear door sticker		\$ 92.00		
67	2	Rear door moulding		\$ 170.00		
68	2	Rear door weather strip		\$ 190.00		
69	2	Rear door regulator		\$ 954.00		
70	2	Rear door lock mechanism		\$ 754.00		
71	1	Rear door lock catch		\$ 66.00		
72	1	Bonnet		\$ 1,130.00		\$ 113.00
73	2	Bonnet hinge LH/RH		\$ 124.00		
74	1	Front tow hook cover		\$ 62.00		
75	1	Bonnet insulator		\$ 160.00		
76	1set	Bonnet insulator clips		\$ 50.00		\$ 50.00
77	2	Bonnet rubber side		\$ 66.80		\$ 66.80
78	1	Bonnet rubber centre		\$ 35.20		\$ 35.20
79	1	Bonnet lock mechanism		\$ 75.00		
80	1	Bonnet lock mechanism cable		\$ 36.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	1	Front grille base		\$ 250.00		\$ 250.00
82	1	Front grille garnish		\$ 285.00		\$ 285.00
83	1	Front grille chrome		\$ 1,150.00		
84	1	Front grille side bracket		\$ 279.00		\$ 279.00
85	1	Front grille centre bracket		\$ 139.50		\$ 139.50
86	1set	Front grille clips		\$ 50.00		\$ 50.00
87	1	Front grille logo		\$ 28.20		\$ 28.20
88	1	Front support panel		\$ 576.20		
89	1	Front suport panel top garnish		\$ 185.00		
90	1set	Front support panel top garnish clips		\$ 35.00		
91	1	Front support lower panel		\$ 422.20		
92	1	Air intake duct		\$ 115.00		
93	1	Washer tank		\$ 120.00		
94	1	Washer tank motor		\$ 59.60		
95	2	Headlamp LH/RH		\$ 5,080.00		\$ 50.80
96	2	Headlamp lower bracket LH/RH		\$ 140.00		\$ 140.00
97	1	Front bumper		\$ 927.50		\$ 927.50
98	1	Front bumper lower rubber		\$ 200.00		
99	1set	Front bumper clips		\$ 50.00		\$ 50.00
100	2	Front bumper retainer LH/RH		\$ 92.00		\$ 92.00
101	1	Front bumper reinforcement		\$ 321.00		\$ 321.00
102	2	Front bumper reinforcement garnish		\$ 60.00		
103	1	Front bumper lower lip		\$ 351.00		\$ 351.00
104	1set	Front bumper lower lip clips		\$ 50.00		\$ 50.00
105	2	Front bumper fog lamp garnish LH/RH		\$ 180.00		\$ 180.00
106	2	Front bumper fog lamp LH/RH		\$ 775.40		
107	2	Front lower splash cover LH/RH		\$ 210.00		
108	1set	Front lower splash cover clips		\$ 50.00		
109	1	Front lower splash cover centre		\$ 249.00		
110	1set	Front lower splash cover centre clips		\$ 30.00		
111	2	Radiator side garnish LH/RH		\$ 150.00		
112	1	A/C Condenser		\$ 538.50		\$ 538.50
113	1	A/C fan assy		\$ 392.00		
114	1	Radiator		\$ 1,220.00		\$ 1,220.00
115	1	Radiator fan assy		\$ 483.00		
116	1	Radiator spare tank		\$ 55.00		
117	1	Air resonator		\$ 173.00		
118	2	Front door		\$ 2,284.00		
119	1	Horn		\$ 64.00		
120	2	Front fender inner shield LH/RH		\$ 302.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**

Vehicle Reg. Date: **27/7/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4401468**

Chassis No. : **RU11201466**

PAGE 4

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
121	2	Front fender inner shield clips		\$ 80.00		
122	2	Front fender arch garnish LH/RH		\$ 330.00		
123	2	Front fender arch garnish clips		\$ 80.00		
124	2	Front fender LH/RH		\$ 1,320.00		
125	2	Rear fender inner upper trim		\$ 146.00		
126	1	Roof lining		\$ 1,250.00		\$ 1,250.00
127	1	Radiator coolant			\$ 60.00	
128	1	Front number plate with casing			\$ 35.00	
129	1	Top up gas			\$ 100.00	
130	2	Rear chassic member		\$ 1,440.00		
131	2	Rear wheel house LH/RH		\$ 1,396.40		
132	2	Rear floor side panel LH/RH		\$ 320.00		
133	1	Rear tow hook panel center		\$ 95.00		
134	1	Rear crossmember		\$ 250.00		
135	1	EDCL MODULE		\$ 1,043.30		
136	1	TAILGATE WINDSCREEN		\$ 1,150.10		
137	1	TAILGATE SPOILER		\$ 430.20		
138	1	THIRD BRAKE LIGHT		\$ 280.00		
139	1	ROOF PANEL		\$ 915.40		
140	2	REAR SEAT CUSHION			\$ -	
141	2	REAR SEAT BELT		\$ 1,360.00		
142	2	SIDE SKIRT		\$ 755.00		
143	2SET	SIDE SKIRT CLIPS		\$ 70.00		
144	2	ROCKEL PANEL		\$ 1,321.20		
145	1	TAILGATE WIRE HARNESS		\$ 891.10		
146	1	REAR WIRE HARNESS		\$ 963.80		
147	0	0				
148	0	0				
149	0	0				
150	0	0				
151	0	0				
152	0	0				
153	0	0				
154	0	0				
155	0	0				
156	0	0				
157	0	0				
158	0	0				
159	0	0				
160	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE5993H**
Vehicle Reg. Date: **27/7/2016**
Make / Model : **H. VEZEL 1.5X CVT**
Engine No. : **L15B4401468**
Chassis No. : **RU11201466**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion.	\$ 3,500.00	\$ 1,800.00
	TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER X2,		
	RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL X2, RR FENDER X2,		
	RR DOOR X2, RR WHEEL HOUSE X2, REAR FLOOR SIDE PANEL X2, RR CROSSMEMBER.		
2	To putty, respray painting and polish accident area. Rear Portion.	\$ 2,600.00	\$ 1,600.00
	TAILGATE, TAILGATE GANISH, RR BUMPER, RR BUMPER SIDE COVER X2,		
	RR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL X2, REAR FENDER X2,		
	RR DOOR X2, RR WHEEL HOUSE X2, RR FLOOR SIDE PANEL X2, RR CROSSMEMBER,		
	RR CHASSIS MEMBER X2		
3	To remove and transfer tailgate components.	\$ 180.00	\$ 80.00
4	To remove and refit tailgate windscreen.	\$ 180.00	\$ 120.00
5	To remove and refit reverse sensor.	\$ 150.00	\$ 60.00
6	To rust proof affected areas.	\$ 300.00	\$ 150.00
7	To check and rectify wiring after disconnect and connect.	\$ 180.00	\$ 60.00
8	To remove and refit interior parts to give way the repair.	\$ 180.00	\$ 80.00
9	To remove and aligned exhaust pipe.	\$ 180.00	
10	To mount vehicle on chassis member	\$ 350.00	\$ 150.00
11	To remove and transfer Rear door LH components.	\$ 180.00	
12	To straighten and panel beating accident area. Front Portion.	\$ 2,400.00	\$ 600.00
	BONNET, FRT BUMPER, FRT BUMPER REINFORCEMENT, FRT SUPPORT PANEL,		
	FRT FENDER LH/RH.		

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 2

[illegible]

Hsiao Tong (LKKAUTO)

From: Minoko Chan <minoko@vermogen-group.com>
Sent: Tuesday, 15 January 2019 8:29 PM
To: Shirley Hiew (LKK Auto)
Cc: Hsiao Tong (LKKAUTO); Pila Ng; Tezano Exequiel Dawal; Baldoz Juan Paulo Bongon; desmond; Vmg admin; Vermogen Ace; Rasul (LKKAUTO); SUR
Subject: Re: SLE5993H FINALISE

Dear Rasul,

1st reminder.

Refer to attachment, kindly confirm & acceptance finalise @ COR \$16,500.00 & 19 repair days (excluding PRS/RS/Weekend & PH).

please revert ASAP

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

On Wed, Jan 2, 2019 at 1:38 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Hsiao Tong,

CC4/ASM18021806/R1pb3

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Minoko Chan [mailto:minoko@vermogen-group.com]

Sent: Wednesday, 2 January 2019 12:40 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Pila Ng <pila@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>; desmond <desmond@vermogen-group.com>; Vmg admin <vmg@vermogen-group.com>; Vermogen Ace <ace@vermogen-group.com>

Subject: SLE5993H FINALISE

Dear Rasul,

Refer to attachment, kindly confirm & acceptance finalise @ COR \$16,500.00 & 19 repair days (excluding PRS/RS/Weekend & PH).

please revert.ASAP

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

















